


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wollondilly Public School (4438)
Region : Illawarra and South East
State Electorate : Goulburn
Local Government Area : Goulburn Mulwaree

Initial Survey : Noel Arnold & Associates : 07 - May - 2008
Reviewed By : Parsons Brinckerhoff : 13 - Jul - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Library - 1973 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00A - R0001 - Interview (18.51 m2)

Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00A - R0002 - Interview (12.48 m2)

Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00A - R0003 - Interview (40.46 m2)

Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00A - R0005 - Staff Toilet (4 m2)

Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00A - R0006 - General Storeroom (7.01 m2)

Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4438/B00A/R0027/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)

B00A - R0007 - Distribution Board (0.54 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4438/B00A/R0027/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)

B00A - R0008 - General Storeroom (0.41 m2)

Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4438/B00A/R0027/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)

Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00A - R0011 - Clerical Office (15.26 m2)

Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00A - R0012 - Uniform Shop (4.17 m2)


Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00A - R0013 - Sick Bay (6.24 m2)

Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0014 - Cleaning Distributed Store (4.05 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4438/B00A/R0027/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)	
B00A - R0015 - Staff Toilet (4.57 m2)						
No Asbestos						
B00A - R0016 - Movement (36.34 m2)						
Ceiling Structures/Linings	Vermiculite					
4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R0017 - Movement (1.35 m2)						
No Asbestos						
B00A - R0018 - Staff Room Annexe (28.65 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4438/B00A/R0027/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)	
B00A - R0019 - Principal (24.1 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4438/B00A/R0027/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)	
B00A - R0020 - Deputy Principal (18.51 m2)						
Ceiling Structures/Linings	Vermiculite					
4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R0022 - Movement (1.34 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4438/B00A/R0022/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R0023 - Movement (95.41 m2)						
No Asbestos						
B00A - R0024 - Movement (2.5 m2)						
Ceiling Structures/Linings	Vermiculite					
4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R0025 - Staff Toilet (3.46 m2)						
Ceiling Structures/Linings	Vermiculite					
4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R0027 - Communications Room (3.84 m2)						
Ceiling Structures/Linings	Vermiculite					
4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4438/B00A/R0027/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)	
B00A - R0029 - Movement (55.81 m2)						
Ceiling Structures/Linings	Vermiculite					
4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R0030 - Stairs (1.61 m2)						
Ceiling Structures/Linings	Vermiculite					
4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R0031 - Stairs (1.55 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0032 - General Storeroom (11.05 m2)						
Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4438/B00A/R0027/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)
B00A - R1001 - Staff Room (104.45 m2)						
Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R1002 - General Storeroom (6.86 m2)						
Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R1003 - Staff Kitchen (22.3 m2)						
Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R1004 - Movement (5.8 m2)						
Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R1005 - Distribution Board (0.26 m2)						
						Note: No inspection of live electrical installation.
Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R1006 - Movement (2.09 m2)						
Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R1007 - Stairs (1.61 m2)						
Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R1008 - Stairs (1.55 m2)						
Ceiling Structures/Linings	Vermiculite					
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Building Services/Electrical Services - 1973 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00B - R0001 - Cleaning Distributed Store (10.83 m2)

No Asbestos

B00B - R0002 - Main Switch Board (3.09 m2)

Electrical Backing Board	Resinous Board	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4438/B00B/R0002/Electrical Backing Board/S12					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Building Services - 2003 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00C - R0001 - Garden Store (61.02 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Support Unit - 2005 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00D - R0001 - General Storeroom (15.28 m2)

No Asbestos

B00D - R0002 - General Storeroom (14.99 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Support Unit - 1971 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	15m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4438/B00E/Room+1/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Bituminous debris					No Asbestos Detected
	4438/B00E/Underfloor Voids/S13					
Underfloor Voids	AC Fragments/Debris	1m2	Throughout	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	4438/B00E/Underfloor Voids/S14				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4438/B00E/Underfloor Voids - Packing to Floor Joists/S15				Chrysotile (white asbestos)	

Interior**B00E - R0001 - Kitchen - Pre (7.9 m2)**

No Asbestos

B00E - R0003 - Home Base - E (53.35 m2)

No Asbestos

B00E - R0007 - Access Shower/Toilet (6.76 m2)

Wall Linings Internal	Flat AC Sheeting					
	4438/B00E/R0007/Wall Linings Internal/S11				No Asbestos Detected	

B00E - R0008 - Toilet - E (1.19 m2)

Wall Linings Internal	Flat AC Sheeting					
	4438/B00E/R0007/Wall Linings Internal/S11				No Asbestos Detected	

B00E - R0009 - Clerical Office - Pre (21.25 m2)

Floor Coverings Res/Textile	Vinyl Tiles	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4438/B00E/R0011/Floor Coverings Res/Textile/S9				Chrysotile (white asbestos)	

B00E - R0010 - Clerical Office - Pre (14.35 m2)

Floor Coverings Res/Textile	Vinyl Tiles	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4438/B00E/R0011/Floor Coverings Res/Textile/S9				Chrysotile (white asbestos)	

B00E - R0011 - Clerical Office - Pre (16.83 m2)

Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4438/B00E/R0011/Floor Coverings Res/Textile/S9				Chrysotile (white asbestos)	

B00E - R0012 - Movement (14.63 m2)

Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4438/B00E/R0012/Ceiling Structures/Linings/S16				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Communal Facilities - 1973 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids Non Accessible Area
- No void access

Underfloor Voids - Slab on Ground No Asbestos Found

Interior**B00H - M0001 - General Storeroom (12.56 m2)**

Ceiling Structures/Linings Vermiculite
4438/B00A/R0003/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00H - M0002 - General Storeroom (12.62 m2)

Ceiling Structures/Linings Vermiculite
4438/B00A/R0003/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00H - R0001 - Communal Space (220.4 m2)

Ceiling Structures/Linings Vermiculite
4438/B00A/R0003/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00H - R0009 - Movement (1.88 m2)

Ceiling Structures/Linings Flat AC Sheeting 2m2 North, South Good Condition (1) Low (1) Low Priority (2-3)
4438/B00I/R0001/Ceiling Structures/Linings/S5 **Chrysotile (white asbestos)**

B00H - R0010 - Movement (1.89 m2)

Ceiling Structures/Linings Flat AC Sheeting 2m2 North, South Good Condition (1) Low (1) Low Priority (2-3)
4438/B00I/R0001/Ceiling Structures/Linings/S5 **Chrysotile (white asbestos)**

B00H - R0011 - Raised Platform (79.09 m2)

Ceiling Structures/Linings Flat AC Sheeting 20m2 North, South Good Condition (1) Low (1) Low Priority (2-3)
4438/B00I/R0001/Ceiling Structures/Linings/S5 **Chrysotile (white asbestos)**

Ceiling Structures/Linings Vermiculite
4438/B00A/R0003/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00H - R0012 - Stairs (1.14 m2)

Ceiling Structures/Linings Flat AC Sheeting 2m2 North, South Good Condition (1) Low (1) Low Priority (2-3)
4438/B00I/R0001/Ceiling Structures/Linings/S5 **Chrysotile (white asbestos)**

B00H - R0013 - Movement (65.31 m2)

No Asbestos

B00H - R0014 - Stairs (2.49 m2)

No Asbestos

B00H - R0015 - Stairs (1.13 m2)

Ceiling Structures/Linings Flat AC Sheeting 2m2 North, South Good Condition (1) Low (1) Low Priority (2-3)
4438/B00I/R0001/Ceiling Structures/Linings/S5 **Chrysotile (white asbestos)**

B00H - R9001 - Movement (4.03 m2)

No Asbestos

B00H - R9002 - General Storeroom (2.96 m2)

No Asbestos

B00H - R9003 - Cleaning Distributed Store (16.49 m2)

Ceiling Structures/Linings Flat AC Sheeting
4438/B00H/R9003/Ceiling Structures/Linings/S6 **No Asbestos Detected**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00H - R9004 - Staff Toilet (1.93 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	4438/B00H/R9003/Ceiling Structures/Linings/S6					No Asbestos Detected
B00H - R9005 - General Assistant/Bulk Store (11.08 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	4438/B00H/R9003/Ceiling Structures/Linings/S6					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting					
	4438/B00H/R9005/Wall Linings Internal/S7					No Asbestos Detected
B00H - R9006 - General Assistant/Bulk Store (13.72 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	4438/B00H/R9003/Ceiling Structures/Linings/S6					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting					
	4438/B00H/R9005/Wall Linings Internal/S7					No Asbestos Detected
B00H - R9007 - General Storeroom (17.25 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	4438/B00H/R9003/Ceiling Structures/Linings/S6					No Asbestos Detected
B00H - R9008 - Staff Toilet (1.92 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	4438/B00H/R9003/Ceiling Structures/Linings/S6					No Asbestos Detected
B00H - R9009 - Movement (3.87 m2)						
No Asbestos						
B00H - R9010 - Garden Store (10.32 m2)						
No Asbestos						
B00H - R9011 - Movement (35.22 m2)						
No Asbestos						
B00H - R9012 - General Storeroom (2.81 m2)						
No Asbestos						
B00H - R9013 - Stairs (2.49 m2)						
No Asbestos						
B00H - R9014 - Stairs (1.13 m2)						
No Asbestos						
B00H - R9015 - Stairs (1.14 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - General Learning/Pupil Facilities - 1973 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids	No Asbestos Found					
Ceiling Voids	AC Fragments/Debris	1m2	Above IR0002, IR0004 and IR0005	Poor Condition - Extensive Damage (4)	Medium (2)	High Priority (6-8)
	4438/B001/Ceiling Voids/S17					Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior

B001 - R0001 - Toilets - Girls (26.45 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	4438/B001/R0001/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)

Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4438/B001/R0001/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B001 - R0002 - Movement (11.87 m2)

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4438/B001/R0001/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B001 - R0003 - Other-Vacant (1.8 m2)

No Asbestos

B001 - R0004 - Communal Space (111.3 m2)

Ceiling Structures/Linings	Flat AC Sheeting	112m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4438/B001/R0001/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B001 - R0005 - Movement (11.9 m2)

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4438/B001/R0001/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B001 - R0006 - Other-Vacant (1.8 m2)

No Asbestos

B001 - R0007 - Toilets - Boys (23.72 m2)

Ceiling Structures/Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4438/B001/R0001/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

Partition Walls (Cubicles)	Compressed AC Sheet	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4438/B001/R0001/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)

B001 - R0008 - Sports Store (4.22 m2)

No Asbestos

B001 - R0009 - Cleaning Distributed Store (4.28 m2)

No Asbestos

B001 - R0010 - Movement (1.95 m2)

No Asbestos

B001 - R0011 - Movement (64.43 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4438/B00A/R0003/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0012 - Movement (1.9 m2)

No Asbestos

B001 - R0013 - Personal Effects Storage (7.72 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00I - R0017 - Home Base Store (5.8 m2)						
Floor Coverings Res/Textile	Vinyl Tiles 4438/B00A/R0027/Floor Coverings Res/Textile/S2	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00I - R0018 - Toilets - Boys/Girls (4.1 m2)						
No Asbestos						
B00I - R0022 - Toilets - Boys/Girls (3.54 m2)						
No Asbestos						
B00I - R0023 - Home Base Store (5.47 m2)						
Floor Coverings Res/Textile	Vinyl Tiles 4438/B00A/R0027/Floor Coverings Res/Textile/S2	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00I - R0024 - Personal Effects Storage (14.09 m2)						
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00I - R0025 - Distribution Board (0.74 m2)						
				Note: No inspection of live electrical installation.		
Electrical Backing Board	Resinous Board 4438/B00I/R0025/Electrical Backing Board/S18	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting 4438/B00I/R0025/Wall Linings Internal/S19	6m2	Door lining	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
B00I - R0026 - Home Base (73.61 m2)						
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00I - R0027 - Home Base Store (6.52 m2)						
Floor Coverings Res/Textile	Vinyl Tiles 4438/B00A/R0027/Floor Coverings Res/Textile/S2	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00I - R0028 - Stairs (0.52 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4438/B00I/R0001/Ceiling Structures/Linings/S5	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00I - R0029 - Movement (4.91 m2)						
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00I - R0030 - Movement (4.75 m2)						
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00I - R0031 - Stairs (0.51 m2)						
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00I - R0032 - Covered Outdoor Learning Area (153.93 m2)						
No Asbestos						
B00I - R0033 - Home Base (96.06 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	22m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
4438/B001/R0033/Floor Coverings Res/Textile/S20					Chrysotile (white asbestos)	
B001 - R0034 - Home Base (105.98 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	22m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
4438/B001/R0033/Floor Coverings Res/Textile/S20					Chrysotile (white asbestos)	
B001 - R1001 - Home Base (73.6 m2)						
Ceiling Structures/Linings	Vermiculite					
4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B001 - R1002 - Home Base Store (9.12 m2)						
Ceiling Structures/Linings	Vermiculite					
4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B001 - R1003 - Personal Effects Storage (17.05 m2)						
Ceiling Structures/Linings	Vermiculite					
4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B001 - R1004 - Interview (18.8 m2)						
Ceiling Structures/Linings	Vermiculite					
4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B001 - R1005 - Special Programs Room (35.59 m2)						
Ceiling Structures/Linings	Vermiculite					
4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B001 - R1006 - Home Base (73.8 m2)						
Ceiling Structures/Linings	Vermiculite					
4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B001 - R1007 - Home Base Store (7.18 m2)						
Ceiling Structures/Linings	Vermiculite					
4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4438/B00A/R0027/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)	
B001 - R1008 - Personal Effects Storage (14.45 m2)						
Ceiling Structures/Linings	Vermiculite					
4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B001 - R1009 - Distribution Board (0.8 m2)						
Note: No inspection of live electrical installation.						
Wall Linings Internal	Flat AC Sheeting	2m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
4438/B001/R1009/Wall Linings Internal/S8					Chrysotile (white asbestos)	
Electrical Backing Board	Resinous Board	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
4438/B001/R0025/Electrical Backing Board/S18					Chrysotile (white asbestos)	
B001 - R1013 - Home Base Store (8.29 m2)						
Ceiling Structures/Linings	Vermiculite					
4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4438/B00A/R0027/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00I - R1014 - Cleaning Supplies (7.78 m2)						
Ceiling Structures/Linings	Vermiculite					
		4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00I - R1015 - Movement (50.15 m2)						
Ceiling Structures/Linings	Vermiculite					
		4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00I - R1016 - Stairs (4.18 m2)						
Ceiling Structures/Linings	Vermiculite					
		4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00I - R1017 - Stairs (4.16 m2)						
Ceiling Structures/Linings	Vermiculite					
		4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00I - R1018 - Home Base (73.52 m2)						
Ceiling Structures/Linings	Vermiculite					
		4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Library - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00J - R0001 - External Movement (67.29 m2)

No Asbestos

B00J - R0002 - Toilet - Lobby (2.48 m2)

No Asbestos

B00J - R0003 - Staff Toilet (4.83 m2)

No Asbestos

B00J - R0004 - Cleaning Distributed Store (3.68 m2)

No Asbestos

B00J - R0005 - Main Switch Board Cupboard (0.7 m2)

No Asbestos

B00J - R0006 - Reading Area (169.45 m2)

No Asbestos

B00J - R0007 - Library Office/Workroom (22.82 m2)

No Asbestos

B00J - R0008 - Communications Room (8.02 m2)

No Asbestos

B00J - R0009 - K.L.A. Store (14.79 m2)

No Asbestos

B00J - R0010 - Special Programs Room (33.52 m2)

No Asbestos

B00J - R0011 - Movement (6.22 m2)

No Asbestos

B00J - R0012 - Special Programs Store (5.92 m2)

No Asbestos

B00J - R0013 - Special Programs Store (5.87 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00K - R0001 - External Movement (35.05 m2)

No Asbestos

B00K - R0002 - Special Programs Store (6.29 m2)

No Asbestos

B00K - R0003 - Special Programs Store (6.26 m2)

No Asbestos

B00K - R0004 - Special Programs Room (34.8 m2)

No Asbestos

B00K - R0005 - Home Base (57.22 m2)

No Asbestos

B00K - R0006 - Home Base Store (5.88 m2)

No Asbestos

B00K - R0007 - Withdrawal Space - 1hb (9.04 m2)

No Asbestos

B00K - R0008 - Practical Activities - 1hb (20.16 m2)

No Asbestos

B00K - R0009 - Covered Outdoor Learning Area (185.9 m2)

No Asbestos

B00K - R0010 - Movement (6.17 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00P - General Learning/Support Unit - 1973 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	Non Accessible Area - Only inspected false ceiling void.
Underfloor Voids	No Asbestos Found

Interior**B00P - R0001 - Home Base - M (71.96 m2)**

Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00P - R0002 - Home Base - M (43.4 m2)

Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00P - R0003 - Movement (12.35 m2)

Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00P - R0004 - Cleaning Distributed Store (1.83 m2)

Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00P - R0005 - Home Base (65.14 m2)

Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00P - R0006 - Practical Activities - 1hb (34.07 m2)

Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Floor Coverings Res/Textile	Vinyl Tiles	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4438/B00A/R0027/Floor Coverings Res/Textile/S2						Chrysotile (white asbestos)

B00P - R0007 - Craft Store (16.57 m2)

Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4438/B00A/R0027/Floor Coverings Res/Textile/S2						Chrysotile (white asbestos)

B00P - R0008 - Sports Store (9.5 m2)

Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4438/B00A/R0027/Floor Coverings Res/Textile/S2						Chrysotile (white asbestos)

B00P - R0009 - Distribution Board (0.42 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Wall Linings Internal	Flat AC Sheeting	4m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
4438/B00I/R1009/Wall Linings Internal/S8						Chrysotile (white asbestos)

Electrical Backing Board	Resinous Board	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
4438/B00P/R0009/Electrical Backing Board/S21						Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00P - R0010 - Movement (10.96 m2)						
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00P - R0011 - Home Base (74.43 m2)						
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00P - R0012 - Home Base Store (6.76 m2)						
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 4438/B00A/R0027/Floor Coverings Res/Textile/S2	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00P - R0014 - Canteen Office/Store (3.08 m2)						
No Asbestos						
B00P - R0015 - Canteen Office/Store (2.65 m2)						
No Asbestos						
B00P - R0016 - Movement (3.39 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4438/B00I/R0001/Ceiling Structures/Linings/S5	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00P - R0017 - Toilets - Girls (26.49 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet 4438/B00I/R0001/Partition Walls (Cubicles)/S4	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Incinerator	Encapsulated Insulation material within unit	1Unit(s)	South, East	Friable Asbestos (5)	Low (1)	Low Priority (2-3) Assumed Asbestos - Unable to sample as material is within
B00P - R0019 - General Storeroom (2.36 m2)						
No Asbestos						
B00P - R0020 - General Storeroom (2.34 m2)						
No Asbestos						
B00P - R0022 - Cleaning Distributed Store (2.33 m2)						
No Asbestos						
B00P - R0023 - Staff Toilet (10.68 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet 4438/B00I/R0001/Partition Walls (Cubicles)/S4	4m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00P - R0024 - Toilets - Boys (29.77 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet 4438/B00I/R0001/Partition Walls (Cubicles)/S4	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00P - R0025 - General Storeroom (2.44 m2)						
No Asbestos						
B00P - R0026 - General Storeroom (2.45 m2)						
No Asbestos						
B00P - R0027 - Movement (0.9 m2)						
No Asbestos						
B00P - R0028 - Movement (4.17 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite	4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00P - R0029 - Stairs (0.33 m2)						
Ceiling Structures/Linings	Vermiculite	4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00P - R0030 - Stairs (0.33 m2)						
Ceiling Structures/Linings	Vermiculite	4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00P - R0031 - Movement (4.44 m2)						
Ceiling Structures/Linings	Vermiculite	4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00P - R0032 - Canteen (23.9 m2)						
Wall Linings Internal	Flat AC Sheeting	4438/B00H/R9005/Wall Linings Internal/S7				No Asbestos Detected
B00P - R0034 - Disabled Shower/Toilet (14.78 m2)						
No Asbestos						
B00P - R0035 - Movement (241.98 m2)						
Wall Linings Internal	Flat AC Sheeting	4438/B00H/R9005/Wall Linings Internal/S7				No Asbestos Detected
B00P - R1001 - Home Base (74.02 m2)						
Ceiling Structures/Linings	Vermiculite	4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00P - R1002 - General Storeroom (20.15 m2)						
Ceiling Structures/Linings	Vermiculite	4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00P - R1003 - Cleaning Distributed Store (0.63 m2)						
Ceiling Structures/Linings	Vermiculite	4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00P - R1004 - Movement (5.06 m2)						
Ceiling Structures/Linings	Vermiculite	4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00P - R1005 - Home Base (74.56 m2)						
Ceiling Structures/Linings	Vermiculite	4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00P - R1006 - Home Base (73.83 m2)						
Ceiling Structures/Linings	Vermiculite	4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00P - R1007 - General Storeroom (20.9 m2)						
Ceiling Structures/Linings	Vermiculite	4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00P - R1008 - Distribution Board (0.64 m2)						
						Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
Electrical Backing Board	Resinous Board 4438/B00P/R0009/Electrical Backing Board/S21	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
Wall Linings Internal	Flat AC Sheeting 4438/B00P/R1008/Wall Linings Internal/S22	6m2	East	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
B00P - R1009 - Movement (5.33 m2)						
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
B00P - R1010 - Home Base (74.25 m2)						
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
B00P - R1011 - Home Base (74.02 m2)						
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
B00P - R1012 - General Storeroom (22.12 m2)						
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
B00P - R1013 - Movement (6.78 m2)						
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
B00P - R1014 - Home Base (73.1 m2)						
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
B00P - R1015 - Home Base (76.07 m2)						
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
B00P - R1016 - Withdrawal Space - 1hb (21.54 m2)						
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
B00P - R1017 - Movement (6.6 m2)						
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
B00P - R1018 - Home Base - M (74.43 m2)						
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
B00P - R1019 - Movement (4.16 m2)						
Ceiling Structures/Linings	Vermiculite 4438/B00A/R0003/Ceiling Structures/Linings/S1				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
B00P - R1020 - Stairs (3.93 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Ceiling Structures/Linings Vermiculite
 4438/B00A/R0003/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00P - R1021 - Stairs (3.95 m2)

Ceiling Structures/Linings Vermiculite
 4438/B00A/R0003/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00P - R1022 - Movement (4.45 m2)

Ceiling Structures/Linings Vermiculite
 4438/B00A/R0003/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 535 - D11918 - Library/Group Study/Office/A V Store : Placement Date - 25/02/1999

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		28.8 m2

Interior

R1 - Clerical Office

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		8 m2

R2 - Staff Room

Ceiling	Flat AC Sheet	Assumed Asbestos		36 m2
---------	---------------	------------------	--	-------

R3 - Security Store

Ceiling	Flat AC Sheet	Assumed Asbestos		8 m2
---------	---------------	------------------	--	------

R4 - Principal

Ceiling	Flat AC Sheet	Assumed Asbestos		16 m2
---------	---------------	------------------	--	-------

R5 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos		4 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		5 m2

R6 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos		4 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		5 m2

R7 - Reading Area

Ceiling	Flat AC Sheet	Assumed Asbestos		90 m2
---------	---------------	------------------	--	-------

R8 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		14 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017