

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Library - 1973 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior**B00A - R0001 - External Movement (193.4 m2)**

No Asbestos

B00A - R0002 - Interview (12.93 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Floor Coverings Res/Textile Vinyl Tiles (Under Floor Covering/Carpet) 13m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2 **Chrysotile (white asbestos)**

B00A - R0003 - Staff Toilet (2.92 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0004 - General Storeroom (1.33 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Floor Coverings Res/Textile Vinyl Tiles 2m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2 **Chrysotile (white asbestos)**

B00A - R0005 - Staff Toilet (5.13 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0006 - Staff Toilet (6.05 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0007 - Movement (15.47 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Floor Coverings Res/Textile Vinyl Tiles (Under Floor Covering/Carpet) 16m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2 **Chrysotile (white asbestos)**

B00A - R0008 - Staff Room (76.01 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Floor Coverings Res/Textile Vinyl Tiles (Under Floor Covering/Carpet) 76m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2 **Chrysotile (white asbestos)**

B00A - R0009 - General Storeroom (7.66 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)		
B00A - R0010 - Movement (27.17 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Floor Coverings Res/Textile	Vinyl Tiles	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)		
B00A - R0011 - Cleaning Distributed Store (3.72 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)		
B00A - R0012 - Sick Bay (17.43 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)		
B00A - R0013 - Movement (6.44 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)		
B00A - R0014 - Staff Room Annexe (13.85 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)		
B00A - R0015 - Staff Room Annexe (12.67 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)		
B00A - R0016 - Staff Toilet (3.46 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
B00A - R0017 - Staff Toilet (2.98 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)		
B00A - R0018 - General Storeroom (2.63 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 4459/B00A/R0025/Floor Coverings Res/Textile/S2	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R0019 - Principal (15.01 m2)						
Ceiling Structures/Linings	Vermiculite 4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4459/B00A/R0025/Floor Coverings Res/Textile/S2	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R0020 - Principal (9.21 m2)						
Ceiling Structures/Linings	Vermiculite 4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4459/B00A/R0025/Floor Coverings Res/Textile/S2	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R0021 - Entry Vestibule (23.45 m2)						
Ceiling Structures/Linings	Vermiculite 4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 4459/B00A/R0025/Floor Coverings Res/Textile/S2	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R0022 - Clerical Office (10.66 m2)						
Ceiling Structures/Linings	Vermiculite 4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4459/B00A/R0025/Floor Coverings Res/Textile/S2	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R0023 - General Storeroom (4.86 m2)						
Ceiling Structures/Linings	Vermiculite 4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 4459/B00A/R0025/Floor Coverings Res/Textile/S2	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R0024 - Duplicating Workroom (18.6 m2)						
Ceiling Structures/Linings	Vermiculite 4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4459/B00A/R0025/Floor Coverings Res/Textile/S2	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R0025 - Main Switch Board (3.38 m2)						
No Asbestos						
B00A - R0026 - Stairs (5.01 m2)						
Ceiling Structures/Linings	Vermiculite 4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00A - R1001 - External Movement (193.4 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	194m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	
B00A - R1002 - Reading Area (181.95 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00A - R1003 - Home Base (50.83 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00A - R1004 - Library Office/Workroom (18.67 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00A - R1005 - Library Office/Workroom (6.11 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00A - R1006 - K.L.A. Store (11.87 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00A - R1007 - K.L.A. Store (12.46 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00A - R1008 - Movement (16.95 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00A - R1009 - Toilets - Girls (4.44 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R1009/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)	
B00A - R1010 - Cleaning Distributed Store (1.81 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00A - R1011 - Distribution Board (0.43 m2)						
Note: No inspection of live electrical installation.						
Linning to back of door	Flat AC Sheeting	2m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R1011/Linning to back of door/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00A - R1012 - Toilets - Boys (4.4 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Partition Walls (Cubicles)	Compressed AC Sheet	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R1009/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)	
B00A - R1013 - Stairs (8.13 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Ceiling Structures/Linings

Vermiculite

4459/B00A/R0002/Ceiling Structures/Linings/S1

Limited Samples Taken

Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - General Learning/Pupil Facilities - 1973 - Brick/Block (Brick/Block)						
Exterior						
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Interior						
B00B - R0001 - External Movement (410.59 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	411m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)
B00B - R0002 - General Assistant/Bulk Store (10.08 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)
B00B - R0003 - Garden Store (9.55 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)
B00B - R0004 - Practical Activities - 1hb (16.63 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4459/B00A/R0002/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00B - R0005 - Toilets - Boys/Girls (3.2 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4459/B00A/R0002/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00B - R0007 - Home Base (85.33 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4459/B00A/R0002/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	86m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4459/B00A/R0025/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)
B00B - R0008 - Practical Activities - 1hb (16.69 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4459/B00A/R0002/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00B - R0009 - Toilets - Boys/Girls (3.11 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4459/B00A/R0002/Ceiling Structures/Linings/S1					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00B - R0010 - Toilets - Boys (28.82 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4459/B00A/R1009/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)
B00B - R0011 - Darkroom Space (8.56 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)
B00B - R0012 - Cleaning Supplies (7.28 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00C/R0010/Ceiling Structures/Linings/S6				Chrysotile (white asbestos)		
B00B - R0013 - Toilets - Girls (29.85 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00C/R0010/Ceiling Structures/Linings/S6				Chrysotile (white asbestos)		
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R1009/Partition Walls (Cubicles)/S4				Chrysotile (white asbestos)		
B00B - R0014 - General Storeroom (7.3 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00C/R0010/Ceiling Structures/Linings/S6				Chrysotile (white asbestos)		
B00B - R0015 - Distribution Board (0.33 m2)						
				Note: No inspection of live electrical installation.		
No Asbestos						
B00B - R0016 - Practical Activities - 1hb (16.75 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)		
B00B - R0017 - Cleaning Distributed Store (3.22 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)		
B00B - R0018 - Home Base (86.07 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	87m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)		
B00B - R0019 - Home Base (85.53 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	86m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)		
B00B - R0020 - Practical Activities - 1hb (16.82 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)		
B00B - R0021 - Toilets - Boys/Girls (3.18 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4459/B00A/R0002/Ceiling Structures/Linings/S1				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
B00B - R0022 - General Storeroom (9.89 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4459/B00A/R0025/Floor Coverings Res/Textile/S2	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite 4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0023 - Home Base (74.84 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4459/B00A/R0025/Floor Coverings Res/Textile/S2	75m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite 4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities/Communal Facilities - 1973 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior**B00C - R0001 - External Movement (187.05 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	188m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	

B00C - R0002 - Toilets - Boys (23.82 m2)

Ceiling Structures/Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R1009/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)	

B00C - R0003 - General Storeroom (6.51 m2)

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)	

B00C - R0004 - Distribution Board (0.69 m2)

Note: No inspection of live electrical installation.

Linning to back of door	Flat AC Sheeting	2m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R1011/Linning to back of door/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00C - R0005 - Canteen Office/Store (5.6 m2)

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)	

B00C - R0006 - Canteen (31.76 m2)

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
4459/B00C/R0006/Ceiling Structures/Linings/S3						

B00C - R0007 - Canteen Office/Store (3.93 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)	

B00C - R0008 - Movement (6.47 m2)

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R0025/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)	

B00C - R0009 - General Storeroom (3.9 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	
B00C - R0010 - Staff Toilet (3.12 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	
B00C - R0011 - Toilets - Girls (23.68 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R1009/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)	
B00C - R0012 - Sports Store (9.86 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	
B00C - R0013 - Sports Store (9.98 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Pupil Facilities - 1973 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior**B00D - R0001 - External Movement (304.01 m2)**

No Asbestos

B00D - R0002 - Practical Activities - 1hb (16.69 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00D - R0003 - Home Base (54 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00D - R0004 - Home Base (53.78 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00D - R0005 - Practical Activities - 1hb (16.36 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00D - R0006 - Garden Store (3.61 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00D - R0007 - Cleaning Distributed Store (3.22 m2)

Ceiling Structures/Linings Vermiculite
4459/B00C/R0006/Ceiling Structures/Linings/S3 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00D - R0008 - Cleaning Distributed Store (3.18 m2)

No Asbestos

B00D - R0009 - Practical Activities - 1hb (16.87 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00D - R0010 - Home Base (54.56 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00D - R0011 - Home Base (53.38 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00D - R0012 - Practical Activities - 1hb (20.55 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00D - R0013 - Distribution Board (0.37 m2)

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Electrical Backing Board	Resinous Board	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
B00D - R0014 - External Stairs (7.82 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	
B00D - R1001 - External Movement (295.68 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	296m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	
B00D - R1002 - Practical Activities - 1hb (16.37 m2)						
Ceiling Structures/Linings	Vermiculite					
4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00D - R1003 - Home Base (53.84 m2)						
Ceiling Structures/Linings	Vermiculite					
4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00D - R1004 - Home Base (54.13 m2)						
Ceiling Structures/Linings	Vermiculite					
4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00D - R1005 - Practical Activities - 1hb (15.93 m2)						
Ceiling Structures/Linings	Vermiculite					
4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00D - R1006 - Toilets - Girls (3.74 m2)						
Ceiling Structures/Linings	Vermiculite					
4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Incinerette	Encapsulated Insulation material within unit	1Unit(s)	North	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Area inaccessible						
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R1009/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)	
B00D - R1007 - Cleaning Distributed Store (3.2 m2)						
Ceiling Structures/Linings	Vermiculite					
4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00D - R1008 - Toilets - Boys (3.18 m2)						
Ceiling Structures/Linings	Vermiculite					
4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Partition Walls (Cubicles)	Compressed AC Sheet	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
4459/B00A/R1009/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)	
B00D - R1009 - Practical Activities - 1hb (16.83 m2)						
Ceiling Structures/Linings	Vermiculite					
4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00D - R1010 - Home Base (54.52 m2)						
Ceiling Structures/Linings	Vermiculite					
4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R1011 - Home Base (53.07 m2)						
Ceiling Structures/Linings	Vermiculite 4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 4459/B00A/R0025/Floor Coverings Res/Textile/S2	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R1012 - Practical Activities - 1hb (20.49 m2)						
Ceiling Structures/Linings	Vermiculite 4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 4459/B00A/R0025/Floor Coverings Res/Textile/S2	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R1013 - Distribution Board (0.37 m2) Note: No inspection of live electrical installation.						
Electrical Backing Board	Resinous Board	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3) Assumed Asbestos - Electrical Hazard
B00D - R1014 - External Stairs (16.23 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4459/B00C/R0010/Ceiling Structures/Linings/S6	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Pupil Facilities - 1973 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior**B00E - R0002 - Practical Activities - 1hb (21.43 m2)**

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0005 - Practical Activities - 1hb (21.4 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0006 - Distribution Board (0.49 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0007 - Cleaning Distributed Store (0.48 m2)

No Asbestos

B00E - R0008 - Toilets - Girls (18.72 m2)

Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				4459/B00C/R0010/Ceiling Structures/Linings/S6	Chrysotile (white asbestos)	

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
				4459/B00A/R1009/Partition Walls (Cubicles)/S4	Chrysotile (white asbestos)	

B00E - R0009 - Toilets - Boys (19.91 m2)

Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				4459/B00C/R0010/Ceiling Structures/Linings/S6	Chrysotile (white asbestos)	

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
				4459/B00A/R1009/Partition Walls (Cubicles)/S4	Chrysotile (white asbestos)	

B00E - R0010 - Practical Activities - 1hb (21.51 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0013 - Practical Activities - 1hb (21.37 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0014 - External Stairs (7.82 m2)

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				4459/B00C/R0010/Ceiling Structures/Linings/S6	Chrysotile (white asbestos)	

B00E - R0015 - Special Programs Room (85.37 m2)

No Asbestos

B00E - R0016 - General Storeroom (20.3 m2)

No Asbestos

B00E - R0017 - Home Base (106.44 m2)

Ceiling Structures/Linings Vermiculite
4459/B00A/R0002/Ceiling Structures/Linings/S1 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0018 - Home Base Store (18.81 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00E - R0019 - Home Base Store (24.68 m2)						
No Asbestos						
B00E - R0020 - External Movement (290.81 m2)						
No Asbestos						
B00E - R1002 - Practical Activities - 1hb (21.48 m2)						
Ceiling Structures/Linings	Vermiculite					
	4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00E - R1003 - Home Base (52.8 m2)						
Ceiling Structures/Linings	Vermiculite					
	4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00E - R1004 - Home Base (53.12 m2)						
Ceiling Structures/Linings	Vermiculite					
	4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00E - R1005 - Practical Activities - 1hb (21.48 m2)						
Ceiling Structures/Linings	Vermiculite					
	4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00E - R1006 - Distribution Board (0.51 m2)						
Note: No inspection of live electrical installation.						
Ceiling Structures/Linings	Flat AC Sheeting	0.5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)
Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
B00E - R1007 - Toilets - Girls (9 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	5m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4459/B00A/R1009/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)
B00E - R1008 - Cleaning Distributed Store (0.37 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	0.5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)
B00E - R1009 - General Storeroom (9.73 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)
B00E - R1010 - Toilets - Boys (8.35 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4459/B00A/R1009/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)
B00E - R1011 - Practical Activities - 1hb (21.53 m2)						
Ceiling Structures/Linings	Vermiculite					
	4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00E - R1012 - Home Base (52.82 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1013 - Home Base (52.72 m2)						
Ceiling Structures/Linings	Vermiculite					
	4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1014 - Practical Activities - 1hb (21.32 m2)						
Ceiling Structures/Linings	Vermiculite					
	4459/B00A/R0002/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1015 - Craft Store (11.67 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)
B00E - R1016 - External Stairs (15.4 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)
B00E - R1017 - Home Base Store (42.71 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)
B00E - R1018 - External Movement (281.33 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	282m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4459/B00C/R0010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Communal Facilities - 1973 - Concrete (Concrete)

Exterior

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior

B00F - R0001 - Communal Space (221.1 m2)

No Asbestos

B00F - R0002 - Raised Platform (43.01 m2)

No Asbestos

B00F - R0003 - Hall Chair Store (12.47 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Communal Facilities - 1973 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00G - R0001 - P.E. Store (17.08 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Administration - 1973 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00H - R0001 - General Storeroom (17.44 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017