


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Woodland Road Public School (4492)
Region : South Western Sydney
State Electorate : Campbelltown
Local Government Area : Campbelltown

Initial Survey : Noel Arnold & Associates : 08 - May - 2008
Reviewed By : Parsons Brinckerhoff : 25 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Communal Facilities/Tiered Learning - 1976 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4492/B00F/Gable Verge Lining/S11				Chrysotile (white asbestos)	
Ceiling Void	No Asbestos Found					

Interior

B00A - M0001 - General Storeroom

No Asbestos

B00A - R0001 - Special Programs Room

No Asbestos

B00A - R0002 - Staff Toilet

Non Accessible

B00A - R0003 - Canteen Office/Store

No Asbestos

B00A - R0004 - Canteen Office/Store

No Asbestos

B00A - R0005 - Canteen

No Asbestos

B00A - R0006 - General Assistant/Bulk Store

No Asbestos

B00A - R0007 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	1m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4492/B00A/R0007/Partition Walls (Cubicles)/S3				Chrysotile (white asbestos)	

B00A - R0008 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	5m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4492/B00A/R0007/Partition Walls (Cubicles)/S3				Chrysotile (white asbestos)	

B00A - R0009 - Cleaning Distributed Store

No Asbestos

B00A - R0010 - Drinking Facilities

No Asbestos

B00A - R0011 - Security Store

No Asbestos

B00A - R0012 - Main Switch Board

No Asbestos

B00A - R0013 - Movement

No Asbestos

B00A - R0014 - Distribution Board

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4492/B00A/R0014/Electrical Backing Board/S2				Chrysotile (white asbestos)	

B00A - R0015 - Movement

No Asbestos

B00A - R0016 - Movement

No Asbestos

B00A - R0017 - Raised Platform

No Asbestos

B00A - R0018 - Communal Space

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00A - R0019 - General Storeroom

No Asbestos

B00A - R0020 - General Storeroom

No Asbestos

B00A - R0021 - Hall Chair Store

No Asbestos

B00A - R0022 - P.E. Store

No Asbestos

B00A - R0023 - Sports Store

No Asbestos

B00A - R0024 - External Movement

No Asbestos

B00A - R0025 - External Movement

No Asbestos

B00A - R0026 - External Movement

No Asbestos

B00A - R0027 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library - 1976 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00F/Gable Verge Lining/S11					Chrysotile (white asbestos)	

Interior

B00B - R0001 - General Storeroom

Ceiling Structures/Linings	Compressed AC Sheet	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00B/R0001/Ceiling Structures/Linings/S8					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00B/R0012/Floor Coverings Res/Textile/S13					Chrysotile (white asbestos)	

B00B - R0002 - Special Programs Room

No Asbestos

B00B - R0003 - Distribution Board

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00B/R0003/Electrical Backing Board/S7					Chrysotile (white asbestos)	

B00B - R0004 - Security Store

Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00B/R0012/Floor Coverings Res/Textile/S13					Chrysotile (white asbestos)	

B00B - R0005 - Library Office/Workroom

No Asbestos

B00B - R0006 - Library Office/Workroom

Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00B/R0012/Floor Coverings Res/Textile/S13					Chrysotile (white asbestos)	

B00B - R0007 - K.L.A. Store

No Asbestos

B00B - R0008 - K.L.A. Store

No Asbestos

B00B - R0009 - Reading Area

No Asbestos

B00B - R0010 - External Movement

No Asbestos

B00B - R0011 - Special Programs Room

No Asbestos

B00B - R0012 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00B/R0012/Floor Coverings Res/Textile/S13					Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1976 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00F/Gable Verge Lining/S11					Chrysotile (white asbestos)	

Interior

B00C - R0001 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	1m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00C/R0001/Partition Walls (Cubicles)/S6					Chrysotile (white asbestos)	

B00C - R0002 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	5m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00C/R0001/Partition Walls (Cubicles)/S6					Chrysotile (white asbestos)	

B00C - R0003 - Drinking Facilities

No Asbestos

B00C - R0004 - Cleaning Distributed Store

No Asbestos

B00C - R0005 - Home Base

No Asbestos

B00C - R0006 - Movement

No Asbestos

B00C - R0007 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00C/R0031/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)	

B00C - R0008 - Toilets - Boys/Girls

No Asbestos

B00C - R0009 - Withdrawal Space - 1hb

No Asbestos

B00C - R0010 - Toilets - Boys/Girls

No Asbestos

B00C - R0011 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00C/R0031/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)	

B00C - R0012 - Home Base

No Asbestos

B00C - R0013 - Home Base

No Asbestos

B00C - R0014 - Movement

No Asbestos

B00C - R0015 - Toilets - Boys/Girls

No Asbestos

B00C - R0016 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00C/R0031/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)	

B00C - R0017 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R0018 - Withdrawal Space - 1hb						
No Asbestos						
B00C - R0019 - Movement						
No Asbestos						
B00C - R0020 - Home Base Store						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00C/R0031/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)	
B00C - R0021 - Home Base						
No Asbestos						
B00C - R0022 - General Storeroom						
No Asbestos						
B00C - R0023 - Practical Activities - 1hb						
No Asbestos						
B00C - R0024 - Distribution Board						
Note: No inspection of live electrical installation.						
Wall Linings Internal	Flat AC Sheeting	6m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00C/R0024/Wall Linings Internal/S4					Chrysotile (white asbestos)	
Electrical Backing Board	Resinous Board	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00C/R0024/Electrical Backing Board/S5					Chrysotile (white asbestos)	
B00C - R0025 - Craft Store						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00C/R0031/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)	
B00C - R0026 - Staff Room Annexe						
No Asbestos						
B00C - R0027 - Practical Activities - 1hb						
No Asbestos						
B00C - R0028 - Kiln Room						
No Asbestos						
B00C - R0029 - Movement						
No Asbestos						
B00C - R0030 - Personal Effects Storage						
No Asbestos						
B00C - R0031 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles	49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00C/R0031/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)	
B00C - R0032 - General Storeroom						
No Asbestos						
B00C - R0033 - Movement						
No Asbestos						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1976 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00F/Gable Verge Lining/S11					Chrysotile (white asbestos)	

Interior**B00D - R0001 - Home Base Store**

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00D/R0021/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)	

B00D - R0002 - Movement

No Asbestos

B00D - R0003 - Home Base

No Asbestos

B00D - R0004 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00D/R0021/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)	

B00D - R0005 - Home Base

No Asbestos

B00D - R0006 - Withdrawal Space - 1hb

No Asbestos

B00D - R0007 - Movement

No Asbestos

B00D - R0008 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00D/R0021/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)	

B00D - R0009 - Movement

No Asbestos

B00D - R0010 - Home Base

No Asbestos

B00D - R0011 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00D/R0021/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)	

B00D - R0012 - Withdrawal Space - 1hb

No Asbestos

B00D - R0013 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00D/R0021/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)	

B00D - R0014 - Home Base

No Asbestos

B00D - R0015 - Cleaning Distributed Store

No Asbestos

B00D - R0016 - General Storeroom

No Asbestos

B00D - R0017 - Practical Activities - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R0018 - Practical Activities - 1hb						
No Asbestos						
B00D - R0019 - Kiln Room						
No Asbestos						
B00D - R0020 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00D - R0021 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles	75m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00D/R0021/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)	
B00D - R0022 - Movement						
No Asbestos						
B00D - R0023 - Special Programs Room						
No Asbestos						
B00D - R0024 - Toilets - Girls						
No Asbestos						
B00D - R0025 - Toilets - Boys						
No Asbestos						
B00D - R0026 - Drinking Facilities						
No Asbestos						
B00D - R0027 - General Storeroom						
Partition Walls (Cubicles)	Compressed AC Sheet	5m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00D/R0027/Partition Walls (Cubicles)/S9					Chrysotile (white asbestos)	
B00D - R0028 - General Storeroom						
Partition Walls (Cubicles)	Compressed AC Sheet	1m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00D/R0027/Partition Walls (Cubicles)/S9					Chrysotile (white asbestos)	
B00D - R0029 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Administration/General Learning - 1976 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	15m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4492/B00F/Gable Verge Lining/S11					Chrysotile (white asbestos)
Ceiling Void	No Asbestos Found					

Interior

B00E - R0001 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4492/B00D/R0021/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)

B00E - R0002 - Home Base

No Asbestos

B00E - R0003 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4492/B00D/R0021/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)

B00E - R0004 - Home Base

No Asbestos

B00E - R0005 - Withdrawal Space - 1hb

No Asbestos

B00E - R0006 - Home Base

No Asbestos

B00E - R0007 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4492/B00D/R0021/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)

B00E - R0008 - External Movement

No Asbestos

B00E - R0009 - External Movement

No Asbestos

B00E - R0010 - External Movement

No Asbestos

B00E - R0011 - External Movement

No Asbestos

B00E - R0012 - Home Base

No Asbestos

B00E - R0013 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4492/B00D/R0021/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)

B00E - R0014 - Withdrawal Space - 1hb

No Asbestos

B00E - R0015 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4492/B00D/R0021/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)

B00E - R0016 - Home Base

No Asbestos

B00E - R0017 - General Storeroom

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00D/R0021/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)	
B00E - R0018 - General Storeroom						
No Asbestos						
B00E - R0019 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00D/R0021/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)	
B00E - R0020 - Practical Activities - 1hb						
No Asbestos						
B00E - R0021 - Practical Activities - 1hb						
No Asbestos						
B00E - R0022 - General Storeroom						
No Asbestos						
B00E - R0023 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles	81m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00D/R0021/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)	
B00E - R0024 - Movement						
No Asbestos						
B00E - R0025 - Distribution Board						
				Note: No inspection of live electrical installation.		
Electrical Backing Board	Resinous Board	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00E/R0025/Electrical Backing Board/S10					Chrysotile (white asbestos)	
B00E - R0026 - Toilets - Girls						
No Asbestos						
B00E - R0027 - Toilets - Boys						
No Asbestos						
B00E - R0028 - Drinking Facilities						
No Asbestos						
B00E - R0030 - Clerical Office						
No Asbestos						
B00E - R0031 - Duplicating Workroom						
No Asbestos						
B00E - R0033 - Cleaning Distributed Store						
Non Accessible						
B00E - R0035 - Distribution Board						
				Note: No inspection of live electrical installation.		
No Asbestos						
B00E - R0036 - Security Store						
No Asbestos						
B00E - R0037 - Movement						
No Asbestos						
B00E - R0038 - Entry Vestibule						
No Asbestos						
B00E - R0039 - Staff Toilet						
No Asbestos						
B00E - R0040 - Community Clinic						
No Asbestos						
B00E - R0041 - Interview						
No Asbestos						
B00E - R0042 - Sick Bay						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - R0043 - Staff Room Annexe						
No Asbestos						
B00E - R0044 - Staff Room Annexe						
No Asbestos						
B00E - R0045 - Principal						
No Asbestos						
B00E - R0048 - General Storeroom						
No Asbestos						
B00E - R0050 - Cleaning Supplies						
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00D/R0021/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)	
B00E - R0051 - External Movement						
No Asbestos						
B00E - R0052 - External Movement						
No Asbestos						
B00E - R0053 - Entry Vestibule						
No Asbestos						
B00E - R0054 - Movement						
No Asbestos						
B00E - R0055 - Toilet - Lobby						
No Asbestos						
B00E - R0056 - Staff Toilet						
No Asbestos						
B00E - R0057 - Toilet - Lobby						
No Asbestos						
B00E - R0058 - Staff Toilet						
No Asbestos						
B00E - R0059 - Staff Kitchen						
No Asbestos						
B00E - R0060 - Staff Room						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Building Services - 1976 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	4m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
4492/B00F/Gable Verge Lining/S11					Chrysotile (white asbestos)	

Interior

B00F - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 837 - D15159 - Hcap Shower/Change/Toilet : Placement Date - 6/01/2011

Exterior

No Asbestos Found.

Interior

R1 - Disabled Shower/Toilet

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017