


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wyalaliba Public School (4556)
Region : New England
State Electorate : Northern Tablelands
Local Government Area : Glen Innes Severn

Initial Survey : Noel Arnold & Associates : 20 - May - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Staff Facilities - 1894 - Steel (Steel)

Exterior

No Asbestos

Ceiling Voids Requires Inspection

Underfloor Voids Requires Inspection

Interior

B00A - R0001 - Movement

No Asbestos

B00A - R0002 - General Storeroom

Floor Coverings Res/Textile Vinyl Sheet
 4556/B00A/R0002/Floor Coverings Res/Textile/S1 **No Asbestos Detected**

B00A - R0003 - Staff Toilet

Floor Coverings Res/Textile Vinyl Sheet
 4556/B00A/R0002/Floor Coverings Res/Textile/S1 **No Asbestos Detected**

B00A - R0004 - Staff Room

No Asbestos

B00A - R0005 - Movement

Floor Coverings Res/Textile Vinyl Sheet
 4556/B00A/R0002/Floor Coverings Res/Textile/S1 **No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Building Services - 1894 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Plant

Wall Linings Internal	Flat AC Sheeting 4556/B00B/R0001/Wall Linings Internal/S2	No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 4556/B00B/R0001/Wall Linings Internal/S2	No Asbestos Detected

B00B - R0002 - General Storeroom

No Asbestos

B00B - R0003 - Cleaning Distributed Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Communal Facilities - 1894 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Shed - 1894 - Brick/Block (Brick/Block)

Exterior

No Asbestos

Ceiling Voids Requires Inspection

Underfloor Voids Requires Inspection

Interior

B00D - R0001 - General Assistant/Bulk Store

Loose Panel by Kiln Compressed AC Sheet
 4556/B00D/R0001/Loose Panel by Kiln/S3

No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Library - 2009 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Reading Area

No Asbestos

B00E - R0002 - K.L.A. Store

No Asbestos

B00E - R0003 - Practical Activities

No Asbestos

B00E - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 601 - D10736 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 844 - D10737 - Country Toilet - Reltc - Boys/Girls : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	2.88 m2

Interior

R1 - Staff Toilet

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	9 m2

R2 - Staff Toilet

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	9 m2

OS 750 - D11573 - Learning Unit - ESL : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	5.76 m2

Interior

R1 - Esl

End wall panel	Flat AC Sheet	Assumed Asbestos	50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	36 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017