


# Asbestos Register

(Hazardous Materials and Risk Assessment)



**School :** William Bayldon Public School (4602)  
**Region :** North Coast  
**State Electorate :** Coffs Harbour  
**Local Government Area :** Coffs Harbour

**Initial Survey :** Noel Arnold & Associates : 22 - May - 2008  
**Register Issue Date :** 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - General Learning/Support Unit - 1993 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B001 - R0001 - Movement**

No Asbestos

**B001 - R0002 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0003 - Practical Activities - 1hb**

No Asbestos

**B001 - R0004 - Home Base - M**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0005 - Withdrawal - M**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0006 - General Storeroom**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0007 - Toilet - M**

No Asbestos

**B001 - R0008 - Laundry - S**

No Asbestos

**B001 - R0009 - Practical Activities - S - 1hb**

No Asbestos

**B001 - R0010 - Toilet - S**

No Asbestos

**B001 - R0011 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0012 - Practical Activities - 1hb**

No Asbestos

**B001 - R0013 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0014 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0015 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B001 - R0016 - Toilets - Boys/Girls**

No Asbestos

**B001 - R0017 - Practical Activities - 1hb**

No Asbestos

**B001 - R0018 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0019 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0020 - Withdrawal Space - 1hb**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0021 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0022 - Practical Activities - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0023 - Toilets - Boys/Girls**

No Asbestos

**B001 - R0024 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0025 - Cleaning Supplies**

No Asbestos

**B001 - R0026 - Toilets - Girls**

No Asbestos

**B001 - R0027 - Toilets - Boys**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B002 - Administration/Staff Facilities - 1993 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B002 - R0001 - Movement**

No Asbestos

**B002 - R0002 - General Assistant/Bulk Store**

No Asbestos

**B002 - R0003 - Clerical Office**

No Asbestos

**B002 - R0004 - Entry Vestibule**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B002 - R0005 - Duplicating Workroom**

No Asbestos

**B002 - R0006 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B002 - R0007 - Principal**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B002 - R0008 - Security Store**

No Asbestos

**B002 - R0009 - Staff Toilet**

No Asbestos

**B002 - R0010 - Staff Toilet**

No Asbestos

**B002 - R0011 - Staff Toilet**

No Asbestos

**B002 - R0012 - Staff Room**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B002 - R0013 - Staff Room Annexe**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B002 - R0014 - Cleaning Supplies**

No Asbestos

**B002 - R0015 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B002 - R0016 - Deputy Principal**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B002 - R0017 - Interview**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B002 - R0018 - Deputy Principal**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B002 - R0019 - Toilets - Boys/Girls**

No Asbestos

**B002 - R0020 - Sick Bay**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B002 - R0021 - Clerical Office/Workroom**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B002 - R0022 - Main Switch Board**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B003 - Pupil Facilities - 1993 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B003 - R0001 - Movement**

No Asbestos

**B003 - R0002 - Canteen**

No Asbestos

**B003 - R0003 - Canteen Office/Store**

No Asbestos

**B003 - R0004 - Disabled Toilet**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B004 - Communal Facilities - 1993 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B004 - R0001 - Movement**

No Asbestos

**B004 - R0002 - Communal Space**

No Asbestos

**B004 - R0003 - Raised Platform**

No Asbestos

**B004 - R0004 - Plant**

No Asbestos

**B004 - R0005 - Plant**

No Asbestos

**B004 - R0006 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B004 - R0007 - Movement**

No Asbestos

**B004 - R0008 - Hall Chair Store**

No Asbestos

**B004 - R0009 - P.E. Store**

No Asbestos

**B004 - R0010 - General Storeroom**

No Asbestos

**B004 - R0011 - Movement**

No Asbestos

**B004 - R0012 - Movement**

No Asbestos

**B004 - R0013 - Movement**

No Asbestos

**B004 - R0014 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B005 - Library - 1993 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B005 - R0001 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B005 - R0002 - K.L.A. Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B005 - R0003 - Communications Room**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B005 - R0004 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B005 - R0005 - Special Programs Room**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B005 - R0006 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B005 - R0007 - Special Programs Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B005 - R0008 - Cleaning Supplies**

No Asbestos

**B005 - R0009 - Communications Room**

No Asbestos

**B005 - R0010 - Movement**

No Asbestos

**B005 - R0011 - Disabled Toilet**

No Asbestos

**B005 - R0012 - Cleaning Supplies**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B006 - General Learning - 1993 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B006 - R0001 - Movement**

No Asbestos

**B006 - R0002 - Practical Activities - 1hb**

No Asbestos

**B006 - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B006 - R0004 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B006 - R0005 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B006 - R0006 - Practical Activities - 1hb**

No Asbestos

**B006 - R0007 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B006 - R0008 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B006 - R0009 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B006 - R0010 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B006 - R0011 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B006 - R0012 - Practical Activities - 1hb**

No Asbestos

**B006 - R0013 - Practical Activities - 1hb**

No Asbestos

**B006 - R0014 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B006 - R0015 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B006 - R0016 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B006 - R0017 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B006 - R0018 - Practical Activities - 1hb**

No Asbestos

**B006 - R0019 - Home Base**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B006 - R0020 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B006 - R0021 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B006 - R0022 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B006 - R0023 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B006 - R0024 - Withdrawal Space - 1hb</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B006 - R0025 - Toilets - Girls</b>						
No Asbestos						
<b>B006 - R0026 - Toilets - Boys</b>						
No Asbestos						
<b>B006 - R0027 - Cleaning Supplies</b>						
No Asbestos						
<b>B006 - R0028 - General Storeroom</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B007 - General Learning/Other - Dse Admin - 1992 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B007 - R0001 - Staff Shower/Change**

No Asbestos

**B007 - R0002 - Cleaning Supplies**

No Asbestos

**B007 - R0003 - Toilets - Boys**

No Asbestos

**B007 - R0004 - Toilets - Girls**

No Asbestos

**B007 - R0005 - Practical Activities - 1hb**

No Asbestos

**B007 - R0006 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B007 - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B007 - R0008 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B007 - R0009 - Practical Activities - 1hb**

No Asbestos

**B007 - R0010 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B007 - R0011 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B007 - R0012 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B007 - R0013 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B007 - R0014 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B007 - R0015 - Practical Activities - 1hb**

No Asbestos

**B007 - R0016 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B007 - R0017 - Plant**

No Asbestos

**B007 - R0018 - Practical Activities - 1hb**

No Asbestos

**B007 - R0019 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B007 - R0020 - Home Base Store**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B007 - R0021 - Withdrawal Space - 1hb</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B007 - R0022 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B007 - R0023 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B007 - R0024 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B007 - R0025 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B007 - R0028 - Distribution Board</b>						
No Asbestos					Note: No inspection of live electrical installation.	
<b>B007 - R0029 - Plant</b>						
No Asbestos						
<b>B007 - R0034 - Practical Activities</b>						
No Asbestos						
<b>B007 - R0035 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B007 - R0036 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B007 - R0037 - Withdrawal Space - 1hb</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B007 - R0038 - Disabled Toilet</b>						
No Asbestos						
<b>B007 - R0039 - Movement</b>						
No Asbestos						
<b>B007 - R0041 - Practical Activities</b>						
No Asbestos						
<b>B007 - R0043 - General Storeroom</b>						
No Asbestos						
<b>B007 - R0044 - General Storeroom</b>						
No Asbestos						
<b>B007 - R0045 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B007 - R0047 - Home Base</b>						
No Asbestos						
<b>B007 - R0049 - Home Base</b>						
No Asbestos						
<b>B007 - R0050 - Withdrawal Space - 2hb</b>						
No Asbestos						
<b>B007 - R9001 - General Storeroom</b>						
No Asbestos						
<b>B007 - R9002 - Movement</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B008 - Building Services - 1999 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B008 - R0001 - Garden Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017