


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Woongarra Public School (4637)  
**Region :** Hunter/Central Coast  
**State Electorate :** Wyong  
**Local Government Area :** Wyong

**Initial Survey :** Noel Arnold & Associates : 29 - Mar - 2008  
**Register Issue Date :** 24 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/Staff Facilities - 2004 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

**Interior**

**B00A - R0001 - Staff Room Annexe**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0002 - Staff Room**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0003 - Staff Kitchen**

No Asbestos

**B00A - R0004 - Deputy Principal**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0005 - Deputy Principal**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0006 - Security Store**

No Asbestos

**B00A - R0007 - Interview**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0008 - Clerical Office/Workroom**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0009 - Entry Vestibule**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0010 - Interview**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0011 - Sick Bay**

No Asbestos

**B00A - R0012 - Sick Bay - Shower/Toilet**

No Asbestos

**B00A - R0013 - Principal**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0014 - Staff Toilet**

No Asbestos

**B00A - R0015 - Distribution Board**

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

**B00A - R0016 - Cleaning Distributed Store**

No Asbestos

**B00A - R0017 - Staff Toilet**

No Asbestos

**B00A - R0018 - Staff Toilet**

No Asbestos

**B00A - R0019 - Movement**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00A - R0020 - Movement**

No Asbestos

**B00A - R0021 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Communal Facilities/Pupil Facilities - 2004 - Brick/Veneer (Brick/Veneer)****Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

**Interior****B00B - R0002 - Toilets - Boys**

No Asbestos

**B00B - R0003 - Toilets - Girls**

No Asbestos

**B00B - R0004 - General Assistant/Bulk Store**

No Asbestos

**B00B - R0005 - P.E. Store**

No Asbestos

**B00B - R0006 - Hall Chair Store**

No Asbestos

**B00B - R0007 - General Assistant/Bulk Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0008 - Movement**

No Asbestos

**B00B - R0009 - Raised Platform**

No Asbestos

**B00B - R0010 - Movement**

No Asbestos

**B00B - R0011 - Main Switch Board**

No Asbestos

**B00B - R0012 - Communal/Performance Store**

No Asbestos

**B00B - R0013 - Movement**

No Asbestos

**B00B - R0015 - Staff Kitchen**

No Asbestos

**B00B - R0016 - Movement**

No Asbestos

**B00B - R0017 - Toilets - Girls**

No Asbestos

**B00B - R0018 - Toilets - Boys**

No Asbestos

**B00B - R0019 - Communications Cupboard**

No Asbestos

**B00B - R0022 - Access Shower/Toilet**

No Asbestos

**B00B - R0023 - Canteen**

No Asbestos

**B00B - R0024 - Movement**

No Asbestos

**B00B - R0025 - Canteen Office/Store**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R0026 - Cleaning Supplies</b>						
No Asbestos						
<b>B00B - R0027 - Sports Store</b>						
No Asbestos						
<b>B00B - R0028 - Garden Store</b>						
No Asbestos						
<b>B00B - R0029 - Communal Space</b>						
No Asbestos						
<b>B00B - R0030 - Home Base</b>						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)						
No Asbestos Found						
<b>B00B - R0031 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00B - R0032 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00B - R0033 - Home Base</b>						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)						
No Asbestos Found						
<b>B00B - R0034 - Home Base Store</b>						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)						
No Asbestos Found						
<b>B00B - R0035 - Withdrawal Space - 2hb</b>						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)						
No Asbestos Found						
<b>B00B - R0036 - Home Base Store</b>						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)						
No Asbestos Found						
<b>B00B - R0037 - Movement</b>						
No Asbestos						
<b>B00B - R0038 - General Storeroom</b>						
No Asbestos						
<b>B00B - R0039 - External Movement</b>						
No Asbestos						
<b>B00B - R0040 - Covered Outdoor Learning Area</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Library - 2004 - Brick/Veneer (Brick/Veneer)****Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

**Interior****B00D - R0001 - Special Programs Room**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0002 - Special Programs Room**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0003 - Special Programs Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0004 - Reading Area**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0005 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0006 - Library Office/Workroom**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0007 - Communications Room**

No Asbestos

**B00D - R0008 - K.L.A. Store**

No Asbestos

**B00D - R0009 - Cleaning Distributed Store**

No Asbestos

**B00D - R0010 - Special Programs Room**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0011 - Special Programs Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0012 - Staff Toilet**

No Asbestos

**B00D - R0013 - Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00E - General Learning/Pupil Facilities - 2004 - Brick/Veneer (Brick/Veneer)****Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

**Interior****B00E - R0001 - Practical Activities - 1hb**

No Asbestos

**B00E - R0002 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0003 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0004 - Withdrawal Space - 2hb**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0005 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0006 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0007 - Practical Activities - 1hb**

No Asbestos

**B00E - R0008 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0009 - Practical Activities - 2hb**

No Asbestos

**B00E - R0010 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0011 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0012 - Withdrawal Space - 2hb**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0013 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0014 - Home Base Store**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R0015 - Practical Activities - 1hb**

No Asbestos

**B00E - R0016 - Toilets - Girls**

No Asbestos

**B00E - R0017 - Toilets - Boys**

No Asbestos

**B00E - R0018 - Kiln Room**

No Asbestos

**B00E - R0019 - Movement**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00F - General Learning/Pupil Facilities - 2004 - Brick/Veneer (Brick/Veneer)****Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

**Interior****B00F - R0001 - Practical Activities - 1hb**

No Asbestos

**B00F - R0002 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0003 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0004 - Withdrawal Space - 2hb**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0005 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0006 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0007 - Practical Activities - 1hb**

No Asbestos

**B00F - R0008 - Access Shower/Toilet - Type 2**

No Asbestos

**B00F - R0009 - Laundry - Type 2**

No Asbestos

**B00F - R0010 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00F - R0011 - Practical Activities - 1hb**

No Asbestos

**B00F - R0012 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0013 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0014 - Withdrawal Space - 2hb**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0015 - Home Base**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00F - R0016 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00F - R0017 - Practical Activities - 2hb**

No Asbestos

**B00F - R0018 - Toilets - Girls**

No Asbestos

**B00F - R0019 - Toilets - Boys**

No Asbestos

**B00F - R0020 - Cleaning Distributed Store**

No Asbestos

**B00F - R0021 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning - 2004 - Brick/Veneer (Brick/Veneer)****Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

**Interior****B00G - R0001 - Practical Activities - 1hb**

No Asbestos

**B00G - R0002 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0003 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0004 - Withdrawal Space - 2hb**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0005 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0006 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0007 - Practical Activities - 1hb**

No Asbestos

**B00G - R0008 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00G - R0009 - Practical Activities - 1hb**

No Asbestos

**B00G - R0010 - Home Base Store**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0011 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0012 - Withdrawal Space - 2hb**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0013 - Home Base**

No Asbestos

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0014 - Home Base Store**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00G - R0015 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00G - R0016 - Distribution Board</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00G - R0017 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00G - R0018 - Home Base Store</b>						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00G - R0019 - Home Base</b>						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00G - R0020 - Withdrawal Space - 2hb</b>						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00G - R0021 - Home Base</b>						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00G - R0022 - Home Base Store</b>						
No Asbestos						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00G - R0023 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00G - R0024 - Movement</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Special Purpose - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

Ceiling Voids                      No Asbestos Found

Underfloor Voids                      No Asbestos Found

**Interior**

**B00H - R0001 - Special Programs Room**

No Asbestos

**B00H - R0002 - Staff Kitchen**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

**NS 100 - D10472 - Learning Unit - Single Primary/PAA : Placement Date - 21/09/2009**

### Exterior

No Asbestos Found.

### Interior

#### R1 - Home Base

No Asbestos Found.

#### R2 - Practical Activity Area

No Asbestos Found.

#### R3 - Home Base Store

No Asbestos Found.

#### R4 - Entry

No Asbestos Found.

**OS 602 - D12431 - Learning Unit - Standard With P.A.A. : Placement Date - 17/12/2011**

### Exterior

No Asbestos Found.

### Interior

#### R1 - Learning space/withdrawal/entry

No Asbestos Found.

#### R2 - Home Base Store

No Asbestos Found.

**NS 100 - D13179 - Learning Unit - Single Primary/PAA : Placement Date - 3/12/2009**

### Exterior

No Asbestos Found.

### Interior

#### R1 - Home Base

No Asbestos Found.

#### R2 - Practical Activity Area

No Asbestos Found.

#### R3 - Home Base Store

No Asbestos Found.

#### R4 - Entry

No Asbestos Found.

**OS 602 - D14219 - Learning Unit - Standard With P.A.A. : Placement Date - 17/12/2011**

### Exterior

No Asbestos Found.

### Interior

#### R1 - Learning space/withdrawal/entry

No Asbestos Found.

#### R2 - Home Base Store

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017