


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Wilton Public School (4650)  
**Region :** South Western Sydney  
**State Electorate :** Wollondilly  
**Local Government Area :** Wollondilly

**Initial Survey :** :  
**Register Issue Date :** 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00A - Administration - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids Requires Inspection

**Interior**

**B00A - R0001 - External Movement**

No Asbestos

**B00A - R0002 - External Movement**

No Asbestos

**B00A - R0003 - Entry Vestibule**

No Asbestos

**B00A - R0004 - Movement**

No Asbestos

**B00A - R0005 - Interview**

No Asbestos

**B00A - R0006 - Principal**

No Asbestos

**B00A - R0007 - Communications Room**

No Asbestos

**B00A - R0008 - Deputy Principal**

No Asbestos

**B00A - R0009 - Staff Room Annexe**

No Asbestos

**B00A - R0010 - Staff Room**

No Asbestos

**B00A - R0011 - Staff Room Annexe**

No Asbestos

**B00A - R0012 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0013 - Cleaning Distributed Store**

No Asbestos

**B00A - R0014 - Interview/Office - Type 3**

No Asbestos

**B00A - R0015 - Access Shower/Toilet**

No Asbestos

**B00A - R0016 - Sick Bay**

No Asbestos

**B00A - R0017 - Clerical Office**

No Asbestos

**B00A - R0018 - Clerical/Printing**

No Asbestos

**B00A - R0019 - Security Store**

No Asbestos

**B00A - R0020 - Staff Toilet**

No Asbestos

**B00A - R0021 - Staff Toilet**

No Asbestos

**B00A - R0022 - Staff Toilet**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning/Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

Ceiling Voids                      No Asbestos Found

Underfloor Voids                      Requires Inspection

**Interior**

**B00B - R0001 - External Movement**

No Asbestos

**B00B - R0002 - Laundry - Type 3**

No Asbestos

**B00B - R0003 - Toilet - Lobby**

No Asbestos

**B00B - R0004 - Access Shower/Toilet**

No Asbestos

**B00B - R0005 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0006 - Practical Activities/Movement - 1hb**

No Asbestos

**B00B - R0007 - Home Base Store**

No Asbestos

**B00B - R0008 - Home Base**

No Asbestos

**B00B - R0009 - Withdrawal Space - 2hb**

No Asbestos

**B00B - R0010 - Home Base**

No Asbestos

**B00B - R0011 - Home Base Store**

No Asbestos

**B00B - R0012 - Practical Activities/Movement - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

Ceiling Voids                      No Asbestos Found

Underfloor Voids                      Requires Inspection

**Interior**

**B00C - R0001 - External Movement**

No Asbestos

**B00C - R0002 - Toilets - Boys**

No Asbestos

**B00C - R0003 - Toilets - Girls**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids Requires Inspection

**Interior**

**B00D - R0001 - External Movement**

No Asbestos

**B00D - R0002 - Practical Activities/Movement - 1hb**

No Asbestos

**B00D - R0003 - Home Base Store**

No Asbestos

**B00D - R0004 - Home Base**

No Asbestos

**B00D - R0005 - Withdrawal Space - 2hb**

No Asbestos

**B00D - R0006 - Home Base**

No Asbestos

**B00D - R0007 - Home Base Store**

No Asbestos

**B00D - R0008 - Practical Activities/Movement - 1hb**

No Asbestos

**B00D - R0009 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0010 - Practical Activities/Movement - 1hb**

No Asbestos

**B00D - R0011 - Home Base Store**

No Asbestos

**B00D - R0012 - Home Base**

No Asbestos

**B00D - R0013 - Withdrawal Space - 2hb**

No Asbestos

**B00D - R0014 - Home Base**

No Asbestos

**B00D - R0015 - Home Base Store**

No Asbestos

**B00D - R0016 - Practical Activities/Movement - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Library/General Learning - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

Ceiling Voids                      No Asbestos Found

Underfloor Voids                  Requires Inspection

**Interior**

**B00E - R0001 - External Movement**

No Asbestos

**B00E - R0002 - Special Programs Room**

No Asbestos

**B00E - R0003 - Special Programs Store**

No Asbestos

**B00E - R0004 - Toilet - Lobby**

No Asbestos

**B00E - R0005 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0006 - Staff Toilet**

No Asbestos

**B00E - R0007 - K.L.A. Store**

No Asbestos

**B00E - R0008 - General Storeroom**

No Asbestos

**B00E - R0009 - Library Office/Workroom**

No Asbestos

**B00E - R0010 - Reading Area**

No Asbestos

**B00E - R0011 - Special Programs Room**

No Asbestos

**B00E - R0012 - Special Programs Store**

No Asbestos

**B00E - R0013 - Cleaning Distributed Store**

No Asbestos

**B00E - R0014 - Practical Activities**

No Asbestos

**B00E - R0015 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

Ceiling Voids                      No Asbestos Found

Underfloor Voids                  Requires Inspection

**Interior**

**B00F - R0001 - External Movement**

No Asbestos

**B00F - R0002 - Toilets - Boys**

No Asbestos

**B00F - R0003 - Toilets - Girls**

No Asbestos

**B00F - R0004 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### B00G - General Learning/Pupil Facilities - 2015 - Brick/Veneer (Brick/Veneer)

#### Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

#### Interior

##### B00G - R0001 - External Movement

No Asbestos

##### B00G - R0002 - Home Base

No Asbestos

##### B00G - R0003 - Home Base

No Asbestos

##### B00G - R0004 - Home Base

No Asbestos

##### B00G - R0005 - Staff Kitchen

No Asbestos

##### B00G - R0006 - Movement

No Asbestos

##### B00G - R0007 - General Storeroom

No Asbestos

##### B00G - R0008 - Withdrawal Space - 1hb

No Asbestos

##### B00G - R0009 - Withdrawal Space - 1hb

No Asbestos

##### B00G - R0010 - Communal Space

No Asbestos

##### B00G - R0011 - Movement

No Asbestos

##### B00G - R0012 - External Movement

No Asbestos

##### B00G - R0013 - Movement

No Asbestos

##### B00G - R0014 - Movement

No Asbestos

##### B00G - R0015 - Withdrawal Space - 1hb

No Asbestos

##### B00G - R0016 - Withdrawal Space - 1hb

No Asbestos

##### B00G - R0017 - General Storeroom

No Asbestos

##### B00G - R0018 - Access Shower/Toilet - Type 2

No Asbestos

##### B00G - R0019 - Home Base

No Asbestos

##### B00G - R0020 - Breakout Area

No Asbestos

##### B00G - R0021 - Home Base

No Asbestos

##### B00G - R0022 - Home Base

No Asbestos

##### B00G - R0023 - Communications Cupboard



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

<b>B00G - R0024 - Distribution Board</b>	Note: No inspection of live electrical installation.
--	--

No Asbestos

<b>B00G - R0025 - External Movement</b>
---

No Asbestos

<b>B00G - R0026 - Movement</b>
--------------------------------

No Asbestos

<b>B00G - R0027 - Home Base</b>
---------------------------------

No Asbestos

<b>B00G - R0028 - Home Base</b>
---------------------------------

No Asbestos

<b>B00G - R0029 - Home Base</b>
---------------------------------

No Asbestos

<b>B00G - R0030 - Home Base</b>
---------------------------------

No Asbestos

<b>B00G - R0031 - External Movement</b>
---

No Asbestos

<b>B00G - R0032 - Distribution Board</b>	Note: No inspection of live electrical installation.
--	--

No Asbestos

<b>B00G - R0033 - Distribution Board</b>	Note: No inspection of live electrical installation.
--	--

No Asbestos

<b>B00G - R0034 - Other</b>
-----------------------------

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Communal Facilities/Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids Requires Inspection

**Interior**

**B00H - R0001 - Communal Space**

No Asbestos

**B00H - R0002 - Raised Platform**

No Asbestos

**B00H - R0003 - Chair Storeroom**

No Asbestos

**B00H - R0004 - Sports Store**

No Asbestos

**B00H - R0005 - P.E. Store**

No Asbestos

**B00H - R0006 - Toilet - Lobby**

No Asbestos

**B00H - R0007 - Toilets - Boys**

No Asbestos

**B00H - R0008 - Cleaning Distributed Store**

No Asbestos

**B00H - R0009 - Access Shower/Toilet**

No Asbestos

**B00H - R0010 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00H - R0011 - Toilet - Lobby**

No Asbestos

**B00H - R0012 - Toilets - Girls**

No Asbestos

**B00H - R0013 - Sound Cupboard**

No Asbestos

**B00H - R0014 - Cleaning Supplies**

No Asbestos

**B00H - R0015 - Garden Store**

No Asbestos

**B00H - R0016 - General Assistant/Bulk Store**

No Asbestos

**B00H - R0017 - Communal/Performance Store**

No Asbestos

**B00H - R0018 - Movement**

No Asbestos

**B00H - R0019 - Ramp**

No Asbestos

**B00H - R0020 - Movement**

No Asbestos

**B00H - R0021 - Covered Outdoor Learning Area**

No Asbestos

**B00H - R0022 - Canteen**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00H - R0023 - Canteen Office/Store</b>						
No Asbestos						
<b>B00H - R0024 - Movement</b>						
No Asbestos						
<b>B00H - R0025 - External Movement</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00I - Mechanical Services - 2015 - #N/A (#N/A)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00I - R0001 - Plant**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 602 - D10077 - Learning Unit - Standard With P.A.A. : Placement Date - 24/12/2014**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D13743 - Learning Unit - Standard With P.A.A. : Placement Date - 6/09/2013**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D13926 - Learning Unit - Standard With P.A.A. : Placement Date - 23/10/2012**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D14077 - Learning Unit - Standard With P.A.A. : Placement Date - 24/01/2013**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D14337 - Learning Unit - Standard With P.A.A. : Placement Date - 6/09/2013**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017