


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Willans Hill School (5550)
Region : Riverina
State Electorate : Wagga Wagga
Local Government Area : Wagga Wagga

Initial Survey : Noel Arnold & Associates : 04 - May - 2008
Reviewed By : Greencap-NAA : 12 - Jul - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Library - 1986 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
Ceiling void	Non Accessible Area - Area inaccessible - no manhole available					
Wall Cladding	Compressed AC Sheet 5550/B00A/Wall Cladding/S17					No Asbestos Detected

Interior**B00A - R0002 - Reading Area (61.87 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected

B00A - R0003 - Toilets - Girls (7.58 m2)

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00A - R0004 - Distribution Board (1.28 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00A - R0005 - General Storeroom (2.16 m2)

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Sheet 5550/B00A/R0016/Floor Coverings Res/Textile/S2					No Asbestos Detected

B00A - R0006 - Toilets - Boys (6.72 m2)

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00A - R0007 - Library Office/Workroom (14.24 m2)

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Sheet 5550/B00A/R0016/Floor Coverings Res/Textile/S2					No Asbestos Detected

B00A - R0008 - Staff Room Annexe (12.11 m2)

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00A - R0009 - Deputy Principal (12.14 m2)

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00A - R0010 - Principal (16.33 m2)

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00A - R0011 - Duplicating Workroom (12.11 m2)

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Sheet 5550/B00A/R0016/Floor Coverings Res/Textile/S2					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0012 - Interview (12.15 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5550/B00A/Eaves Linings/S1				No Asbestos Detected
B00A - R0013 - External Movement (2.76 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5550/B00A/Eaves Linings/S1				No Asbestos Detected
B00A - R0014 - Entry Vestibule (34.45 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5550/B00A/Eaves Linings/S1				No Asbestos Detected
B00A - R0015 - Clerical Office (17.37 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5550/B00A/Eaves Linings/S1				No Asbestos Detected
B00A - R0016 - Cleaning Supplies (8.03 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5550/B00A/Eaves Linings/S1				No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Sheet	5550/B00A/R0016/Floor Coverings Res/Textile/S2				No Asbestos Detected
B00A - R0018 - Staff Toilet (2.8 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5550/B00A/Eaves Linings/S1				No Asbestos Detected
B00A - R0020 - Cleaning Supplies (2.27 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5550/B00A/Eaves Linings/S1				No Asbestos Detected
B00A - R0021 - General Storeroom (8.86 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5550/B00A/Eaves Linings/S1				No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Sheet	5550/B00A/R0016/Floor Coverings Res/Textile/S2				No Asbestos Detected
B00A - R0023 - Staff Room (25.09 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5550/B00A/Eaves Linings/S1				No Asbestos Detected
B00A - R0024 - Staff Kitchen (15.03 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5550/B00A/Eaves Linings/S1				No Asbestos Detected
B00A - R0026 - Garage/Carport (96.79 m2)						
No Asbestos						
B00A - R0027 - K.L.A. Store (15.03 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5550/B00A/Eaves Linings/S1				No Asbestos Detected
B00A - R0028 - External Movement (71.85 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5550/B00A/Eaves Linings/S1				No Asbestos Detected
B00A - R0029 - Movement (17.05 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5550/B00A/Eaves Linings/S1				No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	

B00B - Communal Facilities/Support Unit (M P S) - 1973 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
Ceiling void	No Asbestos Found					
Wall Cladding	Flat AC Sheeting 5550/B00B/R0030/Wall Linings Internal/S10					No Asbestos Detected

Interior**B00B - R0001 - P.E. Store (11.45 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00B - R0003 - Canteen (12.81 m2)

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Sheet 5550/B00A/R0016/Floor Coverings Res/Textile/S2					No Asbestos Detected

B00B - R0004 - Movement (1.17 m2)

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Sheet 5550/B00A/R0016/Floor Coverings Res/Textile/S2					No Asbestos Detected

B00B - R0005 - Canteen Office/Store (1.75 m2)

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Sheet 5550/B00A/R0016/Floor Coverings Res/Textile/S2					No Asbestos Detected

B00B - R0006 - Staff Toilet (4.07 m2)

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Sheet 5550/B00A/R0016/Floor Coverings Res/Textile/S2					No Asbestos Detected

B00B - R0007 - Cleaning Supplies (1.29 m2)

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00B - R0008 - Hall Chair Store (9.48 m2)

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00B - R0009 - External Movement (40.21 m2)

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00B - R0010 - Staff Room Annexe (14.03 m2)

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Sheet 5550/B00A/R0016/Floor Coverings Res/Textile/S2					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0011 - Staff Toilet (2.29 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	5550/B00A/Eaves Linings/S1					No Asbestos Detected
B00B - R0012 - Home Base (53.43 m2)						
Ceiling Structures/Linings	Vermiculite					
	5550/B00B/R0012/Ceiling Structures/Linings/S3					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Sheet					
	5550/B00B/R0013/Floor Coverings Res/Textile/S4					No Asbestos Detected
B00B - R0013 - Movement (105.84 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	5550/B00B/R0013/Floor Coverings Res/Textile/S4					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	5550/B00A/Eaves Linings/S1					No Asbestos Detected
B00B - R0015 - Toilets - Boys (20.78 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	5550/B00A/Eaves Linings/S1					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting					
	5550/B00B/R0040/Wall Linings Internal/S9					No Asbestos Detected
B00B - R0016 - Staff Shower/Change (5.67 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	5550/B00A/Eaves Linings/S1					No Asbestos Detected
B00B - R0017 - General Storeroom (11.7 m2)						
Ceiling Structures/Linings	Vermiculite					
	5550/B00B/R0012/Ceiling Structures/Linings/S3					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5550/B00B/R0022/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)
B00B - R0018 - Distribution Board (0.85 m2)						
Note: No inspection of live electrical installation.						
Ceiling Structures/Linings	Flat AC Sheeting					
	5550/B00A/Eaves Linings/S1					No Asbestos Detected
Electrical Mounting Board	Resinous Board	2Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
B00B - R0019 - Hydrotherapy - Pool (16.81 m2)						
Ceiling Structures/Linings	Vermiculite					
	5550/B00A/Eaves Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	16.8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5550/B00B/R0022/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)
B00B - R0020 - General Storeroom (8.54 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	5550/B00A/Eaves Linings/S1					No Asbestos Detected
B00B - R0021 - Cleaning Supplies (1.33 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	5550/B00A/Eaves Linings/S1					No Asbestos Detected
B00B - R0022 - Cleaning Distributed Store (7.66 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	5550/B00A/Eaves Linings/S1					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
5550/B00B/R0022/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	
B00B - R0023 - Hall Chair Store (4.72 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
5550/B00A/Eaves Linings/S1					No Asbestos Detected	
B00B - R0024 - Movement (11.52 m2)						
No Asbestos						
B00B - R0025 - Home Base (52.77 m2)						
Ceiling Structures/Linings	Vermiculite					
5550/B00B/R0012/Ceiling Structures/Linings/S3					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Sheet					
5550/B00B/R0013/Floor Coverings Res/Textile/S4					No Asbestos Detected	
B00B - R0026 - Home Base Store (6.07 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
5550/B00A/Eaves Linings/S1					No Asbestos Detected	
B00B - R0027 - Withdrawal Space - 1hb (8.56 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
5550/B00A/Eaves Linings/S1					No Asbestos Detected	
B00B - R0028 - Home Base Store (6.09 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
5550/B00A/Eaves Linings/S1					No Asbestos Detected	
B00B - R0029 - Home Base (53.14 m2)						
Ceiling Structures/Linings	Vermiculite					
5550/B00B/R0012/Ceiling Structures/Linings/S3					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Sheet					
5550/B00B/R0013/Floor Coverings Res/Textile/S4					No Asbestos Detected	
B00B - R0030 - External Movement (43.46 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
5550/B00A/Eaves Linings/S1					No Asbestos Detected	
Wall Linings Internal	Flat AC Sheeting					
5550/B00B/R0030/Wall Linings Internal/S10					No Asbestos Detected	
B00B - R0031 - Home Base Store (5.71 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
5550/B00A/Eaves Linings/S1					No Asbestos Detected	
B00B - R0032 - Shower/Change (7.31 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
5550/B00A/Eaves Linings/S1					No Asbestos Detected	
B00B - R0033 - Shower/Change (7.35 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
5550/B00A/Eaves Linings/S1					No Asbestos Detected	
B00B - R0034 - Sports Store (11.58 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
5550/B00A/Eaves Linings/S1					No Asbestos Detected	
Wall Linings Internal	Flat AC Sheeting					
5550/B00A/Eaves Linings/S1					No Asbestos Detected	
B00B - R0035 - External Movement (0.83 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
5550/B00B/R0012/Ceiling Structures/Linings/S3					No Asbestos Detected	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
5550/B00B/R0030/Wall Linings Internal/S10						
B00B - R0036 - Distribution Board (0.76 m2)					Note: No inspection of live electrical installation.	
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
5550/B00A/Eaves Linings/S1						
B00B - R0037 - External Movement (0.88 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
5550/B00B/R0012/Ceiling Structures/Linings/S3						
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
5550/B00B/R0030/Wall Linings Internal/S10						
B00B - R0038 - Raised Platform (14.14 m2)						
No Asbestos						
B00B - R0040 - Cleaning Distributed Store (2.9 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
5550/B00A/Eaves Linings/S1						
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
5550/B00B/R0040/Wall Linings Internal/S9						
B00B - R0041 - Toilet - S (24.28 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
5550/B00A/Eaves Linings/S1						
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
5550/B00B/R0040/Wall Linings Internal/S9						
B00B - R0042 - Communal Space (133.21 m2)						
No Asbestos						
B00B - R0043 - External Movement (33.18 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
5550/B00A/Eaves Linings/S1						
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
5550/B00A/Eaves Linings/S1						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Support Unit (M P S) - 1985 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting 5550/B00A/Eaves Linings/S1					No Asbestos Detected
Wall Cladding	Compressed AC Sheet 5550/B00C/Wall Cladding/S8					No Asbestos Detected
Underfloor void	No Asbestos Found					
Ceiling void	No Asbestos Found					

Interior**B00C - R0001 - Other-Vacant (3.97 m2)**

Wall Linings Internal	Flat AC Sheeting 5550/B00C/R0001/Wall Linings Internal/S18					No Asbestos Detected
-----------------------	---	--	--	--	--	----------------------

B00C - R0002 - Other-Vacant (6.59 m2)

No Asbestos

B00C - R0003 - General Storeroom (0.51 m2)

No Asbestos

B00C - R0004 - Staff Kitchen (6.88 m2)

No Asbestos

B00C - R0005 - Other-Vacant (21.63 m2)

No Asbestos

B00C - R0006 - Other-Vacant (13.07 m2)

No Asbestos

B00C - R0007 - Laundry (2.71 m2)

No Asbestos

B00C - R0008 - General Storeroom (0.32 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities/Support Unit (M P S) - 1985 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 5550/B00D/Eaves Linings/S14					No Asbestos Detected
Ceiling void	No Asbestos Found					

Interior**B00D - R0001 - External Movement (18.34 m2)**

Wall Linings Internal	Flat AC Sheeting 5550/B00D/R0001/Wall Linings Internal/S12					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 5550/B00D/R0001/Wall Linings Internal/S13					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 5550/B00D/Eaves Linings/S14					No Asbestos Detected

B00D - R0002 - Home Base (51.61 m2)

No Asbestos

B00D - R0003 - External Movement (230.07 m2)

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00D/Eaves Linings/S14					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 5550/B00D/R0001/Wall Linings Internal/S12					No Asbestos Detected

B00D - R0004 - Main Switch Board (6.48 m2)

Electrical Mounting Board	Resinous Board 5550/B00D/R0004/Electrical Mounting Board/S15					No Asbestos Detected
---------------------------	---	--	--	--	--	----------------------

B00D - R0005 - Home Base (49.9 m2)

No Asbestos

B00D - R0008 - General Learning Space (50.53 m2)

No Asbestos

B00D - R0009 - Practical Activities - 1hb (17.35 m2)

Floor Coverings Res/Textile	Vinyl Sheet 5550/B00D/R0014/Floor Coverings Res/Textile/S6					No Asbestos Detected
-----------------------------	---	--	--	--	--	----------------------

B00D - R0010 - External Movement (29.81 m2)

Ceiling Structures/Linings	Flat AC Sheeting 5550/B00D/Eaves Linings/S14					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 5550/B00D/R0001/Wall Linings Internal/S12					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 5550/B00D/R0001/Wall Linings Internal/S13					No Asbestos Detected

B00D - R0011 - Home Base (50.83 m2)

No Asbestos

B00D - R0012 - Practical Activities - 1hb (17.05 m2)

Floor Coverings Res/Textile	Vinyl Sheet 5550/B00D/R0014/Floor Coverings Res/Textile/S6					No Asbestos Detected
-----------------------------	---	--	--	--	--	----------------------

B00D - R0013 - Toilets - Boys/Girls (5.36 m2)

No Asbestos

B00D - R0014 - Food Technology L.S. (67.24 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Sheet					
	5550/B00D/R0014/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00D - R0015 - Special Learning Space (82.2 m2)						
No Asbestos						
B00D - R0016 - General Storeroom (17.84 m2)						
No Asbestos						
B00D - R0017 - Study Space (17.79 m2)						
No Asbestos						
B00D - R0019 - Practical Activities - 1hb (17.53 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	5550/B00D/R0014/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00D - R0020 - Toilets - Boys (15.16 m2)						
No Asbestos						
B00D - R0021 - Cleaning Supplies (2.55 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	5550/B00D/R0021/Floor Coverings Res/Textile/S7					No Asbestos Detected
B00D - R0022 - Toilets - Girls (32.85 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	5550/B00D/R0021/Floor Coverings Res/Textile/S7					No Asbestos Detected
B00D - R0023 - Movement (2.11 m2)						
No Asbestos						
B00D - R0024 - Home Base (51.78 m2)						
No Asbestos						
B00D - R0025 - Practical Activities - 1hb (29.72 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	5550/B00D/R0014/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00D - R0026 - Toilet - S (24.34 m2)						
Wall Linings Internal	Flat AC Sheeting					
	5550/B00D/R0026/Wall Linings Internal/S11					No Asbestos Detected
B00D - R0027 - Withdrawal - S (45.16 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	5550/B00D/R0014/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00D - R0028 - Covered Outdoor Learning Area - S (55.92 m2)						
Wall Linings Internal	Flat AC Sheeting					
	5550/B00D/R0028/Wall Linings Internal/S16					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Building Services - 1981 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling
 Non Accessible Area
 - Area inaccessible

Underfloor Voids - Slab on Ground
 Non Accessible Area
 - Area inaccessible

Interior

B00E - R0001 - Covered Vehicle Area/Porte Cochere (59.07 m2)

Ceiling Structures/Linings
 Flat AC Sheeting
 5550/B00A/Eaves Linings/S1

No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Building Services - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00F - R0001 - Garden Store (18.96 m2)

No Asbestos

B00F - R0002 - Garden Store (19.19 m2)

No Asbestos

B00F - R0003 - Sports Store (18.84 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017