

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : William Rose School (5614)
Region : Western Sydney
State Electorate : Blacktown
Local Government Area : Blacktown

Initial Survey : Noel Arnold & Associates : 24 - Apr - 2008
Reviewed By : Parsons Brinckerhoff : 07 - Feb - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Other-Garage - 2002 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00A - R0001 - Garage/Carport

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration/Library - 1957 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	100m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5614/B00B/Eaves Linings/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Roof has being replaced however					
Ceiling Voids	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris					No Asbestos Detected
	5614/B00B/Underfloor Voids/S12					

Interior**B00B - R0010 - Cleaning Distributed Store**

No Asbestos

B00B - R0011 - Communications Room

No Asbestos

B00B - R0012 - Special Programs Room

No Asbestos

B00B - R0013 - K.L.A. Store

No Asbestos

B00B - R0014 - Special Programs Store

No Asbestos

B00B - R0020 - Movement

No Asbestos

B00B - R0021 - Staff Toilet

No Asbestos

B00B - R0022 - K.L.A. Store

No Asbestos

B00B - R0023 - General Assistant/Bulk Store

No Asbestos

B00B - R0024 - Staff Toilet

No Asbestos

B00B - R0025 - Disabled Toilet

No Asbestos

B00B - R0026 - Multi-Purpose Space

No Asbestos

B00B - R0027 - Multi-Purpose Space

No Asbestos

B00B - R0028 - P.E. Store

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	5614/B00B/R0028/Wall Linings Internal/S5					
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	5614/B00B/R0028/Ceiling Structures/Linings/S6					

B00B - R0032 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	141m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	5614/B00B/R0032/Ceiling Structures/Linings/S3	Chrysotile (white asbestos)				

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	5614/B00B/R0032/Wall Linings Internal/S4					

B00B - R0033 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0034 - Movement						
No Asbestos						
B00B - R0035 - Movement						
No Asbestos						
B00B - R0037 - Practical Activities						
No Asbestos						
B00B - R0038 - Home Base						
No Asbestos						
B00B - R0039 - Home Base Store						
No Asbestos						
B00B - R0040 - Home Base						
No Asbestos						
B00B - R0041 - Practical Activities						
No Asbestos						
B00B - R0042 - External Movement						
Recently Modified Space Requires Inspection						
B00B - R0043 - General Storeroom						
Recently Modified Space Requires Inspection						
B00B - R0044 - Staff Kitchen						
Recently Modified Space Requires Inspection						
B00B - R0045 - General Storeroom						
Recently Modified Space Requires Inspection						
B00B - R0046 - Staff Toilet						
Recently Modified Space Requires Inspection						
B00B - R0047 - Staff Toilet						
Recently Modified Space Requires Inspection						
B00B - R0048 - Toilet - Lobby						
Recently Modified Space Requires Inspection						
B00B - R0049 - Duplicating Workroom						
Recently Modified Space Requires Inspection						
B00B - R0050 - Clerical Office/Workroom						
Recently Modified Space Requires Inspection						
B00B - R0051 - Clerical Office						
Recently Modified Space Requires Inspection						
B00B - R0052 - Staff Room						
Recently Modified Space Requires Inspection						
B00B - R0053 - Principal						
Recently Modified Space Requires Inspection						
B00B - R0054 - Interview						
Recently Modified Space Requires Inspection						
B00B - R0055 - Entry Vestibule						
Recently Modified Space Requires Inspection						
B00B - R0056 - Movement						
Recently Modified Space Requires Inspection						
B00B - R0057 - External Movement						
Recently Modified Space Requires Inspection						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Support Unit - 1957 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	5614/B00C/Eaves Linings/S13					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	5614/B00C/Gable Verge Lining/S14					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids						

Interior**B00C - R0001 - Movement**

No Asbestos

B00C - R0002 - Cleaning Supplies

No Asbestos

B00C - R0003 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5614/B00C/R0004/Ceiling Structures/Linings/S7					Chrysotile (white asbestos) , Amosite (brown asbestos)
In-fill-panel	Flat AC Sheeting	1m	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	5614/B00C/R0004/In-fill-panel/S8					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00C - R0005 - Movement

No Asbestos

B00C - R0006 - Toilet - P

No Asbestos

B00C - R0007 - Staff Room

No Asbestos

B00C - R0008 - Home Base - P

No Asbestos

B00C - R0009 - Practical Activities - P - 1hb

No Asbestos

B00C - R0010 - Practical Activities - P - 1hb

No Asbestos

B00C - R0011 - Withdrawal - P

No Asbestos

B00C - R0012 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5614/B00C/R0004/Ceiling Structures/Linings/S7					Chrysotile (white asbestos) , Amosite (brown asbestos)
In-fill-panel	Flat AC Sheeting	1m	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	5614/B00C/R0004/In-fill-panel/S8					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00C - R0013 - Movement

No Asbestos

B00C - R0014 - Home Base Store - P

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Support Unit/Pupil Facilities - 2002 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00D - R0001 - Home Base - P**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00D - R0002 - Home Base Store - P

No Asbestos

B00D - R0003 - Withdrawal - P

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00D - R0004 - Home Base Store - P

No Asbestos

B00D - R0005 - Main Switch Board

No Asbestos

B00D - R0006 - Home Base - P

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00D - R0007 - Toilet - P

No Asbestos

B00D - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0009 - Laundry - P

No Asbestos

B00D - R0010 - Toilet - P

No Asbestos

B00D - R0011 - Shower/Change

No Asbestos

B00D - R0012 - Shower/Change

No Asbestos

B00D - R0013 - Practical Activities - P - 2hb

No Asbestos

B00D - R0014 - Withdrawal - P

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00D - R0015 - Home Base - P

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00D - R0016 - Home Base - P

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00D - R0017 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00D - R0018 - Home Base Store - P

No Asbestos

B00D - R0019 - Home Base Store - P

No Asbestos

B00D - R0020 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
B00D - R0021 - Withdrawal - P						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R0022 - Home Base Store - P						
No Asbestos						
B00D - R0023 - Home Base Store - P						
No Asbestos						
B00D - R0024 - Withdrawal - P						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R0025 - Home Base - P						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R0026 - Home Base - P						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R0027 - Practical Activities - P - 2hb						
No Asbestos						
B00D - R0028 - Shower/Change						
No Asbestos						
B00D - R0029 - Shower/Change						
No Asbestos						
B00D - R0030 - Toilet - P						
No Asbestos						
B00D - R0031 - Distribution Board						Note: No inspection of live electrical installation.
No Asbestos						
B00D - R0032 - Laundry - P						
No Asbestos						
B00D - R0033 - Toilet - P						
No Asbestos						
B00D - R0034 - Home Base - P						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R0035 - Withdrawal - P						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R0036 - Home Base - P						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R0037 - Home Base Store - P						
No Asbestos						
B00D - R0038 - Staff Room						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R0039 - Home Base Store - P						
No Asbestos						
B00D - R0041 - Movement						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Building Services - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00F - R0001 - Movement

No Asbestos

B00F - R0002 - Sports Store

No Asbestos

B00F - R0003 - General Assistant/Bulk Store

No Asbestos

B00F - R0004 - Covered Vehicle Area/Porte Cochere

No Asbestos

B00F - R0005 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Special Purpose - 1957 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting 5614/B00H/Eaves Linings/S9					No Asbestos Detected
Wall Cladding	Flat AC Sheeting 5614/B00H/Wall Cladding/S10					No Asbestos Detected
Underfloor Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Interior**B00H - R0001 - Special Programs Room**

No Asbestos

B00H - R0002 - Movement

Flooring	Compressed AC Sheet 5614/B00H/R0002/Floor Coverings Res/Textile/S11					No Asbestos Detected
----------	------------------------------------------------------------------------	--	--	--	--	-----------------------------

B00H - R0003 - Access Shower/Toilet

No Asbestos

B00H - R0004 - Special Programs Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Pupil Facilities/Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B001 - R0001 - Communal Space

No Asbestos

B001 - R0002 - P.E. Store

No Asbestos

B001 - R0003 - Covered Outdoor Learning Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00J - General Learning - 2013 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00J - R0001 - Practical Activities**

No Asbestos

B00J - R0002 - Home Base

No Asbestos

B00J - R0003 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00J - R0004 - Home Base Store

No Asbestos

B00J - R0005 - Withdrawal Space - 1hb

No Asbestos

B00J - R0006 - Breakout Area

No Asbestos

B00J - R0007 - Access Shower/Toilet

No Asbestos

B00J - R0008 - Change - Type 2

No Asbestos

B00J - R0009 - Practical Activities

No Asbestos

B00J - R0010 - Home Base

No Asbestos

B00J - R0011 - Access Shower/Toilet

No Asbestos

B00J - R0012 - Breakout Area

No Asbestos

B00J - R0013 - Withdrawal Space - 1hb

No Asbestos

B00J - R0014 - Home Base Store

No Asbestos

B00J - R0015 - Laundry - S

No Asbestos

B00J - R0016 - Access Shower/Toilet

No Asbestos

B00J - R0017 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Library/General Learning - 2013 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00K - R0001 - Reading Area**

No Asbestos

B00K - R0002 - Library Office/Workroom

No Asbestos

B00K - R0003 - K.L.A. Store

No Asbestos

B00K - R0004 - Communications Room

No Asbestos

B00K - R0005 - Access Shower/Toilet

No Asbestos

B00K - R0006 - Practical Activities

No Asbestos

B00K - R0007 - Home Base

No Asbestos

B00K - R0008 - Home Base Store

No Asbestos

B00K - R0009 - Withdrawal Space - 1hb

No Asbestos

B00K - R0010 - Breakout Area

No Asbestos

B00K - R0011 - Access Shower/Toilet

No Asbestos

B00K - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00K - R0013 - Home Base Store

No Asbestos

B00K - R0014 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Staff Facilities - 2013 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00L - R0001 - Staff Room**

No Asbestos

B00L - R0002 - Staff Toilet

No Asbestos

B00L - R0003 - Staff Toilet

No Asbestos

B00L - R0004 - Access Shower/Toilet

No Asbestos

B00L - R0005 - Movement

No Asbestos

B00L - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0007 - Staff Room Annexe

No Asbestos

B00L - R0008 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Building Services - 2013 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00M - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Building Services - 1980 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B000 - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D16861 - Learning Unit - Standard With P.A.A. : Placement Date - 16/11/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017