


Asbestos Register

(Hazardous Materials and Risk Assessment)



School : Woodberry Learning Centre (5764)
Region : Hunter/Central Coast
State Electorate : Maitland
Local Government Area : Maitland

Initial Survey : Noel Arnold & Associates : 27 - Jun - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 2007 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Entry Vestibule**

No Asbestos

B00A - R0002 - Interview

No Asbestos

B00A - R0003 - Principal

No Asbestos

B00A - R0004 - Access Shower/Toilet

No Asbestos

B00A - R0005 - Security Store

No Asbestos

B00A - R0006 - Staff Room Annexe

No Asbestos

B00A - R0007 - Staff Room

No Asbestos

B00A - R0008 - Staff Toilet

No Asbestos

B00A - R0009 - Cleaning Distributed Store

No Asbestos

B00A - R0010 - Sick Bay

No Asbestos

B00A - R0011 - Clerical Office/Workroom

No Asbestos

B00A - R0012 - Movement

No Asbestos

B00A - R0013 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 2007 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Home Base

No Asbestos

B00B - R0002 - Toilets-Unisex

No Asbestos

B00B - R0003 - Toilets-Unisex

No Asbestos

B00B - R0004 - Home Base

No Asbestos

B00B - R0005 - Home Base Store

No Asbestos

B00B - R0006 - Home Base Store

No Asbestos

B00B - R0007 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 2007 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00C - R0001 - Home Base/Practical Activities**

No Asbestos

B00C - R0002 - Access Shower/Toilet

No Asbestos

B00C - R0003 - Staff Toilet

No Asbestos

B00C - R0004 - Home Base

No Asbestos

B00C - R0005 - Home Base Store

No Asbestos

B00C - R0006 - Home Base Store

No Asbestos

B00C - R0007 - Nutrition Room

No Asbestos

B00C - R0008 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - External Movement

No Asbestos

B00D - R0002 - Home Base - Bd/Cd/Ed

No Asbestos

B00D - R0003 - Home Base - Bd/Cd/Ed

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017