


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Wingham Public School (7314)  
**Region :** North Coast  
**State Electorate :** Myall Lakes  
**Local Government Area :** Greater Taree

**Initial Survey :** Noel Arnold & Associates : 07 - Apr - 2008  
**Reviewed By :** Parsons Brinckerhoff : 01 - Nov - 2016



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/Staff Facilities - 1987 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Void      No Asbestos Found

**Interior****B00A - R0001 - Staff Room**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00A - R0002 - K.L.A. Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00A - R0003 - Principal**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00A - R0004 - Clerical Office/Workroom**

No Asbestos

**B00A - R0005 - Staff Room Annexe**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00A - R0006 - Entry Vestibule**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00A - R0007 - Deputy Principal**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00A - R0008 - Sick Bay**

No Asbestos

**B00A - R0009 - Staff Toilet**

No Asbestos

**B00A - R0010 - Staff Toilet**

No Asbestos

**B00A - R0011 - Cleaning Distributed Store**

No Asbestos

**B00A - R0012 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0013 - Staff Room Annexe**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00A - R0014 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00A - R0015 - Security Store**

No Asbestos

**B00A - R0016 - Security Store**

No Asbestos

**B00A - R0017 - Clerical Office**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00A - R0018 - Movement**

No Asbestos

**B00A - R0019 - Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning - 1987 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Wall Cladding	Compressed AC Sheet 7314/B00B/Wall Cladding/S2					<b>No Asbestos Detected</b>
Ceiling Void	No Asbestos Found					

**Interior**

**B00B - R0001 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00B - R0002 - Cleaning Distributed Store**

No Asbestos						
-------------	--	--	--	--	--	--

**B00B - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00B - R0004 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00B - R0005 - Movement**

No Asbestos						
-------------	--	--	--	--	--	--

**B00B - R0006 - Practical Activities - 1hb**

No Asbestos						
-------------	--	--	--	--	--	--

**B00B - R0007 - Movement**

No Asbestos						
-------------	--	--	--	--	--	--

**B00B - R0008 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00B - R0009 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00B - R0010 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00B - R0011 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00B - R0012 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00B - R0013 - Movement**

No Asbestos						
-------------	--	--	--	--	--	--

**B00B - R0014 - Practical Activities - 1hb**

No Asbestos						
-------------	--	--	--	--	--	--

**B00B - R0015 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00B - R0016 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00B - R0017 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00B - R0018 - Movement**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

<b>B00B - R0019 - Distribution Board</b>	Note: No inspection of live electrical installation.
--	--

No Asbestos

<b>B00B - R0020 - Movement</b>
--------------------------------

No Asbestos

<b>B00B - R0021 - Movement</b>
--------------------------------

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 1987 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Wall Cladding	Compressed AC Sheet 7314/B00B/Wall Cladding/S2					<b>No Asbestos Detected</b>
Ceiling Void	No Asbestos Found					

**Interior**

**B00C - R0001 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0002 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00C - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0004 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0005 - Movement**

No Asbestos

**B00C - R0006 - Practical Activities - 1hb**

No Asbestos

**B00C - R0007 - Movement**

No Asbestos

**B00C - R0008 - Movement**

No Asbestos

**B00C - R0009 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0010 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0011 - General Storeroom**

No Asbestos

**B00C - R0012 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Pupil Facilities - 1987 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

**Interior**

**B00D - R0001 - Movement**

No Asbestos

**B00D - R0002 - Canteen**

No Asbestos

**B00D - R0003 - Canteen Office/Store**

No Asbestos

**B00D - R0004 - Canteen Office/Store**

No Asbestos

**B00D - R0005 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning - 1987 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Wall Cladding	Compressed AC Sheet 7314/B00B/Wall Cladding/S2					<b>No Asbestos Detected</b>
Ceiling Void	No Asbestos Found					

**Interior**

**B00E - R0001 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00E - R0002 - General Storeroom**

No Asbestos						
-------------	--	--	--	--	--	--

**B00E - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00E - R0004 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00E - R0005 - Movement**

No Asbestos						
-------------	--	--	--	--	--	--

**B00E - R0006 - Practical Activities - 1hb**

No Asbestos						
-------------	--	--	--	--	--	--

**B00E - R0007 - Movement**

No Asbestos						
-------------	--	--	--	--	--	--

**B00E - R0008 - Movement**

No Asbestos						
-------------	--	--	--	--	--	--

**B00E - R0009 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00E - R0010 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos						
-------------	--	--	--	--	--	--

**B00E - R0011 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00E - R0012 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00E - R0013 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00E - R0014 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00E - R0015 - Movement**

No Asbestos						
-------------	--	--	--	--	--	--

**B00E - R0016 - Practical Activities - 1hb**

No Asbestos						
-------------	--	--	--	--	--	--

**B00E - R0017 - Kiln Room**

No Asbestos						
-------------	--	--	--	--	--	--

**B00E - R0018 - Movement**

No Asbestos						
-------------	--	--	--	--	--	--

**B00E - R0019 - Movement**

--	--	--	--	--	--	--

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00E - R0020 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R0021 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R0022 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R0023 - Disabled Toilet**

No Asbestos

**B00E - R0024 - Movement**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning - 1987 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Wall Cladding	Compressed AC Sheet 7314/B00B/Wall Cladding/S2					No Asbestos Detected
Ceiling Void	No Asbestos Found					

**Interior**

**B00F - R0001 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00F - R0002 - General Storeroom**

No Asbestos						
-------------	--	--	--	--	--	--

**B00F - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00F - R0004 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00F - R0005 - Movement**

No Asbestos						
-------------	--	--	--	--	--	--

**B00F - R0006 - Practical Activities - 1hb**

No Asbestos						
-------------	--	--	--	--	--	--

**B00F - R0007 - Movement**

No Asbestos						
-------------	--	--	--	--	--	--

**B00F - R0008 - Movement**

No Asbestos						
-------------	--	--	--	--	--	--

**B00F - R0009 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00F - R0010 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00F - R0011 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00F - R0012 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00F - R0013 - Distribution Board**

No Asbestos						Note: No inspection of live electrical installation.
-------------	--	--	--	--	--	--

**B00F - R0014 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00F - R0015 - Movement**

No Asbestos						
-------------	--	--	--	--	--	--

**B00F - R0016 - Practical Activities - 1hb**

No Asbestos						
-------------	--	--	--	--	--	--

**B00F - R0017 - Movement**

No Asbestos						
-------------	--	--	--	--	--	--

**B00F - R0018 - Movement**

No Asbestos						
-------------	--	--	--	--	--	--

**B00F - R0019 - Home Base**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00F - R0020 - Withdrawal Space - 1hb</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00F - R0021 - General Storeroom</b>						
No Asbestos						
<b>B00F - R0022 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00F - R0023 - Movement</b>						
No Asbestos						
<b>B00F - R0024 - External Movement</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Pupil Facilities - 1987 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

**Interior**

**B00G - R0001 - Movement**

No Asbestos

**B00G - R0002 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting 7314/B00J/R0001/Ceiling Structures/Linings/S1	<b>No Asbestos Detected</b>
----------------------------	---	-----------------------------

**B00G - R0003 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting 7314/B00J/R0001/Ceiling Structures/Linings/S1	<b>No Asbestos Detected</b>
----------------------------	---	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Communal Facilities - 1987 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

**Interior**

**B00H - R0001 - Movement**

No Asbestos

**B00H - R0002 - Movement**

No Asbestos

**B00H - R0003 - Drinking Facilities**

No Asbestos

**B00H - R0004 - Drinking Facilities**

No Asbestos

**B00H - R0005 - Movement**

No Asbestos

**B00H - R0006 - Communal Space**

No Asbestos

**B00H - R0007 - Disabled Toilet**

No Asbestos

**B00H - R0008 - Hall Chair Store**

No Asbestos

**B00H - R0009 - General Storeroom**

No Asbestos

**B00H - R0010 - Main Switch Board**

No Asbestos

**B00H - R0011 - Movement**

No Asbestos

**B00H - R0012 - Interview**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00H - R0013 - Toilets - Boys**

No Asbestos

**B00H - R0014 - Movement**

No Asbestos

**B00H - R0015 - Raised Platform**

No Asbestos

**B00H - R0016 - Movement**

No Asbestos

**B00H - R0017 - Plant**

No Asbestos

**B00H - R0018 - Movement**

No Asbestos

**B00H - R0019 - General Storeroom**

No Asbestos

**B00H - R0020 - General Assistant/Bulk Store**

Stored material Flat AC Sheeting  
7314/B00H/R0020/Stored material/S6

No Asbestos Detected

**B00H - R0021 - Sports Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00H - R0022 - Shower/Change</b>						
No Asbestos						
<b>B00H - R0023 - Movement</b>						
No Asbestos						
<b>B00H - R0024 - Toilets - Girls</b>						
No Asbestos						
<b>B00H - R0025 - Cleaning Distributed Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00H - R0026 - Cleaning Supplies</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - Pupil Facilities - 1987 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

**Interior**

**B001 - R0001 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting	7314/B00J/R0001/Ceiling Structures/Linings/S1	<b>No Asbestos Detected</b>
----------------------------	------------------	---	-----------------------------

**B001 - R0002 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Pupil Facilities - 1988 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00J - R0001 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting	7314/B00J/R0001/Ceiling Structures/Linings/S1	<b>No Asbestos Detected</b>
----------------------------	------------------	---	-----------------------------

**B00J - R0002 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Pupil Facilities - 1987 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

**Interior**

**B00K - R0001 - Movement**

No Asbestos

**B00K - R0002 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting 7314/B00J/R0001/Ceiling Structures/Linings/S1	<b>No Asbestos Detected</b>
----------------------------	---	-----------------------------

**B00K - R0003 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting 7314/B00J/R0001/Ceiling Structures/Linings/S1	<b>No Asbestos Detected</b>
----------------------------	---	-----------------------------

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - Library/Tiered Learning - 1987 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

**Interior**

**B00L - R0001 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00L - R0002 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00L - R0003 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00L - R0004 - Library Office/Workroom**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00L - R0005 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00L - R0006 - Seminar/Study**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00L - R0007 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00L - R0008 - Movement**

No Asbestos

**B00L - R0009 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00L - R0010 - Special Programs Store**

No Asbestos

**B00L - R0011 - Special Programs Room**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00L - R0012 - Movement**

No Asbestos

**B00L - R0013 - Plant**

No Asbestos

**B00L - R0014 - Movement**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - Pupil Facilities/Administration - 1987 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 7314/B00M/Eaves Linings/S5					<b>No Asbestos Detected</b>
Ceiling Void	No Asbestos Found					

**Interior**

**B00M - R0001 - Canteen**

Ceiling Structures/Linings	Flat AC Sheeting 7314/B00M/R0001/Ceiling Structures/Linings/S3					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

**B00M - R0002 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 7314/B00M/R0002/Ceiling Structures/Linings/S4					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

**B00M - R0003 - General Storeroom**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00N - Museum - 1878 - Timber (Timber)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Void      No Asbestos Found

**Interior**

**B00N - R0001 - Other-Vacant**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B000 - Storage - 2011 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B000 - R0001 - Sports Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0DD - Special Purpose/Building Services - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B0DD - R0001 - Special Programs Room**

No Asbestos

**B0DD - R0002 - Special Programs Store**

No Asbestos

**B0DD - R0003 - Cleaning Distributed Store**

No Asbestos

**B0DD - R0004 - Sports Store**

No Asbestos

**B0DD - R0005 - General Storeroom**

No Asbestos

**B0DD - R0006 - General Assistant/Bulk Store**

No Asbestos

**B0DD - R0007 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017