

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Wauchope High School (8173)  
**Region :** North Coast  
**State Electorate :** Oxley  
**Local Government Area :** Port Macquarie-Hastings

**Initial Survey :** Noel Arnold & Associates : 05 - May - 2008  
**Reviewed By :** Greencap-NAA : 14 - Apr - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Administration - 1959 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible sealed ceiling					
Gable verge lining	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B0AS/R0001/Ceiling Structures/Linings/S12			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Eaves Linings	Flat AC Sheeting	60m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00A/Eaves Linings/S19			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Under floor space	Non Accessible Area - Area inaccessible too low to access					

**Interior**

**B00A - R0001 - Staff - Toilet (9.96 m2)**

No Asbestos

**B00A - R0005 - Interview/Office - Type 1 (10.53 m2)**

No Asbestos

**B00A - R0006 - Staff - Toilet (7.74 m2)**

No Asbestos

**B00A - R0007 - Administration - Clerical (23.58 m2)**

No Asbestos

**B00A - R0008 - Administration - Clerical (11.98 m2)**

No Asbestos

**B00A - R0009 - Resources Store (3.59 m2)**

Floor Coverings Res/Textile	Vinyl Sheet					
	8173/B00A/R0009/Floor Coverings Res/Textile/S4			<b>No Asbestos Detected</b>		

**B00A - R0010 - General Storeroom (2.49 m2)**

No Asbestos

**B00A - R0011 - Principal Office (21.28 m2)**

No Asbestos

**B00A - R0012 - Administration - Clerical (14.89 m2)**

No Asbestos

**B00A - R0013 - General Storeroom (2.73 m2)**

No Asbestos

**B00A - R0014 - Movement (2.21 m2)**

No Asbestos

**B00A - R0015 - Main Switchroom (2.89 m2)**

Electrical Backing Board	Resinous Board	3Unit	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Electrical Hazard</b>						

**B00A - R0016 - General Storeroom (7.11 m2)**

No Asbestos

**B00A - R0017 - Movement (11.94 m2)**

No Asbestos

**B00A - R0018 - Public Entry (30.18 m2)**

No Asbestos

**B00A - R0020 - General Learning Space (53.29 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0021 - General Learning Space (53.29 m2)</b>						
No Asbestos						
<b>B00A - R0022 - General Learning Space (53.29 m2)</b>						
No Asbestos						
<b>B00A - R0023 - General Learning Space (53.14 m2)</b>						
No Asbestos						
<b>B00A - R0024 - General Learning Space (53.22 m2)</b>						
No Asbestos						
<b>B00A - R0025 - Duplicating Workroom (26.26 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8173/B00A/R0025/Floor Coverings Res/Textile/S16					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Adhesive					
	8173/B00A/R0025/Floor Coverings Res/Textile/S17					<b>No Asbestos Detected</b>
<b>B00A - R0026 - Resources Store (9.55 m2)</b>						
Wall Linings Internal	Flat AC Sheeting					
	8173/B00A/R0026/Wall Linings Internal/S2					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles					
	8173/B00A/R0050/Floor Coverings Res/Textile/S14					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Adhesive					
	8173/B00A/R0050/Floor Coverings Res/Textile/S15					<b>No Asbestos Detected</b>
<b>B00A - R0027 - Staff Study (35.48 m2)</b>						
No Asbestos						
<b>B00A - R0028 - Administration - Clerical (12.21 m2)</b>						
No Asbestos						
<b>B00A - R0029 - Resources Store (5.22 m2)</b>						
No Asbestos						
<b>B00A - R0030 - Staff Study (19.07 m2)</b>						
No Asbestos						
<b>B00A - R0031 - Cleaning Store - Distributed (0.93 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8173/B00A/R0050/Floor Coverings Res/Textile/S14					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Adhesive					
	8173/B00A/R0050/Floor Coverings Res/Textile/S15					<b>No Asbestos Detected</b>
<b>B00A - R0032 - Movement (1.08 m2)</b>						
No Asbestos						
<b>B00A - R0033 - Movement (1.07 m2)</b>						
No Asbestos						
<b>B00A - R0034 - Resources Store (9.07 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8173/B00A/R0025/Floor Coverings Res/Textile/S16					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Adhesive					
	8173/B00A/R0025/Floor Coverings Res/Textile/S17					<b>No Asbestos Detected</b>
<b>B00A - R0036 - Movement (1.08 m2)</b>						
No Asbestos						
<b>B00A - R0037 - Movement (1.07 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00A - R0038 - Cleaning Store - Distributed (0.44 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	8173/B00A/R0050/Floor Coverings Res/Textile/S14					No Asbestos Detected

Floor Coverings Res/Textile	Adhesive					
	8173/B00A/R0050/Floor Coverings Res/Textile/S15					No Asbestos Detected

**B00A - R0039 - Movement (42.77 m2)**

No Asbestos

**B00A - R0040 - Cleaning Supplies Store (6.79 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00A/R0040/Ceiling Structures/Linings/S18					Chrysotile (white asbestos) , Amosite (brown asbestos)

**B00A - R0041 - Deputy Principal Office (22.91 m2)**

No Asbestos

**B00A - R0042 - Movement (16.16 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	8173/B00A/R0050/Floor Coverings Res/Textile/S1					No Asbestos Detected

**B00A - R0043 - Movement (2 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00A/R0040/Ceiling Structures/Linings/S18					Chrysotile (white asbestos) , Amosite (brown asbestos)

**B00A - R0044 - External Movement (2.02 m2)**

No Asbestos

**B00A - R0045 - Clinic - Girls (9.59 m2)**

No Asbestos

**B00A - R0046 - Clinic - Boys (9.62 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	8173/B00A/R0050/Floor Coverings Res/Textile/S14					No Asbestos Detected

Floor Coverings Res/Textile	Adhesive					
	8173/B00A/R0050/Floor Coverings Res/Textile/S15					No Asbestos Detected

**B00A - R0047 - Movement (22.86 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	8173/B00A/R0050/Floor Coverings Res/Textile/S14					No Asbestos Detected

Floor Coverings Res/Textile	Adhesive					
	8173/B00A/R0050/Floor Coverings Res/Textile/S15					No Asbestos Detected

**B00A - R0048 - Movement (13.17 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	8173/B00A/R0050/Floor Coverings Res/Textile/S1					No Asbestos Detected

**B00A - R0049 - Stairs (7.69 m2)**

No Asbestos

**B00A - R0050 - Movement (114.74 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	8173/B00A/R0050/Floor Coverings Res/Textile/S14					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Adhesive					
	8173/B00A/R0050/Floor Coverings Res/Textile/S15					<b>No Asbestos Detected</b>
<b>B00A - R0051 - Administration - Clerical (26.72 m2)</b>						
No Asbestos						
<b>B00A - R0052 - Deputy Principal Office (16.15 m2)</b>						
No Asbestos						
<b>B00A - R0053 - Entry (8.69 m2)</b>						
No Asbestos						
<b>B00A - R0054 - External Movement (12.61 m2)</b>						
No Asbestos						
<b>B00A - R0056 - Toilets-Disabled (5.67 m2)</b>						
No Asbestos						
<b>B00A - R0057 - External Movement (72.94 m2)</b>						
No Asbestos						
<b>B00A - R1001 - Staff Study (20.59 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00A/R1001/Floor Coverings Res/Textile/S20					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00A/R0040/Ceiling Structures/Linings/S18					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Floor Coverings Res/Textile	Adhesive					
	8173/B00A/R1001/Floor Coverings Res/Textile/S21					<b>No Asbestos Detected</b>
<b>B00A - R1002 - Resources Store (4.65 m2)</b>						
No Asbestos						
<b>B00A - R1003 - Movement (2.75 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00A/R1021/Floor Coverings Res/Textile/S5					<b>Chrysotile (white asbestos)</b>
<b>B00A - R1004 - Staff Study (21.3 m2)</b>						
No Asbestos						
<b>B00A - R1005 - Commonroom (70.64 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00A/R1001/Floor Coverings Res/Textile/S20					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					
	8173/B00A/R1001/Floor Coverings Res/Textile/S21					<b>No Asbestos Detected</b>
<b>B00A - R1006 - General Storeroom (9 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00A/R1001/Floor Coverings Res/Textile/S20					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					
	8173/B00A/R1001/Floor Coverings Res/Textile/S21					<b>No Asbestos Detected</b>
<b>B00A - R1007 - Music Store (8.2 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00A/R1021/Floor Coverings Res/Textile/S5					<b>Chrysotile (white asbestos)</b>
<b>B00A - R1008 - Music Learning Space (51.47 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8173/B00A/R1001/Floor Coverings Res/Textile/S20	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 8173/B00A/R1001/Floor Coverings Res/Textile/S21					<b>No Asbestos Detected</b>
<b>B00A - R1009 - General Learning Space (55.19 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8173/B00A/R1001/Floor Coverings Res/Textile/S20	56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 8173/B00A/R1001/Floor Coverings Res/Textile/S21					<b>No Asbestos Detected</b>
<b>B00A - R1010 - General Learning Space (55.87 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8173/B00A/R1001/Floor Coverings Res/Textile/S20	56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 8173/B00A/R1001/Floor Coverings Res/Textile/S21					<b>No Asbestos Detected</b>
<b>B00A - R1011 - General Learning Space (55.95 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8173/B00A/R1001/Floor Coverings Res/Textile/S20	56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 8173/B00A/R1001/Floor Coverings Res/Textile/S21					<b>No Asbestos Detected</b>
<b>B00A - R1012 - Computer Learning Space (55.2 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8173/B00A/R1001/Floor Coverings Res/Textile/S20	55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 8173/B00A/R1001/Floor Coverings Res/Textile/S21					<b>No Asbestos Detected</b>
<b>B00A - R1013 - Computer Learning Space (55.8 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8173/B00A/R1001/Floor Coverings Res/Textile/S20	56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 8173/B00A/R1001/Floor Coverings Res/Textile/S21					<b>No Asbestos Detected</b>
<b>B00A - R1014 - Preparation (27.37 m2)</b>						
Electrical Mounting Board	Resinous Board	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Assumed Asbestos - Electrical Hazard</b>
<b>B00A - R1015 - Laboratory L.S. (89.02 m2)</b>						
No Asbestos						
<b>B00A - R1016 - Resources Store (20.21 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 8173/B00A/R1001/Floor Coverings Res/Textile/S20	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 8173/B00A/R1001/Floor Coverings Res/Textile/S21					<b>No Asbestos Detected</b>
<b>B00A - R1017 - Cleaning Store - Distributed (2.53 m2)</b>						
No Asbestos						
<b>B00A - R1018 - Movement (3.58 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00A - R1020 - Resources Store (9.01 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8173/B00A/R1001/Floor Coverings Res/Textile/S20					<b>Chrysotile (white asbestos)</b>	

Floor Coverings Res/Textile	Adhesive					
8173/B00A/R1001/Floor Coverings Res/Textile/S21					<b>No Asbestos Detected</b>	

**B00A - R1022 - Movement (170.95 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Pupil Facilities - 1954 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	60m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00C/Eaves Linings/S22					<b>Chrysotile (white asbestos)</b>

**Interior**

**B00C - R0001 - Movement (55.15 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00C/R0009/Ceiling Structures/Linings/S23					<b>Chrysotile (white asbestos)</b>

**B00C - R0002 - General Storeroom (5.62 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00C/R0009/Ceiling Structures/Linings/S23					<b>Chrysotile (white asbestos)</b>

**B00C - R0003 - General Storeroom (2.51 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00C/R0009/Ceiling Structures/Linings/S23					<b>Chrysotile (white asbestos)</b>

**B00C - R0004 - General Storeroom (3.67 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00C/R0009/Ceiling Structures/Linings/S23					<b>Chrysotile (white asbestos)</b>

**B00C - R0005 - Staff - Toilet (5.06 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00C/R0009/Ceiling Structures/Linings/S23					<b>Chrysotile (white asbestos)</b>

**B00C - R0006 - Student Canteen (52.08 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00C/R0009/Ceiling Structures/Linings/S23					<b>Chrysotile (white asbestos)</b>

**B00C - R0007 - Toilets-Girls (58.71 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00C/R0009/Ceiling Structures/Linings/S23					<b>Chrysotile (white asbestos)</b>

Wall Linings Internal	Flat AC Sheeting	2m2	Above entry door	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00C/R0009/Ceiling Structures/Linings/S23					<b>Chrysotile (white asbestos)</b>

**B00C - R0008 - Student Drinking Facilities (32.76 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00C/R0009/Ceiling Structures/Linings/S23					<b>Chrysotile (white asbestos)</b>

**B00C - R0009 - Movement (110.28 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	111m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00C/R0009/Ceiling Structures/Linings/S23					<b>Chrysotile (white asbestos)</b>

**B00C - R0010 - Movement (40.36 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00C/R0009/Ceiling Structures/Linings/S23					<b>Chrysotile (white asbestos)</b>

**B00C - R0011 - Toilets-Boys (65.22 m2)**



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	66m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8173/B00C/R0009/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)	
<b>B00C - R0012 - Toilets-Boys (23.8 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8173/B00C/R0009/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	5m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8173/B00C/R0009/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)	
<b>B00C - R0013 - Cleaning Store - Distributed (1.57 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8173/B00C/R0009/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)	
<b>B00C - R0014 - Cleaning Store - Distributed (5.89 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8173/B00C/R0009/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	4m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8173/B00C/R0009/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)	
<b>B00C - R0016 - Covered Area (9.46 m2)</b>						
No Asbestos						
<b>B00C - R0017 - Covered Area (10.07 m2)</b>						
No Asbestos						
<b>B00C - R0018 - Toilets-Disabled (7.45 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8173/B00C/R0009/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)	
<b>B00C - R0019 - External Movement (3.34 m2)</b>						
No Asbestos						
<b>B00C - R0020 - Ramp (5.17 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Science/General Learning - 1954 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found
Subfloor void	No Asbestos Found

**Interior****B00E - R0001 - Staff Study (58.46 m2)**

Ceiling Structures/Linings	Vermiculite					
	8173/B00E/R0001/Ceiling Structures/Linings/S7					Limited Samples Taken
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00E/R0004/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)

**B00E - R0002 - Preparation (43.41 m2)**

Ceiling Structures/Linings	Vermiculite					
	8173/B00E/R0001/Ceiling Structures/Linings/S7					Limited Samples Taken
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					

**B00E - R0003 - Staff Study (7.32 m2)**

Ceiling Structures/Linings	Vermiculite					
	8173/B00E/R0001/Ceiling Structures/Linings/S7					Limited Samples Taken
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					

**B00E - R0004 - Movement (3.67 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00E/R0004/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)

**B00E - R0005 - Staff - Toilet (2.94 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00E/R0005/Partition Walls (Cubicles)/S24					Chrysotile (white asbestos)

**B00E - R0006 - Staff - Toilet (2.85 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00E/R0005/Partition Walls (Cubicles)/S24					Chrysotile (white asbestos)

**B00E - R0007 - Chemical Store (23.43 m2)**

No Asbestos

**B00E - R0008 - Laboratory L.S. (91.59 m2)**

Ceiling Structures/Linings	Vermiculite					
	8173/B00E/R0001/Ceiling Structures/Linings/S7					Limited Samples Taken
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Vinyl Tiles	92m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00E/R0004/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)

**B00E - R0009 - Laboratory L.S. (91.69 m2)**

No Asbestos

**B00E - R0010 - Distribution Board Cupboard (0.7 m2)**

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	<b>Assumed Asbestos - Electrical Hazard</b>					

**B00E - R0011 - Cleaning Store - Distributed (0.45 m2)**

No Asbestos

**B00E - R0012 - External Movement (56.92 m2)**

No Asbestos

**B00E - R0013 - External Movement (22.64 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00E - R0014 - Stairs (5.89 m2)</b>						
No Asbestos						
<b>B00E - R1015 - Stairs (5.89 m2)</b>						
No Asbestos						
<b>B00E - R1017 - External Movement (68.68 m2)</b>						
No Asbestos						
<b>B00E - R1018 - Interview/Office - Type 1 (12.74 m2)</b>						
No Asbestos						
<b>B00E - R1019 - Interview/Office - Type 1 (12.78 m2)</b>						
No Asbestos						
<b>B00E - R1020 - Shared Study Space (76.03 m2)</b>						
No Asbestos						
<b>B00E - R1021 - General Learning Space - Type 2 (63.73 m2)</b>						
No Asbestos						
<b>B00E - R1022 - Seminar (23.81 m2)</b>						
No Asbestos						
<b>B00E - R1023 - General Learning Space - Type 1 (58.78 m2)</b>						
No Asbestos						
<b>B00E - R1024 - General Storeroom (19.01 m2)</b>						
No Asbestos						
<b>B00E - R1025 - General Learning Space - Type 1 (56.64 m2)</b>						
No Asbestos						
<b>B00E - R1026 - Distribution Board Cupboard (0.78 m2)</b>					Note: No inspection of live electrical installation.	
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Art/General Learning - 1972 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Subfloor void	No Asbestos Found					

**Interior**

**B00F - R0001 - Art Learning Space (65.59 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8173/B00F/R1009/Floor Coverings Res/Textile/S9	66m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite 8173/B00F/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					

**B00F - R0002 - Laboratory L.S. (91.34 m2)**

Floor Coverings Res/Textile	Vinyl Tiles 8173/B00F/R1009/Floor Coverings Res/Textile/S9	92m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite 8173/B00F/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					

**B00F - R0003 - Resources Space (26.46 m2)**

Floor Coverings Res/Textile	Vinyl Tiles 8173/B00F/R1009/Floor Coverings Res/Textile/S9	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite 8173/B00F/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					

**B00F - R0004 - Apparatus Store (3.05 m2)**

Floor Coverings Res/Textile	Vinyl Tiles 8173/B00F/R1009/Floor Coverings Res/Textile/S9	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite 8173/B00F/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					

**B00F - R0005 - Staff Shower (4.78 m2)**

Floor Coverings Res/Textile	Vinyl Tiles 8173/B00F/R1009/Floor Coverings Res/Textile/S9	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
<b>B00F - R0006 - No Access (0.85 m2)</b>	Electrical Backing Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1) Low Priority (2-3)
						<b>Assumed Asbestos - Electrical Hazard</b>

**B00F - R0007 - Kiln Space (8.55 m2)**

No Asbestos						
-------------	--	--	--	--	--	--

**B00F - R0008 - Resources Store (12.03 m2)**

Floor Coverings Res/Textile	Vinyl Tiles 8173/B00F/R1009/Floor Coverings Res/Textile/S9	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
<b>B00F - R0009 - Art Learning Space (79.98 m2)</b>	Floor Coverings Res/Textile	Vinyl Tiles	80m2	Throughout	Good Condition (1)	Low (1) Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite 8173/B00F/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
<b>B00F - R0010 - Resources Store (7.5 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00F/R1009/Floor Coverings Res/Textile/S9					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8173/B00F/R0001/Ceiling Structures/Linings/S10					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00F - R0011 - Resources Store (4.54 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00F/R1009/Floor Coverings Res/Textile/S9					<b>Chrysotile (white asbestos)</b>
<b>B00F - R0012 - Resources Store (9.32 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00F/R1009/Floor Coverings Res/Textile/S9					<b>Chrysotile (white asbestos)</b>
<b>B00F - R0013 - Garden Store Room (9.34 m2)</b>						
No Asbestos						
<b>B00F - R0014 - External Movement (120.51 m2)</b>						
No Asbestos						
<b>B00F - R0015 - Stairs (7.03 m2)</b>						
No Asbestos						
<b>B00F - R0016 - External Movement (30 m2)</b>						
No Asbestos						
<b>B00F - R1001 - General Learning Space (66 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	66m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00F/R1009/Floor Coverings Res/Textile/S9					<b>Chrysotile (white asbestos)</b>
<b>B00F - R1002 - Resources Store (12.74 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00F/R1009/Floor Coverings Res/Textile/S9					<b>Chrysotile (white asbestos)</b>
<b>B00F - R1003 - Cleaning Store - Distributed (1.09 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00F/R1009/Floor Coverings Res/Textile/S9					<b>Chrysotile (white asbestos)</b>
<b>B00F - R1004 - Staff - Toilet (3.53 m2)</b>						
No Asbestos						
<b>B00F - R1005 - Staff - Toilet (3.53 m2)</b>						
No Asbestos						
<b>B00F - R1006 - Cleaning Store - Distributed (4.59 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00F/R1009/Floor Coverings Res/Textile/S9					<b>Chrysotile (white asbestos)</b>
<b>B00F - R1008 - Staff Study (25.4 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00F/R1009/Floor Coverings Res/Textile/S9					<b>Chrysotile (white asbestos)</b>
<b>B00F - R1010 - General Learning Space (53.06 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00F/R1009/Floor Coverings Res/Textile/S9					<b>Chrysotile (white asbestos)</b>
<b>B00F - R1011 - Resources Store (8.24 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00F/R1009/Floor Coverings Res/Textile/S9					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00F - R1012 - Distribution Board Cupboard (2.93 m2)</b>				Note: No inspection of live electrical installation.		
Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Electrical Hazard</b>						
<b>B00F - R1013 - Interview/Office - Type 1 (12.97 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8173/B00F/R1009/Floor Coverings Res/Textile/S9					<b>Chrysotile (white asbestos)</b>	
<b>B00F - R1014 - External Movement (29.19 m2)</b>						
No Asbestos						
<b>B00F - R1015 - Stairs (7.02 m2)</b>						
No Asbestos						
<b>B00F - R1016 - General Learning Space (54.16 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8173/B00F/R1009/Floor Coverings Res/Textile/S9					<b>Chrysotile (white asbestos)</b>	
<b>B00F - R1017 - General Learning Space (49.25 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8173/B00F/R1009/Floor Coverings Res/Textile/S9					<b>Chrysotile (white asbestos)</b>	
<b>B00F - R1018 - Movement (25.29 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8173/B00F/R1009/Floor Coverings Res/Textile/S9					<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Technological & Applied Studies - 1954 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	60m2	Surround	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00A/Eaves Linings/S19					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					

**Interior****B00G - R0024 - Performance Workshop (98.09 m2)**

No Asbestos

**B00G - R0025 - Performing Arts Store (20.09 m2)**

No Asbestos

**B00G - R0026 - Cleaning Store - Distributed (4.21 m2)**

No Asbestos

**B00G - R0027 - Distribution Board Cupboard (0.67 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00G - R0028 - Movement (8.46 m2)**

No Asbestos

**B00G - R0029 - Practice/Seminar (26.17 m2)**

No Asbestos

**B00G - R0030 - General Learning Space - Type 1 (56.65 m2)**

No Asbestos

**B00G - R0031 - Seminar - Type 1 (32.1 m2)**

No Asbestos

**B00G - R0032 - Practical Activities (5 m2)**

No Asbestos

**B00G - R0033 - General Learning Space - Type 10 (65.25 m2)**

No Asbestos

**B00G - R0034 - Distribution Board Cupboard (0.86 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00G - R0035 - General Storeroom (19.95 m2)**

No Asbestos

**B00G - R0036 - Access Student Shower/Toilet/Change (13.41 m2)**

No Asbestos

**B00G - R0037 - Access Staff Shower/Toilet (6.82 m2)**

No Asbestos

**B00G - R0038 - Access Staff Shower/Toilet (6.81 m2)**

No Asbestos

**B00G - R0039 - Laundry (5.51 m2)**

No Asbestos

**B00G - R0040 - Practical Activities (7.52 m2)**

No Asbestos

**B00G - R0041 - General Learning Space - S/P (63.43 m2)**

No Asbestos

**B00G - R0042 - External Movement (116.63 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>				<b>Test Result</b>	
Ceiling Structures/Linings	Flat AC Sheeting	30m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)

8173/B00C/Eaves Linings/S22

**Chrysotile (white asbestos)**

**B00G - R0043 - External Movement (18.58 m2)**

No Asbestos

**B00G - R0044 - Covered Outdoor Space (91.21 m2)**

No Asbestos

**B00G - R0045 - Covered Outdoor Space (36.92 m2)**

No Asbestos

**B00G - R0046 - External Movement (4.47 m2)**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Multi Purpose Facilities/Pupil Facilities - 1954 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 8173/B00A/Eaves Linings/S19	30m2	North facing, South facing	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
In-fill-panel	Flat AC Sheeting 8173/B00H/Infill panels/S13 <b>No Asbestos Detected</b>					
Subfloor void	No Asbestos Found					

**Interior**

**B00H - M0001 - Performing Arts Store (12.59 m2)**

No Asbestos

**B00H - R0006 - Movement (0.91 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 8173/B00A/R0040/Ceiling Structures/Linings/S18	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
----------------------------	--	-----	------------	--------------------	---------	---

**B00H - R0007 - General Assistants (6.77 m2)**

No Asbestos

**B00H - R0008 - Stage (80.39 m2)**

No Asbestos

**B00H - R0009 - Multi-Purpose Space (278.04 m2)**

No Asbestos

**B00H - R0010 - Staff Shower (2.19 m2)**

No Asbestos

**B00H - R0011 - Sport Equipment Store (16.18 m2)**

No Asbestos

**B00H - R0012 - Movement (10.81 m2)**

No Asbestos

**B00H - R0013 - Interview/Office - Type 1 (13.99 m2)**

No Asbestos

**B00H - R0014 - Music Store (4.13 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 8173/B00A/R0040/Ceiling Structures/Linings/S18	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
----------------------------	--	-----	------------	--------------------	---------	---

**B00H - R0015 - Movement (1.69 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 8173/B00A/R0040/Ceiling Structures/Linings/S18	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
----------------------------	--	-----	------------	--------------------	---------	---

**B00H - R0016 - Music Learning Space (74.25 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 8173/B00A/R0040/Ceiling Structures/Linings/S18	75m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
----------------------------	--	------	------------	--------------------	---------	---

**B00H - R0017 - Toilets-Unisex (2.51 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 8173/B00A/R0040/Ceiling Structures/Linings/S18	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
----------------------------	--	-----	------------	--------------------	---------	---

**B00H - R0018 - Music Store (11.81 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8173/B00A/R0040/Ceiling Structures/Linings/S18				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00H - R0019 - Music Store (15.5 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8173/B00A/R0040/Ceiling Structures/Linings/S18				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00H - R0020 - Toilets-Unisex (2.46 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8173/B00A/R0040/Ceiling Structures/Linings/S18				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00H - R0021 - Practice/Seminar (8.64 m2)</b>						
No Asbestos						
<b>B00H - R0022 - Movement (19.38 m2)</b>						
No Asbestos						
<b>B00H - R0023 - External Movement (4.21 m2)</b>						
No Asbestos						
<b>B00H - R0024 - External Movement (2.22 m2)</b>						
No Asbestos						
<b>B00H - R1001 - Movement (0.6 m2)</b>						
No Asbestos						
<b>B00H - R1002 - Plant Space (24.81 m2)</b>						
Electrical Backing Board	Resinous Board	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Electrical Hazard</b>						
<b>B00H - R1003 - Plant Space (13.32 m2)</b>						
No Asbestos						
<b>B00H - R9003 - Movement (3.4 m2)</b>						
No Asbestos						
<b>B00H - R9004 - Garden Store (68.04 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00K - Multi Purpose Facilities - 1997 - Brick/Veneer (Brick/Veneer)****Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

**Interior****B00K - R0001 - Gymnasium (478.33 m2)**

No Asbestos

**B00K - R0002 - External Movement (8.55 m2)**

No Asbestos

**B00K - R0004 - Movement (5.09 m2)**

No Asbestos

**B00K - R0005 - Shower/Change (31.78 m2)**

No Asbestos

**B00K - R0006 - Movement (3.44 m2)**

No Asbestos

**B00K - R0007 - Cleaning Store - Distributed (0.62 m2)**

No Asbestos

**B00K - R0008 - Shower/Change (31.11 m2)**

No Asbestos

**B00K - R0009 - Sport Equipment Store (28.68 m2)**

No Asbestos

**B00K - R0010 - Sport Equipment Store (50.02 m2)**

No Asbestos

**B00K - R0011 - Self Help Toilet (6.39 m2)**

No Asbestos

**B00K - R0012 - Staff Shower (1.65 m2)**

No Asbestos

**B00K - R0015 - External Movement (9.14 m2)**

No Asbestos

**B00K - R0016 - External Movement (9.13 m2)**

No Asbestos

**B00K - R0017 - External Movement (41.49 m2)**

No Asbestos

**B00K - R0018 - Staff Study (24.16 m2)**

No Asbestos

**B00K - R0019 - Staff Kitchen (1.58 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - Library - 1954 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Raked Ceiling No Asbestos Found

**Interior**

**B00L - R0001 - Movement (2.65 m2)**

No Asbestos

**B00L - R0002 - Entry (9.97 m2)**

No Asbestos

**B00L - R0003 - Main Area (431.56 m2)**

No Asbestos

**B00L - R0004 - Staff - Toilet (3.96 m2)**

No Asbestos

**B00L - R0005 - Seminar (11.32 m2)**

No Asbestos

**B00L - R0006 - Seminar (12.82 m2)**

No Asbestos

**B00L - R0007 - Seminar (14.32 m2)**

No Asbestos

**B00L - R0008 - Audio Visual Workroom (27.15 m2)**

No Asbestos

**B00L - R0009 - Workroom (36.68 m2)**

No Asbestos

**B00L - R0010 - Librarian (10.73 m2)**

No Asbestos

**B00L - R0011 - Cleaning Store - Distributed (3.42 m2)**

No Asbestos

**B00L - R0012 - Distribution Board Cupboard (0.88 m2)**

Note: No inspection of live electrical installation.

Electrical Backing Board Resinous Board 1Unit South Good Condition (1) Low (1) Low Priority (2-3)

**Assumed Asbestos - Electrical Hazard**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - Technological & Applied Studies - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

**Interior**

**B00M - R0001 - L.P.G. Store (2.62 m2)**

No Asbestos

**B00M - R0002 - Pottery Store (10.42 m2)**

No Asbestos

**B00M - R0003 - Kiln Space (9.16 m2)**

No Asbestos

**B00M - R0004 - Project Store - Type 1 (13.5 m2)**

No Asbestos

**B00M - R0005 - Wood Technology Bay (58.92 m2)**

No Asbestos

**B00M - R0006 - Outdoor Workshop (82.47 m2)**

No Asbestos

**B00M - R0007 - Welding Area (12.09 m2)**

No Asbestos

**B00M - R0008 - Materials Workshop - Type 2 (119.81 m2)**

No Asbestos

**B00M - R0009 - Materials Store - Type 2 (35.06 m2)**

No Asbestos

**B00M - R0010 - Materials Workshop - Type 2 (119.15 m2)**

No Asbestos

**B00M - R0011 - Dust Extraction Space (8.35 m2)**

No Asbestos

**B00M - R0012 - Project Store - Type 1 (48.34 m2)**

No Asbestos

**B00M - R0013 - Distribution Board Cupboard (0.92 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00M - R0014 - General Learning Space - Type 8 (59.85 m2)**

No Asbestos

**B00M - R0015 - General Learning Space - Type 9 (59.73 m2)**

No Asbestos

**B00M - R0016 - General Learning Space - Type 9 (60.04 m2)**

No Asbestos

**B00M - R0017 - General Learning Space - Type 8 (59.99 m2)**

No Asbestos

**B00M - R0018 - Cleaning Store - Distributed (3.48 m2)**

No Asbestos

**B00M - R0019 - Distribution Board Cupboard (0.74 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00M - R0020 - Movement (6.5 m2)**

No Asbestos

**B00M - R0021 - Lift (2.23 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00M - R0022 - External Movement (156.17 m2)</b>						
No Asbestos						
<b>B00M - R0023 - Store (28.27 m2)</b>						
No Asbestos						
<b>B00M - R0024 - External Stairs (18.81 m2)</b>						
No Asbestos						
<b>B00M - R0025 - External Stairs (25.68 m2)</b>						
No Asbestos						
<b>B00M - R1001 - Materials Store - Type 1 (20.78 m2)</b>						
No Asbestos						
<b>B00M - R1002 - Access Staff Shower/Toilet (5.06 m2)</b>						
No Asbestos						
<b>B00M - R1003 - Staff Study (53.79 m2)</b>						
No Asbestos						
<b>B00M - R1004 - General Learning Space - Type 6 (59.64 m2)</b>						
No Asbestos						
<b>B00M - R1005 - Seminar - Type 2 (21.74 m2)</b>						
No Asbestos						
<b>B00M - R1006 - Distribution Board Cupboard (3 m2)</b>						
No Asbestos					Note: No inspection of live electrical installation.	
<b>B00M - R1007 - Laundry (9.02 m2)</b>						
No Asbestos						
<b>B00M - R1008 - Kitchen - Type 2 (106.52 m2)</b>						
No Asbestos						
<b>B00M - R1009 - Movement (18.43 m2)</b>						
No Asbestos						
<b>B00M - R1010 - Pantry (8.3 m2)</b>						
No Asbestos						
<b>B00M - R1011 - Pantry (19.89 m2)</b>						
No Asbestos						
<b>B00M - R1012 - Kitchen - Type 1 (106.37 m2)</b>						
No Asbestos						
<b>B00M - R1013 - Materials Store - Type 1 (24.83 m2)</b>						
No Asbestos						
<b>B00M - R1014 - Materials Store - Type 1 (21.93 m2)</b>						
No Asbestos						
<b>B00M - R1015 - Distribution Board Cupboard (0.8 m2)</b>						
No Asbestos					Note: No inspection of live electrical installation.	
<b>B00M - R1016 - External Stairs (25.75 m2)</b>						
No Asbestos						
<b>B00M - R1017 - General Learning Space - Type 7 (60.21 m2)</b>						
No Asbestos						
<b>B00M - R1018 - General Learning Space - Type 6 (59.77 m2)</b>						
No Asbestos						
<b>B00M - R1019 - External Movement (145.77 m2)</b>						
No Asbestos						
<b>B00M - R1020 - Distribution Board Cupboard (0.54 m2)</b>						
No Asbestos					Note: No inspection of live electrical installation.	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - R1021 - Movement (6.5 m2)**

No Asbestos

**B00M - R1022 - External Stairs (18.86 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00N - Agricultural Science - 2012 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00N - R0001 - General Learning Space (65.16 m2)**

No Asbestos

**B00N - R0002 - Main Switchroom (8.07 m2)**

No Asbestos

**B00N - R0003 - Agriculture Covered Area (75.34 m2)**

No Asbestos

**B00N - R0004 - External Movement (38.62 m2)**

No Asbestos

**B00N - R0005 - Shower (4.31 m2)**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0AS - Agricultural Science - 1954 - Timber (Timber)****Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	25m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00A/Eaves Linings/S19			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Wall Cladding	Flat AC Sheeting	30m2	Variable positions	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8173/B0AS/R0001/Wall Linings Internal/S11			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**Interior****B0AS - R0001 - General Storeroom (12.51 m2)**

Wall Linings Internal	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B0AS/R0001/Wall Linings Internal/S11			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B0AS/R0001/Ceiling Structures/Linings/S12			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B0AS - R0002 - Machine Storage (63.21 m2)**

Wall Linings Internal	Flat AC Sheeting	12m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B0AS/R0001/Wall Linings Internal/S11			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B0AS - R0003 - Class Tools Storage (19.88 m2)**

No Asbestos

**B0AS - R0004 - Animal Space (21.38 m2)**

No Asbestos

**B0AS - R0005 - Animal Space (22.91 m2)**

Wall Linings Internal	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B0AS/R0001/Wall Linings Internal/S11			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**BD10 - Pupil Facilities/Physical Education - 1954 - Timber (Timber)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	10m2	East and West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00A/Eaves Linings/S19			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**Interior**

**BD10 - R0001 - General Storeroom (42.83 m2)**

No Asbestos

**BD10 - R0002 - Sport Equipment Store (40.59 m2)**

No Asbestos

**BD10 - R0003 - General Storeroom (4.32 m2)**

No Asbestos

**BD10 - R1001 - Movement (17.54 m2)**

No Asbestos

**BD10 - R1002 - Interview/Office - Type 1 (52.27 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/BD13/R0001/Ceiling Structures/Linings/S25			<b>Chrysotile (white asbestos)</b>		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**BD11 - General Learning - 1954 - Timber (Timber)**

**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found
Subfloor void	No Asbestos Found

**Interior**

**BD11 - R0001 - General Learning Space (39.37 m2)**

No Asbestos

**BD11 - R0002 - Movement (10.85 m2)**

No Asbestos

**BD11 - R0003 - Movement (19.02 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

8173/BD13/R0002/Ceiling Structures/Linings/S27

**Chrysotile (white asbestos)**

**BD11 - R0004 - External Movement (29.3 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**BD13 - Staff Facilities - 1954 - Timber (Timber)**

**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found
Under floor void	No Asbestos Found

**Interior**

**BD13 - R0001 - Staff Study (28.07 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	29m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8173/BD13/R0001/Ceiling Structures/Linings/S25					<b>Chrysotile (white asbestos)</b>	
Wall Linings Internal	Flat AC Sheeting	5m2	West	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8173/BD13/R0001/Wall Linings Internal/S26					<b>Chrysotile (white asbestos)</b>	

**BD13 - R0002 - Movement (12.66 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8173/BD13/R0002/Ceiling Structures/Linings/S27					<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**BD14 - Support Unit - 1954 - Timber (Timber)**

**Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found
Subfloor void	No Asbestos Found

**Interior**

**BD14 - R0004 - General Learning Space - S/P (70.63 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

8173/BD13/R0001/Ceiling Structures/Linings/S25

**Chrysotile (white asbestos)**

**BD14 - R0005 - Movement (4.92 m2)**

No Asbestos

**BD14 - R0006 - Student Laundry - Type 3 (5.88 m2)**

No Asbestos

**BD14 - R0007 - Toilets-Disabled (15.94 m2)**

No Asbestos

**BD14 - R0008 - External Movement (4.13 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**BDT5 - Technological & Applied Studies - 1954 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	18m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8173/B00A/Eaves Linings/S19			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
subfloor void	Non Accessible Area - Area inaccessible area too low to access					

**Interior**

**BDT5 - R0003 - General Learning Space - S/P (61.29 m2)**

No Asbestos

**BDT5 - R0004 - General Storeroom (32.63 m2)**

No Asbestos

**BDT5 - R0005 - Movement (6.27 m2)**

No Asbestos

**BDT5 - R0006 - Cleaning Store - Distributed (2.62 m2)**

No Asbestos

**BDT5 - R0007 - Distribution Board Cupboard (0.63 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**BDT5 - R0008 - Practical Activities (5 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 700 - D10591 - Art Learning Space/Workshop/Store : Placement Date - 30/06/1995

#### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		17.28 m2

#### Interior

##### R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		8 m2

##### R2 - Art Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		91 m2

##### R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos		10 m2
---------	---------------	------------------	--	-------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017