


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wellington High School (8197)
Region : Western NSW
State Electorate : Dubbo
Local Government Area : Wellington

Initial Survey : Noel Arnold & Associates : 19 - Mar - 2008
Reviewed By : : 25 - Mar - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Various - 1951 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	100m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00A/Eaves Linings/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)
Gable Verge Lining	Non Accessible Area - Height Restriction					
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	No Asbestos Found					

Interior

B00A - R0001 - Computer Learning Space (64.72 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8197/B00A/R0044/Floor Coverings Res/Textile/S14					No Asbestos Detected

B00A - R0002 - General Learning Space (49.6 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8197/B00A/R0044/Floor Coverings Res/Textile/S14					No Asbestos Detected

B00A - R0003 - Movement (57.5 m2)

No Asbestos

B00A - R0004 - Cleaning Store - Distributed (4.03 m2)

No Asbestos

B00A - R0005 - External Movement (0.68 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8197/B00A/R0044/Floor Coverings Res/Textile/S14					No Asbestos Detected

B00A - R0007 - General Storeroom (10.02 m2)

No Asbestos

B00A - R0009 - Commonroom (49.6 m2)

No Asbestos

B00A - R0010 - General Learning Space (49.6 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8197/B00A/R0044/Floor Coverings Res/Textile/S14					No Asbestos Detected

B00A - R0011 - General Learning Space (49.6 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8197/B00A/R0044/Floor Coverings Res/Textile/S14					No Asbestos Detected

B00A - R0012 - General Learning Space (49.61 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8197/B00A/R0044/Floor Coverings Res/Textile/S14					No Asbestos Detected

B00A - R0013 - General Learning Space (49.45 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8197/B00A/R0044/Floor Coverings Res/Textile/S14					No Asbestos Detected

B00A - R0015 - Staff Study (23.81 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8197/B00A/R0044/Floor Coverings Res/Textile/S14					No Asbestos Detected

B00A - R0016 - Clinic - Girls (11.78 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0017 - Clinic-Toilets (2.72 m2)						
No Asbestos						
B00A - R0018 - Clinic - Boys (11.79 m2)						
No Asbestos						
B00A - R0019 - Clinic-Toilets (3.06 m2)						
No Asbestos						
B00A - R0020 - Deputy Principal Office (13.8 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
8197/B00A/R0044/Floor Coverings Res/Textile/S14					No Asbestos Detected	
B00A - R0021 - Interview/Office - Type 1 (13.47 m2)						
No Asbestos						
B00A - R0022 - Principal Office (18.04 m2)						
No Asbestos						
B00A - R0023 - Staff - Toilet (5.17 m2)						
No Asbestos						
B00A - R0024 - Interview/Office - Type 1 (14.88 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
8197/B00A/R0044/Floor Coverings Res/Textile/S14					No Asbestos Detected	
B00A - R0025 - Duplicating Workroom (18.74 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
8197/B00A/R0044/Floor Coverings Res/Textile/S14					No Asbestos Detected	
B00A - R0026 - Security Store (8.45 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
8197/B00A/R0044/Floor Coverings Res/Textile/S14					No Asbestos Detected	
B00A - R0027 - Administration - Clerical (24.01 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
8197/B00A/R0044/Floor Coverings Res/Textile/S14					No Asbestos Detected	
B00A - R0028 - External Movement (3.72 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	3.52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00A/Eaves Linings/S15				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R0030 - Distribution Board Cupboard (0.46 m2)						
					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R0031 - Movement (12.74 m2)						
No Asbestos						
B00A - R0032 - External Movement (3.29 m2)						
No Asbestos						
B00A - R0034 - Movement (4.4 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00A/Eaves Linings/S15				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R0035 - Covered Area (7.12 m2)						
No Asbestos						
B00A - R0036 - Stairs (7.2 m2)						
No Asbestos						
B00A - R0037 - Stairs (0.48 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
No Asbestos						
B00A - R0038 - External Movement (125.83 m2)						
No Asbestos						
B00A - R0039 - Staff Kitchen (6.13 m2)						
No Asbestos						
B00A - R0040 - Commonroom (43.25 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
8197/B00A/R0044/Floor Coverings Res/Textile/S14						No Asbestos Detected
B00A - R0041 - Movement (126.98 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
8197/B00A/R0044/Floor Coverings Res/Textile/S14						No Asbestos Detected
B00A - R0042 - Movement (20.49 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
8197/B00A/R0044/Floor Coverings Res/Textile/S14						No Asbestos Detected
B00A - R0043 - Public Reception (18.42 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
8197/B00A/R0044/Floor Coverings Res/Textile/S14						No Asbestos Detected
B00A - R0044 - Movement (14.47 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
8197/B00A/R0044/Floor Coverings Res/Textile/S14						No Asbestos Detected
B00A - R0045 - Toilet - Lobby (2.3 m2)						
No Asbestos						
B00A - R0046 - Staff - Toilet (1.99 m2)						
No Asbestos						
B00A - R0048 - Toilets-Disabled (11.85 m2)						
No Asbestos						
B00A - R0049 - Plant (0.66 m2)						
No Asbestos						
B00A - R1001 - Computer Learning Space (65.03 m2)						
No Asbestos						
B00A - R1002 - General Learning Space (49.6 m2)						
No Asbestos						
B00A - R1003 - General Storeroom (11.51 m2)						
No Asbestos						
B00A - R1004 - Cleaning Store - Distributed (4.47 m2)						
No Asbestos						
B00A - R1005 - General Storeroom (7.52 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	7.51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00A/R1005/Floor Coverings Res/Textile/S16						Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00A - R1006 - General Storeroom (1.83 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	1.83m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00A/R1005/Floor Coverings Res/Textile/S16						Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00A - R1007 - Staff Study (24.85 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8197/B00A/R1005/Floor Coverings Res/Textile/S16	24.82m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R1008 - General Learning Space (49.91 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8197/B00A/R1005/Floor Coverings Res/Textile/S16	49.87m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R1009 - General Learning Space (49.98 m2)						
Fume Cupboard	Fibre Cement Pipe	1Unit	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
				Assumed Asbestos - Area inaccessible		
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8197/B00A/R1011/Floor Coverings Res/Textile/S17					No Asbestos Detected
B00A - R1010 - Preparation (24.47 m2)						
Fume Cupboard	Fibre Cement Pipe	1Unit	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
				Assumed Asbestos - Area inaccessible		
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8197/B00A/R1005/Floor Coverings Res/Textile/S16	24.44m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R1011 - General Learning Space (76.29 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8197/B00A/R1011/Floor Coverings Res/Textile/S17					No Asbestos Detected
Fume Cupboard	Fibre Cement Pipe	1Unit	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
				Assumed Asbestos - Area inaccessible		
B00A - R1012 - General Learning Space (50.31 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8197/B00A/R1005/Floor Coverings Res/Textile/S16	50.25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R1013 - General Learning Space (49.99 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8197/B00A/R1005/Floor Coverings Res/Textile/S16	49.93m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R1014 - General Storeroom (24.01 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8197/B00A/R1005/Floor Coverings Res/Textile/S16	23.97m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R1015 - Staff Study (40.28 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8197/B00A/R1005/Floor Coverings Res/Textile/S16	40.25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00A - R1016 - General Storeroom (12.04 m2)						
No Asbestos						
B00A - R1017 - Staff - Toilet (4.13 m2)						
No Asbestos						
B00A - R1018 - Staff - Toilet (6.45 m2)						
No Asbestos						
B00A - R1019 - Movement (151.71 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00A - R1020 - Stairs (11.35 m2)

No Asbestos

B00A - R1021 - Stairs (11.9 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Multi Purpose Facilities - 1982 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Extreme Access Issue - No Access Point into ceiling void identified - Raked Ceilings
Underfloor Voids - Slab on Ground	
Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction - Extreme Access Issue - No Access Point into ceiling void identified - Raked Ceilings

Interior

B00B - R0001 - Sport Equipment Store (12.61 m2)

No Asbestos

B00B - R0002 - Multi-Purpose Space (458.13 m2)

No Asbestos

B00B - R0003 - Chair Store (45.71 m2)

No Asbestos

B00B - R0004 - Main Switchroom (3.15 m2)

Wall Linings Internal	Flat AC Sheeting	6m2	North facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00B/R0005/Wall Linings Internal/S3					Chrysotile (white asbestos)	

B00B - R0005 - Toilets-Boys (19.11 m2)

Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00B/R0005/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00B/R0005/Partition Walls (Cubicles)/S2					Chrysotile (white asbestos)	

Wall Linings Internal	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00B/R0005/Wall Linings Internal/S3					Chrysotile (white asbestos)	

B00B - R0006 - Shower/Change (32.41 m2)

Ceiling Structures/Linings	Flat AC Sheeting	33m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00B/R0005/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00B/R0005/Partition Walls (Cubicles)/S2					Chrysotile (white asbestos)	

Wall Linings Internal	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00B/R0005/Wall Linings Internal/S3					Chrysotile (white asbestos)	

B00B - R0007 - Movement (63.7 m2)

No Asbestos

B00B - R0008 - Stage (63.28 m2)

No Asbestos

B00B - R0009 - Shower/Change (32.57 m2)

Ceiling Structures/Linings	Flat AC Sheeting	33m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00B/R0005/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00B/R0005/Partition Walls (Cubicles)/S2					Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting	33m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00B/R0005/Wall Linings Internal/S3					Chrysotile (white asbestos)	
B00B - R0010 - Toilets-Girls (17.62 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00B/R0005/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00B/R0005/Partition Walls (Cubicles)/S2					Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00B/R0005/Wall Linings Internal/S3					Chrysotile (white asbestos)	
B00B - R0011 - Cleaning Store - Distributed (3.21 m2)						
Wall Linings Internal	Flat AC Sheeting	6m2	South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00B/R0005/Wall Linings Internal/S3					Chrysotile (white asbestos)	
B00B - R0012 - Staff Kitchen (14.15 m2)						
No Asbestos						
B00B - R0013 - General Storeroom (8.66 m2)						
No Asbestos						
B00B - R0014 - Staff Study (8.66 m2)						
No Asbestos						
B00B - R0015 - External Movement (206.41 m2)						
No Asbestos						
B00B - R0016 - Plant (7.88 m2)						
No Asbestos						
B00B - R0017 - Plant (8.31 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00C - Various - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00C/R1014/Ceiling Structures/Linings/S19			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Underfloor Voids	No Asbestos Found					
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					

Interior

B00C - R0001 - Staff - Toilet (5.44 m2)

No Asbestos

B00C - R0002 - Cleaning Store - Distributed (2.07 m2)

No Asbestos

B00C - R0003 - Sport Equipment Store (8.66 m2)

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	8197/B00C/R0004/Floor Coverings Res/Textile/S4					
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8197/B00C/R0004/Ceiling Structures/Linings/S5			Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00C - R0004 - Sport Equipment Store (3.47 m2)

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	8197/B00C/R0004/Floor Coverings Res/Textile/S4					
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8197/B00C/R0004/Ceiling Structures/Linings/S5			Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00C - R0005 - Staff Study (39.25 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8197/B00C/R0004/Ceiling Structures/Linings/S5			Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00C - R0006 - Laboratory L.S. (93.01 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8197/B00C/R0004/Ceiling Structures/Linings/S5			Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00C - R0007 - Preparation (28.75 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8197/B00C/R0004/Ceiling Structures/Linings/S5			Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00C - R0008 - Preparation (9.8 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8197/B00C/R0004/Ceiling Structures/Linings/S5			Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00C - R0009 - Cleaning Store - Distributed (6.3 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8197/B00C/R0004/Ceiling Structures/Linings/S5			Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00C - R0010 - Materials Store (6.04 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8197/B00C/R0004/Ceiling Structures/Linings/S5			Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

B00C - R0011 - Distribution Board Cupboard (0.46 m2)

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Electrical Backing Board	Non Accessible Area - Electrical Hazard					
B00C - R0012 - Materials Technology L.S. (101.98 m2)						
Ceiling Structures/Linings	Vermiculite 8197/B00C/R0004/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00C - R0013 - Materials Store (15.95 m2)						
Ceiling Structures/Linings	Vermiculite 8197/B00C/R0004/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00C - R0014 - Staff - Toilet (5.59 m2)						
No Asbestos						
B00C - R0015 - Cleaning Store - Distributed (2.08 m2)						
No Asbestos						
B00C - R0017 - Plant (5.32 m2)						
Wall Linings Internal	Compressed AC Sheet 8197/B00C/R0023/Wall Linings Internal/S18					No Asbestos Detected
B00C - R0018 - Stairs (1.63 m2)						
No Asbestos						
B00C - R0019 - Garden Store Room (10.27 m2)						
No Asbestos						
B00C - R0020 - Stairs (1.71 m2)						
No Asbestos						
B00C - R0021 - External Movement (10.89 m2)						
No Asbestos						
B00C - R0022 - Movement (10.72 m2)						
No Asbestos						
B00C - R0023 - External Movement (54.22 m2)						
Wall Linings Internal	Compressed AC Sheet 8197/B00C/R0023/Wall Linings Internal/S18					No Asbestos Detected
B00C - R0024 - Movement (10.77 m2)						
No Asbestos						
B00C - R0025 - External Movement (10.87 m2)						
No Asbestos						
B00C - R1001 - General Storeroom (7.02 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 8197/B00C/R1014/Ceiling Structures/Linings/S19	7.01m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</i>
B00C - R1002 - Music Learning Space (52.83 m2)						
Ceiling Structures/Linings	Vermiculite 8197/B00C/R0004/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8197/B00C/R1003/Floor Coverings Res/Textile/S20					No Asbestos Detected
B00C - R1003 - General Storeroom (7.69 m2)						
Ceiling Structures/Linings	Vermiculite 8197/B00C/R0004/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 8197/B00C/R1003/Floor Coverings Res/Textile/S20					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R1004 - Bulk Store (4.49 m2)						
Ceiling Structures/Linings	Vermiculite					
	8197/B00C/R0004/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1005 - Art Learning Space (111.5 m2)						
Ceiling Structures/Linings	Vermiculite					
	8197/B00C/R0004/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1006 - Kiln Space (22.04 m2)						
Ceiling Structures/Linings	Vermiculite					
	8197/B00C/R0004/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1007 - Bulk Store (10.61 m2)						
Ceiling Structures/Linings	Vermiculite					
	8197/B00C/R0004/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1008 - Workshop (12.58 m2)						
Ceiling Structures/Linings	Vermiculite					
	8197/B00C/R0004/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1009 - Bulk Store (12.51 m2)						
Ceiling Structures/Linings	Vermiculite					
	8197/B00C/R0004/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1010 - Art Learning Space (51.96 m2)						
Ceiling Structures/Linings	Vermiculite					
	8197/B00C/R0004/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1011 - Staff Study (12.73 m2)						
Ceiling Structures/Linings	Vermiculite					
	8197/B00C/R0004/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1012 - Movement (4.16 m2)						
Ceiling Structures/Linings	Vermiculite					
	8197/B00C/R0004/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1013 - Darkroom Space (8.56 m2)						
Ceiling Structures/Linings	Vermiculite					
	8197/B00C/R0004/Ceiling Structures/Linings/S5					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1014 - Movement (77.77 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	78m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00C/R1014/Ceiling Structures/Linings/S19					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00C - R1015 - Stairs (12.74 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	12.73m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00C/R1014/Ceiling Structures/Linings/S19					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
B00C - R1016 - Stairs (12.74 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	12.73m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00C/R1014/Ceiling Structures/Linings/S19					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Various - 1951 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	60m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00D/R0005/Ceiling Structures/Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Underfloor Voids - Slab on Ground						
Ceiling Voids	No Asbestos Found					

Interior

B00D - R0001 - Toilets-Boys (28.05 m2)

Ceiling Structures/Linings	Flat AC Sheeting	29m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00D/R0005/Ceiling Structures/Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0002 - Cleaning Store - Distributed (1.29 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00D/R0005/Ceiling Structures/Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0003 - Toilets-Boys (50.32 m2)

Ceiling Structures/Linings	Flat AC Sheeting	51m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00D/R0005/Ceiling Structures/Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0004 - Toilets-Disabled (6.95 m2)

Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00D/R0005/Ceiling Structures/Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0005 - Movement (55.19 m2)

Ceiling Structures/Linings	Flat AC Sheeting	56m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00D/R0005/Ceiling Structures/Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0006 - Student Canteen (39.67 m2)

Ceiling Structures/Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00D/R0005/Ceiling Structures/Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0007 - Pantry (10.05 m2)

Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00D/R0005/Ceiling Structures/Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0008 - Staff - Toilet (4.21 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00D/R0005/Ceiling Structures/Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0009 - Special Learning Space (62.17 m2)

Ceiling Structures/Linings	Flat AC Sheeting	63m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00D/R0005/Ceiling Structures/Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0010 - Toilets-Girls (42.6 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	43m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00D/R0005/Ceiling Structures/Linings/S9				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00D - R0011 - Toilets-Girls (41.48 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	42m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00D/R0005/Ceiling Structures/Linings/S9				Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Technological & Applied Studies - 1951 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00E/Eaves Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Underfloor Voids - Slab on Ground						
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					

Interior

B00E - R0004 - Resource/Project Store (20.52 m2)

No Asbestos

B00E - R0005 - Dust Extraction Space (2.87 m2)

Floor Coverings Res/Textile	Flat AC Sheeting					
	8197/B00E/R0005/Floor Coverings Res/Textile/S10				No Asbestos Detected	

B00E - R0006 - Materials Technology L.S. (103.21 m2)

No Asbestos

B00E - R0007 - Distribution Board Cupboard (0.23 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0008 - General Storeroom (11.44 m2)

No Asbestos

B00E - R0009 - Materials Store (12.08 m2)

No Asbestos

B00E - R0010 - Design L.S. (78.61 m2)

No Asbestos

B00E - R0011 - Movement (67.99 m2)

No Asbestos

B00E - R0012 - Staff Study (18.59 m2)

No Asbestos

B00E - R0013 - Staff - Toilet (6.95 m2)

No Asbestos

B00E - R0014 - Cleaning Store - Distributed (2.23 m2)

No Asbestos

B00E - R0015 - External Movement (1.84 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1.84m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00E/Eaves Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

B00E - R0016 - External Movement (4.11 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4.11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00E/Eaves Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

B00E - R0017 - Workshop Area (139.8 m2)

No Asbestos

B00E - R0018 - Welding Area (4 m2)

No Asbestos

B00E - R0019 - Welding Area (4 m2)

No Asbestos

B00E - R0020 - Welding Area (4 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00E - R0021 - Welding Area (4 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Technological & Applied Studies - 1951 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00E/Eaves Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Underfloor Voids	No Asbestos Found					
Gable Verge Lining	Non Accessible Area - Height Restriction					
Ceiling Voids	Non Accessible Area - Height Restriction					

Interior

B00F - R0001 - Cleaning Store - Distributed (5.55 m2)

No Asbestos

B00F - R0002 - Laundry (13.86 m2)

No Asbestos

B00F - R0003 - Materials Technology L.S. (90.82 m2)

No Asbestos

B00F - R0004 - Materials Store (12.03 m2)

No Asbestos

B00F - R0005 - Food/Research Space (24.65 m2)

No Asbestos

B00F - R0006 - Food Technology L.S. (139.14 m2)

No Asbestos

B00F - R0007 - Staff - Toilet (3.29 m2)

No Asbestos

B00F - R0008 - External Movement (1.48 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00E/Eaves Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

B00F - R0009 - Movement (51.42 m2)

No Asbestos

B00F - R0010 - External Movement (1.27 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00E/Eaves Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

B00F - R0011 - Staff Study (19.83 m2)

No Asbestos

B00F - R0012 - Distribution Board Cupboard (0.29 m2)

Note: No inspection of live electrical installation.

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Library/Science Learning - 1972 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00G/R1012/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)
Underfloor Voids	Non Accessible Area - Area inaccessible					
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					

Interior

B00G - R0001 - Laboratory L.S. (93.16 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8197/B00G/R1008/Ceiling Structures/Linings/S12					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00G - R0002 - Preparation (48.41 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8197/B00G/R1008/Ceiling Structures/Linings/S12					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00G - R0003 - Staff - Toilet (5.13 m2)

Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00G/R0009/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8197/B00G/R1008/Ceiling Structures/Linings/S12					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00G - R0004 - Distribution Board Cupboard (0.63 m2)

Note: No inspection of live electrical installation.

Electrical Mounting Board	Non Accessible Area - Electrical Hazard					
---------------------------	--	--	--	--	--	--

B00G - R0005 - Movement (2.69 m2)

Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00G/R0009/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8197/B00G/R1008/Ceiling Structures/Linings/S12					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00G - R0006 - Chemical Store (14.55 m2)

Floor Coverings Res/Textile	Vinyl Tiles	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00G/R0009/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8197/B00G/R1008/Ceiling Structures/Linings/S12					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00G - R0007 - Laboratory L.S. (91.87 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8197/B00G/R1008/Ceiling Structures/Linings/S12					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00G - R0008 - Staff Study (59.06 m2)

Floor Coverings Res/Textile	Vinyl Tiles	59m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8197/B00G/R0009/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8197/B00G/R1008/Ceiling Structures/Linings/S12					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00G - R0009 - Movement (12.95 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00G/R0009/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8197/B00G/R1008/Ceiling Structures/Linings/S12					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00G - R0010 - External Movement (19.53 m2)						
No Asbestos						
B00G - R0011 - External Stairs (18.1 m2)						
No Asbestos						
B00G - R1001 - Staff - Toilet (2.94 m2)						
No Asbestos						
B00G - R1002 - Distribution Board Cupboard (0.83 m2)				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00G/R1002/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)	
Electrical Mounting Board	Non Accessible Area		- Electrical Hazard			
B00G - R1003 - Cleaning Store - Distributed (2.26 m2)						
No Asbestos						
B00G - R1004 - Staff - Toilet (2.77 m2)						
No Asbestos						
B00G - R1005 - Seminar (12.54 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8197/B00G/R1008/Ceiling Structures/Linings/S12					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00G - R1006 - Audio Visual Workroom (12.87 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8197/B00G/R1008/Ceiling Structures/Linings/S12					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00G - R1007 - Seminar (12.83 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8197/B00G/R1008/Ceiling Structures/Linings/S12					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00G - R1008 - Seminar (12.79 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8197/B00G/R1008/Ceiling Structures/Linings/S12					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00G - R1009 - Main Area (243.46 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8197/B00G/R1008/Ceiling Structures/Linings/S12					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00G - R1010 - Librarian (5.97 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8197/B00G/R1008/Ceiling Structures/Linings/S12					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00G - R1011 - Seminar (19.85 m2)						
No Asbestos						
B00G - R1012 - Movement (19.53 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00G/R1012/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)	
B00G - R1013 - External Stairs (17.45 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	17.43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8197/B00G/R1012/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Agricultural Science - 1951 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground

Ceiling Voids No Asbestos Found

Interior

B00H - R0001 - External Movement (20.97 m2)

Ceiling Structures/Linings	Flat AC Sheeting	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	--------------	--------------------	---------	--------------------

8197/B00H/R0001/Ceiling Structures/Linings/S24

Chrysotile (white asbestos) , Amosite (brown asbestos)

B00H - R0006 - Distribution Board Cupboard (1.3 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0007 - Movement (4.44 m2)

No Asbestos

B00H - R0008 - Class Tools Storage (19.29 m2)

No Asbestos

B00H - R0009 - Secure Storeroom (4.91 m2)

No Asbestos

B00H - R0010 - Toilets-Disabled (7.13 m2)

No Asbestos

B00H - R0011 - Toilets-Boys/Girls (3.21 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Building Services - 1975 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground

Ceiling Voids - Flat Roof

Interior

B001 - R0001 - Garden Store Room (9.79 m2)

No Asbestos

B001 - R0002 - Garden Store Room (26.9 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Building Services - 1975 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground

Ceiling Voids No Asbestos Found

Interior

B00J - R0001 - General Storeroom (46.38 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00K - Building Services - 1975 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground

Ceiling Voids No Asbestos Found

Interior

B00K - R0001 - General Storeroom (45.85 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Other - 2003 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground

Ceiling Voids No Asbestos Found

Interior

B00L - R0001 - General Assistants (49.96 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Railway Carriage - 1960 - Steel (Steel)

Exterior

Underfloor Voids	No Asbestos Found
Ceiling Voids	Non Accessible Area - Area inaccessible

Interior

B00M - R0001 - Railway Carriage (56.53 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Railway Carriage - 1960 - Steel (Steel)

Exterior

Underfloor Voids	No Asbestos Found
Ceiling Voids	Non Accessible Area - Area inaccessible

Interior

B00N - R0001 - Railway Carriage (55.58 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Physical Education - 2003 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids	Non Accessible Area - Area inaccessible

Interior

B000 - R0001 - Gymnasium (86.34 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Other - 2012 - Brick/Veneer (Brick/Veneer)

Exterior

No Asbestos

Interior

B00P - R0001 - General Storeroom (52.16 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00Q - Agricultural Science - 2011 - Steel (Steel)

Exterior

No Asbestos

Interior

B00Q - R0001 - Shed Workshop (100.16 m2)

No Asbestos

B00Q - R0002 - Distribution Board Cupboard (1.47 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00Q - R0003 - Administration - Clerical (12.05 m2)

No Asbestos

B00Q - R0004 - Store (12.08 m2)

No Asbestos

B00Q - R0005 - General Learning Space (47.7 m2)

No Asbestos

B00Q - R0006 - Agriculture Covered Area (51.97 m2)

No Asbestos

B00Q - R0007 - External Movement (26.61 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Build+1 - B001

Exterior

Wall Cladding	Flat AC Sheeting 8197/Build+1/Wall Cladding/S13					No Asbestos Detected
---------------	--	--	--	--	--	----------------------

Interior

Build+1 - Room+1 - R0001

Wall Linings Internal	Flat AC Sheeting 8197/Build+1/Wall Cladding/S13					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

Ceiling Structures/Linings	Flat AC Sheeting 8197/Build+1/Wall Cladding/S13					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

Build+1 - Room+2 - R0002

Wall Linings Internal	Flat AC Sheeting 8197/Build+1/Wall Cladding/S13					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

Ceiling Structures/Linings	Flat AC Sheeting 8197/Build+1/Wall Cladding/S13					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017