


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wyndham College (8277)
Region : Western Sydney
State Electorate : Riverstone
Local Government Area : Blacktown

Initial Survey : Noel Arnold & Associates : 23 - May - 2008
Register Issue Date : 24 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1998 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Clinic - Girls**

No Asbestos

B00A - R0002 - Clinic - Girls

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0003 - Administration - Clerical

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0004 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0005 - Public Entry

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0007 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0008 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0009 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0012 - Security Store

No Asbestos

B00A - R0013 - Principal Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0014 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0015 - Staff Kitchen

No Asbestos

B00A - R0016 - Cleaning Store - Distributed

No Asbestos

B00A - R0017 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0018 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0019 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0020 - Pupil Entry

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0021 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0022 - Clinic - Boys

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00A - R0023 - Disabled Toilet

No Asbestos

B00A - R0025 - Movement

No Asbestos

B00A - R0026 - Staff - Toilet

No Asbestos

B00A - R0027 - Toilet - Lobby

No Asbestos

B00A - R0028 - Toilet - Lobby

No Asbestos

B00A - R0029 - Staff - Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Staff Facilities/Science - 1998 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00B - R0001 - Science Laboratory**

No Asbestos

B00B - R0002 - Preparation

No Asbestos

B00B - R0003 - Science Laboratory

No Asbestos

B00B - R0004 - General Learning SpaceVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R0005 - General Learning Space**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R0006 - Apparatus Store**

No Asbestos

B00B - R0007 - SeminarVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R0008 - Chemical Store**

No Asbestos

B00B - R0009 - General Learning SpaceVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R0010 - General Learning Space**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R0011 - Growing/Breeding**

No Asbestos

B00B - R0012 - Movement

No Asbestos

B00B - R0013 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0014 - Stairs

No Asbestos

B00B - R0015 - Stairs

No Asbestos

B00B - R1001 - Cleaning Store - Distributed

No Asbestos

B00B - R1002 - Staff StudyVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R1003 - Staff Study**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R1004 - Commonroom**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R1005 - Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R1006 - Disabled Toilet						
No Asbestos						
B00B - R1007 - Staff - Toilet						
No Asbestos						
B00B - R1008 - Staff - Toilet						
No Asbestos						
B00B - R1009 - Staff - Toilet						
No Asbestos						
B00B - R1010 - Staff - Toilet						
No Asbestos						
B00B - R1011 - Duplicating Workroom						
No Asbestos						
B00B - R1012 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00B - R1013 - Seminar						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1014 - Seminar						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1015 - Seminar						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1016 - Seminar						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1017 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1018 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1019 - Movement						
No Asbestos						
B00B - R1020 - Stairs						
No Asbestos						
B00B - R1021 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 1998 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00C - R0001 - Toilets-Girls**

No Asbestos

B00C - R0002 - Toilets-Boys

No Asbestos

B00C - R0003 - Movement

No Asbestos

B00C - R0004 - Cleaning Store - Distributed

No Asbestos

B00C - R0005 - Main Switchroom

No Asbestos

B00C - R0006 - Office/Store

No Asbestos

B00C - R0007 - Office/Store

No Asbestos

B00C - R0008 - Student Canteen

No Asbestos

B00C - R0009 - Movement

No Asbestos

B00C - R0011 - Office/Store

No Asbestos

B00C - R0012 - Movement

No Asbestos

B00C - R0013 - Student Drinking Facilities

No Asbestos

B00C - R0014 - Student Drinking Facilities

No Asbestos

B00C - R0015 - Movement

No Asbestos

B00C - R0016 - Staff - Toilet

No Asbestos

B00C - R0017 - Staff Shower

No Asbestos

B00C - R0018 - Toilet - Lobby

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Technological & Applied Studies - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0003 - Toilets-Girls

No Asbestos

B00D - R0004 - Staff - Toilet

No Asbestos

B00D - R0005 - Cleaning Store - Distributed

No Asbestos

B00D - R0006 - Shower/Change

No Asbestos

B00D - R0007 - Shower/Change

No Asbestos

B00D - R0008 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0009 - Secure Storeroom

No Asbestos

B00D - R0010 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0011 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0012 - Performance Workspace

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0013 - Practice/Seminar

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0014 - General Storeroom

No Asbestos

B00D - R0015 - Performing Arts Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0016 - Garden Store Room

No Asbestos

B00D - R0017 - Movement

No Asbestos

B00D - R0018 - Movement

No Asbestos

B00D - R0019 - Stairs

No Asbestos

B00D - R0020 - Stairs

No Asbestos

B00D - R0021 - Toilets-Disabled

No Asbestos

B00D - R0022 - Toilets-Boys

No Asbestos

B00D - R1001 - Seminar

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1002 - Computer Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1003 - Computer Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1004 - Laundry						
No Asbestos						
B00D - R1005 - Staff - Toilet						
No Asbestos						
B00D - R1006 - Cleaning Store - Distributed						
No Asbestos						
B00D - R1007 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1008 - Communication Space						
No Asbestos						
B00D - R1009 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
No Asbestos						
B00D - R1010 - Kitchen - Type 1						
No Asbestos						
B00D - R1011 - Food/Research Space						
No Asbestos						
B00D - R1012 - Pantry						
No Asbestos						
B00D - R1013 - Materials Store						
No Asbestos						
B00D - R1014 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1015 - General Learning Space						
No Asbestos						
B00D - R1016 - Movement						
No Asbestos						
B00D - R1017 - Stairs						
No Asbestos						
B00D - R1018 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Technological & Applied Studies/General Learning - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Resources Store

No Asbestos

B00E - R0002 - Resources Space

No Asbestos

B00E - R0003 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0004 - Visual Arts Workshop

No Asbestos

B00E - R0005 - Darkroom Space

No Asbestos

B00E - R0006 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0007 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0008 - Workshop Area

No Asbestos

B00E - R0009 - Welding Area

No Asbestos

B00E - R0010 - Materials Store

No Asbestos

B00E - R0011 - Kiln Space

No Asbestos

B00E - R0012 - Materials Technology L.S.

No Asbestos

B00E - R0013 - Materials Store

No Asbestos

B00E - R0014 - Dust Extraction Space

No Asbestos

B00E - R0015 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0016 - General Learning Space

No Asbestos

B00E - R0017 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0018 - Movement

No Asbestos

B00E - R0019 - Maintenance Bulk Store

No Asbestos

B00E - R0020 - Cleaning Store - Distributed

No Asbestos

B00E - R0021 - Cleaning Supplies Store

No Asbestos

B00E - R0022 - Lift

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00E - R0023 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R0024 - Stairs						
No Asbestos						
B00E - R0025 - Stairs						
No Asbestos						
B00E - R1001 - General Learning Space						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00E - R1002 - General Learning Space						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00E - R1003 - General Learning Space						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00E - R1004 - General Learning Space						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00E - R1005 - Seminar						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00E - R1006 - General Learning Space						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00E - R1007 - General Learning Space						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00E - R1008 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R1009 - General Learning Space						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00E - R1010 - Movement						
No Asbestos						
B00E - R1011 - Secure Storeroom						
No Asbestos						
B00E - R1012 - General Learning Space						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00E - R1013 - Movement						
No Asbestos						
B00E - R1014 - Secure Storeroom						
No Asbestos						
B00E - R1015 - Secure Storeroom						
No Asbestos						
B00E - R1016 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R1018 - Movement						
No Asbestos						
B00E - R1019 - Cleaning Store - Distributed						
No Asbestos						
B00E - R1020 - Secure Storeroom						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - R1021 - Plant						
No Asbestos						
B00E - R1022 - Lift						
No Asbestos						
B00E - R1023 - Stairs						
No Asbestos						
B00E - R1024 - Stairs						
No Asbestos						
B00E - R1025 - Other-Commercial						
No Asbestos						
B00E - R1026 - Movement						
No Asbestos						
B00E - R1027 - Computer Room						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00F - General Learning/Pupil Facilities - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - Movement

No Asbestos

B00F - R0002 - Stairs

No Asbestos

B00F - R0003 - Toilets - Boys

No Asbestos

B00F - R0004 - Toilets - Girls

No Asbestos

B00F - R0005 - Cleaning Store - Distributed

No Asbestos

B00F - R0006 - Darkroom Space

No Asbestos

B00F - R0007 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0008 - General Learning Space

No Asbestos

B00F - R0009 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0010 - General Learning Space

No Asbestos

B00F - R0011 - Workshop

No Asbestos

B00F - R0012 - Resources Store

No Asbestos

B00F - R0013 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0014 - Art Outdoor Area

No Asbestos

B00F - R0015 - Stairs

No Asbestos

B00F - R0016 - Kiln Space

No Asbestos

B00F - R0017 - Resource/Project Store

No Asbestos

B00F - R0018 - Communications Cupboard

No Asbestos

B00F - R1001 - Movement

No Asbestos

B00F - R1002 - Toilets - Girls

No Asbestos

B00F - R1003 - Toilets-Disabled

No Asbestos

B00F - R1004 - Toilets - Boys

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R1005 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1006 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1007 - Senior Seminar						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1008 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1009 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1010 - General Storeroom						
No Asbestos						
B00F - R1011 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1012 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1013 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1014 - Movement						
No Asbestos						
B00F - R1015 - Stairs						
No Asbestos						
B00F - R1016 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1017 - Cleaning Store - Distributed						
No Asbestos						
B00F - R1018 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Multi Purpose Facilities/Pupil Facilities - 1998 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Gymnasium

No Asbestos

B00G - R0002 - Sport Equipment Store

No Asbestos

B00G - R0003 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0004 - Movement

No Asbestos

B00G - R0005 - Sport Equipment Store

No Asbestos

B00G - R0006 - Sport Equipment Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0007 - Sport Equipment Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0008 - Cleaning Store - Distributed

No Asbestos

B00G - R0009 - Movement

No Asbestos

B00G - R0010 - Shower/Change

No Asbestos

B00G - R0011 - Shower/Change

No Asbestos

B00G - R0012 - Movement

No Asbestos

B00G - R0013 - General Storeroom

No Asbestos

B00G - R0014 - Garden Store Room

No Asbestos

B00G - R0015 - Garden Store Room

No Asbestos

B00G - R0016 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Multi Purpose Facilities/Pupil Facilities - 1998 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - M0001 - Control Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0001 - Multi-Purpose Space

No Asbestos

B00H - R0002 - Movement

No Asbestos

B00H - R0003 - Disabled Toilet

No Asbestos

B00H - R0004 - Cleaning Store - Distributed

No Asbestos

B00H - R0005 - Toilets-Boys

No Asbestos

B00H - R0006 - Movement

No Asbestos

B00H - R0007 - Lift

No Asbestos

B00H - R0008 - Movement

No Asbestos

B00H - R0009 - Chair Store

No Asbestos

B00H - R0010 - Stage

No Asbestos

B00H - R0011 - Control Room

No Asbestos

B00H - R0013 - Performing Arts Store

No Asbestos

B00H - R0014 - Movement

No Asbestos

B00H - R0015 - Toilets-Girls

No Asbestos

B00H - R0016 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0017 - Staff Kitchen

No Asbestos

B00H - R0018 - Movement

No Asbestos

B00H - R0019 - Movement

No Asbestos

B00H - R0020 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0021 - Movement

No Asbestos

B00H - R0022 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00L - Library/Senior Learning - 1998 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00L - R0001 - Audio Visual Workroom**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0002 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0003 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0004 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0005 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0006 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0007 - Senior Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0008 - Main Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0009 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0010 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0011 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0012 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0013 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0014 - Senior Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0015 - Librarian

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0016 - Librarian

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0017 - Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00L - R0018 - Movement						
No Asbestos						
B00L - R0019 - Toilets-Girls						
No Asbestos						
B00L - R0020 - Toilets-Boys						
No Asbestos						
B00L - R0021 - Disabled Toilet						
No Asbestos						
B00L - R0022 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00L - R0023 - Entry						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00L - R0024 - Workroom						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00L - R0025 - Cleaning Store - Distributed						
No Asbestos						
B00L - R0026 - Movement						
No Asbestos						
B00L - R0027 - Movement						
No Asbestos						
B00L - R0028 - Plant						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Performing Arts - 1998 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00P - R0001 - Plant**

No Asbestos

B00P - R0002 - StageVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00P - R0003 - Performance Workspace**

No Asbestos

B00P - R0004 - Movement

No Asbestos

B00P - R0005 - Performing Arts Changeroom

No Asbestos

B00P - R0006 - Cleaning Store - Distributed

No Asbestos

B00P - R0007 - Performing Arts Changeroom

No Asbestos

B00P - R0008 - Control RoomVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00P - R0009 - Performing Arts Store**

No Asbestos

B00P - R0010 - Performing Arts Store

No Asbestos

B00P - R0011 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00P - R0012 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00Q - General Learning/Other - 2011 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00Q - R0001 - Movement**

No Asbestos

B00Q - R0002 - Plant

No Asbestos

B00Q - R0003 - Toilets-Girls

No Asbestos

B00Q - R0004 - Toilets-Disabled

No Asbestos

B00Q - R0005 - Change

No Asbestos

B00Q - R0006 - Change

No Asbestos

B00Q - R0007 - Kitchen - Type 1

No Asbestos

B00Q - R0008 - Pantry

No Asbestos

B00Q - R0009 - Preparation

No Asbestos

B00Q - R0010 - Laundry

No Asbestos

B00Q - R0011 - Toilets-Boys

No Asbestos

B00Q - R0012 - Other-Commercial

No Asbestos

B00Q - R0013 - Chair Store

No Asbestos

B00Q - R0014 - Plant

No Asbestos

B00Q - R0015 - Other-Commercial

No Asbestos

B00Q - R0016 - Other-Commercial

No Asbestos

B00Q - R0017 - Kitchen - Type 1

No Asbestos

B00Q - R0018 - Store - Coolroom

No Asbestos

B00Q - R0019 - External Movement

No Asbestos

B00Q - R0020 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 601 - D10368 - Learning Unit - Standard/Withdrawal : Placement Date - 14/12/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

OS 601 - D10574 - Learning Unit - Standard/Withdrawal : Placement Date - 18/11/2014

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

NS 111 - D10881 - Learning Unit - Double Secondary/Secure : Placement Date - 23/05/2006

Exterior

No Asbestos Found.

Interior

R1 - General Learning Space

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Entry

No Asbestos Found.

R4 - Secure Storeroom

No Asbestos Found.

R5 - Secure Storeroom

No Asbestos Found.

R6 - Entry

No Asbestos Found.

OS 601 - D11228 - Learning Unit - Standard/Withdrawal : Placement Date - 6/01/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Store						
No Asbestos Found.						
OS 601 - D11505 - Learning Unit - Standard/Withdrawal : Placement Date - 14/12/2010						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Store						
No Asbestos Found.						
OS 601 - D12341 - Learning Unit - Standard/Withdrawal : Placement Date - 27/01/2004						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
NS 110 - D13161 - Learning Unit - Single Secondary/Secure : Placement Date - 21/01/2005						
Exterior						
No Asbestos Found.						
Interior						
R1 - General Learning Space						
No Asbestos Found.						
R2 - Entry						
No Asbestos Found.						
R3 - Secure Storeroom						
No Asbestos Found.						
NS 111 - D13293 - Learning Unit - Double Secondary/Secure : Placement Date - 10/01/2007						
Exterior						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - General Learning Space						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Entry						
No Asbestos Found.						
R4 - Secure Storeroom						
No Asbestos Found.						
R5 - Secure Storeroom						
No Asbestos Found.						
R6 - Entry						
No Asbestos Found.						
OS 710 - D14147 - Home Science/Pantry/Laundry : Placement Date - 23/12/2015						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - Food Technology L.S.						
No Asbestos Found.						
R3 - Laundry						
No Asbestos Found.						
OS 601 - D14444 - Learning Unit - Standard/Withdrawal : Placement Date - 6/01/2010						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Store						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

8277_ASB_100913_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017