

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Westfields Sports High School (8384)
Region : South Western Sydney
State Electorate : Fairfield
Local Government Area : Fairfield

Initial Survey : Noel Arnold & Associates : 30 - Mar - 2008
Reviewed By : Grencap-NAA : 13 - Aug - 2014



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - Administration/General Learning - 2004 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00A - R0001 - External Movement (10.39 m2)**

No Asbestos

B00A - R0004 - Interview/Office - Type 1 (13.54 m2)

No Asbestos

B00A - R0005 - Interview/Office - Type 1 (13.6 m2)

No Asbestos

B00A - R0006 - Leading Teacher (13.76 m2)

No Asbestos

B00A - R0007 - Staff - Toilet (4.94 m2)

No Asbestos

B00A - R0008 - Staff - Toilet (5.04 m2)

No Asbestos

B00A - R0009 - Distribution Board Cupboard (3 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0010 - Cleaning Store - Distributed (3.22 m2)

No Asbestos

B00A - R0011 - Secure Storeroom (14.28 m2)

No Asbestos

B00A - R0012 - Principal Office (20.17 m2)

No Asbestos

B00A - R0013 - Tea Room (5.51 m2)

No Asbestos

B00A - R0014 - Public Reception (80.12 m2)

No Asbestos

B00A - R0015 - Administration - Clerical (128.62 m2)

No Asbestos

B00A - R0016 - Ancillary Staff (12.4 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0017 - Toilets-Disabled (5.74 m2)

No Asbestos

B00A - R0018 - Clinic (12.8 m2)

No Asbestos

B00A - R0019 - Deputy Principal Office (12.6 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0020 - Deputy Principal Office (12.66 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0021 - Deputy Principal Office (12.64 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0022 - Interview/Office - Type 1 (12.31 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0023 - Student Reception (52.11 m2)						
No Asbestos						
B00A - R0025 - External Stairs (17.51 m2)						
No Asbestos						
B00A - R0026 - External Movement (92.11 m2)						
No Asbestos						
B00A - R1001 - External Movement (10.81 m2)						
No Asbestos						
B00A - R1002 - Distribution Board Cupboard (1.81 m2)				Note: No inspection of live electrical installation.		
No Asbestos						
B00A - R1003 - General Learning Space (66.19 m2)						
No Asbestos						
B00A - R1004 - Resources Store (19.25 m2)						
No Asbestos						
B00A - R1005 - General Learning Space (60.96 m2)						
No Asbestos						
B00A - R1006 - General Learning Space (59.56 m2)						
No Asbestos						
B00A - R1007 - Senior Study (24.47 m2)						
No Asbestos						
B00A - R1008 - General Learning Space (61.2 m2)						
No Asbestos						
B00A - R1009 - General Learning Space (67.29 m2)						
No Asbestos						
B00A - R1010 - Practical Activity Area (6.93 m2)						
No Asbestos						
B00A - R1011 - Movement (75.53 m2)						
No Asbestos						
B00A - R1012 - General Learning Space (46.8 m2)						
No Asbestos						
B00A - R1013 - External Stairs (25.08 m2)						
No Asbestos						
B00A - R1014 - External Movement (16.67 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1963 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8384/B00B/Eaves Linings/S19				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
In-fill-panel	Flat AC Sheeting	60m2	East, West, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8384/B00B/R1022/In-fill-panel/S3				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00B - R0001 - Movement (64.99 m2)**

No Asbestos

B00B - R0016 - Distribution Board Cupboard (0.57 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0022 - Staff - Toilet (6.59 m2)

No Asbestos

B00B - R0023 - Cleaning Store - Distributed (2.67 m2)

No Asbestos

B00B - R0035 - External Movement (5.28 m2)

No Asbestos

B00B - R0036 - External Movement (5.25 m2)

No Asbestos

B00B - R0038 - Staff - Toilet (8.84 m2)

No Asbestos

B00B - R0039 - Resources Store (12.7 m2)

Floor Coverings Res/Textile	Adhesive under lenolium					
	8384/B00B/R0058/Floor Coverings Res/Textile/S8					No Asbestos Detected

B00B - R0040 - General Learning Space (52.72 m2)

No Asbestos

B00B - R0041 - General Learning Space (52.73 m2)

No Asbestos

B00B - R0042 - General Learning Space (52.65 m2)

No Asbestos

B00B - R0043 - Computer Learning Space (65.64 m2)

Ceiling Structures/Linings	Vermiculite					
	8384/B00B/R0047/Ceiling Structures/Linings/S7					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00B - R0044 - Resources Store (13.03 m2)

Ceiling Structures/Linings	Vermiculite					
	8384/B00B/R0047/Ceiling Structures/Linings/S7					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

Floor Coverings Res/Textile	Adhesive under lenolium					
	8384/B00B/R0058/Floor Coverings Res/Textile/S8					No Asbestos Detected

B00B - R0045 - Senior Seminar (25.92 m2)

Ceiling Structures/Linings	Vermiculite					
	8384/B00B/R0047/Ceiling Structures/Linings/S7					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0046 - General Learning Space (52.36 m2)						
Ceiling Structures/Linings	Vermiculite		8384/B00B/R0047/Ceiling Structures/Linings/S7			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0047 - General Learning Space (52.51 m2)						
Ceiling Structures/Linings	Vermiculite		8384/B00B/R0047/Ceiling Structures/Linings/S7			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0048 - Senior Seminar (25.03 m2)						
No Asbestos						
B00B - R0049 - General Learning Space (61.67 m2)						
No Asbestos						
B00B - R0051 - Toilets-Disabled (7.35 m2)						
No Asbestos						
B00B - R0052 - Stairs (8.36 m2)						
No Asbestos						
B00B - R0053 - Stairs (8.31 m2)						
No Asbestos						
B00B - R0055 - External Movement (72.54 m2)						
No Asbestos						
B00B - R0056 - General Storeroom (7.83 m2)						
No Asbestos						
B00B - R0057 - Staff - Toilet (1.61 m2)						
No Asbestos						
B00B - R0058 - Movement (109.73 m2)						
Floor Coverings Res/Textile	Adhesive under lenolium		8384/B00B/R0058/Floor Coverings Res/Textile/S8			No Asbestos Detected
B00B - R0059 - Stairs (6.72 m2)						
No Asbestos						
B00B - R1003 - General Learning Space (53.31 m2)						
No Asbestos						
B00B - R1007 - Distribution Board Cupboard (0.31 m2)						
					Note: No inspection of live electrical installation.	
No Asbestos						
B00B - R1008 - Seminar (25.89 m2)						
No Asbestos						
B00B - R1009 - General Learning Space (52.65 m2)						
No Asbestos						
B00B - R1010 - Staff - Toilet (6.64 m2)						
No Asbestos						
B00B - R1011 - Resources Store (26.4 m2)						
Floor Coverings Res/Textile	Adhesive under lenolium		8384/B00B/R0058/Floor Coverings Res/Textile/S8			No Asbestos Detected
B00B - R1016 - Cleaning Store - Distributed (3.15 m2)						
No Asbestos						
B00B - R1018 - General Storeroom (9.45 m2)						
Floor Coverings Res/Textile	Adhesive under lenolium		8384/B00B/R0058/Floor Coverings Res/Textile/S8			No Asbestos Detected
B00B - R1021 - Senior Seminar (23.31 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	infill panel	2m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
8384/B00B/R1022/In-fill-panel/S3					Chrysotile (white asbestos)	
B00B - R1022 - Staff Study (23.4 m2)						
In-fill-panel	Flat AC Sheeting	2m	West	Good Condition (1)	Low (1)	Low Priority (2-3)
8384/B00B/R1022/In-fill-panel/S3					Chrysotile (white asbestos)	
B00B - R1023 - General Learning Space (53.16 m2)						
No Asbestos						
B00B - R1024 - General Learning Space (52.87 m2)						
No Asbestos						
B00B - R1025 - General Learning Space (65.81 m2)						
No Asbestos						
B00B - R1026 - General Learning Space (52.65 m2)						
No Asbestos						
B00B - R1027 - General Learning Space (53.02 m2)						
No Asbestos						
B00B - R1028 - General Learning Space (52.68 m2)						
No Asbestos						
B00B - R1029 - Stairs (17.77 m2)						
In-fill-panel	Flat AC Sheeting	4m	East	Good Condition (1)	Low (1)	Low Priority (2-3)
8384/B00B/R1022/In-fill-panel/S3					Chrysotile (white asbestos)	
B00B - R1030 - Stairs (17.78 m2)						
In-fill-panel	Flat AC Sheeting	4m	West	Good Condition (1)	Low (1)	Low Priority (2-3)
8384/B00B/R1022/In-fill-panel/S3					Chrysotile (white asbestos)	
B00B - R1031 - Stairs (8.8 m2)						
No Asbestos						
B00B - R1032 - External Movement (69.85 m2)						
No Asbestos						
B00B - R1033 - Movement (118.55 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Staff/General Learning/Science Learning - 1964 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8384/B00C/Eaves Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
In-fill-panel	Flat AC Sheeting	60m2	East, West, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8384/B00B/R1022/In-fill-panel/S3				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00C - M0001 - Other (6.5 m2)**

No Asbestos

B00C - M0002 - Movement (4.38 m2)

No Asbestos

B00C - R0001 - Laboratory L.S. (86.41 m2)

Ceiling Structures/Linings	Vermiculite					
	8384/B00C/R0022/Wall Linings Internal/S11					Limited Samples Taken
					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

B00C - R0004 - Laboratory L.S. (86.31 m2)

Ceiling Structures/Linings	Vermiculite					
	8384/B00C/R0022/Wall Linings Internal/S11					Limited Samples Taken
					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

B00C - R0005 - Computer Resource (24.74 m2)

Ceiling Structures/Linings	Vermiculite					
	8384/B00C/R0022/Wall Linings Internal/S11					Limited Samples Taken
					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

B00C - R0006 - Distribution Board Cupboard (0.56 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0007 - Staff - Toilet (6.33 m2)

No Asbestos

B00C - R0008 - Cleaning Store - Distributed (3.04 m2)

No Asbestos

B00C - R0009 - Computer Learning Space (51.86 m2)

Ceiling Structures/Linings	Vermiculite					
	8384/B00C/R0022/Wall Linings Internal/S11					Limited Samples Taken
					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

B00C - R0010 - General Learning Space (50.71 m2)

Ceiling Structures/Linings	Vermiculite					
	8384/B00C/R0022/Wall Linings Internal/S11					Limited Samples Taken
					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

B00C - R0011 - General Learning Space (52.58 m2)

Ceiling Structures/Linings	Vermiculite					
	8384/B00C/R0022/Wall Linings Internal/S11					Limited Samples Taken
					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

B00C - R0012 - General Learning Space (52.43 m2)

Ceiling Structures/Linings	Vermiculite					
	8384/B00C/R0022/Wall Linings Internal/S11					Limited Samples Taken
					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

B00C - R0013 - General Learning Space (52.43 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	8384/B00C/R0022/Wall Linings Internal/S11					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R0015 - General Storeroom (4.55 m2)						
No Asbestos						
B00C - R0020 - Archive Store (25.21 m2)						
No Asbestos						
B00C - R0021 - Preparation - Science (38.88 m2)						
No Asbestos						
B00C - R0022 - Movement (37.2 m2)						
Wall Linings Internal	Vermiculite					
	8384/B00C/R0022/Wall Linings Internal/S11					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	37.18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8384/B00C/R0022/Floor Coverings Res/Textile/S9					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive under vinyl					
	8384/B00C/R0022/Floor Coverings Res/Textile/S10					No Asbestos Detected
B00C - R0024 - External Movement (76.85 m2)						
No Asbestos						
B00C - R0025 - Stairs (3.85 m2)						
No Asbestos						
B00C - R0026 - Archive Store (9.64 m2)						
No Asbestos						
B00C - R0028 - External Movement (53.59 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	8384/B00C/R0028/Ceiling Structures/Linings/S4					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting					
	8384/B00C/R0028/Ceiling Structures/Linings/S4					No Asbestos Detected
B00C - R0029 - Stairs (9.52 m2)						
No Asbestos						
B00C - R0030 - Movement (62.16 m2)						
Wall Linings Internal	Vermiculite					
	8384/B00C/R0022/Wall Linings Internal/S11					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R0031 - Movement (6.41 m2)						
No Asbestos						
B00C - R0032 - Lift (2.1 m2)						
No Asbestos						
B00C - R0033 - Plant (0.73 m2)						
No Asbestos						
B00C - R0034 - External Movement (3.1 m2)						
No Asbestos						
B00C - R1008 - Distribution Board Cupboard (0.63 m2)						
No Asbestos						
Note: No inspection of live electrical installation.						
B00C - R1009 - Toilets-Disabled (6.93 m2)						
No Asbestos						
B00C - R1016 - Movement (18.36 m2)						
No Asbestos						
B00C - R1017 - Interview/Office - Type 1 (16.06 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	B00C - R1018 - Interview/Office - Type 1 (15.8 m2)					
	No Asbestos					
	B00C - R1019 - Staff - Toilet (6.19 m2)					
	No Asbestos					
	B00C - R1020 - Staff - Toilet (6.31 m2)					
	No Asbestos					
	B00C - R1021 - Staff - Toilet (6.15 m2)					
	No Asbestos					
	B00C - R1022 - Staff - Toilet (6.31 m2)					
	No Asbestos					
	B00C - R1023 - Staff - Toilet (6.1 m2)					
	No Asbestos					
	B00C - R1024 - Printing/Photocopying (35.22 m2)					
	No Asbestos					
	B00C - R1025 - Cleaning Store - Distributed (3.24 m2)					
	No Asbestos					
	B00C - R1026 - Movement (52.02 m2)					
	No Asbestos					
	B00C - R1030 - Movement (7.03 m2)					
	No Asbestos					
	B00C - R1032 - Stairs (6.96 m2)					
	No Asbestos					
	B00C - R1036 - Stairs (12.96 m2)					
	No Asbestos					
	B00C - R1037 - Staff Study (273.29 m2)					
	No Asbestos					
	B00C - R1038 - Resources Store (3.98 m2)					
	Recently Modified Space Requires Inspection					
	B00C - R1039 - Commonroom (118.39 m2)					
	No Asbestos					
	B00C - R1040 - Tea Room (10.9 m2)					
	No Asbestos					
	B00C - R1041 - Staff Study (121.76 m2)					
	No Asbestos					
	B00C - R1042 - Resources Store (3.9 m2)					
	No Asbestos					
	B00C - R1043 - Movement (8.86 m2)					
	No Asbestos					
	B00C - R1044 - External Movement (57.61 m2)					
	No Asbestos					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Technological & Applied Studies/General Learning - 1962 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						
In-fill-panel	Flat AC Sheeting	60m2	East, West, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8384/B00B/R1022/In-fill-panel/S3					Chrysotile (white asbestos)	
Ceiling Voids	Vermiculite	8384/B00C/R0022/Wall Linings Internal/S11			Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00D - R0002 - Cleaning Store - Distributed (6.73 m2)**

No Asbestos

B00D - R0003 - Cleaning Supplies Store (3.01 m2)

No Asbestos

B00D - R0005 - Resources Store (6.55 m2)

No Asbestos

B00D - R0009 - Distribution Board Cupboard (0.24 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0015 - Cleaning Store - Distributed (3.08 m2)

No Asbestos

B00D - R0027 - External Movement (1.95 m2)

Ceiling Structures/Linings	Flat AC Sheeting	8384/B00C/R0028/Ceiling Structures/Linings/S4			No Asbestos Detected	
----------------------------	------------------	---	--	--	-----------------------------	--

B00D - R0029 - Movement (18.8 m2)

Ceiling Structures/Linings	Vermiculite	8384/B00C/R0022/Wall Linings Internal/S11			Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00D - R0030 - Design/Technology L.S. (52.72 m2)

No Asbestos

B00D - R0031 - Food Technology L.S. (98.5 m2)

No Asbestos

B00D - R0032 - Computer Learning Space (60.78 m2)

Ceiling Structures/Linings	Vermiculite	8384/B00C/R0022/Wall Linings Internal/S11			Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00D - R0033 - Seminar/Study (26.4 m2)

Ceiling Structures/Linings	Vermiculite	8384/B00C/R0022/Wall Linings Internal/S11			Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00D - R0034 - Main Switchroom (13.31 m2)

Electrical Backing Board	Resinous Board	0.5m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
8384/B00D/R0034/Electrical Backing Board/S12					Chrysotile (white asbestos)	

B00D - R0035 - Design/Technology L.S. (52.36 m2)

No Asbestos

B00D - R0039 - General Learning Space (53.02 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite	8384/B00C/R0022/Wall Linings Internal/S11				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0042 - Stairs (1.63 m2)						
No Asbestos						
B00D - R0043 - Stairs (1.63 m2)						
No Asbestos						
B00D - R0045 - External Stairs (29.2 m2)						
No Asbestos						
B00D - R0046 - External Movement (0.91 m2)						
No Asbestos						
B00D - R0047 - External Movement (36.68 m2)						
No Asbestos						
B00D - R0048 - Movement (45.38 m2)						
Ceiling Structures/Linings	Vermiculite	8384/B00D/R0048/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0049 - Distribution Board Cupboard (1.11 m2)						
					Note: No inspection of live electrical installation.	
Infill panels to doors	Flat AC Sheeting	8384/B00D/R0049/Infill panels to doors/S1				No Asbestos Detected
B00D - R0050 - Pantry (21.9 m2)						
Ceiling Structures/Linings	Vermiculite	8384/B00D/R0048/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0051 - Preparation (20.15 m2)						
Ceiling Structures/Linings	Vermiculite	8384/B00D/R0048/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0052 - Laundry (9.46 m2)						
Ceiling Structures/Linings	Vermiculite	8384/B00D/R0048/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0053 - Kitchen - Type 1 (119.33 m2)						
Ceiling Structures/Linings	Vermiculite	8384/B00D/R0048/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0054 - Tea Room (33.85 m2)						
No Asbestos						
B00D - R0055 - Store (2.38 m2)						
No Asbestos						
B00D - R1002 - General Storeroom (6.61 m2)						
No Asbestos						
B00D - R1006 - General Learning Space (52.44 m2)						
No Asbestos						
B00D - R1007 - Distribution Board Cupboard (0.26 m2)						
					Note: No inspection of live electrical installation.	
No Asbestos						
B00D - R1012 - Cleaning Store - Distributed (6.14 m2)						
No Asbestos						
B00D - R1013 - General Learning Space (52.65 m2)						
No Asbestos						
B00D - R1014 - Resources Store (7.24 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00D - R1015 - General Learning Space (66.12 m2)

No Asbestos

B00D - R1021 - General Learning Space (52.58 m2)

No Asbestos

B00D - R1022 - General Learning Space (53.24 m2)

No Asbestos

B00D - R1025 - General Storeroom (12.38 m2)

Floor Coverings
Res/Textile

Adhesive under lenolium

8384/B00B/R0058/Floor Coverings Res/Textile/S8

No Asbestos Detected

B00D - R1026 - General Learning Space (52.58 m2)

No Asbestos

B00D - R1027 - General Learning Space (53.02 m2)

No Asbestos

B00D - R1029 - External Movement (36.71 m2)

No Asbestos

B00D - R1030 - External Stairs (29.2 m2)

No Asbestos

B00D - R1031 - Senior Study (25.37 m2)

No Asbestos

B00D - R1032 - General Storeroom (4.2 m2)

No Asbestos

B00D - R1033 - Toilets-Unisex (2.23 m2)

No Asbestos

B00D - R1034 - General Learning Space (52.38 m2)

No Asbestos

B00D - R1035 - Movement (109.52 m2)

Floor Coverings
Res/Textile

Vinyl Tiles

109.48m2 Throughout

Good Condition (1)

Low (1) Low Priority (2-3)

8384/B00C/R0022/Floor Coverings Res/Textile/S9

Chrysotile (white asbestos)

Floor Coverings
Res/Textile

Adhesive

8384/B00C/R0022/Floor Coverings Res/Textile/S10

No Asbestos Detected

B00D - R1036 - Stairs (5.66 m2)

No Asbestos

B00D - R1037 - Stairs (5.66 m2)

No Asbestos

B00D - Room+1 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00D - Room+2 - Staff Lounge

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Library/Science Learning - 1970 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior**B00E - M1002 - Computer Room (37.11 m2)**

No Asbestos

B00E - M1003 - Plant (4.72 m2)

No Asbestos

B00E - M1004 - Careers Advisers Office (15.11 m2)

No Asbestos

B00E - M1005 - Stairs (2.48 m2)

No Asbestos

B00E - M1006 - Stairs (2.66 m2)

No Asbestos

B00E - M1007 - Plant (53.24 m2)

No Asbestos

B00E - M1008 - Plant (18.01 m2)

No Asbestos

B00E - M1009 - Movement (13.87 m2)

Ceiling Structures/Linings	Vermiculite		
	8384/B00D/R0048/Ceiling Structures/Linings/S2		Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>			

B00E - M1010 - Seminar/Study (15.21 m2)

Ceiling Structures/Linings	Vermiculite		
	8384/B00D/R0048/Ceiling Structures/Linings/S2		Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>			

B00E - M1011 - Seminar/Study (10.33 m2)

Ceiling Structures/Linings	Vermiculite		
	8384/B00D/R0048/Ceiling Structures/Linings/S2		Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>			

B00E - M1012 - Seminar/Study (10.25 m2)

Ceiling Structures/Linings	Vermiculite		
	8384/B00D/R0048/Ceiling Structures/Linings/S2		Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>			

B00E - M1013 - Seminar/Study (15.23 m2)

Ceiling Structures/Linings	Vermiculite		
	8384/B00D/R0048/Ceiling Structures/Linings/S2		Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>			

B00E - R0001 - Laboratory L.S. (91.24 m2)

Ceiling Structures/Linings	Vermiculite		
	8384/B00E/R0009/Ceiling Structures/Linings/S15		Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>			

B00E - R0002 - Preparation - Science (44.69 m2)

Ceiling Structures/Linings	Vermiculite		
	8384/B00E/R0009/Ceiling Structures/Linings/S15		Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>			

B00E - R0003 - General Storeroom (3.13 m2)

Recently Modified Space Requires Inspection

B00E - R0004 - Laboratory L.S. (91.34 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	8384/B00E/R0009/Ceiling Structures/Linings/S15					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R0005 - Distribution Board Cupboard (0.51 m2)						
					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R0006 - Chemical Store (16.91 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8384/B00E/R0002/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)
B00E - R0007 - Laboratory L.S. (91.14 m2)						
Ceiling Structures/Linings	Vermiculite					
	8384/B00E/R0009/Ceiling Structures/Linings/S15					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R0008 - Preparation - Science (44.49 m2)						
Ceiling Structures/Linings	Vermiculite					
	8384/B00E/R0009/Ceiling Structures/Linings/S15					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R0009 - General Storeroom (3.17 m2)						
Ceiling Structures/Linings	Vermiculite					
	8384/B00E/R0009/Ceiling Structures/Linings/S15					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R0010 - Laboratory L.S. (91.24 m2)						
Ceiling Structures/Linings	Vermiculite					
	8384/B00E/R0009/Ceiling Structures/Linings/S15					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R0011 - Movement (40.79 m2)						
No Asbestos						
B00E - R0013 - Plant (10.66 m2)						
Electrical Backing Board	Resinous Board	2m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
<i>Assumed Asbestos - Electrical Hazard</i>						
B00E - R0017 - External Movement (27.88 m2)						
No Asbestos						
B00E - R0018 - Plant Growing Space (16.75 m2)						
No Asbestos						
B00E - R0019 - General Storeroom (4.44 m2)						
No Asbestos						
B00E - R0020 - Stairs (12.15 m2)						
No Asbestos						
B00E - R1001 - Staff - Toilet (2.93 m2)						
No Asbestos						
B00E - R1003 - System Administrators Office (12.25 m2)						
No Asbestos						
B00E - R1004 - Audio Visual Workroom (27.83 m2)						
No Asbestos						
B00E - R1007 - Seminar (24.98 m2)						
No Asbestos						
B00E - R1008 - Cleaning Store - Distributed (4.49 m2)						
No Asbestos						
B00E - R1009 - Distribution Board Cupboard (0.23 m2)					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R1010 - Cleaning Supplies Store (0.32 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	

No Asbestos

B00E - R1011 - Interview/Office - Type 1 (12.09 m2)

No Asbestos

B00E - R1012 - Interview/Office - Type 1 (12.68 m2)

No Asbestos

B00E - R1013 - General Learning Space (69.08 m2)

Ceiling Structures/Linings Vermiculite
8384/B00E/R0009/Ceiling Structures/Linings/S15

Limited Samples Taken

Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R1014 - Staff - Toilet (2.92 m2)

No Asbestos

B00E - R1015 - Plant (5.69 m2)

No Asbestos

B00E - R1016 - Plant (6.23 m2)

No Asbestos

B00E - R1017 - External Movement (22.43 m2)

No Asbestos

B00E - R1018 - Stairs (16.59 m2)

No Asbestos

B00E - R1019 - Stairs (1.62 m2)

No Asbestos

B00E - R1020 - Stairs (1.62 m2)

No Asbestos

B00E - R1021 - Other-Vacant (2.42 m2)

No Asbestos

B00E - R1022 - Main Entry (34.6 m2)

No Asbestos

B00E - R1023 - Main Area (287.45 m2)

Ceiling Structures/Linings Vermiculite
8384/B00E/R0009/Ceiling Structures/Linings/S15

Limited Samples Taken

Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R1024 - Library Administration (17 m2)

No Asbestos

B00E - R1025 - Staff Kitchen (12.43 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Multi Purpose Facilities - 1996 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00F - R0001 - Tiered Learning Area (67.56 m2)

No Asbestos

B00F - R0002 - Distribution Board Cupboard (0.19 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0003 - General Storeroom (2.84 m2)

No Asbestos

B00F - R0004 - Plant (8.51 m2)

No Asbestos

B00F - R0005 - External Movement (1.78 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Music/Art/General Learning - 1996 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids	No Asbestos Found
Ceiling Voids	Non Accessible Area - Inaccessible access points

Interior

B00G - R0001 - General Learning Space (60.16 m2)

No Asbestos

B00G - R0002 - Art Learning Space (59.67 m2)

No Asbestos

B00G - R0003 - Distribution Board Cupboard (0.38 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0004 - Kiln Space (9.02 m2)

Kiln	Encapsulated Insulation material within unit	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - encased innunit						

B00G - R0005 - Art Learning Space (50.77 m2)

No Asbestos

B00G - R0006 - General Learning Space (60.41 m2)

No Asbestos

B00G - R0007 - General Learning Space (60.45 m2)

No Asbestos

B00G - R0008 - Resources Store (30.79 m2)

No Asbestos

B00G - R0009 - General Storeroom (11.98 m2)

No Asbestos

B00G - R0010 - Sport Equipment Store (15.84 m2)

No Asbestos

B00G - R0011 - Cleaning Store - Distributed (3 m2)

No Asbestos

B00G - R0012 - Toilets-Girls (19.48 m2)

No Asbestos

B00G - R0013 - Distribution Board Cupboard (0.73 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0014 - Toilets-Boys (25.77 m2)

No Asbestos

B00G - R0015 - External Movement (40.06 m2)

No Asbestos

B00G - R0016 - External Movement (109.63 m2)

No Asbestos

B00G - R0017 - External Stairs (11.35 m2)

No Asbestos

B00G - R1001 - Music Learning Space (89.54 m2)

No Asbestos

B00G - R1003 - Distribution Board Cupboard (0.36 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00G - R1004 - Music Learning Space (59.61 m2)

No Asbestos

B00G - R1005 - Music Store (19.62 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00G - R1008 - General Learning Space (60.03 m2)

No Asbestos

B00G - R1010 - Distribution Board Cupboard (0.96 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00G - R1011 - Cleaning Store - Distributed (2.75 m2)

No Asbestos

B00G - R1012 - Staff - Toilet (4.3 m2)

No Asbestos

B00G - R1013 - Staff - Toilet (4.3 m2)

No Asbestos

B00G - R1014 - External Movement (133.92 m2)

No Asbestos

B00G - R1016 - External Stairs (23.93 m2)

No Asbestos

B00G - R1017 - Practice/Seminar (27.99 m2)

No Asbestos

B00G - R1018 - Handwashing Facilities (2.08 m2)

No Asbestos

B00G - R1019 - Computer Learning Space (37.49 m2)

No Asbestos

B00G - R1020 - Tea Room (2.29 m2)

No Asbestos

B00G - R1021 - General Learning Space (58.46 m2)

No Asbestos

B00G - R1022 - Tea Room (1.64 m2)

No Asbestos

B00G - R1023 - Darkroom Space (4.63 m2)

No Asbestos

B00G - R1024 - Dark Room (30.1 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Physical Education - 2001 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00H - R0002 - Gymnasium (818.56 m2)

No Asbestos

B00H - R0003 - Change (23.64 m2)

No Asbestos

B00H - R0004 - Movement (7.79 m2)

No Asbestos

B00H - R0015 - External Movement (80.11 m2)

No Asbestos

B00H - R0016 - Plant (0.59 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0017 - Distribution Board Cupboard (0.98 m2)

Note: No inspection of live electrical installation.

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0018 - Sport Equipment Store (24.99 m2)

No Asbestos

B00H - R0021 - Movement (7.35 m2)

No Asbestos

B00H - R0022 - Toilets-Disabled (4.46 m2)

No Asbestos

B00H - R0023 - General Storeroom (0.76 m2)

No Asbestos

B00H - R0024 - Commonroom (22.52 m2)

No Asbestos

B00H - R0025 - Interview/Office - Type 1 (10.27 m2)

No Asbestos

B00H - R0026 - Toilet - Lobby (3.72 m2)

No Asbestos

B00H - R0027 - Staff - Toilet (12.69 m2)

No Asbestos

B00H - R0028 - Toilet - Lobby (2.07 m2)

No Asbestos

B00H - R0029 - Staff - Toilet (8.18 m2)

No Asbestos

B00H - R0030 - General Storeroom (9.66 m2)

No Asbestos

B00H - R0031 - Change (26.78 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0032 - Seminar (38.08 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0033 - External Movement (2.95 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00H - R0034 - External Movement (9.47 m2)						
No Asbestos						
B00H - R0035 - External Movement (2.59 m2)						
No Asbestos						
B00H - R0036 - Toilet - Lobby (4.26 m2)						
No Asbestos						
B00H - R0037 - Change (23.28 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Physical Education - 2001 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00I - R0007 - Uniform Shop (33.54 m2)

No Asbestos

B00I - R0008 - Plant (2.62 m2)

No Asbestos

B00I - R0009 - Toilets-Disabled (4.34 m2)

No Asbestos

B00I - R0010 - Office/Store (11.46 m2)

No Asbestos

B00I - R0011 - Movement (7.15 m2)

No Asbestos

B00I - R0012 - Distribution Board Cupboard (1.33 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00I - R0013 - Fitness Laboratory (188.84 m2)

No Asbestos

B00I - R0015 - External Movement (37.64 m2)

No Asbestos

B00I - R0016 - Outdoor Learning Area (146.36 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Technological & Applied Studies - 1962 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 8384/B00J/Eaves Linings/S14					No Asbestos Detected

Interior

B00J - R0014 - Distribution Board Cupboard (0.67 m2) Note: No inspection of live electrical installation.

No Asbestos

B00J - R0020 - External Movement (31.74 m2)

No Asbestos

B00J - R0021 - Materials Store (31.09 m2)

No Asbestos

B00J - R0022 - General Storeroom (6.51 m2)

No Asbestos

B00J - R0023 - Garden Store Room (15.01 m2)

No Asbestos

B00J - R0024 - General Assistants (15.01 m2)

No Asbestos

B00J - R0025 - Materials Workshop - Type 3 (60.79 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8384/B00J/R0025/Ceiling Structures/Linings/S13					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00J - R0026 - Materials Technology L.S. (60.18 m2)

No Asbestos

B00J - R0027 - Computer Learning Space (65.68 m2)

No Asbestos

B00J - R0028 - Materials Store (36.39 m2)

No Asbestos

B00J - R0029 - Materials Technology L.S. (103.39 m2)

No Asbestos

B00J - R0030 - Movement (94.66 m2)

No Asbestos

B00J - R0031 - Movement (24.01 m2)

No Asbestos

B00J - R0032 - External Movement (10.28 m2)

No Asbestos

B00J - R0033 - Wood Technology L.S. (99.66 m2)

No Asbestos

B00J - R0034 - Plant (9.76 m2)

No Asbestos

B00J - R0035 - Wood Technology Bay (28.52 m2)

No Asbestos

B00J - R0036 - Wood Technology L.S. (98.95 m2)

No Asbestos

B00J - R0037 - Senior Study (26.51 m2)

No Asbestos

B00J - R0038 - Movement (22.55 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00J - R0039 - External Movement (15.78 m2)

No Asbestos

B00J - R0040 - External Movement (5.67 m2)

Ceiling Structures/Linings Flat AC Sheeting
8384/B00J/Eaves Linings/S14

No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Pupil Facilities/Movement Complex - 1962 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00K - R0001 - General Storeroom (12.55 m2)

No Asbestos

B00K - R0002 - Change (34.83 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8384/B00K/R0012/Ceiling Structures/Linings/S6					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00K - R0003 - Shower (14.75 m2)

No Asbestos

B00K - R0005 - External Movement (13.52 m2)

No Asbestos

B00K - R0008 - General Storeroom (6.66 m2)

Wall linings external	Flat AC Sheeting 8384/B00K/R0008/Wall linings external/S18					No Asbestos Detected
-----------------------	---	--	--	--	--	-----------------------------

B00K - R0009 - General Storeroom (10.64 m2)

No Asbestos

B00K - R0010 - Pantry (9.64 m2)

No Asbestos

B00K - R0011 - Student Canteen (49.18 m2)

No Asbestos

B00K - R0013 - Performance Store (12.74 m2)

No Asbestos

B00K - R0014 - Movement Studio (104.71 m2)

No Asbestos

B00K - R0015 - Movement (12.04 m2)

No Asbestos

B00K - R0017 - Change (36.21 m2)

No Asbestos

B00K - R0018 - Shower (14.85 m2)

Cubicle Walls Partition	Compressed AC Sheet	5m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
8384/B00K/R0006/Partition Walls (Cubicles)/S5						Chrysotile (white asbestos)

B00K - R0020 - Staff - Toilet (1.84 m2)

No Asbestos

B00K - R0022 - Sport Equipment Store (2.07 m2)

No Asbestos

B00K - R0024 - Movement (235.32 m2)

No Asbestos

B00K - R0026 - Plant (5.31 m2)

Gas Meter	Encapsulated Insulation material within unit	1Unit	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Gaskets encased in unit						

B00K - R0027 - Toilets-Boys (78.25 m2)

No Asbestos

B00K - R0028 - Plant (10.36 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00K - R0029 - Plant (9.61 m2)						
No Asbestos						
B00K - R0030 - Cleaning Store - Distributed (3.28 m2)						
No Asbestos						
B00K - R0031 - Staff - Toilet (1.51 m2)						
No Asbestos						
B00K - R0032 - Sport Equipment Store (6.69 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	6.68m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8384/B00K/R0032/Floor Coverings Res/Textile/S16					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive under blue vinyl					
8384/B00K/R0032/Floor Coverings Res/Textile/S17					No Asbestos Detected	
B00K - R0033 - Sport Equipment Store (2.87 m2)						
No Asbestos						
B00K - R0034 - Toilets-Girls (76.04 m2)						
No Asbestos						
B00K - R0035 - Plant (11.72 m2)						
No Asbestos						
B00K - R0036 - Handwashing Facilities (6.08 m2)						
No Asbestos						
B00K - R0037 - Plant (4.31 m2)						
No Asbestos						
B00K - R0038 - External Movement (140.72 m2)						
No Asbestos						
B00K - R0039 - External Stairs (1.99 m2)						
No Asbestos						
B00K - R0040 - Sport Equipment Store (6.77 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	6.77m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8384/B00K/R0032/Floor Coverings Res/Textile/S16					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					
8384/B00K/R0032/Floor Coverings Res/Textile/S17					No Asbestos Detected	
B00K - R0041 - Shower (3.03 m2)						
No Asbestos						
B00K - R0042 - Sport Equipment Store (8.22 m2)						
No Asbestos						
B00K - R1001 - Performance Workshop (154.69 m2)						
No Asbestos						
B00K - R1002 - Movement Studio (154.81 m2)						
No Asbestos						
B00K - R1003 - External Movement (19.25 m2)						
No Asbestos						
B00K - R1004 - External Stairs (7.13 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Multi Purpose Facilities/Physical Education - 1994 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00L - R0002 - Toilets-Disabled (3.68 m2)

No Asbestos

B00L - R0003 - Cleaning Store - Distributed (1.21 m2)

No Asbestos

B00L - R0004 - Distribution Board Cupboard (0.27 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0005 - Change (13.83 m2)

No Asbestos

B00L - R0006 - Control Room (15.12 m2)

No Asbestos

B00L - R0007 - Movement (41.99 m2)

No Asbestos

B00L - R0010 - Formal Lease Agreement (2.13 m2)

No Asbestos

B00L - R0011 - Gymnasium (1360.58 m2)

No Asbestos

B00L - R0013 - Formal Lease Agreement (12.03 m2)

No Asbestos

B00L - R0014 - Formal Lease Agreement (12.07 m2)

No Asbestos

B00L - R0015 - Formal Lease Agreement (38.43 m2)

No Asbestos

B00L - R0016 - Formal Lease Agreement (24.9 m2)

No Asbestos

B00L - R0017 - Formal Lease Agreement (4.9 m2)

No Asbestos

B00L - R0018 - Resources Store (10.48 m2)

No Asbestos

B00L - R0019 - Sport Equipment Store (8.48 m2)

No Asbestos

B00L - R0020 - Toilet - Lobby (1.5 m2)

No Asbestos

B00L - R0021 - Change (12.06 m2)

No Asbestos

B00L - R0022 - Staff Study (49.22 m2)

No Asbestos

B00L - R0023 - Tea Room (9.54 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	


B00M - General Learning - 2007 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00M - R0001 - General Learning Space (58.49 m2)	No Asbestos
B00M - R0002 - General Learning Space (58.55 m2)	No Asbestos
B00M - R0004 - General Learning Space (58.46 m2)	No Asbestos
B00M - R0005 - Resources Store (5.38 m2)	No Asbestos
B00M - R0006 - Distribution Board Cupboard (0.41 m2)	Note: No inspection of live electrical installation. No Asbestos
B00M - R0007 - External Movement (6.4 m2)	No Asbestos
B00M - R0008 - External Movement (5.8 m2)	No Asbestos
B00M - R0009 - Movement (17.8 m2)	No Asbestos
B00M - R0010 - Handwashing Facilities (1.66 m2)	No Asbestos
B00M - R1001 - General Learning Space (58.41 m2)	No Asbestos
B00M - R1002 - General Learning Space (58.16 m2)	No Asbestos
B00M - R1003 - Movement (19.44 m2)	No Asbestos
B00M - R1004 - General Learning Space (57.78 m2)	No Asbestos
B00M - R1005 - Resources Store (5.25 m2)	No Asbestos
B00M - R1006 - Cleaning Store - Distributed (0.43 m2)	No Asbestos
B00M - R1007 - External Movement (5.35 m2)	No Asbestos
B00M - R1008 - External Movement (10.37 m2)	No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Storage - 2009 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00N - R0001 - General Storeroom (53.78 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Storage - 2009 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Flat Roof No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior

B000 - R0001 - Covered Vehicle Area/Porte Cochere (137.34 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Physical Education/Pupil Facilities - 2013 - Steel (Steel)**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior**B00P - R0001 - External Movement (27.84 m2)**

No Asbestos

B00P - R0002 - Cleaning Supplies Store (6.16 m2)

No Asbestos

B00P - R0003 - Toilets-Boys (69.17 m2)

No Asbestos

B00P - R0004 - Movement (5.25 m2)

No Asbestos

B00P - R0005 - Utility Space (3.37 m2)

No Asbestos

B00P - R0006 - Hydrotherapy - Spa (11.5 m2)

No Asbestos

B00P - R0007 - Movement (4.72 m2)

No Asbestos

B00P - R0008 - Student Shower (2.75 m2)

No Asbestos

B00P - R0009 - Movement (11.76 m2)

No Asbestos

B00P - R0010 - Toilets-Girls (42.43 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - Storage - 2015 - Metal Shed (Metal Shed)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00Q - R0001 - Garden Store Room (46.71 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 600 - D10608 - Learning Unit - Small : Placement Date - 8/10/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - General Learning Space

No Asbestos Found.

OS 600 - D10817 - Learning Unit - Small : Placement Date - 23/09/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - General Learning Space

No Asbestos Found.

OS 601 - D11561 - Learning Unit - Standard/Withdrawal : Placement Date - 14/09/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

OS 600 - D11708 - Learning Unit - Small : Placement Date - 8/10/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - General Learning Space

No Asbestos Found.

OS 720 - D12199 - Science Laboratory/Prep Room : Placement Date - 28/09/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Laboratory L.S.

No Asbestos Found.

R2 - Preparation

No Asbestos Found.

OS 600 - D13989 - Learning Unit - Small : Placement Date - 9/10/2015

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - General Learning Space						
No Asbestos Found.						
OS 600 - D15189 - Learning Unit - Small : Placement Date - 9/10/2015						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - General Learning Space						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017