



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00A - Administration/General Learning - 1964 - Brick/Block (Brick/Block)****Exterior**

Sun screens	Compressed AC Sheet	100m2	East, West, Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00A/Sun screens/S3			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible					
Ceiling Voids	Non Accessible Area					
	- Area inaccessible					

**Interior****B00A - R0002 - Principal Office (24.16 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00A/R0009/Ceiling Structures/Linings/S1					<b>Limited Samples Taken</b>
				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		

**B00A - R0003 - General Storeroom (2.94 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00A/R0009/Ceiling Structures/Linings/S1					<b>Limited Samples Taken</b>
				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		

**B00A - R0004 - Staff - Toilet (3.2 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00A/R0009/Ceiling Structures/Linings/S1					<b>Limited Samples Taken</b>
				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		

**B00A - R0005 - Cleaning Store - Distributed (2.04 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00A/R0009/Ceiling Structures/Linings/S1					<b>Limited Samples Taken</b>
				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		

**B00A - R0006 - Administration - Clerical (10.66 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00A/R0009/Ceiling Structures/Linings/S1					<b>Limited Samples Taken</b>
				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		

**B00A - R0009 - Deputy Principal Office (16.26 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00A/R0009/Ceiling Structures/Linings/S1					<b>Limited Samples Taken</b>
				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		

**B00A - R0012 - General Storeroom (0.9 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00A/R0009/Ceiling Structures/Linings/S1					<b>Limited Samples Taken</b>
				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		

**B00A - R0013 - General Learning Space (59.31 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00A/R0009/Ceiling Structures/Linings/S1					<b>Limited Samples Taken</b>
				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		

**B00A - R0014 - Laboratory L.S. (91.12 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00A/R0009/Ceiling Structures/Linings/S1					<b>Limited Samples Taken</b>
				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		

Wall Linings Internal	Flat AC Sheeting					
	8418/B00A/R0014/Wall Linings Internal/S29					<b>No Asbestos Detected</b>

**B00A - R0015 - Preparation (23.79 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00A/R0016/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8418/B00A/R0015/Ceiling Structures/Linings/S28					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00A - R0016 - Leading Teacher (8.2 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 8418/B00A/R0016/Floor Coverings Res/Textile/S2	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R0017 - Staff Study (25.98 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00A/R0009/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00A - R0018 - Distribution Board Cupboard (0.91 m2)</b>				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B00A - R0019 - Pupil Entry (13.77 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00A/R0009/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00A - R0020 - Cleaning Supplies Store (8.26 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00A/R0009/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00A - R0023 - Interview/Office - Type 1 (8.4 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00A/R0009/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00A - R0024 - Clinic-Waiting (8.37 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00A/R0009/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00A - R0025 - Movement (15.65 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00A/R0009/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00A - R0027 - External Stairs (1.06 m2)</b>						
No Asbestos						
<b>B00A - R0028 - External Stairs (0.95 m2)</b>						
No Asbestos						
<b>B00A - R0029 - General Storeroom (8.81 m2)</b>						
No Asbestos						
<b>B00A - R0030 - Movement (23.88 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00A/R0009/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00A - R0031 - Staff Study (12.12 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00A/R0009/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00A - R0032 - Staff Study (12.12 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00A/R0009/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00A - R0034 - Toilet - Lobby (2.13 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite	8418/B00A/R0015/Ceiling Structures/Linings/S28				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0035 - Toilet - Lobby (2.14 m2)</b>						
Ceiling Structures/Linings	Vermiculite	8418/B00A/R0015/Ceiling Structures/Linings/S28				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0036 - Staff - Toilet (1.45 m2)</b>						
Ceiling Structures/Linings	Vermiculite	8418/B00A/R0015/Ceiling Structures/Linings/S28				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0037 - Careers Advisers Office (26.75 m2)</b>						
Ceiling Structures/Linings	Vermiculite	8418/B00A/R0015/Ceiling Structures/Linings/S28				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0038 - Interview/Meeting (12.72 m2)</b>						
Ceiling Structures/Linings	Vermiculite	8418/B00A/R0015/Ceiling Structures/Linings/S28				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0039 - Public Reception (38.74 m2)</b>						
Ceiling Structures/Linings	Vermiculite	8418/B00A/R0015/Ceiling Structures/Linings/S28				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0040 - Staff - Toilet (1.46 m2)</b>						
Ceiling Structures/Linings	Vermiculite	8418/B00A/R0015/Ceiling Structures/Linings/S28				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0042 - Uniform Shop (16.33 m2)</b>						
Ceiling Structures/Linings	Vermiculite	8418/B00A/R0047/Ceiling Structures/Linings/S55				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0044 - Administration - Clerical (42.55 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	8418/B00A/R0044/Floor Coverings Res/Textile/S52				No Asbestos Detected
Ceiling Structures/Linings	Vermiculite	8418/B00A/R0047/Ceiling Structures/Linings/S55				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0045 - Printing/Photocopying (11.82 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	8418/B00A/R0044/Floor Coverings Res/Textile/S52				No Asbestos Detected
<b>B00A - R0046 - Printing/Photocopying (14.79 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	8418/B00A/R0044/Floor Coverings Res/Textile/S52				No Asbestos Detected
<b>B00A - R0047 - External Movement (187.44 m2)</b>						
Ceiling Structures/Linings	Vermiculite	8418/B00A/R0047/Ceiling Structures/Linings/S55				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R1003 - Computer Store (9.46 m2)</b>						
Ceiling Structures/Linings	Vermiculite	8418/B00A/R0009/Ceiling Structures/Linings/S1				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Adhesive					
	8418/B00A/R1010/Floor Coverings Res/Textile/S32					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	9.46m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00A/R1010/Floor Coverings Res/Textile/S31					<b>Chrysotile (white asbestos)</b>
<b>B00A - R1004 - Staff Study (19.33 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00A/R0009/Ceiling Structures/Linings/S1					<b>Limited Samples Taken</b>
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Adhesive					
	8418/B00A/R1010/Floor Coverings Res/Textile/S32					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	1.32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00A/R1010/Floor Coverings Res/Textile/S31					<b>Chrysotile (white asbestos)</b>
<b>B00A - R1005 - General Learning Space (52.71 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00A/R0009/Ceiling Structures/Linings/S1					<b>Limited Samples Taken</b>
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Adhesive					
	8418/B00A/R1010/Floor Coverings Res/Textile/S32					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	52.71m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00A/R1010/Floor Coverings Res/Textile/S31					<b>Chrysotile (white asbestos)</b>
<b>B00A - R1006 - Art Learning Space (86 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	81m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00A/R0016/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite					
	8418/B00A/R0009/Ceiling Structures/Linings/S1					<b>Limited Samples Taken</b>
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Adhesive					
	8418/B00A/R1010/Floor Coverings Res/Textile/S32					<b>No Asbestos Detected</b>
<b>B00A - R1007 - Music Learning Space (53.51 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00A/R0009/Ceiling Structures/Linings/S1					<b>Limited Samples Taken</b>
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Adhesive					
	8418/B00A/R1010/Floor Coverings Res/Textile/S32					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00A/R1010/Floor Coverings Res/Textile/S31					<b>Chrysotile (white asbestos)</b>
<b>B00A - R1008 - Distribution Board Cupboard (0.91 m2)</b>						
No Asbestos				Note: No inspection of live electrical installation.		
<b>B00A - R1009 - General Learning Space (59.08 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00A/R0009/Ceiling Structures/Linings/S1					<b>Limited Samples Taken</b>
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Adhesive					
	8418/B00A/R1010/Floor Coverings Res/Textile/S32					<b>No Asbestos Detected</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	59.07m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8418/B00A/R1010/Floor Coverings Res/Textile/S31				<b>Chrysotile (white asbestos)</b>		
<b>B00A - R1010 - General Learning Space (52.56 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
8418/B00A/R0009/Ceiling Structures/Linings/S1				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	52.56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8418/B00A/R1010/Floor Coverings Res/Textile/S31				<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
8418/B00A/R1010/Floor Coverings Res/Textile/S32						
<b>B00A - R1011 - General Learning Space (52.78 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
8418/B00A/R0009/Ceiling Structures/Linings/S1				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
8418/B00A/R1010/Floor Coverings Res/Textile/S32						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	52.78m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8418/B00A/R1010/Floor Coverings Res/Textile/S31				<b>Chrysotile (white asbestos)</b>		
<b>B00A - R1012 - General Learning Space (59.05 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
8418/B00A/R0009/Ceiling Structures/Linings/S1				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
8418/B00A/R1010/Floor Coverings Res/Textile/S32						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	5.05m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8418/B00A/R1010/Floor Coverings Res/Textile/S31				<b>Chrysotile (white asbestos)</b>		
<b>B00A - R1013 - Distribution Board Cupboard (0.91 m2)</b>						
Electrical Backing Board	Resinous Board	1m2	North, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8418/B00A/R1013/Electrical Backing Board/S30				<b>Chrysotile (white asbestos)</b>		
<b>B00A - R1014 - Music Learning Space (53.74 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
8418/B00A/R0009/Ceiling Structures/Linings/S1				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
8418/B00A/R1010/Floor Coverings Res/Textile/S32						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53.73m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8418/B00A/R1010/Floor Coverings Res/Textile/S31				<b>Chrysotile (white asbestos)</b>		
<b>B00A - R1015 - Darkroom Space (12.78 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
8418/B00A/R0009/Ceiling Structures/Linings/S1				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
8418/B00A/R1010/Floor Coverings Res/Textile/S32						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	12.78m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8418/B00A/R1010/Floor Coverings Res/Textile/S31				<b>Chrysotile (white asbestos)</b>		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R1016 - Leading Teacher (12.82 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00A/R0009/Ceiling Structures/Linings/S1					<b>Limited Samples Taken</b>
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Adhesive					
	8418/B00A/R1010/Floor Coverings Res/Textile/S32					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	12.82m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00A/R1010/Floor Coverings Res/Textile/S31					<b>Chrysotile (white asbestos)</b>
<b>B00A - R1017 - External Movement (127.91 m2)</b>						
No Asbestos						
<b>B00A - R1018 - External Stairs (6.45 m2)</b>						
No Asbestos						
<b>B00A - R1019 - External Stairs (6.42 m2)</b>						
No Asbestos						
<b>B00A - R1020 - Commonroom (75.63 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	76m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00A/R1020/Floor Coverings Res/Textile/S53					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles	76m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00A/R1020/Floor Coverings Res/Textile/S53					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles	76m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00A/R1020/Floor Coverings Res/Textile/S53					<b>Chrysotile (white asbestos)</b>
<b>B00A - R1021 - Movement (6.19 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00A/R1020/Floor Coverings Res/Textile/S53					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00A/R1020/Floor Coverings Res/Textile/S53					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00A/R1020/Floor Coverings Res/Textile/S53					<b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00B - Technological & Applied Studies/Art - 1964 - Brick/Block (Brick/Block)****Exterior**

Sun screens	Compressed AC Sheet	100m2	East, West, Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00B/Sun screens/S9					<b>Chrysotile (white asbestos)</b>
Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible					
Ceiling Voids	Non Accessible Area					
	- Area inaccessible					

**Interior****B00B - R0003 - Staff - Toilet (3.64 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00B - R0004 - Staff - Toilet (3.76 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00B - R0005 - General Storeroom (2.55 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00B - R0006 - Art Learning Space (53.44 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00B - R0008 - Distribution Board Cupboard (0.84 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0009 - Food Technology L.S. (72.67 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00B - R0010 - Food/Research Space (26.02 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00B - R0011 - Food Technology L.S. (66.12 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00B - R0012 - Resource/Project Store (17.01 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00B - R0013 - Pantry (11.4 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00B/R0013/Floor Coverings Res/Textile/S12					<b>Chrysotile (white asbestos)</b>

**B00B - R0014 - Laundry (29.74 m2)**



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8418/B00B/R0001/Ceiling Structures/Linings/S10					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 8418/B00B/R0013/Floor Coverings Res/Textile/S12	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00B - R0015 - Distribution Board Cupboard (0.91 m2)</b>				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B00B - R0016 - Staff Study (26.98 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00B/R0001/Ceiling Structures/Linings/S10					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00B - R0017 - Materials Technology L.S. (92.44 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00B/R0001/Ceiling Structures/Linings/S10					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00B - R0018 - Dust Extraction Space (3.37 m2)</b>						
No Asbestos						
<b>B00B - R0019 - Resource/Project Store (6.54 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00B/R0001/Ceiling Structures/Linings/S10					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 8418/B00B/R0013/Floor Coverings Res/Textile/S12	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00B - R0020 - General Storeroom (8.65 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00B/R0001/Ceiling Structures/Linings/S10					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 8418/B00B/R0013/Floor Coverings Res/Textile/S12	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00B - R0024 - General Storeroom (12.8 m2)</b>						
No Asbestos						
<b>B00B - R0025 - External Stairs (1.4 m2)</b>						
No Asbestos						
<b>B00B - R0026 - External Stairs (1.13 m2)</b>						
No Asbestos						
<b>B00B - R0027 - External Movement (145.71 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00B/R0001/Ceiling Structures/Linings/S10					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00B - R0028 - Movement (3.19 m2)</b>						
No Asbestos						
<b>B00B - R0029 - Lift (2.25 m2)</b>						
No Asbestos						
<b>B00B - R0030 - General Storeroom (13.4 m2)</b>						
No Asbestos						
<b>B00B - R0031 - Materials Store - Type 1 (12.96 m2)</b>						
Recently Modified Space	Requires Inspection					
<b>B00B - R0032 - Workshop Area (121.26 m2)</b>						
Recently Modified Space	Requires Inspection					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R0033 - Welding Area (6.36 m2)</b>						
Recently Modified Space	Requires Inspection					
<b>B00B - R0034 - Welding Area (4 m2)</b>						
Recently Modified Space	Requires Inspection					
<b>B00B - R0035 - Welding Area (3.9 m2)</b>						
Recently Modified Space	Requires Inspection					
<b>B00B - R0036 - Distribution Board Cupboard (1.28 m2)</b>					Note: No inspection of live electrical installation.	
Recently Modified Space	Requires Inspection					
<b>B00B - R1001 - Resource/Project Store (12.34 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10				<b>Limited Samples Taken</b>	
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00B/R0013/Floor Coverings Res/Textile/S12				<b>Chrysotile (white asbestos)</b>	
<b>B00B - R1002 - Dust Extraction Space (2.98 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	8418/B00B/R1020/Floor Coverings Res/Textile/S34				<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles	2.98m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00B/R1020/Floor Coverings Res/Textile/S33				<b>Chrysotile (white asbestos)</b>	
<b>B00B - R1003 - Materials Store (15.87 m2)</b>						
Sheeting	Flat AC Sheeting					
	8418/B00B/R1003/Sheeting/S13				<b>No Asbestos Detected</b>	
<b>B00B - R1004 - Secure Storeroom (6.46 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00B/R0013/Floor Coverings Res/Textile/S12				<b>Chrysotile (white asbestos)</b>	
<b>B00B - R1005 - Computer Learning Space (51.02 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10				<b>Limited Samples Taken</b>	
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Adhesive					
	8418/B00B/R1020/Floor Coverings Res/Textile/S34				<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles	51.02m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00B/R1020/Floor Coverings Res/Textile/S33				<b>Chrysotile (white asbestos)</b>	
<b>B00B - R1006 - General Storeroom (6.75 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10				<b>Limited Samples Taken</b>	
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00B/R0013/Floor Coverings Res/Textile/S12				<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive					
	8418/B00B/R1020/Floor Coverings Res/Textile/S34				<b>No Asbestos Detected</b>	
<b>B00B - R1007 - Cleaning Store - Distributed (6.62 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10				<b>Limited Samples Taken</b>	
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Adhesive					
	8418/B00B/R1020/Floor Coverings Res/Textile/S34					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles	6.62m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00B/R1020/Floor Coverings Res/Textile/S33					<b>Chrysotile (white asbestos)</b>
<b>B00B - R1008 - Distribution Board Cupboard (0.88 m2)</b>				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B00B - R1009 - Design L.S. (59.13 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
Floor Coverings Res/Textile	Adhesive					
	8418/B00B/R1020/Floor Coverings Res/Textile/S34					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles	59.13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00B/R1020/Floor Coverings Res/Textile/S33					<b>Chrysotile (white asbestos)</b>
<b>B00B - R1010 - Staff Study (25.77 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
Floor Coverings Res/Textile	Adhesive					
	8418/B00B/R1020/Floor Coverings Res/Textile/S34					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles	25.77m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00B/R1020/Floor Coverings Res/Textile/S33					<b>Chrysotile (white asbestos)</b>
<b>B00B - R1013 - Kiln Space (21 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
Floor Coverings Res/Textile	Vinyl Tiles	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00B/R0013/Floor Coverings Res/Textile/S12					<b>Chrysotile (white asbestos)</b>
<b>B00B - R1014 - Bulk Store (10.83 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00B/R0013/Floor Coverings Res/Textile/S12					<b>Chrysotile (white asbestos)</b>
<b>B00B - R1015 - Distribution Board Cupboard (0.91 m2)</b>				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B00B - R1016 - Design L.S. (67.12 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B00B - R1017 - General Storeroom (6.33 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B00B - R1018 - Materials Store (6.11 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R0001/Ceiling Structures/Linings/S10					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8418/B00B/R0013/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)	
<b>B00B - R1019 - Materials Technology L.S. (79.89 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8418/B00B/R0001/Ceiling Structures/Linings/S10					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B00B - R1020 - Resource/Project Store (12.26 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8418/B00B/R0001/Ceiling Structures/Linings/S10					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles	12.25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8418/B00B/R1020/Floor Coverings Res/Textile/S33					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
8418/B00B/R1020/Floor Coverings Res/Textile/S34						
<b>B00B - R1021 - Welding Store (16.66 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8418/B00B/R0001/Ceiling Structures/Linings/S10					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B00B - R1022 - Welding Area (3.31 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8418/B00B/R0001/Ceiling Structures/Linings/S10					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B00B - R1025 - Materials Technology L.S. (87.57 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8418/B00B/R0001/Ceiling Structures/Linings/S10					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B00B - R1026 - External Movement (133.17 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8418/B00B/R0001/Ceiling Structures/Linings/S10					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B00B - R1027 - External Stairs (6.72 m2)</b>						
No Asbestos						
<b>B00B - R1028 - External Stairs (6.67 m2)</b>						
No Asbestos						
<b>B00B - R1029 - Movement (3.18 m2)</b>						
No Asbestos						
<b>B00B - R1030 - Lift (2.25 m2)</b>						
No Asbestos						
<b>B00B - R1031 - General Learning Space (85.2 m2)</b>						
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
8418/B00B/R1020/Floor Coverings Res/Textile/S34						
Floor Coverings Res/Textile	Vinyl Tiles	85.19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8418/B00B/R1020/Floor Coverings Res/Textile/S33					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8418/B00B/R0001/Ceiling Structures/Linings/S10					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B00B - R1032 - Staff Study (20.19 m2)</b>						
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
8418/B00B/R1020/Floor Coverings Res/Textile/S34						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	20.19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00B/R1020/Floor Coverings Res/Textile/S33				<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Vermiculite					
	8418/B00B/R1032/Ceiling Structures/Linings/S35				<b>Limited Samples Taken</b>	
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Pupil Facilities/Building Services - 1964 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting 8418/B00C/Eaves Linings/S5	6m2	West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids	No Asbestos Found					

**Interior****B00C - R0003 - Movement (21.98 m2)**

No Asbestos

**B00C - R0004 - General Storeroom (15.76 m2)**

No Asbestos

**B00C - R0005 - Staff - Toilet (5.4 m2)**

Ceiling Structures/Linings	Vermiculite 8418/B00C/R0011/Ceiling Structures/Linings/S4					<b>Limited Samples Taken</b> <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	--	--	--	--	--	---

**B00C - R0006 - Cleaning Store - Distributed (1.69 m2)**

No Asbestos

**B00C - R0007 - Garden Store Room (14.06 m2)**

No Asbestos

**B00C - R0008 - Distribution Board Cupboard (0.2 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00C - R0009 - General Storeroom (1.86 m2)**

No Asbestos

**B00C - R0010 - General Storeroom (19.72 m2)**

No Asbestos

**B00C - R0011 - Movement (20.41 m2)**

Ceiling Structures/Linings	Vermiculite 8418/B00C/R0011/Ceiling Structures/Linings/S4					<b>Limited Samples Taken</b> <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	--	--	--	--	--	---

Stored wall lining	Flat AC Sheeting 8418/B00C/R0011/Stored wall lining/S36					<b>No Asbestos Detected</b>
--------------------	--	--	--	--	--	-----------------------------

**B00C - R0012 - External Movement (3.84 m2)**

No Asbestos

**B00C - R0013 - General Assistants (12.91 m2)**

No Asbestos

**B00C - R0014 - Student Canteen (58.65 m2)**

Ceiling Structures/Linings	Vermiculite 8418/B00C/R0011/Ceiling Structures/Linings/S4					<b>Limited Samples Taken</b> <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	--	--	--	--	--	---

**B00C - R0015 - Office/Store (3.63 m2)**

No Asbestos

**B00C - R0017 - Maintenance Bulk Store (5.79 m2)**

No Asbestos

**B00C - R0018 - Cleaning Supplies Store (7.31 m2)**

No Asbestos

**B00C - R0019 - Cleaning Store - Distributed (6.16 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00C - R0020 - Movement (21.6 m2)</b>						
No Asbestos						
<b>B00C - R0021 - Sport Equipment Store (7.84 m2)</b>						
No Asbestos						
<b>B00C - R0023 - External Movement (59.85 m2)</b>						
No Asbestos						
<b>B00C - R0024 - Covered Area (296.96 m2)</b>						
No Asbestos						
<b>B00C - R0025 - Sport Equipment Store (21.7 m2)</b>						
No Asbestos						
<b>B00C - R0026 - Stairs (0.69 m2)</b>						
No Asbestos						
<b>B00C - R0027 - Stairs (0.75 m2)</b>						
No Asbestos						
<b>B00C - R0028 - Staff - Toilet (1.32 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
			8418/B00C/R0011/Ceiling Structures/Linings/S4			<b>Limited Samples Taken</b>
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00C - R0029 - Toilet - Lobby (1.09 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
			8418/B00C/R0011/Ceiling Structures/Linings/S4			<b>Limited Samples Taken</b>
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00C - R0030 - Movement (1.57 m2)</b>						
No Asbestos						
<b>B00C - R0031 - External Movement (5.26 m2)</b>						
No Asbestos						
<b>B00C - R0032 - Sport Equipment Store (30.16 m2)</b>						
No Asbestos						
<b>B00C - R0033 - Sport Equipment Store (20.07 m2)</b>						
No Asbestos						
<b>B00C - R0034 - Workshop Area (127.83 m2)</b>						
Recently Modified Space	Requires Inspection					
<b>B00C - R1001 - Movement (9 m2)</b>						
No Asbestos						
<b>B00C - R1002 - Staff Shower (7.72 m2)</b>						
Floor Coverings Res/Textile	Vinyl Sheet					
			8418/B00C/R1002/Floor Coverings Res/Textile/S6			<b>No Asbestos Detected</b>
<b>B00C - R1003 - Toilets-Girls (34.38 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
			8418/B00C/R1003/Partition Walls (Cubicles)/S7			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B00C - R1004 - Shower/Change (39.09 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
			8418/B00C/R1003/Partition Walls (Cubicles)/S7			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B00C - R1005 - Shower/Change (38.41 m2)</b>						
Insulation to Pipework	Encapsulated Insulation material within unit					
			8418/B00C/R1005/Insulation to Pipework/S8			<b>No Asbestos Detected</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Floor Coverings Res/Textile Vinyl Sheet  
 8418/B00C/R1002/Floor Coverings Res/Textile/S6 **No Asbestos Detected**

**B00C - R1006 - Toilets-Boys (36.42 m2)**

Partition Walls (Cubicles) Compressed AC Sheet 16m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)  
 8418/B00C/R1003/Partition Walls (Cubicles)/S7 **Chrysotile (white asbestos) , Amosite (brown asbestos)**

**B00C - R1007 - Staff Shower (7.72 m2)**

Floor Coverings Res/Textile Vinyl Sheet  
 8418/B00C/R1002/Floor Coverings Res/Textile/S6 **No Asbestos Detected**

**B00C - R1008 - Movement (8.89 m2)**

No Asbestos

**B00C - R1009 - Stairs (13.74 m2)**

No Asbestos

**B00C - R1010 - Stairs (13.77 m2)**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning/Science - 1964 - Brick/Block (Brick/Block)****Exterior**

Sun screens	Compressed AC Sheet	60m2	East, West, Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00D/Sun screens/S14					<b>Chrysotile (white asbestos)</b>
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	Non Accessible Area - Area inaccessible					

**Interior****B00D - R0001 - Laboratory L.S. (86.05 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00D/R0022/Ceiling Structures/Linings/S15					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00D - R0002 - Distribution Board Cupboard (0.91 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0003 - Laboratory L.S. (75.78 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00D/R0022/Ceiling Structures/Linings/S15					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00D - R0008 - Staff - Toilet (4.76 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00D/R0022/Ceiling Structures/Linings/S15					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00D - R0009 - General Storeroom (3.38 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00D/R0022/Ceiling Structures/Linings/S15					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00D - R0010 - Staff - Toilet (4.8 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00D/R0022/Ceiling Structures/Linings/S15					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00D - R0011 - Toilets-Girls (36.57 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00D/R0022/Ceiling Structures/Linings/S15					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Partition Walls (Cubicles)	Compressed AC Sheet	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00D/R0012/Partition Walls (Cubicles)/S19					<b>Chrysotile (white asbestos)</b>

**B00D - R0012 - Toilets-Boys (28.55 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00D/R0012/Partition Walls (Cubicles)/S19					<b>Chrysotile (white asbestos)</b>

Ceiling Structures/Linings	Vermiculite					
	8418/B00D/R0022/Ceiling Structures/Linings/S15					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00D - R0014 - General Learning Space (65.23 m2)**

Ceiling Structures/Linings	Vermiculite					
	8418/B00D/R0022/Ceiling Structures/Linings/S15					<b>Limited Samples Taken</b>
						<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00D - R0015 - Distribution Board Cupboard (0.87 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0016 - Laboratory L.S. (99.7 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	8418/B00D/R0022/Ceiling Structures/Linings/S15					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
<b>B00D - R0017 - Preparation (28.74 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00D/R0022/Ceiling Structures/Linings/S15					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles	29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00D/R0021/Floor Coverings Res/Textile/S16					Chrysotile (white asbestos)
Fume Cupboard	Flat AC Sheeting	2Unit	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00D/R0017/Fume Cupboard/S17					Chrysotile (white asbestos)
<b>B00D - R0018 - Growing/Breeding (10.17 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00D/R0022/Ceiling Structures/Linings/S15					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
<b>B00D - R0019 - External Movement (171.06 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00D/R0022/Ceiling Structures/Linings/S15					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
In-fill-panel	Flat AC Sheeting	1m	North, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00D/R0019/In-fill-panel/S18					Chrysotile (white asbestos)
<b>B00D - R0020 - External Stairs (1.22 m2)</b>						
No Asbestos						
<b>B00D - R0023 - External Stairs (1.48 m2)</b>						
No Asbestos						
<b>B00D - R0025 - Staff Study (15.05 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00D/R0022/Ceiling Structures/Linings/S15					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	15.05m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00D/R0026/Floor Coverings Res/Textile/S42					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	8418/B00D/R0026/Floor Coverings Res/Textile/S43					No Asbestos Detected
<b>B00D - R0026 - Staff Study (10.65 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00D/R0022/Ceiling Structures/Linings/S15					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	10.65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00D/R0026/Floor Coverings Res/Textile/S42					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	8418/B00D/R0026/Floor Coverings Res/Textile/S43					No Asbestos Detected
<b>B00D - R0027 - Toilets-Boys (13.91 m2)</b>						
Wall Linings Internal	Flat AC Sheeting					
	8418/B00D/R0028/Wall Linings Internal/S41					No Asbestos Detected
Ceiling Structures/Linings	Vermiculite					
	8418/B00D/R0022/Ceiling Structures/Linings/S15					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
<b>B00D - R0028 - Toilets-Girls (26.52 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting 8418/B00D/R0028/Wall Linings Internal/S41					No Asbestos Detected
Ceiling Structures/Linings	Vermiculite 8418/B00D/R0022/Ceiling Structures/Linings/S15					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00D - R0029 - Cleaning Store - Distributed (17.15 m2)</b>						
Wall Linings Internal	Flat AC Sheeting 8418/B00D/R0028/Wall Linings Internal/S41					No Asbestos Detected
Ceiling Structures/Linings	Vermiculite 8418/B00D/R0022/Ceiling Structures/Linings/S15					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00D - R0030 - Plant (4.76 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00D/R0022/Ceiling Structures/Linings/S15					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00D - R0031 - Plant (4.51 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00D/R0022/Ceiling Structures/Linings/S15					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00D - R0032 - External Movement (17.99 m2)</b>						
No Asbestos						
<b>B00D - R0033 - Commonroom (32.38 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00A/R0047/Ceiling Structures/Linings/S55					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8418/B00E/R1040/Floor Coverings Res/Textile/S54					No Asbestos Detected
<b>B00D - R1001 - Computer Learning Space (59.31 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00D/R0022/Ceiling Structures/Linings/S15					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Adhesive 8418/B00D/R0026/Floor Coverings Res/Textile/S43					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8418/B00D/R0026/Floor Coverings Res/Textile/S42	59.3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00D - R1002 - Distribution Board Cupboard (0.9 m2)</b> <span style="float: right;">Note: No inspection of live electrical installation.</span>						
Electrical Backing Board	Resinous Board 8418/B00D/R1002/Electrical Backing Board/S44	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00D - R1003 - Staff Study (53.88 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00D/R0022/Ceiling Structures/Linings/S15					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Adhesive 8418/B00D/R0026/Floor Coverings Res/Textile/S43					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8418/B00D/R0026/Floor Coverings Res/Textile/S42	53.87m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00D - R1004 - General Storeroom (5.15 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8418/B00D/R0022/Ceiling Structures/Linings/S15					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles 8418/B00D/R0021/Floor Coverings Res/Textile/S16	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00D - R1005 - Staff Study (12.44 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00D/R0022/Ceiling Structures/Linings/S15					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Adhesive 8418/B00D/R0026/Floor Coverings Res/Textile/S43					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8418/B00D/R0026/Floor Coverings Res/Textile/S42	12.44m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00D - R1006 - General Learning Space (59.13 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00D/R0022/Ceiling Structures/Linings/S15					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Adhesive 8418/B00D/R0026/Floor Coverings Res/Textile/S43					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8418/B00D/R0026/Floor Coverings Res/Textile/S42	59.13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00D - R1007 - General Learning Space (52.56 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00D/R0022/Ceiling Structures/Linings/S15					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Adhesive 8418/B00D/R0026/Floor Coverings Res/Textile/S43					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8418/B00D/R0026/Floor Coverings Res/Textile/S42	52.56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00D - R1008 - General Learning Space (52.64 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00D/R0022/Ceiling Structures/Linings/S15					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Adhesive 8418/B00D/R0026/Floor Coverings Res/Textile/S43					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8418/B00D/R0026/Floor Coverings Res/Textile/S42	52.63m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00D - R1009 - General Learning Space (58.98 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00D/R0022/Ceiling Structures/Linings/S15					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Adhesive 8418/B00D/R0026/Floor Coverings Res/Textile/S43					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8418/B00D/R0026/Floor Coverings Res/Textile/S42	58.98m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00D - R1010 - Secure Storeroom (10.41 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00D - R1011 - General Learning Space (65.23 m2)**

Ceiling Structures/Linings Vermiculite  
 8418/B00D/R0022/Ceiling Structures/Linings/S15 **Limited Samples Taken**  
*Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works*

Floor Coverings Res/Textile Adhesive  
 8418/B00D/R0026/Floor Coverings Res/Textile/S43 **No Asbestos Detected**

Floor Coverings Res/Textile Vinyl Tiles (Under Floor Covering/Carpet) 65.2m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)  
 8418/B00D/R0026/Floor Coverings Res/Textile/S42 **Chrysotile (white asbestos)**

**B00D - R1012 - Distribution Board Cupboard (0.91 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R1013 - General Learning Space (59.21 m2)**

Ceiling Structures/Linings Vermiculite  
 8418/B00D/R0022/Ceiling Structures/Linings/S15 **Limited Samples Taken**  
*Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works*

Floor Coverings Res/Textile Adhesive  
 8418/B00D/R0026/Floor Coverings Res/Textile/S43 **No Asbestos Detected**

Floor Coverings Res/Textile Vinyl Tiles (Under Floor Covering/Carpet) 59.21m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)  
 8418/B00D/R0026/Floor Coverings Res/Textile/S42 **Chrysotile (white asbestos)**

**B00D - R1014 - General Learning Space (52.63 m2)**

Ceiling Structures/Linings Vermiculite  
 8418/B00D/R0022/Ceiling Structures/Linings/S15 **Limited Samples Taken**  
*Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works*

Floor Coverings Res/Textile Adhesive  
 8418/B00D/R0026/Floor Coverings Res/Textile/S43 **No Asbestos Detected**

Floor Coverings Res/Textile Vinyl Tiles (Under Floor Covering/Carpet) 52.63m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)  
 8418/B00D/R0026/Floor Coverings Res/Textile/S42 **Chrysotile (white asbestos)**

**B00D - R1015 - Computer Learning Space (52.71 m2)**

Ceiling Structures/Linings Vermiculite  
 8418/B00D/R0022/Ceiling Structures/Linings/S15 **Limited Samples Taken**  
*Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works*

Floor Coverings Res/Textile Vinyl Tiles (Under Floor Covering/Carpet) 52.71m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)  
 8418/B00D/R0026/Floor Coverings Res/Textile/S42 **Chrysotile (white asbestos)**

Floor Coverings Res/Textile Adhesive  
 8418/B00D/R0026/Floor Coverings Res/Textile/S43 **No Asbestos Detected**

**B00D - R1016 - External Movement (146.83 m2)**

No Asbestos

**B00D - R1017 - External Stairs (5.96 m2)**

No Asbestos

**B00D - R1018 - External Stairs (5.84 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning/Science Learning - 1968 - Brick/Block (Brick/Block)**

**Exterior**

Sun screens	Compressed AC Sheet	100m2	East, West, Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00E/Sun screens/S20					<b>Chrysotile (white asbestos)</b>
Ceiling Voids	Non Accessible Area - Area inaccessible					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

**Interior**

**B00E - R0001 - Laboratory L.S. (85.9 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8418/B00E/R0009/Ceiling Structures/Linings/S21					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00E - R0002 - General Storeroom (2.77 m2)**

No Asbestos

**B00E - R0003 - Distribution Board Cupboard (1.3 m2)**

Note: No inspection of live electrical installation.

In-fill-panel	Flat AC Sheeting	5m	Back of door / on ground	Poor Condition (4)	Low (1)	Low Priority (2-3)
	8418/B00E/R0003/In-fill-panel/S23					<b>Chrysotile (white asbestos)</b>

**B00E - R0004 - General Storeroom (13.45 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					<b>No Asbestos Detected</b>
	8418/B00E/R0009/Ceiling Structures/Linings/S21					
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8418/B00E/R0009/Ceiling Structures/Linings/S21					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00E - R0005 - General Learning Space (50.37 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8418/B00E/R0009/Ceiling Structures/Linings/S21					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00E - R0006 - Apparatus Store (18.89 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8418/B00E/R0009/Ceiling Structures/Linings/S21					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00E - R0007 - General Storeroom (6.37 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8418/B00E/R0009/Ceiling Structures/Linings/S21					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00E - R0011 - Secure Storeroom (5.91 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8418/B00E/R0044/Ceiling Structures/Linings/S38					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00E - R0014 - General Learning Space (53.66 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8418/B00E/R0009/Ceiling Structures/Linings/S21					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00E - R0015 - General Learning Space (52.78 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8418/B00E/R0009/Ceiling Structures/Linings/S21					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B00E - R0020 - Distribution Board Cupboard (1.3 m2)**

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
In-fill-panel	Flat AC Sheeting	6m	Back of door / on ground	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8418/B00E/R0003/In-fill-panel/S23					Chrysotile (white asbestos)	
<b>B00E - R0021 - Staff - Toilet (2.77 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8418/B00E/R0009/Ceiling Structures/Linings/S21					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B00E - R0022 - General Learning Space (58.99 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8418/B00E/R0009/Ceiling Structures/Linings/S21					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B00E - R0023 - General Learning Space (52.42 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8418/B00E/R0009/Ceiling Structures/Linings/S21					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B00E - R0024 - General Storeroom (25.84 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
8418/B00E/R0009/Ceiling Structures/Linings/S21						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8418/B00E/R0009/Ceiling Structures/Linings/S21					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B00E - R0025 - Laboratory L.S. (92.42 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8418/B00E/R0009/Ceiling Structures/Linings/S21					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B00E - R0029 - General Storeroom (6.03 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8418/B00E/R0009/Ceiling Structures/Linings/S21					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B00E - R0030 - Toilets-Disabled (6.46 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8418/B00E/R0009/Ceiling Structures/Linings/S21					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B00E - R0031 - Clinic - Girls (15.11 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8418/B00E/R0009/Ceiling Structures/Linings/S21					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B00E - R0032 - Clinic - Boys (14.65 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8418/B00E/R0009/Ceiling Structures/Linings/S21					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B00E - R0033 - Laundry (7.12 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8418/B00E/R0009/Ceiling Structures/Linings/S21					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B00E - R0034 - Movement (14.63 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8418/B00E/R0009/Ceiling Structures/Linings/S21					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B00E - R0035 - Clinic-Toilets (2.73 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8418/B00E/R0009/Ceiling Structures/Linings/S21					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B00E - R0036 - Secure Storeroom (2.86 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	8418/B00E/R0009/Ceiling Structures/Linings/S21					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R0037 - Special Learning Space (59.04 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00E/R0009/Ceiling Structures/Linings/S21					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R0038 - Staff Study (32.8 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00E/R0009/Ceiling Structures/Linings/S21					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R0039 - External Movement (240.36 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00E/R0009/Ceiling Structures/Linings/S21					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R0040 - External Stairs (0.75 m2)</b>						
No Asbestos						
<b>B00E - R0041 - Stairs (0.45 m2)</b>						
No Asbestos						
<b>B00E - R0042 - General Storeroom (4.12 m2)</b>						
No Asbestos						
<b>B00E - R0043 - External Stairs (0.73 m2)</b>						
No Asbestos						
<b>B00E - R0045 - Computer Learning Space (52.78 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00E/R0044/Ceiling Structures/Linings/S38					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Adhesive					
	8418/B00E/R0044/Floor Coverings Res/Textile/S39					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	52.7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00E/R0044/Floor Coverings Res/Textile/S37					Chrysotile (white asbestos)
<b>B00E - R0046 - Preparation - Science (37.31 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00E/R0009/Ceiling Structures/Linings/S21					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R0047 - Computer Resource (6.2 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00E/R0044/Ceiling Structures/Linings/S38					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Adhesive					
	8418/B00E/R0044/Floor Coverings Res/Textile/S39					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	6.1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00E/R0044/Floor Coverings Res/Textile/S37					Chrysotile (white asbestos)
<b>B00E - R0048 - General Learning Space (47.22 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8418/B00A/R0044/Floor Coverings Res/Textile/S52					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8418/B00A/R0044/Floor Coverings Res/Textile/S52					No Asbestos Detected



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Vermiculite					
	8418/B00A/R0047/Ceiling Structures/Linings/S55					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1001 - General Learning Space (59.14 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00E/R0009/Ceiling Structures/Linings/S21					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1002 - Cleaning Store - Distributed (2.77 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00E/R0009/Ceiling Structures/Linings/S21					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1003 - Distribution Board Cupboard (1.42 m2)</b>						
				Note: No inspection of live electrical installation.		
Electrical Backing Board	Resinous Board	1m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8418/B00E/R1003/Electrical Backing Board/S40					Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting	6m	Back of door / on ground	Poor Condition (4)	Low (1)	Low Priority (2-3)
	8418/B00E/R0003/In-fill-panel/S23					Chrysotile (white asbestos)
<b>B00E - R1004 - General Learning Space (53.44 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00E/R0009/Ceiling Structures/Linings/S21					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1006 - Design L.S. (72.54 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00E/R0009/Ceiling Structures/Linings/S21					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1007 - Resource/Project Store (6.13 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8418/B00E/R0009/Ceiling Structures/Linings/S21					No Asbestos Detected
<b>B00E - R1008 - General Storeroom (6 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00E/R0009/Ceiling Structures/Linings/S21					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1009 - General Learning Space (53.73 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00E/R0009/Ceiling Structures/Linings/S21					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1010 - Staff Study (53.51 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00E/R0009/Ceiling Structures/Linings/S21					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1011 - General Learning Space (52.56 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00E/R0009/Ceiling Structures/Linings/S21					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1015 - General Learning Space (53.59 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8418/B00E/R0009/Ceiling Structures/Linings/S21					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1016 - Distribution Board Cupboard (1.28 m2)</b>						
				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B00E - R1017 - Staff - Toilet (2.77 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8418/B00E/R0009/Ceiling Structures/Linings/S21				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
<b>B00E - R1019 - General Learning Space (52.85 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00E/R0009/Ceiling Structures/Linings/S21				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
<b>B00E - R1020 - General Learning Space (52.93 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00E/R0009/Ceiling Structures/Linings/S21				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
<b>B00E - R1024 - General Storeroom (5.98 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00E/R0009/Ceiling Structures/Linings/S21				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
<b>B00E - R1025 - Study Space (25.95 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00E/R0009/Ceiling Structures/Linings/S21				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
<b>B00E - R1026 - General Learning Space (52.79 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00E/R0009/Ceiling Structures/Linings/S21				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
<b>B00E - R1028 - External Stairs (6.71 m2)</b>						
No Asbestos						
<b>B00E - R1029 - External Stairs (6.66 m2)</b>						
No Asbestos						
<b>B00E - R1030 - External Stairs (7.48 m2)</b>						
No Asbestos						
<b>B00E - R1031 - Staff Study (19.52 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00E/R0009/Ceiling Structures/Linings/S21				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
<b>B00E - R1032 - Staff Study (11.22 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00E/R0044/Ceiling Structures/Linings/S38				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
Floor Coverings Res/Textile	Adhesive 8418/B00E/R0044/Floor Coverings Res/Textile/S39				No Asbestos Detected	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8418/B00E/R0044/Floor Coverings Res/Textile/S37	11.22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
<b>B00E - R1033 - Interview/Office - Type 1 (14.31 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8418/B00E/R0044/Ceiling Structures/Linings/S38				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
Floor Coverings Res/Textile	Adhesive 8418/B00E/R0044/Floor Coverings Res/Textile/S39				No Asbestos Detected	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8418/B00E/R0044/Floor Coverings Res/Textile/S37	14.1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
<b>B00E - R1036 - General Storeroom (24.68 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite		8418/B00E/R0044/Ceiling Structures/Linings/S38			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1037 - External Movement (210.16 m2)</b>						
No Asbestos						
<b>B00E - R1038 - General Learning Space (79.17 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)		8418/B00E/R1040/Floor Coverings Res/Textile/S54			No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)		8418/B00E/R1040/Floor Coverings Res/Textile/S54			No Asbestos Detected
Ceiling Structures/Linings	Vermiculite		8418/B00A/R0047/Ceiling Structures/Linings/S55			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1039 - G.L.S. Store (5.33 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)		8418/B00E/R1040/Floor Coverings Res/Textile/S54			No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)		8418/B00E/R1040/Floor Coverings Res/Textile/S54			No Asbestos Detected
Ceiling Structures/Linings	Vermiculite		8418/B00A/R0047/Ceiling Structures/Linings/S55			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1040 - Commonroom (85.74 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)		8418/B00E/R1040/Floor Coverings Res/Textile/S54			No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)		8418/B00E/R1040/Floor Coverings Res/Textile/S54			No Asbestos Detected
Ceiling Structures/Linings	Vermiculite		8418/B00A/R0047/Ceiling Structures/Linings/S55			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - Room+1 - R1034</b>						
Ceiling Structures/Linings	Vermiculite		8418/B00E/R0009/Ceiling Structures/Linings/S21			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - Room+2 - R1035</b>						
Ceiling Structures/Linings	Vermiculite		8418/B00E/R0009/Ceiling Structures/Linings/S21			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - Room+3 - R1032</b>						
Ceiling Structures/Linings	Vermiculite		8418/B00E/R0009/Ceiling Structures/Linings/S21			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - Room+4 - R1033</b>						
Ceiling Structures/Linings	Vermiculite		8418/B00E/R0009/Ceiling Structures/Linings/S21			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - Room+5 - R0044</b>						
Ceiling Structures/Linings	Vermiculite		8418/B00E/R0009/Ceiling Structures/Linings/S21			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Multi Purpose Facilities - 1971 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	------	--------------------	--------------------	---------	--------------------

**Assumed Asbestos - Height Restriction**

Underfloor Voids - Slab on Ground	No Asbestos Found
-----------------------------------	-------------------

**Interior****B00F - M0001 - Movement (7.06 m2)**

No Asbestos

**B00F - M0002 - Control Room (7.79 m2)**

Electrical Backing Board	Resinous Board	1m2	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	-----	----------------------	--------------------	---------	--------------------

8418/B00F/M0002/Electrical Backing Board/S47

**Chrysotile (white asbestos)****B00F - M0003 - Stairs (5.08 m2)**

No Asbestos

**B00F - M0004 - Stairs (5.09 m2)**

No Asbestos

**B00F - R0002 - Movement (2 m2)**

No Asbestos

**B00F - R0003 - Multi-Purpose Space (453.16 m2)**

No Asbestos

**B00F - R0004 - Toilets-Boys (8.7 m2)**

In-fill-panel	Flat AC Sheeting	3m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	----	-------	--------------------	---------	--------------------

8418/B00F/R0004/In-fill-panel/S25

**Chrysotile (white asbestos)****B00F - R0005 - Toilets-Girls (4.52 m2)**

No Asbestos

**B00F - R0006 - Distribution Board Cupboard (0.46 m2)**

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	-----	----------------	--------------------	---------	--------------------

8418/B00F/M0002/Electrical Backing Board/S47

**Chrysotile (white asbestos)****B00F - R0007 - Movement (22.44 m2)**

No Asbestos

**B00F - R0008 - External Movement (9.14 m2)**

No Asbestos

**B00F - R0009 - Student Canteen (16.71 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	16.71m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------------	-------------	---------	------------	--------------------	---------	--------------------

8418/B00F/R0009/Floor Coverings Res/Textile/S48

**Chrysotile (white asbestos)****B00F - R0010 - Stairs (0.65 m2)**

No Asbestos

**B00F - R0011 - Stairs (0.65 m2)**

No Asbestos

**B00F - R0012 - External Movement (3.54 m2)**

No Asbestos

**B00F - R0014 - External Movement (3.3 m2)**

No Asbestos

**B00F - R0015 - External Movement (3.52 m2)**

No Asbestos

**B00F - R0016 - Movement (2 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

**B00F - R0017 - Stairs (0.65 m2)**

No Asbestos

**B00F - R0018 - Stairs (0.65 m2)**

No Asbestos

**B00F - R0019 - Stage (97.75 m2)**

No Asbestos

**B00F - R0020 - Control Room (1.5 m2)**

No Asbestos

**B00F - R0021 - External Movement (23.36 m2)**

No Asbestos

**B00F - R0022 - External Movement (38.97 m2)**

No Asbestos

**B00F - R9001 - Toilets-Boys (5.88 m2)**

No Asbestos

**B00F - R9002 - Movement (2.87 m2)**

No Asbestos

**B00F - R9003 - Darkroom Space (62.75 m2)**

No Asbestos

**B00F - R9004 - Movement (2.48 m2)**

No Asbestos

**B00F - R9005 - Toilets-Girls (5.62 m2)**

No Asbestos

**B00F - R9006 - Stairs (0.65 m2)**

No Asbestos

**B00F - R9007 - Stairs (0.65 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Library - 1984 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	Non Accessible Area - Area inaccessible

**Interior**

**B00G - R0001 - Main Area (390.12 m2)**

No Asbestos

**B00G - R0002 - Seminar (12.28 m2)**

No Asbestos

**B00G - R0003 - Seminar (12.5 m2)**

No Asbestos

**B00G - R0004 - Seminar (12.39 m2)**

No Asbestos

**B00G - R0006 - Librarian (14.04 m2)**

No Asbestos

**B00G - R0007 - Librarian (10.18 m2)**

No Asbestos

**B00G - R0008 - Workroom (42.67 m2)**

No Asbestos

**B00G - R0009 - Entry (14.57 m2)**

No Asbestos

**B00G - R0011 - Movement (2.04 m2)**

No Asbestos

**B00G - R0012 - Staff - Toilet (2.83 m2)**

No Asbestos

**B00G - R0013 - Cleaning Store - Distributed (1.74 m2)**

No Asbestos

**B00G - R0014 - Distribution Board Cupboard (1.09 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00G - R0015 - External Movement (83.8 m2)**

Ceiling Structures/Linings Flat AC Sheeting  
8418/B00G/R0015/Ceiling Structures/Linings/S26

**No Asbestos Detected**

**B00G - R0016 - Computer Room (9.35 m2)**

No Asbestos

**B00G - R0017 - Library Administration (28.52 m2)**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Building Services - 2003 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00H - R0001 - General Storeroom (44.67 m2)**

No Asbestos

**B00H - R0002 - General Storeroom (51.9 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - Multi Purpose Facilities - 2003 - Concrete (Concrete)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B001 - R0001 - Sport Equipment Store (55.3 m2)**

No Asbestos

**B001 - R0002 - External Movement (12.76 m2)**

No Asbestos

**B001 - R0003 - Multi-Purpose Space (532.82 m2)**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Music - 2003 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	Non Accessible Area - Area inaccessible
Underfloor Voids	Non Accessible Area - Area inaccessible

**Interior****B00J - R0001 - Music Learning Space (63.63 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	
Wall Linings Internal	Flat AC Sheeting 8418/B00J/R0001/Wall Linings Internal/S49	<b>No Asbestos Detected</b>

**B00J - R0002 - Resources (15.22 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	
Wall Linings Internal	Flat AC Sheeting 8418/B00J/R0001/Wall Linings Internal/S49	<b>No Asbestos Detected</b>

**B00J - R0003 - Music Store (5.74 m2)**

Wall Linings Internal	Flat AC Sheeting 8418/B00J/R0001/Wall Linings Internal/S49	<b>No Asbestos Detected</b>
-----------------------	---	-----------------------------

**B00J - R0004 - Staff Study (9.38 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	
Wall Linings Internal	Flat AC Sheeting 8418/B00J/R0001/Wall Linings Internal/S49	<b>No Asbestos Detected</b>

**B00J - R0005 - External Movement (24.32 m2)**

Floor Coverings Res/Textile	Compressed AC Sheet 8418/B00J/R0005/Floor Coverings Res/Textile/S45	<b>No Asbestos Detected</b>
Ceiling Structures/Linings	Flat AC Sheeting 8418/B00J/R0005/Ceiling Structures/Linings/S46	<b>No Asbestos Detected</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - Electrical Services - 2003 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00L - R0001 - External Movement (9.27 m2)**

No Asbestos

**B00L - R0002 - General Storeroom (7.67 m2)**

No Asbestos

**B00L - R0003 - Main Switchroom (4.76 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - General Learning - 2003 - Steel (Steel)**

**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior**

**B00M - R0001 - General Learning Space (33.98 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00N - General Learning - 2003 - Steel (Steel)**

**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior**

**B00N - R0001 - General Learning Space (26.84 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B000 - Art - 2007 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	Non Accessible Area - Area inaccessible					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	160m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Area inaccessible</b>						

**Interior**

**B000 - R0001 - Music Learning Space (66.28 m2)**

No Asbestos

**B000 - R0002 - Pottery Store (14.07 m2)**

No Asbestos

**B000 - R0003 - Movement (6.82 m2)**

No Asbestos

**B000 - R0004 - Art Learning Space (66.26 m2)**

No Asbestos

**B000 - R0005 - External Movement (36.68 m2)**

Floor Coverings Res/Textile	Compressed AC Sheet	4m2	Central	Good Condition (1)	Low (1)	Low Priority (2-3)
8418/B000/R0005/Floor Coverings Res/Textile/S50					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting					
8418/B000/R0005/Ceiling Structures/Linings/S51					<b>No Asbestos Detected</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00P - Art/Staff Facilities - 2007 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	140m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Area inaccessible</b>						

**Interior**

<b>B00P - R0001 - Visual Arts Store (9.28 m2)</b>						
No Asbestos						
<b>B00P - R0002 - Art Learning Space (67.69 m2)</b>						
No Asbestos						
<b>B00P - R0003 - Art Learning Space (47.6 m2)</b>						
No Asbestos						
<b>B00P - R0004 - Visual Arts Store (2.78 m2)</b>						
No Asbestos						
<b>B00P - R0005 - Visual Arts Store (9.13 m2)</b>						
No Asbestos						
<b>B00P - R0006 - General Storeroom (2.59 m2)</b>						
No Asbestos						
<b>B00P - R0007 - Staff Study (29.31 m2)</b>						
No Asbestos						
<b>B00P - R0008 - Movement (9.25 m2)</b>						
No Asbestos						
<b>B00P - R0009 - External Movement (17.05 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00Q - Other - 2012 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00Q - R0001 - Shed Workshop (33.63 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Build+1 - Walkway From Building G/D**

**Exterior**

No Asbestos

**Interior**

**Build+1 - Room+1 - Walkway**

Ceiling Structures/Linings Flat AC Sheeting  
 8418/Build+1/Room+1/Ceiling Structures/Linings/S27

**No Asbestos Detected**

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 601 - D14229 - Learning Unit - Standard/Withdrawal : Placement Date - 25/01/2012**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Entry**

No Asbestos Found.

**R2 - General Learning Space**

No Asbestos Found.

**R3 - Store**

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017