

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wade High School (8470)
Region : Riverina
State Electorate : Murray
Local Government Area : Griffith

Initial Survey : Noel Arnold & Associates : 09 - May - 2008
Reviewed By : Greencap-NAA : 18 - May - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1971 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	East, West and North	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8470/B00A/Eaves Linings/S8					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior**B00A - R0001 - Staff - Toilet (3.25 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B00A/R0001/Partition Walls (Cubicles)/S6					Chrysotile (white asbestos)

B00A - R0002 - General Storeroom (3.18 m2)

Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)

B00A - R0003 - Interview (11.66 m2)

No Asbestos

B00A - R0004 - Interview (11.66 m2)

No Asbestos

B00A - R0005 - Deputy Principal Office (16.69 m2)

No Asbestos

B00A - R0006 - Staff - Toilet (10.13 m2)

Floor Coverings Res/Textile	Vinyl Tiles	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B00A/R0001/Partition Walls (Cubicles)/S6					Chrysotile (white asbestos)

B00A - R0009 - Interview/Office - Type 1 (13.43 m2)

Floor Coverings Res/Textile	Vinyl Tiles	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)

B00A - R0010 - Duplicating Workroom (12.91 m2)

Floor Coverings Res/Textile	Vinyl Tiles	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	8470/B00A/R0010/Floor Coverings Res/Textile/S2					

B00A - R0011 - Interview/Office - Type 1 (12.37 m2)

No Asbestos

B00A - R0012 - Distribution Board Cupboard (2.87 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0013 - General Storeroom (2.75 m2)

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	8470/B00A/R0023/Infill Panels/S7					
Electrical Backing Board	Non Accessible Area - Electrical Hazard					

B00A - R0016 - Principal Office (20.15 m2)

No Asbestos

B00A - R0018 - General Assistants (28.55 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
No Asbestos						
B00A - R0019 - Movement (15.65 m2)						
No Asbestos						
B00A - R0020 - Movement (1.71 m2)						
No Asbestos						
B00A - R0021 - Movement (1.64 m2)						
No Asbestos						
B00A - R0022 - Staff Study (13.74 m2)						
No Asbestos						
B00A - R0023 - Staff Study (16.29 m2)						
Infill Panels	Flat AC Sheeting					No Asbestos Detected
8470/B00A/R0023/Infill Panels/S7						
B00A - R0025 - Store (6.36 m2)						
No Asbestos Found						
B00A - R0026 - Staff - Toilet (13.39 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0001/Partition Walls (Cubicles)/S6						
B00A - R0027 - Public Entry (23.9 m2)						
No Asbestos Found						
B00A - R0028 - Interview/Office - Type 1 (9.56 m2)						
No Asbestos Found						
B00A - R0029 - Interview/Office - Type 2 (12.3 m2)						
No Asbestos Found						
B00A - R0030 - Administration - Clerical (56.1 m2)						
No Asbestos Found						
B00A - R0031 - Public Entry (18.16 m2)						
No Asbestos Found						
B00A - R0032 - Movement (59.48 m2)						
No Asbestos Found						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Technological & Applied Studies/Art - 1971 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Compressed AC Sheet 8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected
Underfloor Voids	Non Accessible Area - Area inaccessible					
Ceiling Voids - Flat Roof	No Asbestos Found					

Interior**B00D - R0001 - Food Technology L.S. (82.09 m2)**

No Asbestos

B00D - R0002 - Movement (86.74 m2)

No Asbestos

B00D - R0003 - Toilets-Girls (65.82 m2)

Partition Walls (Cubicles)	Compressed AC Sheet 8470/B0C3/R0007/Wall Linings Internal/S9	24m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)
Wall Linings Internal	Compressed AC Sheet 8470/B0C3/R0007/Wall Linings Internal/S9	18m2	Behind Cistern	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00D - R0004 - External Movement (59.34 m2)

Ceiling Structures/Linings	Compressed AC Sheet 8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00D - R0005 - Sport Equipment Store (9.95 m2)

No Asbestos

B00D - R0006 - Distribution Board Cupboard (1.82 m2)

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1Unit	to wall	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	-------	---------	--------------------	---------	--------------------

Assumed Asbestos - Height Restriction - Extreme Access**B00D - R0007 - Laundry (21.59 m2)**

No Asbestos

B00D - R0008 - Staff Study (31.91 m2)

No Asbestos

B00D - R0009 - Commonroom (82.08 m2)

Floor Coverings Res/Textile	Vinyl Tiles 8470/B00D/R0009/Floor Coverings Res/Textile/S3					No Asbestos Detected
Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00D - R0010 - Cleaning Store - Distributed (4.63 m2)

Flue	Fibre Cement Pipe 8470/B00D/R0010/Flue/S17	5m	West	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00D - R0011 - Staff - Toilet (4.36 m2)

No Asbestos

B00D - R0016 - External Stairs (6.49 m2)

Ceiling Structures/Linings	Compressed AC Sheet 8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00D - R0017 - Movement (1.38 m2)

No Asbestos

B00D - R0018 - Movement (1.38 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00D - R0020 - Lift (2.1 m2)						
No Asbestos						
B00D - R0021 - Food Technology L.S. (104.52 m2)						
No Asbestos						
B00D - R0022 - Food/Research Space (31.92 m2)						
No Asbestos						
B00D - R1001 - General Learning Space (65.9 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
		8470/B00D/R1002/Floor Coverings Res/Textile/S18				No Asbestos Detected
B00D - R1002 - General Storeroom (4.37 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
		8470/B00D/R1002/Floor Coverings Res/Textile/S18				No Asbestos Detected
B00D - R1003 - General Storeroom (10.75 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
		8470/B0C3/R1004/Floor Coverings Res/Textile/S13				No Asbestos Detected
B00D - R1004 - Design/Technology L.S. (65.83 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
		8470/B0C3/R1004/Floor Coverings Res/Textile/S13				No Asbestos Detected
B00D - R1005 - Movement (59.5 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
		8470/B0L2/R1006/Floor Coverings Res/Textile/S5				No Asbestos Detected
B00D - R1006 - External Movement (50.14 m2)						
Ceiling Structures/Linings	Compressed AC Sheet					
		8470/B0C3/R0020/Ceiling Structures/Linings/S12				No Asbestos Detected
B00D - R1007 - Cleaning Store - Distributed (3.27 m2)						
No Asbestos						
B00D - R1008 - Distribution Board Cupboard (1.63 m2)						
Electrical Backing Board	Non Accessible Area					
	- Electrical Hazard					
						Note: No inspection of live electrical installation.
B00D - R1009 - Art Learning Space (65.75 m2)						
No Asbestos						
B00D - R1011 - Resources Store (13.97 m2)						
No Asbestos						
B00D - R1014 - Staff Study (32.45 m2)						
No Asbestos						
B00D - R1015 - Stairs (10.8 m2)						
Ceiling Structures/Linings	Compressed AC Sheet					
		8470/B0C3/R0020/Ceiling Structures/Linings/S12				No Asbestos Detected
B00D - R1016 - Seminar (23.79 m2)						
No Asbestos						
B00D - R1017 - Workshop (40.35 m2)						
No Asbestos						
B00D - R1018 - Lift (2.1 m2)						
No Asbestos						
B00D - R1019 - Music Learning Space (131.79 m2)						
No Asbestos Found						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Building Services - 2013 - Steel (Steel)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00G - R0001 - General Assistants (33.68 m2)

No Asbestos

B00G - R0002 - General Assistants (13.67 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Technological & Applied Studies - 1971 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Compressed AC Sheet 8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior**B00M - R0001 - Toilets-Boys (59.17 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet 8470/B0C3/R0007/Wall Linings Internal/S9	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)
Wall Linings Internal	Compressed AC Sheet 8470/B0C3/R0007/Wall Linings Internal/S9	16m2	Behind Cisterns	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00M - R0002 - Toilets-Disabled (8.73 m2)

No Asbestos

B00M - R0003 - Cleaning Store - Distributed (1.72 m2)

No Asbestos

B00M - R0004 - No Access (2.66 m2)

Non Accessible

B00M - R0005 - Materials Technology L.S. (83.46 m2)

No Asbestos

B00M - R0006 - Welding Area (9.45 m2)

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00M - R0007 - Materials Store (21.19 m2)

No Asbestos

B00M - R0008 - Materials Technology L.S. (83.28 m2)

No Asbestos

B00M - R0009 - Materials Store (17.41 m2)

Floor Coverings Res/Textile	Vinyl Tiles 8470/B00A/R0010/Floor Coverings Res/Textile/S1	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00M - R0010 - Workshop (66.73 m2)

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Floor Coverings Res/Textile	Vinyl Tiles 8470/B00A/R0010/Floor Coverings Res/Textile/S1	67m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00M - R0011 - Kiln Space (12.67 m2)

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Floor Coverings Res/Textile	Vinyl Tiles 8470/B00A/R0010/Floor Coverings Res/Textile/S1	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

Kiln	Non Accessible Area - Area inaccessible					
------	--	--	--	--	--	--

B00M - R0012 - General Storeroom (0.91 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00M - R0013 - General Storeroom (4.85 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
B00M - R0014 - Movement (37.88 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	38m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
B00M - R0016 - Practice/Seminar (10.79 m2)						
No Asbestos						
B00M - R0017 - Music Learning Space (72.5 m2)						
No Asbestos						
B00M - R0018 - Practice/Seminar (10.85 m2)						
No Asbestos						
B00M - R0019 - Movement (1.87 m2)						
No Asbestos						
B00M - R0020 - Staff Study (28.39 m2)						
No Asbestos						
B00M - R0021 - Music Store (10.38 m2)						
No Asbestos						
B00M - R0022 - Practice/Seminar (10.89 m2)						
No Asbestos						
B00M - R0023 - Practice/Seminar (10.83 m2)						
No Asbestos						
B00M - R0024 - Music Learning Space (72.5 m2)						
No Asbestos						
B00M - R0025 - External Movement (29.24 m2)						
No Asbestos						
B00M - R0026 - External Movement (29.24 m2)						
No Asbestos						
B00M - R0027 - External Movement (30.27 m2)						
No Asbestos						
B00M - R1001 - Design L.S. (52.86 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
B00M - R1002 - Resource/Project Store (13.08 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
B00M - R1003 - Materials Technology L.S. (83.28 m2)						
No Asbestos						
B00M - R1004 - Distribution Board Cupboard (0.8 m2)						
Note: No inspection of live electrical installation.						
Floor Coverings Res/Textile	Vinyl Tiles	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
Electrical Backing Board	Resinous Board	1Unit	to wall	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
B00M - R1005 - Resource/Project Store (4.54 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00M - R1006 - Dust Extraction Space (4.47 m2)						
No Asbestos						
B00M - R1007 - Resource/Project Store (21.35 m2)						
No Asbestos						
B00M - R1008 - Materials Technology L.S. (83.28 m2)						
No Asbestos						
B00M - R1009 - Resource/Project Store (14.21 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
B00M - R1010 - Design L.S. (52.72 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
B00M - R1011 - Staff Study (25.81 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	26m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
B00M - R1012 - General Storeroom (0.98 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
Electrical Backing Board	Non Accessible Area - Electrical Hazard					
B00M - R1013 - Cleaning Store - Distributed (1.97 m2)						
No Asbestos						
B00M - R1014 - Movement (46.04 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	46m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
B00M - R1015 - External Movement (36.48 m2)						
Ceiling Structures/Linings	Compressed AC Sheet					No Asbestos Detected
8470/B0C3/R0020/Ceiling Structures/Linings/S12						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00S - Pupil Facilities - 1971 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Corrugated AC Sheeting 8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00S - R0001 - Multi-Purpose Space (309.18 m2)

No Asbestos

B00S - R0002 - Movement (78.39 m2)

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	---

B00S - R0004 - Materials Store (9.74 m2)

No Asbestos

B00S - R0005 - Project Store - Type 1 (53.28 m2)

No Asbestos

B00S - R0006 - Sport Equipment Store (19.14 m2)

No Asbestos

B00S - R0007 - Staff - Toilet (3.87 m2)

No Asbestos

B00S - R0008 - Cleaning Store - Distributed (0.96 m2)

No Asbestos

B00S - R0009 - Chair Store (15.18 m2)

No Asbestos

B00S - R0010 - General Storeroom (7.31 m2)

No Asbestos

B00S - R0011 - Staff - Toilet (4.04 m2)

No Asbestos

B00S - R0012 - Distribution Board Cupboard (0.5 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00S - R0013 - Student Canteen (54.54 m2)

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	---

Electrical Backing Board	Non Accessible Area - Electrical Hazard					
--------------------------	--	--	--	--	--	--

B00S - R0014 - General Storeroom (6.55 m2)

No Asbestos

B00S - R0015 - General Storeroom (18.09 m2)

No Asbestos

B00S - R0016 - Main Switchroom (9.73 m2)

Electrical Backing Board	Non Accessible Area - Electrical Hazard					
--------------------------	--	--	--	--	--	--

B00S - R0017 - Sport Equipment Store (16.12 m2)

No Asbestos

B00S - R0018 - External Movement (8.91 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00S - R0019 - External Stairs (6.25 m2)						
Ceiling Structures/Linings	Compressed AC Sheet					
	8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected
B00S - R0020 - Sport Equipment Store (11.19 m2)						
No Asbestos						
B00S - R0021 - External Movement (16.53 m2)						
No Asbestos						
B00S - R0022 - External Movement (3.96 m2)						
Ceiling Structures/Linings	Compressed AC Sheet					
	8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected
B00S - R1001 - External Movement (8.91 m2)						
Ceiling Structures/Linings	Compressed AC Sheet					
	8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected
B00S - R1002 - Movement (66.35 m2)						
No Asbestos						
B00S - R1003 - External Movement (24.37 m2)						
Ceiling Structures/Linings	Compressed AC Sheet					
	8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected
B00S - R1004 - Cleaning Store - Distributed (3.3 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B00S/R1009/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)
B00S - R1005 - General Storeroom (9.24 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B00S/R1009/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)
B00S - R1006 - Staff - Toilet (8.31 m2)						
Wall Linings Internal	Compressed AC Sheet	4m2	Behind Cistern	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B0C3/R0007/Wall Linings Internal/S9					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B0C3/R0007/Wall Linings Internal/S9					Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B00S/R1009/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)
B00S - R1007 - Shower/Change (63.21 m2)						
Cistern wall	Compressed AC Sheet	4m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8470/B0C3/R0007/Wall Linings Internal/S9					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B0C3/R0007/Wall Linings Internal/S9					Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B00S/R1009/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)
B00S - R1008 - Cleaning Store - Distributed (0.25 m2)						
Door Lining	Flat AC Sheeting	2m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8470/B00S/R1009/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)
B00S - R1009 - Shower/Change (62.52 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Compressed AC Sheet	10m2	Behind Cistern	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8470/B0C3/R0007/Wall Linings Internal/S9					Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	30m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8470/B0C3/R0007/Wall Linings Internal/S9					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	63m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00S/R1009/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)	
B00S - R1010 - Staff - Toilet (9.24 m2)						
Wall Linings Internal	Compressed AC Sheet	2m2	Behind Cistern	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B0C3/R0007/Wall Linings Internal/S9					Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B0C3/R0007/Wall Linings Internal/S9					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00S/R1009/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)	
B00S - R1011 - General Storeroom (9.32 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00S/R1009/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)	
B00S - R1012 - Cleaning Store - Distributed (3.39 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00S/R1009/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)	
B00S - R1013 - External Stairs (10.08 m2)						
Ceiling Structures/Linings	Compressed AC Sheet					
8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00V - General Learning - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction. Presumed						

Ceiling Voids	Non Accessible Area - Area inaccessible
---------------	--

Underfloor Voids	Non Accessible Area - Area inaccessible
------------------	--

Interior

B00V - R0002 - Staff Study (46.37 m2)

No Asbestos

B00V - R0003 - General Learning Space (46.23 m2)

No Asbestos

B00V - R0005 - External Movement (83.17 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Z - Agricultural Science - 1971 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B00Z/Eaves Linings/S20					Chrysotile (white asbestos)
Underfloor Voids	Non Accessible Area - Area inaccessible					
Ceiling Voids - Raked Ceiling	No Asbestos Found					

Interior**B00Z - R0001 - Shower/Change (4.55 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B00Z/Eaves Linings/S20					Chrysotile (white asbestos)

B00Z - R0002 - Movement (1.15 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B00Z/Eaves Linings/S20					Chrysotile (white asbestos)

B00Z - R0003 - Staff - Toilet (2.44 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B00Z/Eaves Linings/S20					Chrysotile (white asbestos)

B00Z - R0004 - General Storeroom (7.31 m2)

No Asbestos

B00Z - R0005 - Class Tools Storage (12.67 m2)

No Asbestos

B00Z - R0006 - Animal Space (21.07 m2)

No Asbestos

B00Z - R0007 - General Storeroom (2.43 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B00Z/Eaves Linings/S20					Chrysotile (white asbestos)

B00Z - R0008 - Movement (1.18 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B00Z/Eaves Linings/S20					Chrysotile (white asbestos)

B00Z - R0009 - General Storeroom (4.52 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B00Z/Eaves Linings/S20					Chrysotile (white asbestos)

B00Z - R0010 - External Movement (26.63 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0C2 - General Learning - 1971 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Compressed AC Sheet 8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected
Ceiling Voids	Non Accessible Area - Area inaccessible					
Underfloor Voids - Packing to Floor Joists	Non Accessible Area - Area inaccessible					

Interior**B0C2 - R0001 - General Learning Space (52.21 m2)**

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8470/B00A/R0010/Floor Coverings Res/Textile/S1	53m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B0C2 - R0002 - General Learning Space (53.38 m2)

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8470/B00A/R0010/Floor Coverings Res/Textile/S1	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B0C2 - R0005 - Computer Learning Space (52.64 m2)

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8470/B00A/R0010/Floor Coverings Res/Textile/S1	53m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B0C2 - R0009 - General Learning Space (52.5 m2)

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8470/B00A/R0010/Floor Coverings Res/Textile/S1	53m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B0C2 - R0010 - Computer Learning Space (53.08 m2)

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8470/B00A/R0010/Floor Coverings Res/Textile/S1	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B0C2 - R0011 - External Movement (60.55 m2)

Ceiling Structures/Linings	Compressed AC Sheet 8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B0C2 - R0012 - Maintenance Bulk Store (12.79 m2)

No Asbestos

B0C2 - R0013 - General Storeroom (4.61 m2)

Floor Coverings Res/Textile	Vinyl Tiles 8470/B00A/R0010/Floor Coverings Res/Textile/S1	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
--------------------------------	---	-----	--------------	--------------------	---------	--

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B0C2 - R0014 - Staff - Toilet (5.07 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
B0C2 - R0015 - Staff - Toilet (6.8 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
B0C2 - R0016 - Duplicating Workroom (31.73 m2)						
No Asbestos						
B0C2 - R0017 - Distribution Board Cupboard (0.68 m2)				Note: No inspection of live electrical installation.		
Electrical Backing Board	Non Accessible Area - Electrical Hazard					
B0C2 - R0020 - Staff Study (43.5 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	44m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
B0C2 - R0021 - General Storeroom (16.48 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	17m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
B0C2 - R0022 - External Stairs (9.57 m2)						
Ceiling Structures/Linings	Compressed AC Sheet					
8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected	
B0C2 - R0023 - Movement (86.18 m2)						
Ceiling Structures/Linings	Vermiculite					
8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B0C2 - R0024 - Stairs (4.64 m2)						
No Asbestos						
B0C2 - R0027 - Careers Advisers Office (14.65 m2)						
Ceiling Structures/Linings	Vermiculite					
8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
B0C2 - R0028 - External Movement (148.21 m2)						
No Asbestos						
B0C2 - R0030 - Staff Lounge (39.41 m2)						
Recently Modified Space	Requires Inspection					
B0C2 - R1001 - General Learning Space (53.23 m2)						
No Asbestos						
B0C2 - R1002 - General Learning Space (53.08 m2)						
No Asbestos						
B0C2 - R1003 - Interview (17.14 m2)						
No Asbestos						
B0C2 - R1009 - General Learning Space (52.94 m2)						
No Asbestos						
B0C2 - R1010 - External Movement (59.43 m2)						
Ceiling Structures/Linings	Compressed AC Sheet					
8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected	
B0C2 - R1018 - Stairs (13.4 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Ceiling Structures/Linings Compressed AC Sheet
 8470/B0C3/R0020/Ceiling Structures/Linings/S12 **No Asbestos Detected**

B0C2 - R1019 - Stairs (12.6 m2)

No Asbestos

B0C2 - R1020 - Movement (70.08 m2)

No Asbestos

B0C2 - R1021 - General Learning Space (46.99 m2)

No Asbestos

B0C2 - R1022 - General Learning Space (46.48 m2)

No Asbestos

B0C2 - R1023 - General Storeroom (23.56 m2)

No Asbestos

B0C2 - R1024 - Staff Study (45.41 m2)

No Asbestos

B0C2 - R1025 - Staff - Toilet (8.25 m2)

No Asbestos

B0C2 - R1026 - Distribution Board Cupboard (1.17 m2) Note: No inspection of live electrical installation.

Electrical Backing Board Non Accessible Area
 - Electrical Hazard

B0C2 - R1027 - General Learning Space (46.29 m2)

No Asbestos

B0C2 - R1028 - General Learning Space (47.84 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0C3 - General Learning/Library - 1971 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected
Underfloor Voids	Non Accessible Area - Area inaccessible					
Ceiling Voids	Non Accessible Area - Area inaccessible					

Interior**B0C3 - R0001 - Audio Visual Workroom (13.07 m2)**

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B0C3 - R0002 - Workroom (55.11 m2)

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B0C3 - R0003 - Seminar (12.96 m2)

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B0C3 - R0004 - Seminar (13.04 m2)

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B0C3 - R0005 - Movement (69.5 m2)

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Floor Coverings Res/Textile	Vinyl Tiles	2m2	East	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8470/B0C3/R0005/Floor Coverings Res/Textile/S11						Chrysotile (white asbestos)

Floor Coverings Res/Textile	Adhesive attached to sample 11					
8470/B0C3/R0005/Floor Coverings Res/Textile/S21						No Asbestos Detected

B0C3 - R0007 - Toilets-Boys (12.23 m2)

Wall Linings Internal	Compressed AC Sheet	4m2	Behind Cistern	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B0C3/R0007/Wall Linings Internal/S9						Chrysotile (white asbestos)

Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B0C3/R0007/Wall Linings Internal/S9						Chrysotile (white asbestos)

B0C3 - R0008 - Cleaning Store - Distributed (0.77 m2)

No Asbestos

B0C3 - R0009 - General Storeroom (4.14 m2)

Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1						Chrysotile (white asbestos)

B0C3 - R0010 - Toilets-Girls (14.23 m2)

Wall Linings Internal	Compressed AC Sheet	4m2	Behind Cistern	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B0C3/R0007/Wall Linings Internal/S9						Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B0C3/R0007/Wall Linings Internal/S9					Chrysotile (white asbestos)	
B0C3 - R0011 - Plant Space (25.5 m2)						
No Asbestos						
B0C3 - R0012 - External Movement (58.29 m2)						
No Asbestos						
B0C3 - R0013 - General Storeroom (12.45 m2)						
No Asbestos						
B0C3 - R0014 - Secure Storeroom (19.1 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	19m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
Money Safe	Encapsulated Insulation material within unit	1Unit	Variable positions	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
Assumed Asbestos - item inaccessible						
B0C3 - R0015 - Main Area (53.37 m2)						
Ceiling Structures/Linings	Vermiculite					
8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Sheet	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
B0C3 - R0016 - Distribution Board Cupboard (1.27 m2)						
Note: No inspection of live electrical installation.						
Electrical Backing Board	Non Accessible Area - Area inaccessible					
Floor Coverings Res/Textile	Vinyl Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8470/B00A/R0010/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
B0C3 - R0017 - Main Area (224.21 m2)						
Ceiling Structures/Linings	Vermiculite					
8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B0C3 - R0018 - Librarian (12.96 m2)						
Ceiling Structures/Linings	Vermiculite					
8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B0C3 - R0019 - Stairs (4.77 m2)						
No Asbestos						
B0C3 - R0020 - External Stairs (8.6 m2)						
Ceiling Structures/Linings	Compressed AC Sheet					
8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected	
B0C3 - R0021 - Computer Store (12.96 m2)						
Ceiling Structures/Linings	Vermiculite					
8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Wall Linings Internal	Flat AC Sheeting					
8470/B0C3/R0021/Wall Linings Internal/S10					No Asbestos Detected	
B0C3 - R0022 - Interview/Office - Type 1 (6.69 m2)						
Ceiling Structures/Linings	Vermiculite					
8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Wall Linings Internal	Flat AC Sheeting					
8470/B0C3/R0021/Wall Linings Internal/S10					No Asbestos Detected	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B0C3 - R1001 - General Learning Space (53.52 m2)						
No Asbestos						
B0C3 - R1002 - General Learning Space (53.6 m2)						
No Asbestos						
B0C3 - R1003 - Movement (18.91 m2)						
No Asbestos						
B0C3 - R1004 - Cleaning Store - Distributed (1.3 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
8470/B0C3/R1004/Floor Coverings Res/Textile/S13					No Asbestos Detected	
B0C3 - R1005 - General Learning Space (53.6 m2)						
No Asbestos						
B0C3 - R1006 - General Learning Space (52.49 m2)						
No Asbestos						
B0C3 - R1007 - Distribution Board Cupboard (1.04 m2)						
Electrical Backing Board	Non Accessible Area					Note: No inspection of live electrical installation.
		- Electrical Hazard				
B0C3 - R1008 - General Storeroom (15.46 m2)						
No Asbestos						
B0C3 - R1009 - Staff Study (39.21 m2)						
No Asbestos						
B0C3 - R1010 - Movement (20.27 m2)						
No Asbestos						
B0C3 - R1011 - External Movement (44.75 m2)						
Ceiling Structures/Linings	Compressed AC Sheet					
8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected	
B0C3 - R1012 - General Learning Space (53.08 m2)						
No Asbestos						
B0C3 - R1013 - General Learning Space (59.8 m2)						
No Asbestos						
B0C3 - R1014 - General Learning Space (59.6 m2)						
No Asbestos						
B0C3 - R1015 - General Storeroom (4.48 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
8470/B0C3/R1004/Floor Coverings Res/Textile/S13					No Asbestos Detected	
B0C3 - R1016 - General Storeroom (4.39 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
8470/B0C3/R1004/Floor Coverings Res/Textile/S13					No Asbestos Detected	
B0C3 - R1017 - Staff Study (19.82 m2)						
No Asbestos						
B0C3 - R1018 - Stairs (8.02 m2)						
No Asbestos						
B0C3 - R1019 - External Stairs (21.03 m2)						
Ceiling Structures/Linings	Compressed AC Sheet					
8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0L1 - Science Learning - 1971 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Compressed AC Sheet 8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected
Underfloor Voids	Non Accessible Area - Area inaccessible					
Ceiling Voids	Non Accessible Area - Area inaccessible					

Interior**B0L1 - R0002 - Computer Learning Space (91.43 m2)**

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8470/B00A/R0010/Floor Coverings Res/Textile/S1	92m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B0L1 - R0003 - Distribution Board Cupboard (0.67 m2)

Note: No inspection of live electrical installation.

No Asbestos

B0L1 - R0004 - Staff Study (44.14 m2)

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8470/B00A/R0010/Floor Coverings Res/Textile/S1	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B0L1 - R0005 - Resources Store (3.34 m2)

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8470/B00A/R0010/Floor Coverings Res/Textile/S1	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B0L1 - R0006 - Lift (0.3 m2)

No Asbestos

B0L1 - R0007 - Cleaning Store - Distributed (0.41 m2)

Electrical Backing Board	Resinous Board	1Unit	to wall	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						

B0L1 - R0009 - Distribution Board Cupboard (0.66 m2)

Note: No inspection of live electrical installation.

Electrical Backing Board	Non Accessible Area - Area inaccessible					
--------------------------	--	--	--	--	--	--

B0L1 - R0010 - External Movement (119.76 m2)

No Asbestos

B0L1 - R0011 - General Storeroom (12.27 m2)

No Asbestos

B0L1 - R0012 - External Stairs (7.95 m2)

Ceiling Structures/Linings	Compressed AC Sheet 8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B0L1 - R0013 - External Movement (7.63 m2)

Ceiling Structures/Linings	Compressed AC Sheet 8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B0L1 - R0014 - General Storeroom (76.42 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B0L1 - R0015 - General Storeroom (27.85 m2)						
No Asbestos						
B0L1 - R0016 - Computer Room (74.74 m2)						
Recently Modified Space Requires Inspection						
B0L1 - R0017 - Staff Lounge (16.03 m2)						
Recently Modified Space Requires Inspection						
B0L1 - R1001 - External Movement (117.49 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	8470/B0C3/R0020/Ceiling Structures/Linings/S12					
Expansion Joint	Resinous Membrane					No Asbestos Detected
	8470/B0L1/R1001/Expansion Joint/S16					
B0L1 - R1002 - Laboratory L.S. (91.5 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					No Asbestos Detected
	8470/B0L1/R1002/Floor Coverings Res/Textile/S14					
Fume Cupboard	Flat AC Sheeting	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8470/B00A/Eaves Linings/S8					Chrysotile (white asbestos)
B0L1 - R1003 - Cleaning Store - Distributed (0.63 m2)						
No Asbestos						
B0L1 - R1004 - Chemical Store (13.07 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					No Asbestos Detected
	8470/B0L1/R1002/Floor Coverings Res/Textile/S14					
B0L1 - R1005 - Preparation (31 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					No Asbestos Detected
	8470/B0L1/R1002/Floor Coverings Res/Textile/S14					
B0L1 - R1006 - General Storeroom (3.25 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					No Asbestos Detected
	8470/B0L1/R1002/Floor Coverings Res/Textile/S14					
B0L1 - R1008 - Laboratory L.S. (91.51 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					No Asbestos Detected
	8470/B0L1/R1002/Floor Coverings Res/Textile/S14					
B0L1 - R1009 - Distribution Board Cupboard (0.64 m2)						
No Asbestos						
Note: No inspection of live electrical installation.						
B0L1 - R1010 - External Stairs (10.55 m2)						
Ceiling Structures/Linings	Compressed AC Sheet					No Asbestos Detected
	8470/B0C3/R0020/Ceiling Structures/Linings/S12					
B0L1 - R1011 - Plant (0.41 m2)						
Electrical Backing Board	Resinous Board	1Unit	to wall	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					
B0L1 - R1012 - Lift (0.3 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0L2 - Science/General Learning - 1971 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Compressed AC Sheet 8470/B0C3/R0020/Ceiling Structures/Linings/S12					No Asbestos Detected
Underfloor Voids	Non Accessible Area - Area inaccessible					
Ceiling Voids	Non Accessible Area - Area inaccessible					

Interior**B0L2 - R0001 - General Storeroom (8.34 m2)**

No Asbestos

B0L2 - R0002 - Cleaning Store - Distributed (5.51 m2)

No Asbestos

B0L2 - R0003 - General Storeroom (11.4 m2)

No Asbestos

B0L2 - R0004 - External Movement (110.83 m2)

No Asbestos

B0L2 - R0005 - Cleaning Store - Distributed (0.64 m2)

No Asbestos

B0L2 - R0006 - Laboratory L.S. (87.85 m2)

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken
----------------------------	--	--	--	--	--	------------------------------

Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works**B0L2 - R0007 - Distribution Board Cupboard (0.37 m2)**

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1Unit	to wall	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	-------	---------	--------------------	---------	--------------------

Assumed Asbestos - Electrical Hazard**B0L2 - R0008 - Lift (0.3 m2)**

No Asbestos

B0L2 - R0012 - Distribution Board Cupboard (0.66 m2)

Note: No inspection of live electrical installation.

No Asbestos

B0L2 - R0013 - Laboratory L.S. (87.21 m2)

Ceiling Structures/Linings	Vermiculite 8470/B00M/R0004/Ceiling Structures/Linings/S4					Limited Samples Taken
----------------------------	--	--	--	--	--	------------------------------

Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works**B0L2 - R0014 - External Movement (18.04 m2)**

No Asbestos

B0L2 - R0015 - Preparation (42.54 m2)

No Asbestos Found

B0L2 - R1001 - Lift (0.3 m2)

No Asbestos

B0L2 - R1002 - General Storeroom (5.41 m2)

No Asbestos

B0L2 - R1003 - Plant Space (9.65 m2)

No Asbestos

B0L2 - R1004 - External Movement (72.17 m2)

No Asbestos

B0L2 - R1005 - Cleaning Store - Distributed (0.65 m2)

No Asbestos

B0L2 - R1006 - Laboratory L.S. (87.94 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Floor Coverings Res/Textile Vinyl Tiles
 8470/B0L2/R1006/Floor Coverings Res/Textile/S5 **No Asbestos Detected**

B0L2 - R1011 - Distribution Board Cupboard (0.63 m2) Note: No inspection of live electrical installation.

No Asbestos

B0L2 - R1012 - Laboratory L.S. (88.49 m2)

Floor Coverings Res/Textile Vinyl Tiles
 8470/B0L2/R1006/Floor Coverings Res/Textile/S5 **No Asbestos Detected**

B0L2 - R1013 - Plant Space (8.1 m2)

No Asbestos

B0L2 - R1014 - External Movement (15.26 m2)

No Asbestos

B0L2 - R1015 - Plant (0.37 m2)

No Asbestos

B0L2 - R1016 - Preparation (44.09 m2)

No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 601 - D11003 - Learning Unit - Standard/Withdrawal : Placement Date - 15/01/2013

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 601 - D12148 - Learning Unit - Standard/Withdrawal : Placement Date - 14/07/2016

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

OS 601 - D15374 - Learning Unit - Standard/Withdrawal : Placement Date - 15/01/2013

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017