


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wollumbin High School (8596)
Region : North Coast
State Electorate : Lismore
Local Government Area : Tweed

Initial Survey : Noel Arnold & Associates : 11 - Jun - 2008
Register Issue Date : 24 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - Administration - 1994 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Clinic - Boys**

No Asbestos

B00A - R0002 - Clinic-Toilets

No Asbestos

B00A - R0003 - Clinic-Toilets

No Asbestos

B00A - R0004 - Clinic - Girls

No Asbestos

B00A - R0005 - Teachers Aides

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0006 - Staff - Toilet

No Asbestos

B00A - R0007 - Ancillary Staff

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0008 - Pupil Entry

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0009 - Duplicating Workroom

No Asbestos

B00A - R0010 - Administration - Clerical

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0011 - Public Entry

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0012 - Security Store

No Asbestos

B00A - R0013 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0014 - Principal Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0015 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0016 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0017 - Cleaning Store - Distributed

No Asbestos

B00A - R0018 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0019 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0020 - External Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00A - R0021 - External Movement

No Asbestos

B00A - R9001 - Toilets-Boys

No Asbestos

B00A - R9002 - Cleaning Store - Distributed

No Asbestos

B00A - R9003 - Toilets-Girls

No Asbestos

B00A - R9004 - Sport Equipment Store

No Asbestos

B00A - R9005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - Multi Purpose Facilities - 1994 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00B - R0001 - External Movement**

No Asbestos

B00B - R0002 - Student Canteen

No Asbestos

B00B - R0003 - Office/Store

No Asbestos

B00B - R0004 - Staff - Toilet

No Asbestos

B00B - R0005 - Staff Shower

No Asbestos

B00B - R0008 - Gymnasium

No Asbestos

B00B - R0009 - Main Switchroom

No Asbestos

B00B - R0010 - Disabled Toilet

No Asbestos

B00B - R0011 - Movement

No Asbestos

B00B - R0012 - Shower/Change

No Asbestos

B00B - R0013 - Sport Equipment Store

No Asbestos

B00B - R0014 - Shower/Change

No Asbestos

B00B - R0015 - Shower/Change

No Asbestos

B00B - R0016 - Chair Store

No Asbestos

B00B - R0017 - Shower/Change

No Asbestos

B00B - R0018 - Movement

No Asbestos

B00B - R0019 - External Movement

No Asbestos

B00B - R0020 - External Movement

No Asbestos

B00B - R0021 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R9001 - Movement

No Asbestos

B00B - R9002 - Cleaning Supplies Store

No Asbestos

B00B - R9003 - General Assistants

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R9004 - Cleaning Supplies Store						
No Asbestos						
B00B - R9005 - Maintenance Bulk Store						
No Asbestos						
B00B - R9006 - Garden Store Room						
No Asbestos						
B00B - R9007 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Technological & Applied Studies - 1994 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00C - R0001 - Materials Technology L.S.**

No Asbestos

B00C - R0002 - Welding Area

No Asbestos

B00C - R0003 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0004 - Dust Extraction Space

No Asbestos

B00C - R0005 - Wood Technology Bay

No Asbestos

B00C - R0006 - Metal Technology Bay

No Asbestos

B00C - R0007 - Seminar/Technology SpaceVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00C - R0008 - Materials Technology L.S.**

No Asbestos

B00C - R0009 - Resource/Project Store

No Asbestos

B00C - R0010 - Welding Area

No Asbestos

B00C - R0011 - Welding Store

No Asbestos

B00C - R0012 - Materials Store

No Asbestos

B00C - R0013 - Resource/Project Store

No Asbestos

B00C - R0014 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0015 - Cleaning Store - Distributed

No Asbestos

B00C - R0016 - L.P.G. Store

No Asbestos

B00C - R0017 - T.A.S. Outdoor Area

No Asbestos

B00C - R0018 - External Movement

No Asbestos

B00C - R1001 - Laundry

No Asbestos

B00C - R1002 - MovementVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00C - R1003 - Design L.S.**

No Asbestos

B00C - R1004 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R1005 - Design/Technology L.S.						
No Asbestos						
B00C - R1006 - Seminar/Technology Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R1007 - Materials Store						
No Asbestos						
B00C - R1008 - Design L.S.						
No Asbestos						
B00C - R1009 - Food Technology L.S.						
No Asbestos						
B00C - R1010 - Seminar						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R1011 - Pantry						
No Asbestos						
B00C - R1012 - Food Technology L.S.						
No Asbestos						
B00C - R1013 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00C - R1014 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Science Learning - 1994 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00D - R0001 - Laboratory L.S.**

No Asbestos

B00D - R0002 - Staff - Toilet

No Asbestos

B00D - R0003 - General Learning SpaceVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0004 - Movement**

No Asbestos

B00D - R0005 - Laboratory L.S.

No Asbestos

B00D - R0006 - Growing/Breeding

No Asbestos

B00D - R0007 - Preparation

No Asbestos

B00D - R0008 - Chemical Store

No Asbestos

B00D - R0009 - Apparatus Store

No Asbestos

B00D - R0010 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0011 - Laboratory L.S.

No Asbestos

B00D - R0012 - Movement

No Asbestos

B00D - R0013 - Laboratory L.S.

No Asbestos

B00D - R0014 - Serviced Learning SpaceVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0015 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0016 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00E - General Learning - 1994 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00E - R0001 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0002 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0003 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0004 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0005 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0006 - Staff - Toilet

No Asbestos

B00E - R0007 - Cleaning Store - Distributed

No Asbestos

B00E - R0008 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0009 - Security Store

No Asbestos

B00E - R0010 - Study Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0011 - External Movement

No Asbestos

B00E - R0012 - External Movement

No Asbestos

B00E - R1001 - Staff Kitchen

No Asbestos

B00E - R1002 - Commonroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R1003 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R1004 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R1005 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R1006 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R1007 - General Learning Space

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R1008 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B00E - R1009 - Security Store

No Asbestos

B00E - R1010 - Study Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R1011 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00F - Performing Arts/Library - 1994 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00F - R0001 - Performing Arts Changeroom**

No Asbestos

B00F - R0002 - Performing Arts Changeroom

No Asbestos

B00F - R0003 - Performing Arts Store

No Asbestos

B00F - R0004 - Cleaning Store - Distributed

No Asbestos

B00F - R0005 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0006 - Performing Arts Chair Store

No Asbestos

B00F - R0007 - Control RoomVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R0008 - Performance Workspace**

No Asbestos

B00F - R0009 - StageVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R0010 - Movement**

No Asbestos

B00F - R0011 - Control RoomVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R0012 - External Movement**

No Asbestos

B00F - R1001 - Main AreaVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R1002 - Workroom**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R1003 - Audio Visual Workroom**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R1004 - Librarian**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R1005 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

B00F - R1006 - SeminarVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R1007 - Seminar**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R1008 - External Movement**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0002 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0003 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0004 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0005 - Computer Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0006 - Computer Resource

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0007 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0008 - Toilets-Girls

No Asbestos

B00G - R0009 - Toilets-Boys

No Asbestos

B00G - R0010 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0011 - Security Store

No Asbestos

B00G - R0012 - Study Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0013 - External Movement

No Asbestos

B00G - R1001 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R1002 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R1003 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R1004 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R1005 - Study Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R1006 - Security Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00G - R1007 - Senior Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R1008 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R1009 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R1010 - Toilets-Girls

No Asbestos

B00G - R1011 - Toilets-Boys

No Asbestos

B00G - R1012 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00G - R1013 - Security Store

No Asbestos

B00G - R1014 - Cleaning Store - Distributed

No Asbestos

B00G - R1015 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R1016 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Music - 1994 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00H - R0001 - Music Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0002 - Practice/Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0003 - Music Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0004 - Resources

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0005 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0006 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0009 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0010 - External Movement

No Asbestos

B00H - R0011 - Toilets-Disabled

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00J - Art - 1994 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00J - R0001 - Bulk Store**

No Asbestos

B00J - R0002 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00J - R0003 - Disabled Toilet

No Asbestos

B00J - R0004 - Art Learning Space

No Asbestos

B00J - R0005 - Workshop

No Asbestos

B00J - R0006 - Kiln Space

No Asbestos

B00J - R0007 - Art Learning Space

No Asbestos

B00J - R0008 - Resources Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0009 - Darkroom Space

No Asbestos

B00J - R0010 - External Movement

No Asbestos

B00J - R0011 - Art Outdoor Area

No Asbestos

B00J - R0012 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Mechanical Services - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00K - R0001 - Plant

No Asbestos

B00K - R0002 - Lift

No Asbestos

B00K - R1001 - Staff - Toilet

No Asbestos

B00K - R1002 - Lift

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Building Services - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00L - R0001 - Movement

No Asbestos

B00L - R0002 - Stairs

No Asbestos

B00L - R1001 - Movement

No Asbestos

B00L - R1002 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Building Services - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00M - R0001 - Movement

No Asbestos

B00M - R0002 - Stairs

No Asbestos

B00M - R1001 - Movement

No Asbestos

B00M - R1002 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Building Services - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00N - R0001 - Movement

No Asbestos

B00N - R0002 - Stairs

No Asbestos

B00N - R1001 - Movement

No Asbestos

B00N - R1002 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Building Services - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B000 - R0001 - Movement

No Asbestos

B000 - R0002 - Stairs

No Asbestos

B000 - R1001 - Movement

No Asbestos

B000 - R1002 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Building Services - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00P - R0001 - Movement

No Asbestos

B00P - R0002 - Stairs

No Asbestos

B00P - R1001 - Movement

No Asbestos

B00P - R1002 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - Building Services - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00Q - R0001 - Garden Store Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00R - Computer Learning/General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00R - R0001 - Computer Learning Space

No Asbestos

B00R - R0002 - Seminar - Type 2

No Asbestos

B00R - R0003 - Resources Store

No Asbestos

B00R - R0004 - Computer Store

No Asbestos

B00R - R0005 - Covered Area

No Asbestos

B00R - R0006 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00S - Other - 2010 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00S - R0001 - Maintenance Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017