

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Chipping Norton Public School (1560)
Region : South Western Sydney
State Electorate : Holsworthy
Local Government Area : Liverpool

Initial Survey : Noel Arnold & Associates : 29 - Apr - 2008
Reviewed By : AECOM : 26 - May - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00A - General Learning - 1955 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00A/Eaves Linings/S17				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00A - R0001 - Home Base**

In-fill-panel	Compressed AC Sheet	1m	North, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00A/R0002/Heater Bank/S10				Chrysotile (white asbestos)	
Ceiling Structures/Linings	No Asbestos Found					

B00A - R0002 - Home Base

In-fill-panel	Compressed AC Sheet	1m	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00A/R0002/Heater Bank/S10				Chrysotile (white asbestos)	
Ceiling Structures/Linings	No Asbestos Found					

B00A - R0003 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles					
	1560/B00A/R0005/Floor Coverings Res/Textile/S9				No Asbestos Detected	
Ceiling Structures/Linings	No Asbestos Found					

B00A - R0004 - Staff Room Annexe

No Asbestos

B00A - R0005 - Movement

Floor Coverings Res/Textile	Vinyl Tiles					
	1560/B00A/R0005/Floor Coverings Res/Textile/S9				No Asbestos Detected	
Ceiling Structures/Linings	No Asbestos Found					

B00A - R0006 - General Storeroom

No Asbestos

B00A - R0007 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00A/R0007/Ceiling Structures/Linings/S8				Chrysotile (white asbestos) , Amosite (brown asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1922 - Timber (Timber)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00B - R0001 - General Storeroom**

No Asbestos

B00B - R0002 - Special Programs Room

No Asbestos

B00B - R0003 - Special Programs Room

No Asbestos

B00B - R0004 - Movement

No Asbestos

B00B - R0005 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00C - Library - 1955 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	
	1560/B00C/R0005/Ceiling Structures/Linings/S13				Chrysotile (white asbestos)		
Ceiling Voids	No Asbestos Found						
Underfloor Voids	No Asbestos Found						

Interior**B00C - R0001 - Home Base**

In-fill-panel	Compressed AC Sheet	2m	South, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00C/R0001/In-fill-panel/S12			Chrysotile (white asbestos)		

B00C - R0002 - Home Base

In-fill-panel	Compressed AC Sheet	2m	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00C/R0001/In-fill-panel/S12			Chrysotile (white asbestos)		

B00C - R0003 - K.L.A. Store

No Asbestos

B00C - R0004 - Library Office/Workroom

No Asbestos

B00C - R0005 - No Access

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00C/R0005/Ceiling Structures/Linings/S13			Chrysotile (white asbestos)		

B00C - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	39m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00C/R0005/Ceiling Structures/Linings/S13			Chrysotile (white asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1913 - Timber (Timber)**Exterior**

Ceiling Voids Non Accessible Area
- Area inaccessible

Underfloor Voids No Asbestos Found

Interior**B00D - R0001 - Special Programs Room**

In-fill-panel Flat AC Sheeting 2m South, West Good Condition (1) Low (1) Low Priority (2-3)

1560/B00D/R0001/In-fill-panel/S14

Chrysotile (white asbestos)

Ceiling Structures/Linings No Asbestos Found

B00D - R0002 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning/Pupil Facilities - 1975 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior**B00F - R0003 - Personal Effects Storage**

No Asbestos

B00F - R0004 - General Storeroom

No Asbestos

B00F - R0005 - Toilets - Boys/Girls

No Asbestos

B00F - R0006 - Home Base

No Asbestos

B00F - R0007 - Home Base

No Asbestos

B00F - R0008 - Toilets - Boys/Girls

No Asbestos

B00F - R0009 - Home Base Store

No Asbestos

B00F - R0010 - Personal Effects Storage

No Asbestos

B00F - R0012 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 1560/B00F/R0012/Ceiling Structures/Linings/S3	No Asbestos Detected
----------------------------	-------------------------------------------------------------------	----------------------

B00F - R0013 - Disabled Toilet

Wall Linings Internal	Flat AC Sheeting 1560/B00F/R0013/Wall Linings Internal/S18	No Asbestos Detected
-----------------------	---------------------------------------------------------------	----------------------

Ceiling Structures/Linings	Flat AC Sheeting 1560/B00F/R0013/Wall Linings Internal/S18	No Asbestos Detected
----------------------------	---------------------------------------------------------------	----------------------

B00F - R0014 - Staff Room

No Asbestos

B00F - R0015 - Staff Room Annexe

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00G - Pupil Facilities - 1955 - Timber (Timber)**Exterior**

Ceiling Voids - Flat Roof No Asbestos Found

Underfloor Voids - Slab No Asbestos Found
on Ground**Interior****B00G - R0001 - Drinking Facilities**

No Asbestos

B00G - R0002 - Drinking Facilities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
B00I - Administration/Staff Facilities - 1973 - Brick/Veneer (Brick/Veneer)						
Exterior						
Awnings	Flat AC Sheeting 1560/B00I/Awnings/S5				No Asbestos Detected	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Interior						
B00I - R0004 - Plant						
Floor Coverings Res/Textile	Vinyl Tiles 1560/B00I/R0004/Floor Coverings Res/Textile/S1	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 1560/B00I/R0008/Ceiling Structures/Linings/S2	1m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00I - R0008 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting 1560/B00I/R0008/Ceiling Structures/Linings/S2	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00I - R0012 - Security Store						
No Asbestos						
B00I - R0013 - Staff Toilet						
No Asbestos						
B00I - R0014 - Staff Toilet						
No Asbestos						
B00I - R0015 - Sick Bay						
No Asbestos						
B00I - R0016 - Staff Shower/Change						
No Asbestos						
B00I - R0018 - Clerical Office						
No Asbestos						
B00I - R0019 - Principal						
No Asbestos						
B00I - R0023 - Entry Vestibule						
No Asbestos						
B00I - R0024 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting 1560/B00I/R0008/Ceiling Structures/Linings/S2	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00I - R0025 - Deputy Principal						
No Asbestos						
B00I - R0026 - Movement						
No Asbestos						
B00I - R0027 - Interview						
No Asbestos						
B00I - R0028 - Interview/Office - Type 3						
No Asbestos						
B00I - R0029 - Duplicating Workroom						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
B00J - Administration - 1924 - Timber (Timber)						
Exterior						
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Interior						
B00J - R0001 - Movement						
No Asbestos						
B00J - R0002 - Duplicating Workroom						
Wall Linings Internal	Flat AC Sheeting	13m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00J/R0010/Wall Linings Internal/S6				Chrysotile (white asbestos)	
Ceiling Structures/Linings	No Asbestos Found					
B00J - R0003 - Staff Kitchen						
Floor Coverings Res/Textile	Vinyl Tiles				No Asbestos Detected	
	1560/B00J/R0010/Floor Coverings Res/Textile/S7					
Wall Linings Internal	Flat AC Sheeting	10m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00J/R0010/Wall Linings Internal/S6				Chrysotile (white asbestos)	
B00J - R0004 - General Storeroom						
Wall Linings Internal	Flat AC Sheeting	20m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00J/R0010/Wall Linings Internal/S6				Chrysotile (white asbestos)	
B00J - R0005 - Movement						
Ceiling Structures/Linings	No Asbestos Found					
B00J - R0006 - Movement						
Ceiling Structures/Linings	No Asbestos Found					
B00J - R0007 - General Storeroom						
Wall Linings Internal	Flat AC Sheeting	18m2	North, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00J/R0007/Wall Linings Internal/S19				Chrysotile (white asbestos) , Crocidolite (blue asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00J/R0007/Ceiling Structures/Linings/S20				Chrysotile (white asbestos)	
B00J - R0008 - General Storeroom						
Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00J/R0002/Ceiling Structures/Linings/S15				Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00J - R0009 - Interview						
Ceiling Structures/Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00A/R0007/Ceiling Structures/Linings/S8				Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00J - R0010 - Movement						
Wall Linings Internal	Flat AC Sheeting	2m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00J/R0010/Wall Linings Internal/S6				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles				No Asbestos Detected	
	1560/B00J/R0010/Floor Coverings Res/Textile/S7					
B00J - R0011 - No Access						
No Asbestos						
B00J - R0012 - No Access						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00J/R0007/Ceiling Structures/Linings/S20				Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00J/R0007/Ceiling Structures/Linings/S20				Chrysotile (white asbestos)	
B00J - R0013 - No Access						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00J/R0007/Ceiling Structures/Linings/S20				Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00J/R0007/Ceiling Structures/Linings/S20				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00K - Building Services - 1949 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	
	1560/B00K/R0001/Wall Linings Internal/S16				Chrysotile (white asbestos)		
Ceiling Voids	No Asbestos Found						
Underfloor Voids - Slab on Ground	No Asbestos Found						

Interior**B00K - R0001 - General Storeroom**

Wall Linings Internal	Flat AC Sheeting	30m2	North, South, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00K/R0001/Wall Linings Internal/S16				Chrysotile (white asbestos)	

B00K - R0002 - General Storeroom

Wall Linings Internal	Flat AC Sheeting	30m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1560/B00K/R0001/Wall Linings Internal/S16				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00M - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00M - R0001 - Communal Space**

No Asbestos

B00M - R0002 - Raised Platform

No Asbestos

B00M - R0003 - Hall Chair Store

No Asbestos

B00M - R0004 - Communal/Performance Store

No Asbestos

B00M - R0005 - P.E. Store

No Asbestos

B00M - R0006 - Toilet - Lobby

No Asbestos

B00M - R0007 - Toilets - Girls

No Asbestos

B00M - R0008 - Sound Cupboard

No Asbestos

B00M - R0009 - Toilet - Lobby

No Asbestos

B00M - R0010 - Toilets - Boys

No Asbestos

B00M - R0011 - Cleaning Distributed Store

No Asbestos

B00M - R0012 - Plant

No Asbestos

B00M - R0013 - Main Switch Board

No Asbestos

B00M - R0014 - Access Shower/Toilet

No Asbestos

B00M - R0015 - Covered Outdoor Learning Area

No Asbestos

B00M - R0016 - Movement

No Asbestos

B00M - R0017 - Ramp

No Asbestos

B00M - R0018 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B0B1 - General Learning - 2006 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B0B1 - R0001 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

B0B1 - R0002 - Home Base StoreVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0B1 - R0003 - Practical Activities - 1hb**

No Asbestos

B0B1 - R0004 - Home BaseVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0B1 - R0005 - Withdrawal Space - 2hb**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0B1 - R0006 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0B1 - R0007 - Practical Activities - 1hb**

No Asbestos

B0B1 - R0008 - Home Base StoreVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0B1 - R0009 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
B0C1 - General Learning - 2006 - Brick/Veneer (Brick/Veneer)						
Exterior						
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Interior						
B0C1 - R0001 - Practical Activities - 1hb						
No Asbestos						
B0C1 - R0002 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0C1 - R0003 - Distribution Board				Note: No inspection of live electrical installation.		
No Asbestos						
B0C1 - R0004 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0C1 - R0005 - Withdrawal Space - 2hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0C1 - R0006 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0C1 - R0007 - Practical Activities - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0C1 - R0008 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0C1 - R0009 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0C1 - R0010 - Practical Activities - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0C1 - R0011 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0C1 - R0012 - Withdrawal Space - 2hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0C1 - R0013 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0C1 - R0014 - Practical Activities - 1hb						
No Asbestos						
B0C1 - R0015 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0C1 - R0016 - Distribution Board				Note: No inspection of live electrical installation.		
No Asbestos						
B0C1 - R0017 - Movement						
No Asbestos						
B0C1 - R0018 - Laundry - Type 2						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0D1 - Library/Pupil Facilities - 2006 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B0D1 - R0001 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B0D1 - R0002 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B0D1 - R0003 - Communications Room

No Asbestos

B0D1 - R0004 - K.L.A. Store

No Asbestos

B0D1 - R0005 - Cleaning Distributed Store

No Asbestos

B0D1 - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B0D1 - R0007 - Staff Toilet

No Asbestos

B0D1 - R0008 - Movement

No Asbestos

B0D1 - R0009 - Toilets - Girls/Disabled Cubicle

No Asbestos

B0D1 - R0010 - Kiln Room

No Asbestos

B0D1 - R0011 - Toilets - Boys/Disabled Cubicle

No Asbestos

B0D1 - R0012 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables**Demountable details as per the AMS records as of 15 Feb 2017.****OS 750 - D10353 - Learning Unit - ESL : Placement Date - 5/01/2017****Exterior**

No Asbestos Found.

Interior**R1 - Esl**

No Asbestos Found.

OS 801 - D12059 - FSU : Placement Date - 30/04/2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior**R1 - Canteen**

No Asbestos Found.

R2 - Covered Area

No Asbestos Found.

OS 602 - D14939 - Learning Unit - Standard With P.A.A. : Placement Date - 21/02/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

1560_ASB_050813_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017