


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Cherrybrook Technology High School (8592)  
**Region :** Northern Sydney  
**State Electorate :** Epping  
**Local Government Area :** Hornsby

**Initial Survey :** Noel Arnold & Associates : 13 - Mar - 2008  
**Register Issue Date :** 24 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## B00A - Administration/General Learning - 1991 - Brick/Veneer (Brick/Veneer)

### Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

### Interior

#### B00A - R0001 - Computer Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00A - R0002 - External Movement

No Asbestos

#### B00A - R0003 - Resources Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00A - R0004 - Staff - Toilet

No Asbestos

#### B00A - R0005 - Toilets-Disabled

No Asbestos

#### B00A - R0006 - Resources Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00A - R0007 - External Stairs

No Asbestos

#### B00A - R0008 - Computer Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00A - R0009 - External Stairs

No Asbestos

#### B00A - R0010 - Plant

No Asbestos

#### B00A - R0011 - Plant

No Asbestos

#### B00A - R0012 - External Movement

No Asbestos

#### B00A - R0013 - External Stairs

No Asbestos

#### B00A - R0014 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00A - R0015 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00A - R0016 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00A - R0017 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

#### B00A - R0018 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00A - R0019 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00A - R0020 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
No Asbestos						
B00A - R0021 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0022 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0023 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0024 - External Stairs						
No Asbestos						
B00A - R0025 - External Movement						
No Asbestos						
B00A - R0026 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0028 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0030 - Resources Store						
No Asbestos						
B00A - R0031 - Movement						
No Asbestos						
B00A - R0032 - Cleaning Store - Distributed						
No Asbestos						
B00A - R0033 - Resources Store						
No Asbestos						
B00A - R0034 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0037 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0038 - Movement						
No Asbestos						
B00A - R0039 - Shared Learning Space						
No Asbestos						
B00A - R0040 - Movement						
No Asbestos						
B00A - R0041 - Movement						
No Asbestos						
B00A - R0042 - Computer Learning Space						
No Asbestos						
B00A - R0043 - Movement						
No Asbestos						
B00A - R9001 - Public Entry						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R9004 - Printing/Photocopying						
No Asbestos						
B00A - R9013 - Principal Office						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R9015 - General Storeroom						
No Asbestos						
B00A - R9016 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R9018 - Staff - Toilet						
No Asbestos						
B00A - R9019 - Staff - Toilet						
No Asbestos						
B00A - R9020 - Interview/Meeting						
Vinyl Tiles (Under Floor      No Asbestos Found Covering/Carpet)						
B00A - R9021 - Interview/Meeting						
Vinyl Tiles (Under Floor      No Asbestos Found Covering/Carpet)						
B00A - R9023 - Movement						
Vinyl Tiles (Under Floor      No Asbestos Found Covering/Carpet)						
B00A - R9024 - Staff - Toilet						
No Asbestos						
B00A - R9025 - Staff - Toilet						
No Asbestos						
B00A - R9026 - Clinic						
No Asbestos						
B00A - R9027 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor      No Asbestos Found Covering/Carpet)						
B00A - R9028 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor      No Asbestos Found Covering/Carpet)						
B00A - R9029 - Office/Store						
Vinyl Tiles (Under Floor      No Asbestos Found Covering/Carpet)						
B00A - R9030 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor      No Asbestos Found Covering/Carpet)						
B00A - R9031 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor      No Asbestos Found Covering/Carpet)						
B00A - R9032 - Tea Room						
No Asbestos						
B00A - R9033 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R9034 - Plant						
No Asbestos						
B00A - R9035 - Main Switchroom						
No Asbestos						
B00A - R9036 - Toilets-Boys						
No Asbestos						
B00A - R9037 - Toilets-Girls						
No Asbestos						
B00A - R9038 - Archive Store						
No Asbestos						
B00A - R9039 - External Stairs						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
No Asbestos						
B00A - R9040 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00A - R9041 - External Movement						
No Asbestos						
B00A - R9042 - External Stairs						
No Asbestos						
B00A - R9043 - Plant						
No Asbestos						
B00A - R9044 - External Movement						
No Asbestos						
B00A - R9045 - External Stairs						
No Asbestos						
B00A - R9046 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00A - R9048 - Administration - Clerical						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00A - R9049 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00A - R9050 - Administration - Executive						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00A - R9051 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00A - R9052 - Deputy Principal Office						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00A - R9053 - Interview/Meeting						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00A - R9054 - External Stairs						
No Asbestos						
B00A - R9055 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00A - R9056 - Tea Room						
No Asbestos						
B00A - R9057 - Cleaning Store - Distributed						
No Asbestos						
B00A - R9058 - Ancillary Staff						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00A - R9059 - Toilets-Disabled						
No Asbestos						
B00A - R9060 - Staff - Toilet						
No Asbestos						
B00A - R9062 - Public Reception						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00A - R9064 - Deputy Principal Office						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R9065 - Deputy Principal Office</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R9068 - General Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R9069 - Administration - Executive</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R9070 - Independent Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R9071 - Deputy Principal Office</b>						
No Asbestos						
<b>B00A - R9072 - Secure Storeroom</b>						
No Asbestos						
<b>B00A - R9073 - Student Reception</b>						
No Asbestos						
<b>B00A - R9074 - Movement</b>						
No Asbestos						
<b>B00A - R9075 - External Movement</b>						
No Asbestos						
<b>B00A - R9076 - Archive Store</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## B00B - Multi Purpose Facilities - 1991 - Brick/Block (Brick/Block)

### Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

### Interior

#### B00B - R0001 - Plant

No Asbestos

#### B00B - R0002 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00B - R0003 - Plant

No Asbestos

#### B00B - R0004 - Control Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00B - R0005 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00B - R0006 - Cleaning Store - Distributed

No Asbestos

#### B00B - R0007 - Toilets-Boys

No Asbestos

#### B00B - R0008 - Toilets-Girls

No Asbestos

#### B00B - R0009 - Plant

No Asbestos

#### B00B - R0010 - Sport Equipment Store

No Asbestos

#### B00B - R0012 - Performance Store

No Asbestos

#### B00B - R0013 - Movement

No Asbestos

#### B00B - R0014 - General Storeroom

No Asbestos

#### B00B - R0018 - General Storeroom

No Asbestos

#### B00B - R0019 - General Storeroom

No Asbestos

#### B00B - R0020 - General Assistants

No Asbestos

#### B00B - R0021 - Tiered Learning Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00B - R0022 - Cleaning Supplies Store

No Asbestos

#### B00B - R0023 - External Movement

No Asbestos

#### B00B - R0024 - Movement

No Asbestos

#### B00B - R0025 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0026 - Practice/Seminar						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00B - R0027 - Practice/Seminar						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00B - R0028 - Staff Study						
No Asbestos						
B00B - R0029 - Tea Room						
No Asbestos						
B00B - R0030 - Resources Store						
No Asbestos						
B00B - R0031 - Office/Store						
No Asbestos						
B00B - R0032 - Tea Room						
No Asbestos						
B00B - R0033 - External Movement						
No Asbestos						
B00B - R0034 - Office/Store						
No Asbestos						
B00B - R0035 - Tea Room						
No Asbestos						
B00B - R9001 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00B - R9002 - Plant						
No Asbestos						
B00B - R9003 - Toilets-Disabled						
No Asbestos						
B00B - R9004 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00B - R9005 - Toilets-Girls						
No Asbestos						
B00B - R9006 - Toilets-Boys						
No Asbestos						
B00B - R9007 - Fitness Laboratory						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00B - R9008 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00B - R9009 - Machine Storage						
No Asbestos						
B00B - R9010 - Sport Equipment Store						
No Asbestos						
B00B - R9012 - Communications Cupboard						
No Asbestos						
B00B - R9016 - Movement						
No Asbestos						
B00B - R9017 - Plant						
No Asbestos						
B00B - R9018 - Plant						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
No Asbestos						
B00B - R9019 - Stage						
No Asbestos						
B00B - R9020 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R9021 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R9022 - Chair Store						
No Asbestos						
B00B - R9023 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R9024 - Plant						
No Asbestos						
B00B - R9025 - Plant						
No Asbestos						
B00B - R9026 - Staff Kitchen						
No Asbestos						
B00B - R9033 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R9034 - Sport Equipment Store						
No Asbestos						
B00B - R9038 - External Movement						
No Asbestos						
B00B - R9039 - Tiered Learning Area						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R9040 - Multi-Purpose Space						
No Asbestos						
B00B - R9041 - Movement						
No Asbestos						
B00B - R9042 - Chair Store						
No Asbestos						
B00B - R9043 - Sport Equipment Store						
No Asbestos						
B00B - R9044 - Movement						
No Asbestos						
B00B - R9045 - Toilet - Lobby						
No Asbestos						
B00B - R9046 - Change						
No Asbestos						
B00B - R9047 - Shower						
No Asbestos						
B00B - R9048 - Toilet - Lobby						
No Asbestos						
B00B - R9049 - Change						
No Asbestos						
B00B - R9050 - Shower						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - R9051 - Movement**

No Asbestos

**B00B - R9052 - Garden Store Room**

No Asbestos

**B00B - R9053 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

**B00C - Performance Learning/Pupil Facilities - 1991 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00C - R0003 - Lift**

No Asbestos

**B00C - R0004 - Lift**

No Asbestos

**B00C - R0005 - Covered Area**

No Asbestos

**B00C - R0006 - External Stairs**

No Asbestos

**B00C - R0007 - External Movement**

No Asbestos

**B00C - R0008 - Performance Workshop**

No Asbestos

**B00C - R0009 - Handwashing Facilities**

No Asbestos

**B00C - R9001 - Performance Workshop**

No Asbestos

**B00C - R9002 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00C - R9009 - External Stairs**

No Asbestos

**B00C - R9010 - Plant**

No Asbestos

**B00C - R9011 - Change**

No Asbestos

**B00C - R9012 - Change**

No Asbestos

**B00C - R9014 - Plant**

No Asbestos

**B00C - R9015 - Toilet - Lobby**

No Asbestos

**B00C - R9016 - Toilets-Girls**

No Asbestos

**B00C - R9017 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## B00D - Technological & Applied Studies/Music - 1991 - Brick/Block (Brick/Block)

### Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

### Interior

#### B00D - R0002 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00D - R0003 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00D - R0004 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00D - R0005 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00D - R0008 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00D - R0009 - Food/Research Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00D - R0010 - Resources Store

No Asbestos

#### B00D - R0011 - Food Technology L.S.

No Asbestos

#### B00D - R0013 - Laundry

No Asbestos

#### B00D - R0014 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

#### B00D - R0015 - Cleaning Store - Distributed

No Asbestos

#### B00D - R0016 - Covered Area

No Asbestos

#### B00D - R0017 - Pantry

No Asbestos

#### B00D - R0018 - Kitchen - Type 1

No Asbestos

#### B00D - R0020 - Class Tools Storage

No Asbestos

#### B00D - R0021 - Class Tools Storage

No Asbestos

#### B00D - R0022 - Student Canteen

No Asbestos

#### B00D - R0023 - Office/Store

No Asbestos

#### B00D - R0025 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00D - R0026 - Independent Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R0028 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00D - R0029 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00D - R0030 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00D - R0031 - Independent Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00D - R0033 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00D - R0034 - External Movement						
No Asbestos						
B00D - R0036 - Computer Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00D - R0037 - General Storeroom						
No Asbestos						
B00D - R0038 - Plant						
No Asbestos						
B00D - R0039 - Plant						
No Asbestos						
B00D - R0040 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00D - R0041 - Movement						
No Asbestos						
B00D - R0042 - Preparation						
No Asbestos						
B00D - R0043 - Store - Coolroom						
No Asbestos						
B00D - R0044 - Store - Coolroom						
No Asbestos						
B00D - R0045 - Plant						
No Asbestos						
B00D - R0046 - Pantry						
No Asbestos						
B00D - R0047 - Vending Machines						
No Asbestos						
B00D - R0048 - External Movement						
No Asbestos						
B00D - R9001 - Resources Store						
No Asbestos						
B00D - R9002 - Senior Study						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00D - R9003 - Design/Technology L.S.						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00D - R9004 - Music Learning Space						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No			Test Result		

Vinyl Tiles (Under Floor  
Covering/Carpet)      No Asbestos Found

#### B00D - R9005 - Music Store

No Asbestos

#### B00D - R9006 - Practice/Seminar

Vinyl Tiles (Under Floor      No Asbestos Found  
Covering/Carpet)

#### B00D - R9007 - Music Learning Space

Vinyl Tiles (Under Floor      No Asbestos Found  
Covering/Carpet)

#### B00D - R9008 - Practice/Seminar

Vinyl Tiles (Under Floor      No Asbestos Found  
Covering/Carpet)

#### B00D - R9009 - Practice/Seminar

Vinyl Tiles (Under Floor      No Asbestos Found  
Covering/Carpet)

#### B00D - R9010 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## B00E - General Learning/Library - 1991 - Brick/Block (Brick/Block)

### Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

### Interior

#### B00E - R0001 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00E - R0002 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00E - R0003 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00E - R0004 - Careers Advisers Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00E - R0006 - Resources Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00E - R0007 - General Learning Space

No Asbestos

#### B00E - R0010 - Library Administration

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00E - R0011 - General Learning Space

No Asbestos

#### B00E - R0012 - Librarian

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00E - R0013 - Library Administration

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00E - R0014 - Audio Visual Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00E - R0015 - Study Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00E - R0016 - Resources Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00E - R0017 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00E - R0018 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

#### B00E - R0019 - General Learning Space

No Asbestos

#### B00E - R0020 - Resources Store

No Asbestos

#### B00E - R0022 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
B00E - R0023 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00E - R0024 - External Movement						
No Asbestos						
B00E - R0025 - External Movement						
No Asbestos						
B00E - R0026 - Movement						
No Asbestos						
B00E - R0027 - Study Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00E - R0028 - Computer Resource						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00E - R0029 - Plant						
No Asbestos						
B00E - R0030 - Plant						
No Asbestos						
B00E - R0031 - Main Area						
No Asbestos						
B00E - R0032 - Main Entry						
No Asbestos						
B00E - R0033 - Main Entry						
No Asbestos						
B00E - R9002 - Staff Kitchen						
No Asbestos						
B00E - R9005 - Resources Store						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00E - R9007 - External Movement						
No Asbestos						
B00E - R9008 - Coffee Kiosk						
No Asbestos						
B00E - R9009 - Commonroom						
No Asbestos						
B00E - R9010 - Toilet - Lobby						
No Asbestos						
B00E - R9011 - Staff - Toilet						
No Asbestos						
B00E - R9012 - Toilet - Lobby						
No Asbestos						
B00E - R9013 - Staff - Toilet						
No Asbestos						
B00E - R9014 - Staff Study						
No Asbestos						
B00E - R9015 - Tea Room						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## B00F - Technological & Applied Studies/Pupil Facilities - 1991 - Brick/Block (Brick/Block)

### Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

### Interior

#### B00F - R0001 - External Movement

No Asbestos

#### B00F - R0002 - Design/Technology L.S.

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

#### B00F - R0005 - External Stairs

No Asbestos

#### B00F - R0006 - Cleaning Store - Distributed

No Asbestos

#### B00F - R0008 - Computer Resource

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

#### B00F - R0009 - Plant

No Asbestos

#### B00F - R0010 - Plant

No Asbestos

#### B00F - R0011 - Access Student Shower/Toilet/Change

No Asbestos

#### B00F - R0012 - Darkroom Space

No Asbestos

#### B00F - R0013 - Darkroom Space

No Asbestos

#### B00F - R0014 - Dark Room

No Asbestos

#### B00F - R9001 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

#### B00F - R9002 - Printing/Photocopying

No Asbestos

#### B00F - R9003 - Toilets-Girls

No Asbestos

#### B00F - R9004 - Cleaning Store - Distributed

No Asbestos

#### B00F - R9005 - Toilets-Boys

No Asbestos

#### B00F - R9006 - Communications Cupboard

No Asbestos

#### B00F - R9007 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

#### B00F - R9008 - Resources Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

#### B00F - R9009 - Computer Learning Space

No Asbestos

#### B00F - R9010 - Resources Store

No Asbestos

#### B00F - R9014 - Plant

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

No Asbestos

**B00F - R9015 - External Movement**

No Asbestos

**B00F - R9016 - External Movement**

No Asbestos

**B00F - R9017 - Plant**

No Asbestos

**B00F - R9018 - Handwashing Facilities**

No Asbestos

**B00F - R9019 - Design/Technology L.S.**

No Asbestos

**B00F - R9020 - General Storeroom**

No Asbestos

**B00F - R9021 - Resources Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00G - Science Learning/Technological & Applied Studies - 1991 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00G - R0001 - Resources Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00G - R0003 - Art Learning Space**

No Asbestos

**B00G - R0004 - Art Learning Space**

No Asbestos

**B00G - R0005 - Multi Media Workshop**

No Asbestos

**B00G - R0007 - Resources Store**

No Asbestos

**B00G - R0009 - Multi Media Workshop**

No Asbestos

**B00G - R0011 - Resources Store**

No Asbestos

**B00G - R0013 - Materials Workshop - Type 2**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00G - R0014 - Laboratory L.S.**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00G - R0015 - Cleaning Store - Distributed**

No Asbestos

**B00G - R0016 - Chemical Store**

No Asbestos

**B00G - R0017 - Apparatus Store**

No Asbestos

**B00G - R0018 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00G - R0020 - Laboratory L.S.**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00G - R0022 - Laboratory L.S.**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00G - R0023 - Laboratory L.S.**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00G - R0024 - Laboratory L.S.**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00G - R0025 - Laboratory L.S.**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00G - R0027 - External Movement**

No Asbestos

**B00G - R0028 - Resources Store**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
<b>B00G - R0029 - Cleaning Store - Distributed</b>						
No Asbestos						
<b>B00G - R0031 - Kiln Space</b>						
No Asbestos						
<b>B00G - R0032 - Plant</b>						
No Asbestos						
<b>B00G - R0033 - Plant</b>						
No Asbestos						
<b>B00G - R0034 - Movement</b>						
No Asbestos						
<b>B00G - R0035 - Preparation - Science</b>						
No Asbestos						
<b>B00G - R0036 - Movement</b>						
No Asbestos						
<b>B00G - R0037 - Movement</b>						
No Asbestos						
<b>B00G - R0038 - Art Learning Space</b>						
No Asbestos						
<b>B00G - R0039 - Design L.S.</b>						
No Asbestos						
<b>B00G - R0040 - Laundry</b>						
No Asbestos						
<b>B00G - R9001 - Design L.S.</b>						
No Asbestos						
<b>B00G - R9002 - Resources Store</b>						
No Asbestos						
<b>B00G - R9003 - Materials Workshop - Type 2</b>						
No Asbestos						
<b>B00G - R9004 - Materials Store</b>						
No Asbestos						
<b>B00G - R9005 - Materials Technology L.S.</b>						
No Asbestos						
<b>B00G - R9006 - Wood Technology Bay</b>						
No Asbestos						
<b>B00G - R9007 - Materials Technology L.S.</b>						
No Asbestos						
<b>B00G - R9008 - Project Store - Type 1</b>						
No Asbestos						
<b>B00G - R9009 - Resources Store</b>						
No Asbestos						
<b>B00G - R9010 - Project Store - Type 1</b>						
No Asbestos						
<b>B00G - R9011 - Dust Extraction Space</b>						
No Asbestos						
<b>B00G - R9013 - External Movement</b>						
No Asbestos						
<b>B00G - R9014 - Plant</b>						
No Asbestos						
<b>B00G - R9015 - Materials Workshop - Type 2</b>						
No Asbestos						
<b>B00G - R9016 - External Movement</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

**B00H - Agricultural Science - 1991 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00H - R0001 - Agriculture Covered Area**

No Asbestos

**B00H - R0002 - Staff - Toilet**

No Asbestos

**B00H - R0003 - Staff Shower**

No Asbestos

**B00H - R0004 - Resources Store**

No Asbestos

**B00H - R0005 - General Learning Space**

Vinyl Tiles (Under Floor      No Asbestos Found  
Covering/Carpet)

**B00H - R0006 - Machine Storage**

No Asbestos

**B00H - R0007 - General Storeroom**

No Asbestos

**B00H - R0008 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

**B00J - Staff Facilities - 1991 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00J - R0001 - Staff - Toilet**

No Asbestos

**B00J - R0003 - Staff Shower**

No Asbestos

**B00J - R0005 - Staff - Toilet**

No Asbestos

**B00J - R0007 - Sport Equipment Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

## Demountables

**Demountable details as per the AMS records as of 15 Feb 2017.**

**NS 110 - D10567 - Learning Unit - Single Secondary/Secure : Placement Date - 14/07/2008**

### Exterior

No Asbestos Found.

### Interior

#### R1 - General Learning Space

No Asbestos Found.

#### R2 - Entry

No Asbestos Found.

#### R3 - Secure Storeroom

No Asbestos Found.

**OS 720 - D10592 - Science Laboratory/Prep Room : Placement Date - 6/03/2012**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

### Exterior

No Asbestos Found.

### Interior

#### R1 - Laboratory L.S.

No Asbestos Found.

#### R2 - Preparation

No Asbestos Found.

**OS 601 - D10705 - Learning Unit - Standard/Withdrawal : Placement Date - 10/02/2005**

### Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

### Interior

#### R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

#### R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

#### R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

**NS 200 - D10892 - Art Learning Space/Workshop/Bulk Store : Placement Date - 30/06/1995**

### Exterior

No Asbestos Found.

### Interior

#### R1 - Art Learning Space

No Asbestos Found.

#### R2 - Workshop

No Asbestos Found.

#### R3 - Bulk Store

No Asbestos Found.

**OS 760 - D10952 - Woodwork/Store : Placement Date - 22/03/1999**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**Exterior**

Eave Lining	Flat AC Sheet	Assumed Asbestos	17.28 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

**Interior**
**R1 - Woodwork**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	91 m2

**R2 - Store**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	18 m2

**OS 720 - D13064 - Science Laboratory/Prep Room : Placement Date - 16/03/2006**
**Exterior**

Eave Lining	Flat AC Sheet	Assumed Asbestos	17.28 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

**Interior**
**R1 - Laboratory L.S.**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	90 m2

**R2 - Preparation**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	19 m2

**OS 720 - D13125 - Science Laboratory/Prep Room : Placement Date - 29/01/2003**
**Exterior**

Eave Lining	Flat AC Sheet	Assumed Asbestos	17.28 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

**Interior**
**R1 - Laboratory L.S.**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	90 m2

**R2 - Preparation**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	19 m2

**NS 110 - D13164 - Learning Unit - Single Secondary/Secure : Placement Date - 9/02/1998**
**Exterior**

No Asbestos Found.

**Interior**
**R1 - General Learning Space**

No Asbestos Found.

**R2 - Entry**

No Asbestos Found.

**R3 - Secure Storeroom**

No Asbestos Found.

**NS 110 - D13167 - Learning Unit - Single Secondary/Secure : Placement Date - 10/03/2003**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - General Learning Space</b>						
No Asbestos Found.						
<b>R2 - Entry</b>						
No Asbestos Found.						
<b>R3 - Secure Storeroom</b>						
No Asbestos Found.						
<b>NS 210 - D13181 - Home Science/Preparation Area/Laundry : Placement Date - 2/05/1997</b>						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Food Technology L.S.</b>						
No Asbestos Found.						
<b>R2 - Laundry</b>						
No Asbestos Found.						
<b>R3 - Preparation-Materials</b>						
No Asbestos Found.						
<b>R4 - Entry</b>						
No Asbestos Found.						
<b>NS 270 - D13187 - Metal Technics/Heat Area/Storage : Placement Date - 25/01/1996</b>						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Materials Technology L.S.</b>						
No Asbestos Found.						
<b>R2 - Store</b>						
No Asbestos Found.						
<b>R3 - Entry</b>						
No Asbestos Found.						
<b>NS 220 - D13192 - Science Learning/Preparation Space : Placement Date - 30/06/1995</b>						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Laboratory L.S.</b>						
No Asbestos Found.						
<b>R2 - Preparation</b>						
No Asbestos Found.						
<b>R3 - Entry</b>						
No Asbestos Found.						
<b>NS 220 - D13193 - Science Learning/Preparation Space : Placement Date - 27/01/2005</b>						
<b>Exterior</b>						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
Interior						
R1 - Laboratory L.S.						
No Asbestos Found.						
R2 - Preparation						
No Asbestos Found.						
R3 - Entry						
No Asbestos Found.						
OS 600 - D13406 - Learning Unit - Small : Placement Date - 8/03/1996						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos			8.64 m2	
Landing	Compressed AC Sheet	Assumed Asbestos			1.2 m2	
Step Treads	Compressed AC Sheet	Assumed Asbestos			1.08 m2	
Interior						
R1 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos			50 m2	
Ceiling	Flat AC Sheet	Assumed Asbestos			55 m2	
OS 521 - D13422 - Staff Study : Placement Date - 30/06/1995						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos			1.08 m2	
Eave Lining	Flat AC Sheet	Assumed Asbestos			11.52 m2	
Landing	Compressed AC Sheet	Assumed Asbestos			1.2 m2	
Interior						
R1 - Staff Room						
End wall panel	Flat AC Sheet	Assumed Asbestos			18 m2	
Ceiling	Flat AC Sheet	Assumed Asbestos			55 m2	
R2 - Staff Toilet						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos			6 m2	
Ceiling	Flat AC Sheet	Assumed Asbestos			4 m2	
R3 - Staff Toilet						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos			6 m2	
Ceiling	Flat AC Sheet	Assumed Asbestos			4 m2	
R4 - Lobby						
End wall panel	Flat AC Sheet	Assumed Asbestos			18 m2	
Ceiling	Flat AC Sheet	Assumed Asbestos			10 m2	
NS 110 - D14005 - Learning Unit - Single Secondary/Secure : Placement Date - 30/06/1995						
Exterior						
No Asbestos Found.						
Interior						
R1 - General Learning Space						
No Asbestos Found.						
R2 - Entry						
No Asbestos Found.						
R3 - Secure Storeroom						
No Asbestos Found.						
NS 110 - D14006 - Learning Unit - Single Secondary/Secure : Placement Date - 2/05/1997						
Exterior						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
No Asbestos Found.						
Interior						
R1 - General Learning Space						
No Asbestos Found.						
R2 - Entry						
No Asbestos Found.						
R3 - Secure Storeroom						
No Asbestos Found.						
NS 110 - D14007 - Learning Unit - Single Secondary/Secure : Placement Date - 13/12/2008						
Exterior						
No Asbestos Found.						
Interior						
R1 - General Learning Space						
No Asbestos Found.						
R2 - Entry						
No Asbestos Found.						
R3 - Secure Storeroom						
No Asbestos Found.						
OS 601 - D14655 - Learning Unit - Standard/Withdrawal : Placement Date - 19/02/2010						
Exterior						
No Asbestos Found.						
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Store						
No Asbestos Found.						
NS 111 - D14825 - Learning Unit - Double Secondary/Secure : Placement Date - 12/04/2010						
Exterior						
No Asbestos Found.						
Interior						
R1 - General Learning Space						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Entry						
No Asbestos Found.						
R4 - Secure Storeroom						
No Asbestos Found.						
R5 - Secure Storeroom						
No Asbestos Found.						
R6 - Entry						
No Asbestos Found.						
OS 600 - D14882 - Learning Unit - Small : Placement Date - 13/04/2010						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - General Learning Space</b>						
No Asbestos Found.						
<b>NS 111 - D15051 - Learning Unit - Double Secondary/Secure : Placement Date - 20/12/1995</b>						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - General Learning Space</b>						
No Asbestos Found.						
<b>R2 - General Learning Space</b>						
No Asbestos Found.						
<b>R3 - Entry</b>						
No Asbestos Found.						
<b>R4 - Secure Storeroom</b>						
No Asbestos Found.						
<b>R5 - Secure Storeroom</b>						
No Asbestos Found.						
<b>R6 - Entry</b>						
No Asbestos Found.						
<b>NS 110 - D15076 - Learning Unit - Single Secondary/Secure : Placement Date - 30/06/1995</b>						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - General Learning Space</b>						
No Asbestos Found.						
<b>R2 - Entry</b>						
No Asbestos Found.						
<b>R3 - Secure Storeroom</b>						
No Asbestos Found.						
<b>NS 110 - D15240 - Learning Unit - Single Secondary/Secure : Placement Date - 29/01/2009</b>						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - General Learning Space</b>						
No Asbestos Found.						
<b>R2 - Entry</b>						
No Asbestos Found.						
<b>R3 - Secure Storeroom</b>						
No Asbestos Found.						
<b>NS 110 - D15244 - Learning Unit - Single Secondary/Secure : Placement Date - 30/06/1995</b>						
<b>Exterior</b>						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
Interior						
R1 - General Learning Space						
No Asbestos Found.						
R2 - Entry						
No Asbestos Found.						
R3 - Secure Storeroom						
No Asbestos Found.						
NS 111 - D15306 - Learning Unit - Double Secondary/Secure : Placement Date - 30/06/1995						
Exterior						
No Asbestos Found.						
Interior						
R1 - General Learning Space						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Entry						
No Asbestos Found.						
R4 - Secure Storeroom						
No Asbestos Found.						
R5 - Secure Storeroom						
No Asbestos Found.						
R6 - Entry						
No Asbestos Found.						
NS 110 - D15344 - Learning Unit - Single Secondary/Secure : Placement Date - 30/06/1995						
Exterior						
No Asbestos Found.						
Interior						
R1 - General Learning Space						
No Asbestos Found.						
R2 - Entry						
No Asbestos Found.						
R3 - Secure Storeroom						
No Asbestos Found.						
OS 720 - D15412 - Science Laboratory/Prep Room : Placement Date - 23/08/1996						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				17.28 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Interior						
R1 - Laboratory L.S.						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				90 m2
R2 - Preparation						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				19 m2
OS 600 - D15417 - Learning Unit - Small : Placement Date - 28/01/2008						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				8.64 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
NS 110 - D15551 - Learning Unit - Single Secondary/Secure : Placement Date - 25/02/1999						
Exterior						
No Asbestos Found.						
Interior						
R1 - General Learning Space						
No Asbestos Found.						
R2 - Entry						
No Asbestos Found.						
R3 - Secure Storeroom						
No Asbestos Found.						
NS 111 - D15704 - Learning Unit - Double Secondary/Secure : Placement Date - 7/11/1996						
Exterior						
No Asbestos Found.						
Interior						
R1 - General Learning Space						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Entry						
No Asbestos Found.						
R4 - Secure Storeroom						
No Asbestos Found.						
R5 - Secure Storeroom						
No Asbestos Found.						
R6 - Entry						
No Asbestos Found.						
OS 600 - D15889 - Learning Unit - Small : Placement Date - 29/01/2009						
Exterior						
No Asbestos Found.						
Interior						
R1 - General Learning Space						
No Asbestos Found.						
NS 110 - D16068 - Learning Unit - Single Secondary/Secure : Placement Date - 9/02/1998						
Exterior						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
Interior						
R1 - General Learning Space						
No Asbestos Found.						
R2 - Entry						
No Asbestos Found.						
R3 - Secure Storeroom						
No Asbestos Found.						
NS 210 - D16259 - Home Science/Preparation Area/Laundry : Placement Date - 15/02/2007						
Exterior						
No Asbestos Found.						
Interior						
R1 - Food Technology L.S.						
No Asbestos Found.						
R2 - Laundry						
No Asbestos Found.						
R3 - Preparation-Materials						
No Asbestos Found.						
R4 - Entry						
No Asbestos Found.						
OS 521 - D16372 - Staff Study : Placement Date - 1/02/2005						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Interior						
R1 - Staff Room						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R2 - Staff Toilet						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos				6 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				4 m2
R3 - Staff Toilet						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos				6 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				4 m2
R4 - Lobby						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017