


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Dobroyd Point Public School (3873)
Region : Sydney
State Electorate : Summer Hill
Local Government Area : Ashfield

Initial Survey : Noel Arnold & Associates : 10 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 01 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B001 - Administration/Other-After School Care - 1995 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3873/B001/Eaves Linings/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					

Interior**B001 - R0001 - Toilets - Boys/Girls**

No Asbestos

B001 - R0002 - Personal Effects Storage

No Asbestos

B001 - R0003 - Movement

No Asbestos

B001 - R0004 - Home Base

No Asbestos

B001 - R0005 - Home Base

No Asbestos

B001 - R0006 - Movement

No Asbestos

B001 - R0007 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3873/B001/R0007/Ceiling Structures/Linings/S6				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

B001 - R0008 - Interview

No Asbestos

B001 - R0009 - Cleaning Distributed Store

No Asbestos

B001 - R0010 - Home Base

No Asbestos

B001 - R0011 - Home Base

No Asbestos

B001 - R0017 - Handwashing Facilities

Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3873/B001/R0015/Ceiling Structures/Linings/S3				Insufficient Sample	

B001 - R0018 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	25m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3873/B001/R0015/Ceiling Structures/Linings/S3				Insufficient Sample	

B001 - R0019 - Out Of School Hours Care Centre

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3873/B001/R0015/Ceiling Structures/Linings/S3				Insufficient Sample	

B001 - R0020 - Out Of School Hours Care Centre

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3873/B001/R0045/Ceiling Structures/Linings/S8				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B001 - R0024 - General Storeroom

No Asbestos

B001 - R0025 - Duplicating Workroom

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
No Asbestos						
B001 - R0026 - Principal						
No Asbestos						
B001 - R0027 - Interview						
No Asbestos						
B001 - R0028 - Movement						
No Asbestos						
B001 - R0029 - Entry Vestibule						
No Asbestos						
B001 - R0030 - Clerical Office						
No Asbestos						
B001 - R0031 - Sick Bay						
No Asbestos						
B001 - R0032 - Sick Bay - Shower/Toilet						
No Asbestos						
B001 - R0033 - Staff Toilet						
No Asbestos						
B001 - R0034 - Staff Toilet						
No Asbestos						
B001 - R0035 - Staff Toilet						
No Asbestos						
B001 - R0036 - Movement						
No Asbestos						
B001 - R0037 - Staff Room						
No Asbestos						
B001 - R0038 - Security Store						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3873/B001/R0038/Ceiling Structures/Linings/S7			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B001 - R0039 - Movement						
No Asbestos						
B001 - R0040 - Out Of School Hours Care Centre						
Ceiling Structures/Linings	Flat AC Sheeting	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3873/B001/R0045/Ceiling Structures/Linings/S8			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B001 - R0041 - Out Of School Hours Care Centre						
No Asbestos						
B001 - R0042 - Toilets-Unisex						
No Asbestos						
B001 - R0043 - General Storeroom						
No Asbestos						
B001 - R0044 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
	3873/B001/R0044/Ceiling Structures/Linings/S5			No Asbestos Detected		
B001 - R0045 - Toilets - Girls						
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3873/B001/R0045/Ceiling Structures/Linings/S8			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Partition Walls (Cubicles)	Compressed AC Sheet					
	3873/B001/R0045/Partition Walls (Cubicles)/S9			No Asbestos Detected		
B001 - R0046 - Entry Vestibule						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

No Asbestos

B001 - R0047 - Other-After School Care

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B005 - Pupil Facilities - 1960 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Void No Asbestos Found

Interior**B005 - R0001 - K.L.A. Store**

No Asbestos

B005 - R0002 - General Assistant/Bulk Store

No Asbestos

B005 - R0003 - External Movement

No Asbestos

B005 - R0004 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	---------------------	-----	--------------	--------------------	---------	--------------------

3873/B005/R0005/Partition Walls (Cubicles)/S10

Chrysotile (white asbestos) , Amosite (brown asbestos)

B005 - R0005 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	---------------------	------	--------------	--------------------	---------	--------------------

3873/B005/R0005/Partition Walls (Cubicles)/S10

Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B008 - Library - 2008 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B008 - R0001 - Reading Area**

No Asbestos

B008 - R0002 - Library Office/Workroom

No Asbestos

B008 - R0003 - Communications Room

No Asbestos

B008 - R0004 - K.L.A. Store

No Asbestos

B008 - R0005 - Cleaning Distributed Store

No Asbestos

B008 - R0006 - Special Programs Store

No Asbestos

B008 - R0007 - Special Programs Room - Type 2

No Asbestos

B008 - R0008 - External Movement

No Asbestos

B008 - R0009 - Special Programs Room - Type 2

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B009 - Communal Facilities - 2008 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab No Asbestos Found
on Ground

Ceiling Voids No Asbestos Found

Interior**B009 - R0001 - Communal Space**

No Asbestos

B009 - R0002 - Movement

No Asbestos

B009 - R0003 - Raised Platform

No Asbestos

B009 - R0004 - Communal/Performance Store

No Asbestos

B009 - R0005 - Sound Cupboard

No Asbestos

B009 - R0006 - Hall Chair Store

No Asbestos

B009 - R0007 - Access Shower/Toilet

No Asbestos

B009 - R0008 - Canteen

No Asbestos

B009 - R0009 - Canteen Office/Store

No Asbestos

B009 - R0010 - Covered Outdoor Learning Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B010 - General Learning - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B010 - R0001 - Home Base**

No Asbestos

B010 - R0002 - Home Base Store

No Asbestos

B010 - R0003 - Practical Activities - 1hb

No Asbestos

B010 - R0004 - Withdrawal Space - 2hb

No Asbestos

B010 - R0005 - Home Base

No Asbestos

B010 - R0006 - Home Base Store

No Asbestos

B010 - R0007 - Practical Activities - 1hb

No Asbestos

B010 - R0008 - External Movement

No Asbestos

B010 - R0009 - Home Base

No Asbestos

B010 - R0010 - Home Base Store

No Asbestos

B010 - R0011 - Practical Activities - 1hb

No Asbestos

B010 - R0012 - Withdrawal Space - 2hb

No Asbestos

B010 - R0013 - Home Base

No Asbestos

B010 - R0014 - Home Base Store

No Asbestos

B010 - R0015 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

Demountables**Demountable details as per the AMS records as of 15 Feb 2017.****OS 601 - D10044 - Learning Unit - Standard/Withdrawal : Placement Date - 23/01/2005****Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior**R1 - Entry**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 601 - D12263 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior**R1 - Entry**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 602 - D14063 - Learning Unit - Standard With P.A.A. : Placement Date - 26/11/2009**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior**R1 - Learning space/withdrawal/entry**

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 601 - D14127 - Learning Unit - Standard/Withdrawal : Placement Date - 2/03/2004

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Store						
No Asbestos Found.						
OS 971 - D70124 - Shed - Container (Garden/Sports/Bulk) : Placement Date - 11/01/2007						
Exterior						
No Asbestos Found.						
Interior						
R1 - Garden Store						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

3873_ASB_100913_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017