

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Deniliquin North Public School (4281)
Region : Riverina
State Electorate : Murray
Local Government Area : Deniliquin

Initial Survey : Noel Arnold & Associates : 12 - May - 2008
Reviewed By : Parsons Brinckerhoff : 15 - Feb - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - Administration/General Learning - 1963 - Brick/Block (Brick/Block)						
Exterior						
Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	75m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	4281/B00D/R0003/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	
Underfloor Voids	AC Fragments/Debris	2m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4281/B00A/Underfloor Voids/S8				Chrysotile (white asbestos)	
Interior						
B00A - R0001 - Home Base						
Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
	4281/B00A/R0007/Ceiling Structures/Linings/S2					
B00A - R0002 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00D/R0003/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	
B00A - R0003 - Main Switch Board						
Ceiling Structures/Linings	No Asbestos Found					
B00A - R0004 - Shower/Change						
Non Accessible						
B00A - R0005 - Home Base Store						
Floor Coverings Res/Textile	Vinyl Tiles	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00A/R0005/Floor Coverings Res/Textile/S1				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
	4281/B00A/R0007/Ceiling Structures/Linings/S2					
B00A - R0006 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00A/R0005/Floor Coverings Res/Textile/S1				Chrysotile (white asbestos)	
B00A - R0007 - Home Base						
Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
	4281/B00A/R0007/Ceiling Structures/Linings/S2					
B00A - R0008 - Withdrawal Space - 1hb						
No Asbestos						
B00A - R0009 - Sick Bay						
No Asbestos						
B00A - R0010 - Duplicating Workroom						
No Asbestos						
B00A - R0011 - Clerical Office						
No Asbestos						
B00A - R0012 - Movement						
Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
	4281/B00A/R0007/Ceiling Structures/Linings/S2					
B00A - R0013 - Entry Vestibule						
Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
	4281/B00A/R0007/Ceiling Structures/Linings/S2					
B00A - R0014 - Principal						
Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
	4281/B00A/R0007/Ceiling Structures/Linings/S2					
B00A - R0015 - Interview						
Ceiling Structures/Linings	Vermiculite					No Asbestos Detected
	4281/B00A/R0007/Ceiling Structures/Linings/S2					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
B00A - R0016 - Staff Room						
Ceiling Structures/Linings	Vermiculite					
	4281/B00A/R0007/Ceiling Structures/Linings/S2					No Asbestos Detected
B00A - R0017 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00A/R0005/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)
B00A - R0018 - Home Base Store						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00A/R0005/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)
B00A - R0021 - General Storeroom						
No Asbestos						
B00A - R0023 - Cleaning Distributed Store						
No Asbestos						
B00A - R0024 - Movement						
Ceiling Structures/Linings	Vermiculite					
	4281/B00A/R0007/Ceiling Structures/Linings/S2					No Asbestos Detected
B00A - R0026 - Staff Toilet						
No Asbestos						
B00A - R0027 - Toilet - Lobby						
No Asbestos						
B00A - R0028 - Toilet - Lobby						
No Asbestos						
B00A - R0029 - Staff Toilet						
No Asbestos						
B00A - R0030 - Movement						
No Asbestos						
B00A - R0031 - General Storeroom						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
B00B - General Learning - 1973 - Brick/Block (Brick/Block)						
Exterior						
Ceiling Voids - Raked Ceiling	No Asbestos Found					
In-fill-panel below Window	Flat AC Sheeting	10m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00C/Infill panel below windows/S6				Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	20m2	North facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00C/R1008/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	
Underfloor Voids	AC Fragments/Debris	2m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4281/B00B/Underfloor Voids/S9				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	No Asbestos Found					
Interior						
B00B - R0001 - Toilets - Girls						
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00B/R0002/Partition Walls (Cubicles)/S7				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	4m2	South end	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00C/R1008/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	
B00B - R0002 - Toilets - Boys						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00B/R0002/Partition Walls (Cubicles)/S7				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	4m2	South end	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00C/R1008/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	
B00B - R0003 - Distribution Board						
Electrical Mounting Board	Resinous Board	2Unit	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00A/R0005/Floor Coverings Res/Textile/S1				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	4281/B00C/R1008/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	2m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	4281/B00C/R1008/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	
B00B - R0004 - Craft Store						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00A/R0005/Floor Coverings Res/Textile/S1				Chrysotile (white asbestos)	
B00B - R0005 - Music Store						
No Asbestos						
B00B - R0006 - Withdrawal Space - 1hb						
Floor Coverings Res/Textile	Vinyl Tiles	28m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00A/R0005/Floor Coverings Res/Textile/S1				Chrysotile (white asbestos)	
B00B - R0007 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00C/R1008/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	
B00B - R0008 - Personal Effects Storage						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4281/B00A/R0005/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
B00B - R0009 - Home Base Store						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4281/B00A/R0005/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
B00B - R0010 - Toilets - Boys/Girls						
No Asbestos						
B00B - R0011 - Home Base						
No Asbestos						
B00B - R0012 - Home Base						
No Asbestos						
B00B - R0013 - Personal Effects Storage						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4281/B00A/R0005/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
B00B - R0014 - Home Base Store						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4281/B00A/R0005/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
B00B - R0015 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
B00C - General Learning - 1973 - Brick/Block (Brick/Block)						
Exterior						
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					
In-fill-panel below Window	Flat AC Sheeting	32m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00C/Infill panel below windows/S6				Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	18m2	South facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00C/R1008/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	
Gable verge lining	Flat AC Sheeting	12m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction Not able to be					
Interior						
B00C - R0001 - Craft Store						
No Asbestos						
B00C - R0002 - Cleaning Supplies						
No Asbestos						
B00C - R0003 - Home Base Store						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00A/R0005/Floor Coverings Res/Textile/S1				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite					
	4281/B00C/R0003/Ceiling Structures/Linings/S3				No Asbestos Detected	
B00C - R0004 - Personal Effects Storage						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00A/R0005/Floor Coverings Res/Textile/S1				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite					
	4281/B00C/R0003/Ceiling Structures/Linings/S3				No Asbestos Detected	
B00C - R0005 - Home Base						
Ceiling Structures/Linings	Vermiculite					
	4281/B00C/R0003/Ceiling Structures/Linings/S3				No Asbestos Detected	
B00C - R0006 - Home Base						
Ceiling Structures/Linings	Vermiculite					
	4281/B00C/R0003/Ceiling Structures/Linings/S3				No Asbestos Detected	
B00C - R0007 - Home Base Store						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00A/R0005/Floor Coverings Res/Textile/S1				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite					
	4281/B00C/R0003/Ceiling Structures/Linings/S3				No Asbestos Detected	
B00C - R0008 - Distribution Board						
Electrical Mounting Board	Resinous Board	1Unit	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00C/R0008/Electrical Mounting Board/S11				Chrysotile (white asbestos)	
B00C - R0009 - Personal Effects Storage						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00A/R0005/Floor Coverings Res/Textile/S1				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite					
	4281/B00C/R0003/Ceiling Structures/Linings/S3				No Asbestos Detected	
B00C - R0010 - External Movement						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
No Asbestos						
B00C - R0011 - Stairs						
No Asbestos						
B00C - R0012 - Distribution Board				Note: No inspection of live electrical installation.		
No Asbestos						
B00C - R1001 - General Storeroom						
No Asbestos						
B00C - R1002 - Home Base Store						
No Asbestos						
B00C - R1003 - Personal Effects Storage						
No Asbestos						
B00C - R1004 - Home Base						
No Asbestos						
B00C - R1005 - Home Base						
No Asbestos						
B00C - R1006 - Home Base Store						
No Asbestos						
B00C - R1007 - Personal Effects Storage						
No Asbestos						
B00C - R1008 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	49m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4281/B00C/R1008/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00D - Pupil Facilities - 1973 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	18m2	North facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00D/R0003/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting	2m	Below Eaves, North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00D/R0003/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)
Ceiling Voids	AC Fragments/Debris	2m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4281/B00D/Ceiling Voids/S10					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

Interior

B00D - R0001 - Staff Toilet

Incinerator	No Asbestos Found
-------------	-------------------

B00D - R0002 - Canteen

Floor Coverings Res/Textile	Vinyl Tiles	33m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00A/R0005/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)

B00D - R0003 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00D/R0003/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00D - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	44m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00D/R0003/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00D - R0005 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00D/R0003/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00D - R0006 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00D/R0003/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00D - R0007 - Canteen Office/Store

Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00A/R0005/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)

B00D - R0008 - Uniform Shop

Floor Coverings Res/Textile	Vinyl Tiles	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4281/B00A/R0005/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00G - Shed - 1982 - Steel (Steel)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Flat Roof No Asbestos Found

Interior**B00G - R0001 - General Assistant/Bulk Store**

No Asbestos

B00G - R0002 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00H - Shed - 1985 - Metal Shed (Metal Shed)**Exterior**

Ceiling Voids - Flat Roof No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior**B00H - R0001 - Sports Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00I - Communal Facilities - 2008 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00I - R0001 - External Movement**

No Asbestos

B00I - R0002 - Communal Space

No Asbestos

B00I - R0003 - P.E. Store

No Asbestos

B00I - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Library - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00J - R0001 - Reading Area**

No Asbestos

B00J - R0002 - External Movement

No Asbestos

B00J - R0003 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00J - R0004 - Toilet - Lobby

No Asbestos

B00J - R0005 - Cleaning Distributed Store

No Asbestos

B00J - R0006 - Staff Toilet

No Asbestos

B00J - R0007 - K.L.A. Store

No Asbestos

B00J - R0008 - Communications Room

No Asbestos

B00J - R0009 - Library Office/Workroom

No Asbestos

B00J - R9001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Storage - 2016 - Metal Shed (Metal Shed)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00K - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017