

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Eastern Creek Public School (1808)


Region : Western Sydney

State Electorate : Mount Druitt

Local Government Area : Blacktown

Initial Survey : Noel Arnold & Associates : 19 - May - 2008

Reviewed By : Parsons Brinckerhoff : 14 - May - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00A - Administration - 1966 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00F/Eaves Linings/S14			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00F/Gable Verge Lining/S18			Chrysotile (white asbestos) , Amosite (brown asbestos)		
In-fill-panel	Flat AC Sheeting	8m2	Lower window panels	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00A/R0013/In-fill-panel/S9			Chrysotile (white asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00A - R0001 - Staff Room**

No Asbestos

B00A - R0002 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00A/R0014/Floor Coverings Res/Textile/S11			Chrysotile (white asbestos)		

B00A - R0003 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00A/R0013/Ceiling Structures/Linings/S19			Chrysotile (white asbestos)		

B00A - R0004 - Clerical Office

No Asbestos

B00A - R0005 - Clerical Office

No Asbestos

B00A - R0006 - Principal

No Asbestos

B00A - R0007 - Interview

No Asbestos

B00A - R0008 - Sick Bay

No Asbestos

B00A - R0009 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	20m2	North, South, East, West, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00A/R0014/Wall Linings Internal/S10			Chrysotile (white asbestos)		

B00A - R0010 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	20m2	North, South, East, West, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00A/R0014/Wall Linings Internal/S10			Chrysotile (white asbestos)		

B00A - R0011 - Cleaning Distributed Store

No Asbestos

B00A - R0012 - Sports Store

No Asbestos

B00A - R0013 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00A/R0013/Ceiling Structures/Linings/S19			Chrysotile (white asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
In-fill-panel	Flat AC Sheeting	8m	Lower window panels	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00A/R0013/In-fill-panel/S9				Chrysotile (white asbestos)	
B00A - R0014 - Cleaning Distributed Store						
Wall Linings Internal	Flat AC Sheeting	20m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00A/R0014/Wall Linings Internal/S10				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00A/R0014/Floor Coverings Res/Textile/S11				Chrysotile (white asbestos)	
B00A - R0015 - Movement						
No Asbestos						
B00A - R0016 - Entry Vestibule						
No Asbestos						
B00A - R0017 - Covered Outdoor Learning Area						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00B - Pre-School Facilities - 1959 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00B/Eaves Linings/S13				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris	1m2	South	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	1808/B00B/Underfloor Voids/S22				Chrysotile (white asbestos)	
Underfloor Voids	Compressed AC Sheet	12m2	South	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	1808/B00B/Underfloor Voids/S22				Chrysotile (white asbestos)	

Interior**B00B - R0010 - External Movement**

No Asbestos

B00B - R0011 - Movement

No Asbestos

B00B - R0012 - General Storeroom - Pre

No Asbestos

B00B - R0013 - Laundry - Pre

No Asbestos

B00B - R0014 - General Storeroom - Pre

No Asbestos

B00B - R0015 - Home Base - Pre

No Asbestos

B00B - R0016 - Practical Activities - Pre

No Asbestos

B00B - R0017 - General Storeroom - Pre

No Asbestos

B00B - R0018 - Staff Room - Pre

No Asbestos

B00B - R0019 - Kitchen - Pre

No Asbestos

B00B - R0020 - Staff Toilet - Pre

No Asbestos

B00B - R0021 - Toilets - Boys/Girls - Pre

No Asbestos

B00B - R0022 - Covered Outdoor Learning Area - Pre

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00C - General Learning/Special Purpose Learning - 1959 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00F/Eaves Linings/S14			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00F/Gable Verge Lining/S18			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00C - R0001 - Home Base**

In-fill-panel	Flat AC Sheeting	2m	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00F/R0007/In-fill-panel/S1			Chrysotile (white asbestos) , Amosite (brown Asbestos)		

B00C - R0002 - Home Base Store

No Asbestos

B00C - R0003 - Personal Effects Storage

No Asbestos

B00C - R0004 - Movement

No Asbestos

B00C - R0007 - Movement

No Asbestos

B00C - R0008 - Home Base

In-fill-panel	Flat AC Sheeting	2m	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00F/R0007/In-fill-panel/S1			Chrysotile (white asbestos) , Amosite (brown Asbestos)		

B00C - R0009 - Home Base Store

No Asbestos

B00C - R0010 - Personal Effects Storage

No Asbestos

B00C - R0011 - Craft Store

No Asbestos

B00C - R0012 - General Storeroom

No Asbestos

B00C - R0013 - Covered Outdoor Learning Area

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00D - General Learning - 1959 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00F/Eaves Linings/S14			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00F/Gable Verge Lining/S18			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00D - R0002 - Home Base**

No Asbestos

B00D - R0003 - Home Base Store

No Asbestos

B00D - R0004 - Personal Effects Storage

No Asbestos

B00D - R0005 - Movement

No Asbestos

B00D - R0006 - Personal Effects Storage

No Asbestos

B00D - R0007 - Home Base Store

No Asbestos

B00D - R0008 - Home Base

No Asbestos

B00D - R0009 - Home Base

No Asbestos

B00D - R0010 - Home Base Store

No Asbestos

B00D - R0011 - Personal Effects Storage

No Asbestos

B00D - R0012 - Movement

Electrical Backing Board	Resinous Board	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	-----	------	--------------------	---------	--------------------

Assumed Asbestos - Electrical Hazard - Metal cased unit -

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00E - General Learning - 1959 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00F/Eaves Linings/S14			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00F/Gable Verge Lining/S18			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00E - R0001 - Interview**

No Asbestos

B00E - R0002 - Deputy Principal

No Asbestos

B00E - R0003 - General Storeroom

No Asbestos

B00E - R0004 - General Storeroom

No Asbestos

B00E - R0005 - General Storeroom

No Asbestos

B00E - R0006 - Home Base Store

No Asbestos

B00E - R0007 - Movement

No Asbestos

B00E - R0009 - Home Base

No Asbestos

B00E - R0010 - Home Base

No Asbestos

B00E - R0011 - Home Base Store

No Asbestos

B00E - R0012 - Personal Effects Storage

Electrical Backing Board	Resinous Board	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	-----	------	--------------------	---------	--------------------

Assumed Asbestos - Electrical Hazard - Metal cased Unit -**B00E - R0013 - General Storeroom**

No Asbestos

B00E - R0014 - General Storeroom

No Asbestos

B00E - R0015 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00F - General Learning/Library - 1959 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00F/Eaves Linings/S14			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00F/Gable Verge Lining/S18			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00F - R0001 - Special Programs Room**

No Asbestos

B00F - R0002 - Movement

No Asbestos

B00F - R0003 - Withdrawal Space - 1hb

No Asbestos

B00F - R0005 - Movement

No Asbestos

B00F - R0006 - Personal Effects Storage

No Asbestos

B00F - R0007 - Home Base

In-fill-panel	Flat AC Sheeting	2m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	1808/B00F/R0007/In-fill-panel/S1			Chrysotile (white asbestos) , Amosite (brown Asbestos)		

B00F - R0008 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00G - General Learning - 1959 - Brick/Veneer (Brick/Veneer)**Exterior**

Wall Cladding	Flat AC Sheeting 1808/B00G/R0008/Wall cladding/S7	No Asbestos Detected				
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00G - R0001 - Movement**

Wall cladding	Flat AC Sheeting 1808/B00G/R0008/Wall cladding/S7	No Asbestos Detected				
In-fill-panel	Flat AC Sheeting 1808/B00G/R0008/In-fill-panel/S8	No Asbestos Detected				

B00G - R0002 - Movement

Wall cladding	Flat AC Sheeting 1808/B00G/R0008/Wall cladding/S7	No Asbestos Detected				
In-fill-panel	Flat AC Sheeting 1808/B00G/R0008/In-fill-panel/S8	No Asbestos Detected				

B00G - R0003 - Withdrawal Space - 1hb

In-fill-panel	Flat AC Sheeting 1808/B00G/R0008/In-fill-panel/S8	No Asbestos Detected				
---------------	--	----------------------	--	--	--	--

B00G - R0004 - Home Base

No Asbestos

B00G - R0005 - Home Base Store

No Asbestos

B00G - R0006 - General Storeroom

No Asbestos

B00G - R0007 - Practical Activities - 1hb

No Asbestos

B00G - R0008 - Movement

Wall cladding	Flat AC Sheeting 1808/B00G/R0008/Wall cladding/S7	No Asbestos Detected				
In-fill-panel	Flat AC Sheeting 1808/B00G/R0008/In-fill-panel/S8	No Asbestos Detected				

B00G - R0009 - General Storeroom

No Asbestos

B00G - R0010 - Home Base Store

No Asbestos

B00G - R0011 - Home Base

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pupil Facilities/Communal Facilities - 1979 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 1808/B00H/Eaves Linings/S15	No Asbestos Detected				
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00H - R0001 - Garden Store**

No Asbestos

B00H - R0002 - Toilets - Boys

No Asbestos

B00H - R0003 - General Storeroom

No Asbestos

B00H - R0004 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 1808/B00H/R0004/Partition Walls (Cubicles)/S5	No Asbestos Detected				
----------------------------	--	----------------------	--	--	--	--

B00H - R0005 - Sports Store

No Asbestos

B00H - R0006 - Drinking Facilities

No Asbestos

B00H - R0007 - Disabled Toilet

Wall Linings Internal	Flat AC Sheeting 1808/B00H/R0007/Wall Linings Internal/S6	No Asbestos Detected				
Ceiling Structures/Linings	Flat AC Sheeting 1808/B00H/R0007/Ceiling Structures/Linings/S20	No Asbestos Detected				

B00H - R0008 - Cleaning Distributed Store

No Asbestos

B00H - R0009 - Drinking Facilities

No Asbestos

B00H - R0010 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00J - Pupil Facilities - 1985 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1808/B00J/Eaves Linings/S16				Chrysotile (white asbestos)		

Interior**B00J - R0001 - Movement**

No Asbestos

B00J - R0002 - Movement

No Asbestos

B00J - R0003 - Staff Toilet

Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1808/B00J/R0003/Floor Coverings Res/Textile/S12				Chrysotile (white asbestos)		

B00J - R0004 - Canteen Office/Store

Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1808/B00J/R0003/Floor Coverings Res/Textile/S12				Chrysotile (white asbestos)		

B00J - R0005 - Canteen Office/Store

Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1808/B00J/R0003/Floor Coverings Res/Textile/S12				Chrysotile (white asbestos)		

B00J - R0006 - Canteen

Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1808/B00J/R0003/Floor Coverings Res/Textile/S12				Chrysotile (white asbestos)		

B00J - R0007 - Sports Store

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1808/B00J/R0007/Ceiling Structures/Linings/S23				Chrysotile (white asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00K - Administration - 1966 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Eaves Linings	Flat AC Sheeting 1808/B00K/Eaves Linings/S17					No Asbestos Detected
Wall Cladding	Flat AC Sheeting 1808/B00K/Wall Cladding/S2					No Asbestos Detected
Electrical Backing Board	Resinous Board	1m2	West	Minimal Damage (2)	Low (1) Low Priority (2-3)	
	1808/B00K/Electrical Backing Board/S21					Chrysotile (white asbestos)

Interior**B00K - R0001 - Community Clinic**

Wall Linings Internal	Flat AC Sheeting 1808/B00K/Wall Cladding/S2					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles 1808/B00K/R0002/Floor Coverings Res/Textile/S3					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles 1808/B00K/R0002/Floor Coverings Res/Textile/S4					No Asbestos Detected
Electrical Backing Board	Resinous Board	1m2	West	Good Condition (1)	Low (1) Low Priority (2-3)	
	Assumed Asbestos - Electrical Hazard - Unable to access					

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1) Low Priority (2-3)	
	1808/B00K/R0003/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)

B00K - R0002 - Community Clinic

Wall Linings Internal	Flat AC Sheeting 1808/B00K/Wall Cladding/S2					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles 1808/B00K/R0002/Floor Coverings Res/Textile/S3					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles 1808/B00K/R0002/Floor Coverings Res/Textile/S4					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1) Low Priority (2-3)	
	1808/B00K/R0003/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)

B00K - R0003 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting 1808/B00K/Wall Cladding/S2					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles 1808/B00K/R0002/Floor Coverings Res/Textile/S3					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1) Low Priority (2-3)	
	1808/B00K/R0003/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00L - Library - 2008 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00L - R0001 - Reading Area**

No Asbestos

B00L - R0002 - Library Office/Workroom

No Asbestos

B00L - R0003 - Communications Room

No Asbestos

B00L - R0004 - General Storeroom

No Asbestos

B00L - R0005 - Disabled Toilet

No Asbestos

B00L - R0006 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00M - Pupil Facilities/Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00M - R0001 - Communal Space**

No Asbestos

B00M - R0002 - Cleaning Distributed Store

No Asbestos

B00M - R0003 - Main Switch Board

No Asbestos

B00M - R0004 - Toilet - Lobby

No Asbestos

B00M - R0005 - Toilets - Girls

No Asbestos

B00M - R0006 - Toilet - P

No Asbestos

B00M - R0007 - Sound Cupboard

No Asbestos

B00M - R0008 - Toilet - Lobby

No Asbestos

B00M - R0009 - Toilets - Boys

No Asbestos

B00M - R0010 - P.E. Store

No Asbestos

B00M - R0011 - Movement

No Asbestos

B00M - R0012 - Hall Chair Store

No Asbestos

B00M - R0013 - Communal/Performance Store

No Asbestos

B00M - R0014 - Raised Platform

No Asbestos

B00M - R0015 - Movement

No Asbestos

B00M - R0016 - Movement

No Asbestos

B00M - R0017 - Covered Outdoor Learning Area

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

Demountables**Demountable details as per the AMS records as of 15 Feb 2017.****OS 602 - D14868 - Learning Unit - Standard With P.A.A. : Placement Date - 16/05/2011****Exterior**

No Asbestos Found.

Interior**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

NS 100 - D15697 - Learning Unit - Single Primary/PAA : Placement Date - 5/01/2010**Exterior**

No Asbestos Found.

Interior**R1 - Home Base**

No Asbestos Found.

R2 - Practical Activity Area

No Asbestos Found.

R3 - Home Base Store

No Asbestos Found.

R4 - Entry

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017