


(Hazardous Materials and Risk Assessment)

School :	Epping West Public School (1851)
Region :	Northern Sydney
State Electorate :	Epping
Local Government Area :	Hornsby

Initial Survey : Noel Arnold & Associates : 30 - Jan - 2008
Reviewed By : Parsons Brinckerhoff : 13 - Jul - 2016



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00A - General Learning/Administration - 1927 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction >3m.					
Eaves Linings	Flat AC Sheeting 1851/B00H/Eaves Linings/S1	100m2	North facing, South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Gable Verge Lining	Flat AC Sheeting Assumed Asbestos - Height Restriction >3m.	45m	North facing, South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Underfloor Voids	AC Fragments/Debris 1851/B00A/Underfloor Voids/S13	NA	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)

Chrysotile (white asbestos) , Amosite (brown asbestos)

Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

Interior**B00A - R0002 - General Storeroom**

Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1851/B00G/R0017/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)		

B00A - R0003 - Home Base

No Asbestos

B00A - R0004 - Home Base

No Asbestos

B00A - R0005 - Home Base

No Asbestos

B00A - R0006 - Home Base

No Asbestos

B00A - R0007 - Home Base

No Asbestos

B00A - R0009 - Clerical Office

No Asbestos

B00A - R0010 - Principal

No Asbestos

B00A - R0011 - Staff Toilet

No Asbestos

B00A - R0012 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1851/B00G/R0017/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)		

B00A - R0013 - Entry Vestibule

No Asbestos

B00A - R0015 - Staff Room Annexe

No Asbestos

B00A - R0016 - Staff Room

No Asbestos

B00A - R0018 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	76m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1851/B00G/R0017/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)		

B00A - R0019 - Canteen Office/Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
B00A - R0020 - Interview						
No Asbestos						
B00A - R0025 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	52m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1851/B00G/R0017/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	
Infill panel	Flat AC Sheeting	10m2	North facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	1851/B00G/R0017/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	
B00A - R0026 - Staff Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1851/B00A/R0026/Ceiling Structures/Linings/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00A - R0027 - Movement						
No Asbestos						
B00A - R0028 - Staff Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1851/B00A/R0026/Ceiling Structures/Linings/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Wall Linings Internal	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1851/B00A/R0026/Ceiling Structures/Linings/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00A - R0029 - Special Programs Room						
No Asbestos						
B00A - R0030 - Duplicating Workroom						
No Asbestos						
B00A - R0031 - Deputy Principal						
No Asbestos						
B00A - R0033 - Duplicating Workroom						
No Asbestos						
B00A - R0034 - Home Base						
No Asbestos						
B00A - R0035 - Home Base Store						
No Asbestos						
B00A - R0036 - Home Base Store						
No Asbestos						
B00A - R0037 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	1851/B00B/R0004/Ceiling Structures/Linings/S11				No Asbestos Detected
In-fill panel above door	Flat AC Sheeting	1851/B00B/R0004/Ceiling Structures/Linings/S11				No Asbestos Detected
B00A - R0038 - Movement						
No Asbestos						
B00A - R0039 - Personal Effects Storage						
No Asbestos						
B00A - R0041 - Home Base Store						
No Asbestos						
B00A - R0042 - Home Base Store						
No Asbestos						
B00A - R0043 - Home Base						
No Asbestos						
B00A - R0044 - Canteen						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00A - R0045 - Movement

No Asbestos

B00A - R0046 - Movement

No Asbestos

B00A - R0047 - Movement

No Asbestos

B00A - R0048 - Movement

No Asbestos

B00A - R0050 - General Storeroom

Ceiling Structures/Linings Flat AC Sheeting 7.5m2 Upper portion Good Condition (1) Low (1) Low Priority (2-3)

1851/B00A/R0026/Ceiling Structures/Linings/S12

Chrysotile (white asbestos) , Amosite (brown asbestos)

B00A - R0051 - Home Base Store

Ceiling Structures/Linings Flat AC Sheeting 7.5m2 Upper portion Good Condition (1) Low (1) Low Priority (2-3)

1851/B00A/R0026/Ceiling Structures/Linings/S12

Chrysotile (white asbestos) , Amosite (brown asbestos)

B00A - R0052 - Clerical Office

No Asbestos

B00A - R0053 - Sick Bay

No Asbestos

B00A - R0054 - Duplicating Workroom

No Asbestos

B00A - R9001 - General Assistant/Bulk Store

Ceiling Structures/Linings Flat AC Sheeting 6m2 North facing Good Condition (1) Low (1) Low Priority (2-3)

1851/B00A/R9006/Ceiling Structures/Linings/S2

Chrysotile (white asbestos)

B00A - R9007 - Cleaning Supplies

Ceiling Structures/Linings Flat AC Sheeting 8m2 Upper portion Good Condition (1) Low (1) Low Priority (2-3)

1851/B00A/R0026/Ceiling Structures/Linings/S12

Chrysotile (white asbestos) , Amosite (brown asbestos)

B00A - R9008 - Uniform Shop

Ceiling Structures/Linings Flat AC Sheeting 19m2 Upper portion Good Condition (1) Low (1) Low Priority (2-3)

1851/B00A/R0026/Ceiling Structures/Linings/S12

Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1959 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction >3m.					
Eaves Linings	Flat AC Sheeting 1851/B00H/Eaves Linings/S1	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Gable Verge Linings	Flat AC Sheeting Assumed Asbestos - Height Restriction >3m.	10m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Underfloor Voids	AC Fragments/Debris 1851/B00B/Underfloor Voids/S14					No Asbestos Detected

Interior

B00B - R0001 - Home Base

No Asbestos

B00B - R0002 - Home Base Store

No Asbestos

B00B - R0003 - Home Base Store

No Asbestos

B00B - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 1851/B00B/R0004/Ceiling Structures/Linings/S11					No Asbestos Detected
In-fill panel above door	Flat AC Sheeting 1851/B00B/R0004/Ceiling Structures/Linings/S11					No Asbestos Detected

B00B - R0005 - Home Base Store

No Asbestos

B00B - R0006 - Movement

No Asbestos

B00B - R0007 - Personal Effects Storage

No Asbestos

B00B - R0009 - Home Base Store

No Asbestos

B00B - R0010 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00C - General Learning - 1959 - Timber (Timber)**Exterior**

Ceiling Voids - Raked Ceiling
Non Accessible Area
- Height Restriction >3m.

Underfloor Voids - Packing to Floor Joists
No Asbestos Found

Interior**B00C - R0001 - Home Base**

No Asbestos

B00C - R0002 - Home Base

No Asbestos

B00C - R0003 - General Storeroom

Wall Linings Internal	Flat AC Sheeting	3m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
1851/B00C/R0003/Wall Linings Internal/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00C - R0004 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00D - General Learning - 1959 - Timber (Timber)**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction >3m.					
Underfloor Voids - Packing to Floor Joists	Non Accessible Area - Height Restriction <0.3m.					
Eaves Linings	Flat AC Sheeting 1851/B00D/Eaves Linings/S7	30m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior**B00D - R0001 - Home Base - M**

No Asbestos

B00D - R0002 - Home Base

No Asbestos

B00D - R0003 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 1851/B00D/Eaves Linings/S7	26m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0005 - Home Base Store

Ceiling Structures/Linings	Flat AC Sheeting 1851/B00D/Eaves Linings/S7	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00F - General Learning - 1959 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction >3m.					
Underfloor Voids - Packing to Floor Joists	Non Accessible Area - Height Restriction <0.4m.					
Eaves Linings	Flat AC Sheeting 1851/B00H/Eaves Linings/S1	30m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting Assumed Asbestos - Height Restriction >3m.	10m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)

Interior

B00F - R0008 - Home Base

No Asbestos

B00F - R0009 - Home Base Store

No Asbestos

B00F - R0010 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 1851/B00F/R0010/Ceiling Structures/Linings/S4	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
In-fill panel above door	Flat AC Sheeting 1851/B00F/R0010/Ceiling Structures/Linings/S4	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00F - R0011 - Home Base Store

No Asbestos

B00F - R0012 - Movement

No Asbestos

B00F - R0013 - Personal Effects Storage

No Asbestos

B00F - R0015 - Home Base Store

No Asbestos

B00F - R0016 - Home Base Store

No Asbestos

B00F - R0017 - Home Base

No Asbestos

B00F - R0018 - Movement

No Asbestos

B00F - R0021 - Home Base

No Asbestos

B00F - R0022 - Withdrawal Space - 1hb

No Asbestos

B00F - R0023 - Movement

No Asbestos

B00F - R0024 - Special Programs Room

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 1851/B00F/R0024/Floor Coverings Res/Textile/S15					No Asbestos Detected
-----------------------------	--	--	--	--	--	----------------------

B00F - R0025 - Toilet - Lobby

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
Wall Linings Internal	Flat AC Sheeting	4m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	1851/B00F/R0025/Wall Linings Internal/S16				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	2.5m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1851/B00F/R0026/Ceiling Structures/Linings/S17				Chrysotile (white asbestos)	
B00F - R0026 - Toilets-Unisex						
Wall Linings Internal	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1851/B00F/R0025/Wall Linings Internal/S16				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	2.5m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1851/B00F/R0026/Ceiling Structures/Linings/S17				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00G - General Learning/Support Unit - 1959 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area					
	- Height Restriction >3m.					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	100m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	1851/B00H/Eaves Linings/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting	10m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction >3m.					

Interior**B00G - R0001 - Home Base**

No Asbestos

B00G - R0003 - Movement

No Asbestos

B00G - R0005 - Home Base

No Asbestos

B00G - R0006 - Home Base

No Asbestos

B00G - R0007 - Movement

No Asbestos

B00G - R0010 - Home Base

No Asbestos

B00G - R0011 - Home Base

No Asbestos

B00G - R0012 - Movement

No Asbestos

B00G - R0014 - Home Base Store

No Asbestos

B00G - R0015 - Toilet - M

No Asbestos

B00G - R0016 - Home Base - M

No Asbestos

B00G - R0020 - External Movement

No Asbestos

B00G - R0021 - General Storeroom

No Asbestos

B00G - R0022 - Home Base Store

No Asbestos

B00G - R0023 - Home Base Store

No Asbestos

B00G - R0024 - Home Base Store

No Asbestos

B00G - R0025 - Home Base Store

No Asbestos

B00G - R0026 - Home Base Store

No Asbestos

B00G - R0027 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

No Asbestos

B00G - R0028 - Home Base Store

No Asbestos

B00G - R0029 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00H - General Learning - 1959 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction >3m.					
Underfloor Voids - Packing to Floor Joists	Non Accessible Area - Height Restriction <0.3m.					
Eaves Linings	Flat AC Sheeting 1851/B00H/Eaves Linings/S1	35m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting Assumed Asbestos - Height Restriction >3m.	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)

Interior**B00H - R0001 - General Storeroom**

No Asbestos

B00H - R0007 - Staff Toilet

Floor Coverings Res/Textile	Vinyl Tiles 1851/B00H/R0007/Floor Coverings Res/Textile/S5	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		

B00H - R0014 - General Storeroom

No Asbestos

B00H - R0017 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 1851/B00H/Eaves Linings/S1	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00H - R0018 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 1851/B00H/Eaves Linings/S1	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00H - R0019 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 1851/B00H/Eaves Linings/S1	20m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00H - R0020 - Movement

No Asbestos

B00H - R0024 - Movement

No Asbestos

B00H - R0025 - Special Programs Room

No Asbestos

B00H - R0026 - Practical Activities - 1hb

No Asbestos

B00H - R0027 - Home Base

No Asbestos

B00H - R0028 - Home Base Store

No Asbestos

B00H - R0029 - Withdrawal Space - 2hb

No Asbestos

B00H - R0030 - Practical Activities - 1hb

No Asbestos

B00H - R0031 - Home Base

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

No Asbestos

B00H - R0032 - Cleaning Distributed Store

No Asbestos

B00H - R0033 - General Storeroom

No Asbestos

B00H - R0034 - Movement

No Asbestos

B00H - R0036 - External Movement

No Asbestos

B00H - R0037 - External Movement

No Asbestos

B00H - R0038 - Toilets-Unisex

No Asbestos

B00H - R0039 - Staff Kitchen

No Asbestos

B00H - R0040 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00I - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00I - R0001 - Movement**

No Asbestos

B00I - R0002 - Practical Activities - 1hb

No Asbestos

B00I - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00J - Pupil Facilities - 1959 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Flat Roof No Asbestos Found

Interior**B00J - R0003 - Toilets - Boys**

No Asbestos

B00J - R0004 - Toilets - Girls

No Asbestos

B00J - R0005 - Drinking Facilities

No Asbestos

B00J - R0006 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00K - Pupil Facilities - 1959 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Flat Roof No Asbestos Found

Interior**B00K - R0001 - Toilets - Girls**

No Asbestos

B00K - R0002 - Toilets - Boys

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00L - Other-After School Care - 2008 - Steel (Steel)**Exterior**

Underfloor Voids -
Packing to Floor Joists

No Asbestos Found

Ceiling Voids

No Asbestos Found

Interior**B00L - R0001 - No Access**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00M - Communal Facilities - 2009 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00M - R0001 - Covered Outdoor Learning Area**

No Asbestos

B00M - R0004 - P.E. Store

No Asbestos

B00M - R0005 - Hall Chair Store

No Asbestos

B00M - R0006 - External Movement

No Asbestos

B00M - R0007 - Movement

No Asbestos

B00M - R0008 - Communal/Performance Store

No Asbestos

B00M - R0009 - Communal/Performance Store

No Asbestos

B00M - R0011 - Ramp

No Asbestos

B00M - R0012 - Movement

No Asbestos

B00M - R0013 - Main Switch Board

No Asbestos

B00M - R0014 - Other

No Asbestos

B00M - R0015 - Other

No Asbestos

B00M - R0016 - Movement

No Asbestos

B00M - R0017 - Toilets - Girls

No Asbestos

B00M - R0018 - Toilet - Lobby

No Asbestos

B00M - R0019 - Sound Cupboard

No Asbestos

B00M - R0020 - Toilets - Boys

No Asbestos

B00M - R0021 - Toilet - Lobby

No Asbestos

B00M - R0022 - Access Shower/Toilet

No Asbestos

B00M - R0023 - Canteen

No Asbestos

B00M - R0024 - External Movement

No Asbestos

B00M - R0025 - Communal Space

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - R0026 - Raised Platform

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00N - Building Services - 2009 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00N - R0001 - Plant**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B000 - Library/General Learning - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B000 - R0001 - Reading Area**

No Asbestos

B000 - R0002 - Library Office/Workroom

No Asbestos

B000 - R0003 - Communications Room

No Asbestos

B000 - R0004 - K.L.A. Store

No Asbestos

B000 - R0005 - Staff Toilet

No Asbestos

B000 - R0006 - Toilet - Lobby

No Asbestos

B000 - R0007 - Cleaning Distributed Store

No Asbestos

B000 - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B000 - R0009 - External Movement

No Asbestos

B000 - R0010 - External Stairs

No Asbestos

B000 - R0011 - External Stairs

No Asbestos

B000 - R1001 - Home Base

No Asbestos

B000 - R1002 - Home Base

No Asbestos

B000 - R1003 - Home Base

No Asbestos

B000 - R1004 - Practical Activities - 1hb

No Asbestos

B000 - R1005 - Withdrawal Space - 1hb

No Asbestos

B000 - R1006 - Home Base Store

No Asbestos

B000 - R1007 - Home Base Store

No Asbestos

B000 - R1008 - Practical Activities - 1hb

No Asbestos

B000 - R1009 - Withdrawal Space - 2hb

No Asbestos

B000 - R1010 - Practical Activities - 1hb

No Asbestos

B000 - R1011 - Home Base Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - R1012 - External Movement

No Asbestos

B000 - R1013 - External Stairs

No Asbestos

B000 - R1014 - External Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00P - Pupil Facilities - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00P - R0001 - Toilets - Girls**

No Asbestos

B00P - R0002 - Toilets - Boys

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00Q - Building Services - 2010 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00Q - R0001 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00R - Music - 2013 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00R - R0001 - Home Base**

No Asbestos

B00R - R0002 - General Storeroom

No Asbestos

B00R - R0003 - Chair Storeroom

No Asbestos

B00R - R0004 - Toilets - Boys

No Asbestos

B00R - R0005 - Toilets-Unisex

No Asbestos

B00R - R0006 - Toilets - Girls

No Asbestos

B00R - R0007 - External Movement

No Asbestos

B00R - R0008 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables**Demountable details as per the AMS records as of 15 Feb 2017.****OS 602 - D10060 - Learning Unit - Standard With P.A.A. : Placement Date - 3/07/2014**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D10283 - Learning Unit - Standard With P.A.A. : Placement Date - 15/04/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 751 - D11192 - Learning Unit - ESL : Placement Date - 26/03/2007**Exterior**

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior**R1 - Esl**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	36 m2

R2 - Esl

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	36 m2

OS 602 - D11202 - Learning Unit - Standard With P.A.A. : Placement Date - 19/12/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11588 - Learning Unit - Standard With P.A.A. : Placement Date - 27/12/2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D11954 - Learning Unit - Standard With P.A.A. : Placement Date - 27/10/2015						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D12868 - Learning Unit - Standard With P.A.A. : Placement Date - 11/12/2014						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D13116 - Learning Unit - Standard With P.A.A. : Placement Date - 13/12/2016						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D13433 - Learning Unit - Standard With P.A.A. : Placement Date - 17/12/2013						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D13540 - Learning Unit - Standard With P.A.A. : Placement Date - 12/01/2013						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D13755 - Learning Unit - Standard With P.A.A. : Placement Date - 28/10/2014						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D14274 - Learning Unit - Standard With P.A.A. : Placement Date - 26/09/2013						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D14576 - Learning Unit - Standard With P.A.A. : Placement Date - 15/11/2016						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D14941 - Learning Unit - Standard With P.A.A. : Placement Date - 30/04/2013						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D15570 - Learning Unit - Standard With P.A.A. : Placement Date - 12/01/2013						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Interior**R1 - Learning space/withdrawal/entry**

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 602 - D16078 - Learning Unit - Standard With P.A.A. : Placement Date - 17/07/2015**Exterior**

No Asbestos Found.

Interior**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D17121 - Learning Unit - Standard With P.A.A. : Placement Date - 8/04/2015**Exterior**

No Asbestos Found.

Interior**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

1851_ASB_010313_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017