


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Eureka Public School (1879)
Region : North Coast
State Electorate : Ballina
Local Government Area : Byron

Initial Survey : Noel Arnold & Associates : 10 - Jun - 2008
Reviewed By : Parsons Brinckerhoff : 29 - Aug - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00A - Administration/General Learning - 1912 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1879/B00A/Eaves Linings/S4	Chrysotile (white asbestos)				
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					

Interior**B00A - R0009 - Staff Toilet**

No Asbestos

B00A - R0010 - Movement

No Asbestos

B00A - R0011 - Staff Toilet

No Asbestos

B00A - R0012 - Covered Outdoor Learning Area

No Asbestos

B00A - R0013 - External Movement

No Asbestos

B00A - R0014 - Communal Space

Wall Linings Internal	Flat AC Sheeting	14m2	North & East	Good Condition (1)	Low (1)	Low Priority (2-3)
	1879/B00A/R0014/Wall Linings Internal/S12	Chrysotile (white asbestos)				

B00A - R0015 - Home Base

No Asbestos

B00A - R0016 - Home Base Store

No Asbestos

B00A - R0017 - Staff Kitchen

No Asbestos

B00A - R0018 - Staff Room

No Asbestos

B00A - R0019 - Principal

No Asbestos

B00A - R0020 - Sick Bay

No Asbestos

B00A - R0021 - General Storeroom

No Asbestos

B00A - R0022 - Movement

No Asbestos

B00A - R0023 - Clerical Office/Workroom

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00B - General Learning - 1958 - Timber (Timber)**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior**B00B - R0001 - Home Base Store**

No Asbestos

B00B - R0002 - Home Base

No Asbestos

B00B - R0003 - Withdrawal Space - 1hb

No Asbestos

B00B - R0004 - Withdrawal Space - 1hb

No Asbestos

B00B - R0005 - Withdrawal Space - 1hb

No Asbestos

B00B - R0006 - Home Base Store

No Asbestos

B00B - R0007 - Home Base

No Asbestos

B00B - R0008 - Practical Activities - 1hb

No Asbestos

B00B - R0009 - Personal Effects Storage

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

1879/B00B/R0009/Ceiling Structures/Linings/S7

Chrysotile (white asbestos)**B00B - R0010 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00C - General Learning - 1999 - Timber (Timber)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior**B00C - R0001 - Practical Activities - 1hb**

No Asbestos

B00C - R0002 - Home Base Store

No Asbestos

B00C - R0003 - Home Base

No Asbestos

B00C - R0004 - Outdoor Learning Area

Ceiling Structures/Linings	Flat AC Sheeting	
	1879/B00C/R0004/Ceiling Structures/Linings/S8	No Asbestos Detected

B00C - R0005 - Withdrawal Space - 1hb

No Asbestos

B00C - R0006 - Outdoor Learning Area

Ceiling Structures/Linings	Flat AC Sheeting	
	1879/B00C/R0004/Ceiling Structures/Linings/S8	No Asbestos Detected

B00C - R0007 - Home Base

No Asbestos

B00C - R0008 - Home Base Store

No Asbestos

B00C - R0009 - Practical Activities - 1hb

No Asbestos

B00C - R0010 - Personal Effects Storage

Ceiling Structures/Linings	Flat AC Sheeting	
	1879/B00C/R0004/Ceiling Structures/Linings/S8	No Asbestos Detected

B00C - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1958 - Timber (Timber)**Exterior**

Ceiling Void	No Asbestos Found					
Underfloor Void	AC Fragments/Debris	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
1879/B00D/Underfloor Void/S6					Chrysotile (white asbestos)	

Interior**B00D - R0001 - Canteen**

No Asbestos

B00D - R0002 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Building Services - 1958 - Timber Shed (Timber Shed)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00E - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00F - Pupil Facilities - 1958 - Timber (Timber)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found	
Eaves Linings	Flat AC Sheeting 1879/B00F/Eaves Linings/S5	No Asbestos Detected
Ceiling Void	No Asbestos Found	

Interior**B00F - R0004 - Cleaning Distributed Store**

No Asbestos

B00F - R0005 - Toilets - Girls

No Asbestos

B00F - R0006 - Toilets - Boys

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00G - Building Services - 1958 - Timber (Timber)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Wall Cladding	Flat AC Sheeting 1879/B00G/High level wall cladding above entrance and at the rear/S2				No Asbestos Detected	
Eaves Linings	Flat AC Sheeting 1879/B00G/Eaves Linings/S3				No Asbestos Detected	
Ceiling Void	No Asbestos Found					

Interior**B00G - R0001 - General Assistant/Bulk Store**

No Asbestos

B00G - R0002 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00H - Library - 1917 - Timber (Timber)**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior**B00H - R0001 - External Movement**

Wall Linings Internal	Flat AC Sheeting	2m2	East, Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1879/B00H/R0001/Wall Linings Internal/S1					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1879/B00H/R0001/Wall Linings Internal/S1					Chrysotile (white asbestos)	

B00H - R0002 - Movement

No Asbestos

B00H - R0003 - Staff Toilet

No Asbestos

B00H - R0004 - Staff Shower/Change

No Asbestos

B00H - R0005 - K.L.A. Store

No Asbestos

B00H - R0006 - Movement

No Asbestos

B00H - R0007 - Staff Kitchen

No Asbestos

B00H - R0008 - Seminar/Study

No Asbestos

B00H - R0009 - Reading Area

No Asbestos

B00H - R0010 - Seminar/Study

No Asbestos

B00H - R0011 - Library Office/Workroom

No Asbestos

B00H - R0012 - General Storeroom

No Asbestos

B00H - R0013 - External Movement

No Asbestos

B00H - R0014 - Kiln Room

Ceiling Structures/Linings	Flat AC Sheeting	1879/B00H/R0014/Ceiling Structures/Linings/S9				No Asbestos Detected
Debris on floor	AC Fragments/Debris	1879/B00H/R0014/Debris on floor/S10				No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting	1879/B00H/R0014/Ceiling Structures/Linings/S9				No Asbestos Detected

B00H - R9001 - Cleaning Distributed Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00I - Pupil Facilities - 1958 - Timber (Timber)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00I - R0001 - Canteen Covered Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables
There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017