


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Ross Hill Public School (2997)
Region : New England
State Electorate : Northern Tablelands
Local Government Area : Inverell

Initial Survey : Noel Arnold & Associates : 20 - May - 2008
Reviewed By : Greencap-NAA : 01 - Apr - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
		Sample No			Test Result	
B00A - Support Unit - 1978 - Timber (Timber)						
Exterior						
Eaves Linings	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00D/Eaves Linings/S10			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00D/Gable Verge Lining/S11			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Underfloor Voids	No Asbestos Found					
Ceiling Voids	Non Accessible Area - Height Restriction					
Interior						
B00A - R0001 - Distribution Board				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00B/R0008/Ceiling Structures/Linings/S4			Chrysotile (white asbestos)		
B00A - R0003 - Home Base - M						
No Asbestos						
B00A - R0004 - Home Base - M						
No Asbestos						
B00A - R0005 - Movement						
No Asbestos						
B00A - R0006 - General Storeroom						
No Asbestos						
B00A - R0007 - Toilet - M						
No Asbestos						
B00A - R0009 - Movement						
No Asbestos						
B00A - R0010 - Movement						
No Asbestos						
B00A - R0011 - Disabled Shower/Toilet						
No Asbestos						
B00A - R0012 - Movement						
No Asbestos						
B00A - R0013 - Disabled Toilet						
No Asbestos						
B00A - R0014 - Laundry - P						
No Asbestos						
B00A - R0015 - Special Programs Store						
No Asbestos						
B00A - R0016 - Movement						
No Asbestos						
B00A - R0017 - External Movement						
Recently Modified Space	Requires Inspection					
B00A - R0018 - External Movement						
Recently Modified Space	Requires Inspection					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00B - General Learning - 1965 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids Non Accessible Area
- Height Restriction

Underfloor Voids No Asbestos Found

Interior**B00B - R0001 - Home Base**

No Asbestos

B00B - R0002 - Movement

Wall Linings Internal Flat AC Sheeting
2997/B00B/R0002/Wall Linings Internal/S5 **No Asbestos Detected**

B00B - R0003 - Practical Activities - 1hb

Floor Coverings Vinyl Tiles
Res/Textile
2997/B00K/R0016/Floor Coverings Res/Textile/S3 **No Asbestos Detected**

B00B - R0004 - Home Base

No Asbestos

B00B - R0005 - Personal Effects Storage

No Asbestos

B00B - R0006 - Home Base

No Asbestos

B00B - R0007 - Personal Effects Storage

Floor Coverings Vinyl Tiles
Res/Textile
2997/B00K/R0016/Floor Coverings Res/Textile/S3 **No Asbestos Detected**

B00B - R0008 - Movement

Ceiling Structures/Linings Flat AC Sheeting 2m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
2997/B00B/R0008/Ceiling Structures/Linings/S4 **Chrysotile (white asbestos)**

B00B - R0009 - Movement

Electrical Backing Board Resinous Board 1Unit East to West corridor east end Good Condition (1) Low (1) Low Priority (2-3)

Assumed Asbestos - Electrical Hazard**B00B - R0010 - General Storeroom**

No Asbestos

B00B - R0011 - Home Base

No Asbestos

B00B - R0012 - External Movement

Recently Modified Space Requires Inspection

B00B - R0013 - External Movement

Recently Modified Space Requires Inspection

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00C - General Learning/Staff Facilities - 1948 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids	Non Accessible Area - Area inaccessible

Interior**B00C - R0001 - Staff Room Annexe**

Floor Coverings Res/Textile	Vinyl Tiles	
	2997/B00K/R0016/Floor Coverings Res/Textile/S3	No Asbestos Detected
Floor Coverings Res/Textile	Adhesive	
	2997/B00C/R0001/Floor Coverings Res/Textile/S12	No Asbestos Detected

B00C - R0002 - Home Base

No Asbestos

B00C - R0003 - Home Base

No Asbestos

B00C - R0004 - Movement

No Asbestos

B00C - R0005 - Personal Effects Storage

No Asbestos

B00C - R0006 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00D - General Learning/Support Unit - 1963 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	16m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00D/Eaves Linings/S10			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00D/Gable Verge Lining/S11			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	No Asbestos Found					

Interior**B00D - R0001 - Home Base - M**

Floor Coverings Res/Textile	Adhesive					
	2997/B00D/R0002/Floor Coverings Res/Textile/S9				No Asbestos Detected	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	2997/B00D/R0002/Floor Coverings Res/Textile/S8				No Asbestos Detected	

B00D - R0002 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	37m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00B/R0008/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	2997/B00D/R0002/Floor Coverings Res/Textile/S8				No Asbestos Detected	
Floor Coverings Res/Textile	Adhesive					
	2997/B00D/R0002/Floor Coverings Res/Textile/S9				No Asbestos Detected	
Electrical Backing Board	Resinous Board	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					

B00D - R0003 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00B/R0008/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	

B00D - R0004 - Withdrawal Space - 1hb

No Asbestos

B00D - R0005 - Staff Toilet

No Asbestos

B00D - R0006 - Home Base

Floor Coverings Res/Textile	Adhesive					
	2997/B00D/R0002/Floor Coverings Res/Textile/S9				No Asbestos Detected	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	2997/B00D/R0002/Floor Coverings Res/Textile/S8				No Asbestos Detected	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00E - Pupil Facilities/Electrical Services - 1893 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00E/Eaves Linings/S20				Chrysotile (white asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00E/Eaves Linings/S20				Chrysotile (white asbestos)	

Interior**B00E - R0001 - Movement**

No Asbestos

B00E - R0002 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00E/Eaves Linings/S20				Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	30m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00E/R0003/Partition Walls (Cubicles)/S6				Chrysotile (white asbestos)	

B00E - R0003 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00E/R0003/Partition Walls (Cubicles)/S6				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00E/Eaves Linings/S20				Chrysotile (white asbestos)	

B00E - R0004 - Main Switch Board

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00E/Eaves Linings/S20				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00F - General Learning/Administration - 1970 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	80m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00F/Eaves Linings/S27				Chrysotile (white asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction					
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00F - R0001 - Movement**

No Asbestos

B00F - R0002 - Personal Effects Storage

No Asbestos

B00F - R0003 - Home Base Store

No Asbestos

B00F - R0004 - Withdrawal Space - 1hb

No Asbestos

B00F - R0005 - Home Base

No Asbestos

B00F - R0006 - Practical Activities - 1hb

No Asbestos

B00F - R0007 - Movement

No Asbestos

B00F - R0008 - Craft Store

No Asbestos

B00F - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0010 - General Storeroom

No Asbestos

B00F - R0011 - Movement

No Asbestos

B00F - R0012 - General Storeroom

No Asbestos

B00F - R0013 - Cleaning Distributed Store

No Asbestos

B00F - R0014 - Staff Toilet

Ceiling Structures/Linings	Vermiculite 2997/B00F/R0015/Ceiling Structures/Linings/S24				No Asbestos Detected	
Incinerette	Encapsulated Insulation material within unit	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Area inaccessible					

B00F - R0015 - Cleaning Distributed Store

Ceiling Structures/Linings	Vermiculite 2997/B00F/R0015/Ceiling Structures/Linings/S24				No Asbestos Detected	
----------------------------	---	--	--	--	-----------------------------	--

B00F - R0016 - Staff Toilet

Ceiling Structures/Linings	Vermiculite 2997/B00F/R0015/Ceiling Structures/Linings/S24				No Asbestos Detected	
----------------------------	---	--	--	--	-----------------------------	--

B00F - R0017 - Distribution Board

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00F/R1003/Floor Coverings Res/Textile/S21				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite				No Asbestos Detected	
	2997/B00F/R0015/Ceiling Structures/Linings/S24					
Floor Coverings Res/Textile	Adhesive				No Asbestos Detected	
	2997/B00F/R1003/Floor Coverings Res/Textile/S22					
B00F - R0018 - Duplicating Workroom						
Ceiling Structures/Linings	Vermiculite				No Asbestos Detected	
	2997/B00F/R0015/Ceiling Structures/Linings/S24					
B00F - R0019 - Staff Room Annexe						
Ceiling Structures/Linings	Vermiculite				No Asbestos Detected	
	2997/B00F/R0015/Ceiling Structures/Linings/S24					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00F/R1003/Floor Coverings Res/Textile/S21				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive				No Asbestos Detected	
	2997/B00F/R1003/Floor Coverings Res/Textile/S22					
B00F - R0020 - Sick Bay - Shower/Toilet						
Ceiling Structures/Linings	Vermiculite				No Asbestos Detected	
	2997/B00F/R0015/Ceiling Structures/Linings/S24					
B00F - R0021 - Sick Bay						
Ceiling Structures/Linings	Vermiculite				No Asbestos Detected	
	2997/B00F/R0015/Ceiling Structures/Linings/S24					
B00F - R0022 - Movement						
No Asbestos						
B00F - R0023 - Entry Vestibule						
Ceiling Structures/Linings	Vermiculite				No Asbestos Detected	
	2997/B00F/R0015/Ceiling Structures/Linings/S24					
Floor Coverings Res/Textile	Adhesive				No Asbestos Detected	
	2997/B00F/R1003/Floor Coverings Res/Textile/S22					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00F/R1003/Floor Coverings Res/Textile/S21				Chrysotile (white asbestos)	
B00F - R0024 - Clerical Office						
Ceiling Structures/Linings	Vermiculite				No Asbestos Detected	
	2997/B00F/R0015/Ceiling Structures/Linings/S24					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00F/R1003/Floor Coverings Res/Textile/S21				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive				No Asbestos Detected	
	2997/B00F/R1003/Floor Coverings Res/Textile/S22					
B00F - R0025 - Principal						
Ceiling Structures/Linings	Vermiculite				No Asbestos Detected	
	2997/B00F/R0015/Ceiling Structures/Linings/S24					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00F/R1003/Floor Coverings Res/Textile/S21				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive				No Asbestos Detected	
	2997/B00F/R1003/Floor Coverings Res/Textile/S22					
B00F - R0026 - Interview						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
Ceiling Structures/Linings	Vermiculite 2997/B00F/R0015/Ceiling Structures/Linings/S24				No Asbestos Detected	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2997/B00F/R1003/Floor Coverings Res/Textile/S21	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive 2997/B00F/R1003/Floor Coverings Res/Textile/S22				No Asbestos Detected	
B00F - R0027 - Movement						
Ceiling Structures/Linings	Vermiculite 2997/B00F/R0015/Ceiling Structures/Linings/S24				No Asbestos Detected	
Floor Coverings Res/Textile	Adhesive 2997/B00F/R1003/Floor Coverings Res/Textile/S22				No Asbestos Detected	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2997/B00F/R1003/Floor Coverings Res/Textile/S21	31m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00F - R0028 - External Movement						
Recently Modified Space	Requires Inspection					
B00F - R0029 - Stairs						
Recently Modified Space	Requires Inspection					
B00F - R0030 - Stairs						
Recently Modified Space	Requires Inspection					
B00F - R1001 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting 2997/B00F/R1001/Ceiling Structures/Linings/S23	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00F - R1002 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2997/B00F/R1003/Floor Coverings Res/Textile/S21	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive 2997/B00F/R1003/Floor Coverings Res/Textile/S22				No Asbestos Detected	
B00F - R1003 - Home Base Store						
Floor Coverings Res/Textile	Vinyl Tiles 2997/B00F/R1003/Floor Coverings Res/Textile/S21	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive 2997/B00F/R1003/Floor Coverings Res/Textile/S22				No Asbestos Detected	
B00F - R1004 - Home Base Store						
Floor Coverings Res/Textile	Vinyl Tiles 2997/B00F/R1003/Floor Coverings Res/Textile/S21	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive 2997/B00F/R1003/Floor Coverings Res/Textile/S22				No Asbestos Detected	
B00F - R1005 - Distribution Board				Note: No inspection of live electrical installation.		
Floor Coverings Res/Textile	Vinyl Tiles 2997/B00F/R1003/Floor Coverings Res/Textile/S21	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive 2997/B00F/R1003/Floor Coverings Res/Textile/S22				No Asbestos Detected	
Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)

Assumed Asbestos - Electrical Hazard

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
B00F - R1006 - Personal Effects Storage						
Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00F/R1003/Floor Coverings Res/Textile/S21				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					
	2997/B00F/R1003/Floor Coverings Res/Textile/S22				No Asbestos Detected	
B00F - R1007 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00F/R1003/Floor Coverings Res/Textile/S21				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					
	2997/B00F/R1003/Floor Coverings Res/Textile/S22				No Asbestos Detected	
B00F - R1008 - Movement						
No Asbestos						
B00F - R1009 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00F/R1003/Floor Coverings Res/Textile/S21				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					
	2997/B00F/R1003/Floor Coverings Res/Textile/S22				No Asbestos Detected	
B00F - R1010 - Home Base Store						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00F/R1003/Floor Coverings Res/Textile/S21				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					
	2997/B00F/R1003/Floor Coverings Res/Textile/S22				No Asbestos Detected	
B00F - R1011 - Distribution Board						
Note: No inspection of live electrical installation.						
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00F/R1003/Floor Coverings Res/Textile/S21				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					
	2997/B00F/R1003/Floor Coverings Res/Textile/S22				No Asbestos Detected	
Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
B00F - R1012 - Personal Effects Storage						
Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00F/R1003/Floor Coverings Res/Textile/S21				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					
	2997/B00F/R1003/Floor Coverings Res/Textile/S22				No Asbestos Detected	
B00F - R1013 - Home Base Store						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00F/R1003/Floor Coverings Res/Textile/S21				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					
	2997/B00F/R1003/Floor Coverings Res/Textile/S22				No Asbestos Detected	
B00F - R1014 - Home Base						
Floor Coverings Res/Textile	Adhesive					
	2997/B00F/R1003/Floor Coverings Res/Textile/S22				No Asbestos Detected	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00F/R1003/Floor Coverings Res/Textile/S21				Chrysotile (white asbestos)	
B00F - R1015 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	73m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00F/R1001/Ceiling Structures/Linings/S23				Chrysotile (white asbestos)	
B00F - R1016 - Stairs						
Recently Modified Space	Requires Inspection					
B00F - R1017 - Stairs						
Recently Modified Space	Requires Inspection					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
B00G - Pupil Facilities/Staff Facilities - 1978 - Brick/Block (Brick/Block)						
Exterior						
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00G/Gable Verge Lining/S19			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Eaves Linings	Flat AC Sheeting					No Asbestos Detected
	2997/B00G/R0001/Ceiling Structures/Linings/S18					
Panels Under Windows	Flat AC Sheeting	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00J/R0007/Panels Under Windows/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Interior						
B00G - R0001 - Sports Store						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	2997/B00G/R0001/Ceiling Structures/Linings/S18					
B00G - R0002 - Disabled Toilet						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	2997/B00G/R0001/Ceiling Structures/Linings/S18					
B00G - R0003 - Toilets - Girls						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	2997/B00G/R0001/Ceiling Structures/Linings/S18					
Partition Walls (Cubicles)	Compressed AC Sheet	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00E/R0003/Partition Walls (Cubicles)/S6			Chrysotile (white asbestos)		
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	2997/B00G/R0001/Ceiling Structures/Linings/S18					
B00G - R0004 - Toilets - Boys						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	2997/B00G/R0001/Ceiling Structures/Linings/S18					
Partition Walls (Cubicles)	Compressed AC Sheet	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00E/R0003/Partition Walls (Cubicles)/S6			Chrysotile (white asbestos)		
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	2997/B00G/R0001/Ceiling Structures/Linings/S18					
B00G - R0006 - General Assistant/Bulk Store						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	2997/B00G/R0001/Ceiling Structures/Linings/S18					
B00G - R0007 - General Storeroom						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	2997/B00G/R0001/Ceiling Structures/Linings/S18					
B00G - R0008 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	2997/B00G/R0001/Ceiling Structures/Linings/S18					
B00G - R0009 - Staff Room						
Recently Modified Space	Requires Inspection					
B00G - R0010 - Staff Kitchen						
Recently Modified Space	Requires Inspection					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Communal Facilities/Pupil Facilities - 1995 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00H - R0001 - Movement**

No Asbestos

B00H - R0002 - Movement

No Asbestos

B00H - R0003 - Raised Platform

No Asbestos

B00H - R0004 - Movement

No Asbestos

B00H - R0005 - Movement

No Asbestos

B00H - R0006 - Toilets - Girls

No Asbestos

B00H - R0007 - Hall Chair Store

No Asbestos

B00H - R0008 - General Storeroom

No Asbestos

B00H - R0009 - Craft Store

No Asbestos

B00H - R0010 - Kiln Room

No Asbestos

B00H - R0011 - Cleaning Supplies

No Asbestos

B00H - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0013 - Disabled Toilet

No Asbestos

B00H - R0014 - Plant

No Asbestos

B00H - R0015 - Movement

No Asbestos

B00H - R0016 - Canteen

No Asbestos

B00H - R0017 - Canteen Office/Store

No Asbestos

B00H - R0018 - Sports Store

No Asbestos

B00H - R0019 - P.E. Store

No Asbestos

B00H - R0020 - Garden Store

No Asbestos

B00H - R0021 - Toilets - Boys

No Asbestos

B00H - R0022 - Shower/Change

No Asbestos

B00H - R0023 - Communal Space

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00I - Library/Tiered Learning - 1995 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior**B00I - R0001 - Movement**

No Asbestos

B00I - R0002 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00I - R0003 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00I - R0004 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00I - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00I - R0006 - Movement

No Asbestos

B00I - R0007 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00I - R0008 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00I - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00I - R0010 - Plant

No Asbestos

B00I - R0011 - Cleaning Distributed Store

No Asbestos

B00I - R0012 - Special Programs Room

No Asbestos

B00I - R0013 - Staff Room

No Asbestos

B00I - R0014 - Movement

No Asbestos

B00I - R0015 - Stairs

No Asbestos

B00I - R0016 - Stairs

No Asbestos

B00I - R1001 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00I - R1002 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00I - R1003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00I - R1004 - Practical Activities - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

No Asbestos

B00I - R1005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00I - R1006 - Practical Activities - 1hb

No Asbestos

B00I - R1007 - Home BaseVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00I - R1008 - Home Base Store**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00I - R1009 - Withdrawal Space - 1hb**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00I - R1010 - Home Base Store**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00I - R1011 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00I - R1012 - Practical Activities - 1hb**

No Asbestos

B00I - R1013 - Movement

No Asbestos

B00I - R1014 - Stairs

No Asbestos

B00I - R1015 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00J - General Learning - 1979 - Brick/Block (Brick/Block)**Exterior**

Panels Under Windows	Flat AC Sheeting	10m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
2997/B00J/R0007/Panels Under Windows/S1				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Panels Above Windows	Flat AC Sheeting	3m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
2997/B00J/Panels Above Windows/S15				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
2997/B00D/Gable Verge Lining/S11				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Eaves Linings	Flat AC Sheeting	15m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
2997/B00J/Eaves Linings/S14				Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior**B00J - R0001 - Home Base**

Thermacon Heater	Encapsulated Insulation material within unit	2Unit	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Area inaccessible						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
2997/B00J/R0001/Floor Coverings Res/Textile/S16				No Asbestos Detected		
Floor Coverings Res/Textile	Adhesive					
2997/B00J/R0001/Floor Coverings Res/Textile/S17				No Asbestos Detected		

B00J - R0002 - Home Base Store

No Asbestos

B00J - R0003 - Movement

No Asbestos

B00J - R0004 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00J/R0004/Wall Linings Internal/S7			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00J/R0004/Wall Linings Internal/S7			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Floor Coverings Res/Textile	Vinyl Tiles					
	2997/B00K/R0016/Floor Coverings Res/Textile/S3				No Asbestos Detected	

B00J - R0005 - Home Base Store

No Asbestos

B00J - R0006 - Home Base

Thermacon Heater	Encapsulated Insulation material within unit	3Unit	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Area inaccessible						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
2997/B00J/R0001/Floor Coverings Res/Textile/S16				No Asbestos Detected		
Floor Coverings Res/Textile	Adhesive					
2997/B00J/R0001/Floor Coverings Res/Textile/S17				No Asbestos Detected		

B00J - R0007 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
Panels Under Windows	Flat AC Sheeting	10m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00J/R0007/Panels Under Windows/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Panels Above Windows	Flat AC Sheeting	3m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00J/R0007/Panels Under Windows/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Structures/Linings	Moulded Fibre Cement	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2997/B00J/Eaves Linings/S14			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00J - R0008 - External Movement						
Recently Modified Space	Requires Inspection					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning/Staff Facilities - 1975 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 2997/B00K/R0004/Ceiling Structures/Linings/S13	No Asbestos Detected				
Underfloor Voids	Non Accessible Area - Area inaccessible					
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					

Interior**B00K - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 2997/B00K/R0004/Ceiling Structures/Linings/S13	No Asbestos Detected				
Panels Above Windows	Flat AC Sheeting 2997/B00J/Panels Above Windows/S15	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)						

B00K - R0002 - Staff Toilet

Ceiling Structures/Linings	Vermiculite 2997/B00K/R0004/Ceiling Structures/Linings/S13	No Asbestos Detected				
Incinerette	Encapsulated Insulation material within unit	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Area inaccessible						

B00K - R0003 - General Storeroom

Ceiling Structures/Linings	Vermiculite 2997/B00K/R0004/Ceiling Structures/Linings/S13	No Asbestos Detected				
----------------------------	---	----------------------	--	--	--	--

B00K - R0004 - Craft Store

Ceiling Structures/Linings	Vermiculite 2997/B00K/R0004/Ceiling Structures/Linings/S13	No Asbestos Detected				
----------------------------	---	----------------------	--	--	--	--

B00K - R0005 - Distribution Board

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						

B00K - R0006 - Staff Room Annexe

Ceiling Structures/Linings	Vermiculite 2997/B00K/R0004/Ceiling Structures/Linings/S13	No Asbestos Detected				
----------------------------	---	----------------------	--	--	--	--

B00K - R0007 - Movement

Ceiling Structures/Linings	Vermiculite 2997/B00K/R0004/Ceiling Structures/Linings/S13	No Asbestos Detected				
----------------------------	---	----------------------	--	--	--	--

B00K - R0008 - Home Base

Ceiling Structures/Linings	Vermiculite 2997/B00K/R0004/Ceiling Structures/Linings/S13	No Asbestos Detected				
----------------------------	---	----------------------	--	--	--	--

B00K - R0009 - Cleaning Distributed Store

Ceiling Structures/Linings	Vermiculite 2997/B00K/R0004/Ceiling Structures/Linings/S13	No Asbestos Detected				
Panels Below Windows	Flat AC Sheeting 2997/B00K/R0009/Panels Below Windows/S2	2m2	South, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
Chrysotile (white asbestos)						

B00K - R0010 - Personal Effects Storage

Ceiling Structures/Linings	Vermiculite 2997/B00K/R0004/Ceiling Structures/Linings/S13	No Asbestos Detected				
----------------------------	---	----------------------	--	--	--	--

B00K - R0011 - Personal Effects Storage

Ceiling Structures/Linings	Vermiculite 2997/B00K/R0004/Ceiling Structures/Linings/S13	No Asbestos Detected				
----------------------------	---	----------------------	--	--	--	--

B00K - R0012 - Toilets - Boys/Girls

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
Ceiling Structures/Linings	Vermiculite 2997/B00K/R0004/Ceiling Structures/Linings/S13				No Asbestos Detected	
Panels Below Windows	Flat AC Sheeting 2997/B00K/R0009/Panels Below Windows/S2	2m2	South, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
B00K - R0013 - Practical Activities - 1hb						
Ceiling Structures/Linings	Vermiculite 2997/B00K/R0004/Ceiling Structures/Linings/S13				No Asbestos Detected	
B00K - R0014 - Home Base						
Ceiling Structures/Linings	Vermiculite 2997/B00K/R0004/Ceiling Structures/Linings/S13				No Asbestos Detected	
B00K - R0015 - Home Base						
Ceiling Structures/Linings	Vermiculite 2997/B00K/R0004/Ceiling Structures/Linings/S13				No Asbestos Detected	
B00K - R0016 - Practical Activities - 1hb						
Ceiling Structures/Linings	Vermiculite 2997/B00K/R0004/Ceiling Structures/Linings/S13				No Asbestos Detected	
B00K - R0017 - Home Base Store						
Ceiling Structures/Linings	Vermiculite 2997/B00K/R0004/Ceiling Structures/Linings/S13				No Asbestos Detected	
B00K - R0018 - Personal Effects Storage						
Ceiling Structures/Linings	Vermiculite 2997/B00K/R0004/Ceiling Structures/Linings/S13				No Asbestos Detected	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00L - General Learning - 2011 - Brick/Veneer (Brick/Veneer)**Exterior**

No Asbestos

Interior**B00L - R0001 - External Movement**

No Asbestos

B00L - R0002 - Home Base/Practical Activities

No Asbestos

B00L - R0003 - Home Base Store

No Asbestos

B00L - R0004 - Home Base

No Asbestos

B00L - R0005 - Special Programs Room

No Asbestos

B00L - R0006 - Home Base/Practical Activities

No Asbestos

B00L - R0007 - Home Base

No Asbestos

B00L - R0008 - Home Base Store

No Asbestos

B00L - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0010 - Special Programs Room

No Asbestos

B00L - R0011 - Home Base Store

No Asbestos

B00L - R0012 - Home Base/Practical Activities

No Asbestos

B00L - R0013 - Home Base

No Asbestos

B00L - R0014 - P.E. Store

No Asbestos

B00L - R0015 - General Storeroom

No Asbestos

B00L - R0016 - External Stairs

No Asbestos

B00L - R0017 - External Stairs

No Asbestos

B00L - R1001 - External Movement

No Asbestos

B00L - R1002 - Home Base/Practical Activities

No Asbestos

B00L - R1003 - Home Base Store

No Asbestos

B00L - R1004 - Home Base

No Asbestos

B00L - R1005 - Special Programs Room

No Asbestos

B00L - R1006 - Home Base/Practical Activities

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
B00L - R1007 - Home Base						
No Asbestos						
B00L - R1008 - Home Base Store						
No Asbestos						
B00L - R1009 - Distribution Board				Note: No inspection of live electrical installation.		
No Asbestos						
B00L - R1010 - Special Programs Room						
No Asbestos						
B00L - R1011 - Home Base Store						
No Asbestos						
B00L - R1012 - Home Base/Practical Activities						
No Asbestos						
B00L - R1013 - Home Base						
No Asbestos						
B00L - R1014 - External Stairs						
No Asbestos						
B00L - R1015 - External Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

Demountables**Demountable details as per the AMS records as of 15 Feb 2017.****OS 601 - D10731 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995****Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior**R1 - Entry**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

2997_ASB_221112_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017