Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Castle Hill Public School (1529)**
Region :	**Northern Sydney**
State Electorate :	**Castle Hill**
Local Government Area :	**The Hills**

Initial Survey :	**Noel Arnold & Associates : 28 - Mar - 2008**
Register Issue Date :	**22 - Mar - 2017**

1529 - Castle Hill Public School
Site Plan (13258)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B0AA - Administration/General Learning - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0AA - R0001 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0AA - R0002 - Duplicating Workroom

No Asbestos

B0AA - R0003 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0AA - R0004 - Security Store

No Asbestos

B0AA - R0005 - Staff Toilet

No Asbestos

B0AA - R0006 - Staff Toilet

No Asbestos

B0AA - R0007 - Staff Toilet

No Asbestos

B0AA - R0008 - Cleaning Distributed Store

No Asbestos

B0AA - R0009 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0AA - R0011 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0AA - R0012 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0AA - R0013 - Teachers Aide Special Ed

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0AA - R0014 - Disabled Toilet

No Asbestos

B0AA - R0015 - Sick Bay

No Asbestos

B0AA - R0016 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0AA - R0017 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0AA - R0018 - Community Clinic

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0AA - R0019 - Staff Toilet

No Asbestos

B0AA - R0020 - Community Clinic

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0AA - R0021 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

No Asbestos

B0AA - R0022 - Stairs

No Asbestos

B0AA - R0023 - No Access

No Asbestos

B0AA - R0024 - No Access

No Asbestos

B0AA - R0025 - Canteen Office/Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0AA - R0026 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0AA - R1001 - Home Base Store

No Asbestos

B0AA - R1002 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0AA - R1003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0AA - R1004 - Practical Activities - 1hb

No Asbestos

B0AA - R1005 - Practical Activities - 1hb

No Asbestos

B0AA - R1006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0AA - R1007 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0AA - R1008 - Home Base Store

No Asbestos

B0AA - R1009 - Home Base Store

No Asbestos

B0AA - R1010 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B0AA - R1011 - Practical Activities - 1hb

No Asbestos

B0AA - R1012 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0AA - R1013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0AA - R1014 - Practical Activities - 1hb

No Asbestos

B0AA - R1015 - Home Base Store

No Asbestos

B0AA - R1016 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0AA - R1017 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B0AA - R1018 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B0BB - General Learning/Pupil Facilities - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0BB - R0001 - Toilets-Boys

No Asbestos

B0BB - R0002 - Toilets-Girls

No Asbestos

B0BB - R0003 - Cleaning Distributed Store

No Asbestos

B0BB - R0004 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B0BB - R0005 - Practical Activities - 1hb

No Asbestos

B0BB - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0BB - R0007 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0BB - R0008 - Home Base Store

No Asbestos

B0BB - R0009 - Home Base Store

No Asbestos

B0BB - R0010 - Practical Activities - 1hb

No Asbestos

B0BB - R0011 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0BB - R0012 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0BB - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0BB - R0014 - Home Base Store

No Asbestos

B0BB - R0015 - Practical Activities - 1hb

No Asbestos

B0BB - R0016 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B0BB - R0017 - Practical Activities - 1hb

No Asbestos

B0BB - R0018 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0BB - R0019 - Home Base Store

No Asbestos

B0BB - R0020 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0BB - R0021 - Practical Activities - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

No Asbestos

B0BB - R0022 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0BB - R0023 - Home Base Store

No Asbestos

B0BB - R0024 - Movement

No Asbestos

B0BB - R0025 - Stairs

No Asbestos

B0BB - R0026 - Stairs

No Asbestos

B0BB - R1001 - Home Base Store

No Asbestos

B0BB - R1002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0BB - R1003 - Practical Activities - 1hb

No Asbestos

B0BB - R1004 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0BB - R1005 - Practical Activities - 1hb

No Asbestos

B0BB - R1006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0BB - R1007 - Home Base Store

No Asbestos

B0BB - R1008 - Home Base Store

No Asbestos

B0BB - R1009 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B0BB - R1010 - Practical Activities - 1hb

No Asbestos

B0BB - R1011 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0BB - R1012 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0BB - R1013 - Practical Activities - 1hb

No Asbestos

B0BB - R1014 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0BB - R1015 - Home Base Store

No Asbestos

B0BB - R1016 - Practical Activities - 1hb

No Asbestos

B0BB - R1017 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B0BB - R1018 - Home Base Store						
No Asbestos						
B0BB - R1019 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0BB - R1020 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
No Asbestos						
B0BB - R1021 - Cleaning Distributed Store						
No Asbestos						
B0BB - R1022 - Special Programs Room						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B0BB - R1023 - Movement						
No Asbestos						
B0BB - R1024 - Stairs						
No Asbestos						
B0BB - R1025 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B0CC - Library - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0CC - R0001 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0CC - R0002 - Audio Visual Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0CC - R0003 - Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0CC - R0004 - Movement

No Asbestos

B0CC - R0005 - Toilets-Disabled

No Asbestos

B0CC - R0006 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0CC - R0007 - Security Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0CC - R0008 - Toilets-Unisex

No Asbestos

B0CC - R0009 - Cleaning Distributed Store

No Asbestos

B0CC - R0010 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B0DD - General Learning/Pupil Facilities - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0DD - R0001 - Toilets-Boys

No Asbestos

B0DD - R0002 - Kiln Room

No Asbestos

B0DD - R0003 - Toilets-Girls

No Asbestos

B0DD - R0004 - Sports Store

No Asbestos

B0DD - R0005 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B0DD - R0006 - Cleaning Distributed Store

No Asbestos

B0DD - R0007 - Practical Activities - 1hb

No Asbestos

B0DD - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0DD - R0009 - Home Base Store

No Asbestos

B0DD - R0010 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0DD - R0011 - Practical Activities - 1hb

No Asbestos

B0DD - R0012 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0DD - R0013 - Home Base Store

No Asbestos

B0DD - R0014 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0DD - R0015 - Movement

No Asbestos

B0DD - R0016 - Practical Activities - 1hb

No Asbestos

B0DD - R0017 - Home Base Store

No Asbestos

B0DD - R0018 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0DD - R0019 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0DD - R0020 - Practical Activities - 1hb

No Asbestos

B0DD - R0021 - Home Base

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					

B0DD - R0022 - Home Base Store

No Asbestos

B0DD - R0023 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0DD - R0024 - Home Base Store

No Asbestos

B0DD - R0025 - Practical Activities - 1hb

No Asbestos

B0DD - R0026 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0DD - R0027 - Practical Activities - 1hb

No Asbestos

B0DD - R0028 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0DD - R0029 - Home Base Store

No Asbestos

B0DD - R0030 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0DD - R0031 - Home Base Store

No Asbestos

B0DD - R0032 - Practical Activities - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0DD - R0033 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0DD - R0034 - Garden Store

No Asbestos

B0DD - R0035 - Movement

No Asbestos

B0DD - R0036 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B0EE - Communal Facilities - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0EE - R0001 - Communal Space

No Asbestos

B0EE - R0002 - Canteen

No Asbestos

B0EE - R0003 - Canteen Office/Store

No Asbestos

B0EE - R0004 - P.E. Store

No Asbestos

B0EE - R0005 - Control Room

No Asbestos

B0EE - R0006 - General Storeroom

No Asbestos

B0EE - R0007 - Hall Chair Store

No Asbestos

B0EE - R0008 - Covered Area

No Asbestos

B0EE - R0009 - Movement

No Asbestos

B0EE - R0010 - Toilets-Girls

No Asbestos

B0EE - R0011 - Toilets-Boys

No Asbestos

B0EE - R0012 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B0EE - R0013 - Stage

No Asbestos

B0EE - R0014 - Cleaning Distributed Store

No Asbestos

B0EE - R0015 - Movement

No Asbestos

B0EE - R0016 - General Assistants

No Asbestos

B0EE - R0017 - E.S.L.

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B0EE - R0018 - Toilets-Disabled

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B0FF - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0FF - R0001 - Practical Activities

No Asbestos

B0FF - R0002 - Home Base Store

No Asbestos

B0FF - R0003 - Home Base

No Asbestos

B0FF - R0004 - Withdrawal Space - 2hb

No Asbestos

B0FF - R0005 - Practical Activities

No Asbestos

B0FF - R0006 - Home Base

No Asbestos

B0FF - R0007 - Home Base Store

No Asbestos

B0FF - R0008 - General Assistant/Bulk Store

No Asbestos

B0FF - R0009 - Toilets - Girls

No Asbestos

B0FF - R0010 - Toilets - Boys

No Asbestos

B0FF - R0011 - External Movement

No Asbestos

B0FF - R0012 - General Storeroom

No Asbestos

B0FF - R0013 - Stairs

No Asbestos

B0FF - R1001 - External Movement

No Asbestos

B0FF - R1002 - Practical Activities

No Asbestos

B0FF - R1003 - Home Base Store

No Asbestos

B0FF - R1004 - Home Base

No Asbestos

B0FF - R1005 - Withdrawal Space - 2hb

No Asbestos

B0FF - R1006 - Practical Activities

No Asbestos

B0FF - R1007 - Home Base

No Asbestos

B0FF - R1008 - Home Base Store

No Asbestos

B0FF - R1009 - Home Base Store

No Asbestos

B0FF - R1010 - Withdrawal Space - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

No Asbestos

B0FF - R1011 - Practical Activities

No Asbestos

B0FF - R1012 - Home Base

No Asbestos

B0FF - R1013 - External Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B0GG - Administration - 1955 - Timber (Timber)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B0GG - R0001 - Staff Room

No Asbestos

B0GG - R0002 - Home Base

No Asbestos

B0GG - R0003 - External Movement

No Asbestos

B0GG - R0004 - Staff Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10332 - Learning Unit - Standard With P.A.A. : Placement Date - 15/01/2003

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 603 - D12698 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 21/02/2002

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D12737 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 18/10/2004

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12881 - Learning Unit - Standard With P.A.A. : Placement Date - 3/08/2005

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 602 - D13018 - Learning Unit - Standard With P.A.A. : Placement Date - 10/04/2015

Exterior

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D13219 - Learning Unit - Standard With P.A.A. : Placement Date - 7/04/1999

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D13222 - Learning Unit - Standard With P.A.A. : Placement Date - 25/01/2000

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D15489 - Learning Unit - Standard With P.A.A. : Placement Date - 3/12/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D15956 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 10/01/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D16248 - Learning Unit - Standard With P.A.A. : Placement Date - 6/04/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D16630 - Learning Unit - Standard With P.A.A. : Placement Date - 29/10/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017