Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Currans Hill Public School (4625)**
Region :	**South Western Sydney**
State Electorate :	**Camden**
Local Government Area :	**Camden**

Initial Survey :	**Noel Arnold & Associates : 21 - May - 2008**
Register Issue Date :	**23 - Mar - 2017**

4625 - Currans Hill Public School
Site Plan (03094)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00A - Administration/Staff Facilities - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00A - R0001 - External Movement

No Asbestos

B00A - R0002 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0003 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0004 - Sick Bay

No Asbestos

B00A - R0005 - Disabled Shower/Toilet

No Asbestos

B00A - R0006 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0007 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0008 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0009 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0010 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0011 - Cleaning Distributed Store

No Asbestos

B00A - R0012 - Staff Toilet

No Asbestos

B00A - R0013 - Staff Toilet

No Asbestos

B00A - R0014 - Staff Toilet

No Asbestos

B00A - R0015 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0016 - Security Store

No Asbestos

B00A - R0017 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0018 - Duplicating Workroom

No Asbestos

B00A - R0019 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00B - General Learning/Pupil Facilities - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - External Movement

No Asbestos

B00B - R0002 - Toilets - Boys

No Asbestos

B00B - R0003 - Kiln Room

No Asbestos

B00B - R0004 - Toilets - Girls

No Asbestos

B00B - R0005 - Garden Store

No Asbestos

B00B - R0006 - Cleaning Distributed Store

No Asbestos

B00B - R0007 - Sports Store

No Asbestos

B00B - R0008 - Home Base Store

No Asbestos

B00B - R0009 - Practical Activities - 1hb

No Asbestos

B00B - R0010 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00B - R0011 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00B - R0012 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00B - R0013 - Practical Activities - 1hb

No Asbestos

B00B - R0014 - Home Base Store

No Asbestos

B00B - R0015 - Home Base Store

No Asbestos

B00B - R0016 - Practical Activities - 1hb

No Asbestos

B00B - R0017 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00B - R0018 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00B - R0019 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00B - R0020 - Practical Activities - 1hb

No Asbestos

B00B - R0021 - Home Base Store

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

No Asbestos

B00B - R0022 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00C - General Learning/Library - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - External Movement

No Asbestos

B00C - R0002 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0003 - Cleaning Distributed Store

No Asbestos

B00C - R0004 - Toilets - Boys/Girls

No Asbestos

B00C - R0005 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0006 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0007 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0008 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0009 - Home Base Store

No Asbestos

B00C - R0010 - Practical Activities - 1hb

No Asbestos

B00C - R0011 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0012 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0014 - Practical Activities - 1hb

No Asbestos

B00C - R0015 - Home Base Store

No Asbestos

B00C - R0016 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0017 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00E - Communal Facilities/Pupil Facilities - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0002 - Movement

No Asbestos

B00E - R0003 - Cleaning Distributed Store

No Asbestos

B00E - R0004 - Raised Platform

No Asbestos

B00E - R0005 - Movement

No Asbestos

B00E - R0007 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00E - R0008 - P.E. Store

No Asbestos

B00E - R0009 - P.E. Store

No Asbestos

B00E - R0010 - Hall Chair Store

No Asbestos

B00E - R0011 - Toilets - Boys

No Asbestos

B00E - R0012 - Plant

No Asbestos

B00E - R0013 - Disabled Toilet

No Asbestos

B00E - R0014 - Communal Space

No Asbestos

B00E - R0015 - External Movement

No Asbestos

B00E - R0016 - Toilets - Girls

No Asbestos

B00E - R0017 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00E - R0018 - Toilets - Boys/Girls

No Asbestos

B00E - R0019 - Community Clinic

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00E - R0020 - Cleaning Distributed Store

No Asbestos

B00E - R0021 - Canteen

No Asbestos

B00E - R0022 - Canteen Office/Store

No Asbestos

B00E - R0023 - Main Switch Board

No Asbestos

B00E - R0024 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

B00F - General Learning/Pupil Facilities - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - External Movement

No Asbestos

B00F - R0002 - Toilets - Boys

No Asbestos

B00F - R0003 - Disabled Toilet

No Asbestos

B00F - R0004 - Toilets - Girls

No Asbestos

B00F - R0005 - Home Base Store

No Asbestos

B00F - R0006 - Practical Activities - 1hb

No Asbestos

B00F - R0007 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0009 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0010 - Practical Activities - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0011 - Home Base Store

No Asbestos

B00F - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0013 - Home Base Store

No Asbestos

B00F - R0014 - Practical Activities - 1hb

No Asbestos

B00F - R0015 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0017 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0018 - Practical Activities - 1hb

No Asbestos

B00F - R0019 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00G - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - External Movement

No Asbestos

B00G - R0002 - Practical Activities - 1hb

No Asbestos

B00G - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00H - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - R0001 - External Movement

No Asbestos

B00H - R0002 - Practical Activities - 1hb

No Asbestos

B00H - R0003 - Home Base Store

No Asbestos

B00H - R0004 - Home Base

No Asbestos

B00H - R0005 - Withdrawal Space - 2hb

No Asbestos

B00H - R0006 - Home Base

No Asbestos

B00H - R0007 - Home Base Store

No Asbestos

B00H - R0008 - Practical Activities - 1hb

No Asbestos

B00H - R0009 - Main Switch Board Cupboard

No Asbestos

B00H - R0010 - Practical Activities - 1hb

No Asbestos

B00H - R0011 - Home Base Store

No Asbestos

B00H - R0012 - Home Base

No Asbestos

B00H - R0013 - Withdrawal Space - 2hb

No Asbestos

B00H - R0014 - Home Base

No Asbestos

B00H - R0015 - Home Base Store

No Asbestos

B00H - R0016 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00I - General Learning/Pupil Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00I - R0001 - External Movement

No Asbestos

B00I - R0002 - Toilets - Boys

No Asbestos

B00I - R0003 - Toilets - Girls

No Asbestos

B00I - R0004 - Withdrawal Space - 1hb

No Asbestos

B00I - R0005 - Home Base Store

No Asbestos

B00I - R0006 - Practical Activities - 1hb

No Asbestos

B00I - R0007 - Home Base

No Asbestos

B00I - R0008 - Main Switch Board Cupboard

No Asbestos

B00I - R0009 - Sports Store

No Asbestos

B00I - R0010 - General Assistant/Bulk Store

No Asbestos

B00I - R0011 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 603 - D10139 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 24/01/2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D10275 - Learning Unit - Standard With P.A.A. : Placement Date - 17/12/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11091 - Learning Unit - Standard With P.A.A. : Placement Date - 27/09/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11119 - Learning Unit - Standard With P.A.A. : Placement Date - 20/01/2001

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 602 - D11655 - Learning Unit - Standard With P.A.A. : Placement Date - 20/01/2001

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 603 - D12713 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 17/12/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D13446 - Learning Unit - Standard With P.A.A. : Placement Date - 7/10/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14494 - Learning Unit - Standard With P.A.A. : Placement Date - 27/09/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D15295 - Learning Unit - Standard With P.A.A. : Placement Date - 11/03/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D15747 - Learning Unit - Standard With P.A.A. : Placement Date - 10/12/2012

Exterior

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017