Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Darlington Point Public School (1736)**
Region :	**Riverina**
State Electorate :	**Murray**
Local Government Area :	**Murrumbidgee**

Initial Survey :	**Noel Arnold & Associates : 09 - May - 2008**
Reviewed By :	**Parsons Brinckerhoff : 09 - Feb - 2017**



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00A - Administration/General Learning - 1956 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1736/B00C/Eaves Linings/S1					**Chrysotile (white asbestos)**

Interior

B00A - R0001 - Distribution Board

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Not able to be sampled due to height					
Wall Linings Internal	Flat AC Sheeting					
	1736/B00C/R0008/Wall Linings Internal/S2					**No Asbestos Detected**
Electrical Mounting Board	Resinous Board	1Unit	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Not able to be sampled due to live					

B00A - R0002 - Canteen

No Asbestos

B00A - R0003 - Home Base

No Asbestos

B00A - R0006 - Duplicating Workroom

No Asbestos

B00A - R0007 - Clerical Office/Workroom

No Asbestos

B00A - R0008 - Sick Bay

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Not able to be sampled due to height					
Wall Linings Internal	Flat AC Sheeting					
	1736/B00C/R0008/Wall Linings Internal/S2					**No Asbestos Detected**

B00A - R0009 - Movement

Flooring	Compressed AC Sheet					
	1736/B00C/R0008/Floor Coverings Res/Textile/S3					**No Asbestos Detected**
Ceiling Structures/Linings	Flat AC Sheeting	37m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Not able to be sampled due to height					
Wall Linings Internal	Flat AC Sheeting					
	1736/B00C/R0008/Wall Linings Internal/S2					**No Asbestos Detected**

B00A - R0010 - Entry Vestibule

No Asbestos

B00A - R0011 - Interview

No Asbestos

B00A - R0012 - Principal

No Asbestos

B00A - R0013 - Security Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00B - General Learning/Staff Facilities - 1969 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	14m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	1736/B00C/Eaves Linings/S1					**Chrysotile (white asbestos)**
In-fill-panel	Flat AC Sheeting					
	1736/B00C/R0008/Wall Linings Internal/S2					**No Asbestos Detected**

Interior

B00B - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	47m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1736/B00C/Eaves Linings/S1					**Chrysotile (white asbestos)**
In-fill-panel	Flat AC Sheeting					
	1736/B00C/R0008/Wall Linings Internal/S2					**No Asbestos Detected**

B00B - R0002 - Home Base

No Asbestos

B00B - R0003 - Kiln Room

No Asbestos

B00B - R0004 - Home Base Store

No Asbestos

B00B - R0005 - Home Base

No Asbestos

B00B - R0006 - Staff Toilet

Incinerator	Encapsulated Insulation material within unit	1Unit(s)	All surfaces	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Not able to be sampled due to no					

B00B - R0007 - Staff Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00C - Library - 1956 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1736/B00C/Eaves Linings/S1					**Chrysotile (white asbestos)**

Interior

B00C - R0001 - Cleaning Supplies

No Asbestos

B00C - R0002 - Movement

No Asbestos

B00C - R0003 - Reading Area

No Asbestos

B00C - R0004 - Reading Area

No Asbestos

B00C - R0005 - Sports Store

Floor Coverings Res/Textile	Vinyl Tiles	
	1736/B00C/R0007/Floor Coverings Res/Textile/S4	**No Asbestos Detected**

B00C - R0006 - Sports Store

Floor Coverings Res/Textile	Vinyl Tiles	
	1736/B00C/R0007/Floor Coverings Res/Textile/S4	**No Asbestos Detected**

B00C - R0007 - Sports Store

Floor Coverings Res/Textile	Vinyl Tiles	
	1736/B00C/R0007/Floor Coverings Res/Textile/S4	**No Asbestos Detected**

B00C - R0008 - Movement

Wall Linings Internal	Flat AC Sheeting	
	1736/B00C/R0008/Wall Linings Internal/S2	**No Asbestos Detected**
Flooring	Compressed AC Sheet	
	1736/B00C/R0008/Floor Coverings Res/Textile/S3	**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00D - General Learning - 1956 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00D - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	35m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Not able to be sampled due to height					
In-fill-panel	Flat AC Sheeting					
	1736/B00C/R0008/Wall Linings Internal/S2					**No Asbestos Detected**

B00D - R0002 - Personal Effects Storage

No Asbestos

B00D - R0003 - Home Base Store

No Asbestos

B00D - R0004 - Home Base

No Asbestos

B00D - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Not able to be sampled due to height					
In-fill-panel	Flat AC Sheeting					
	1736/B00C/R0008/Wall Linings Internal/S2					**No Asbestos Detected**

B00D - R0006 - Home Base

No Asbestos

B00D - R0007 - Home Base Store

No Asbestos

B00D - R0008 - Personal Effects Storage

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00E - General Learning - 1934 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00E - R0001 - Movement

Flooring	Compressed AC Sheet	
	1736/B00C/R0008/Floor Coverings Res/Textile/S3	**No Asbestos Detected**

B00E - R0003 - General Storeroom

No Asbestos

B00E - R0004 - Withdrawal Space - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00F - Building Services - 1934 - Timber Shed (Timber Shed)

Exterior

Ceiling Voids	No Asbestos Found

Interior

B00F - R0001 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00G - Pupil Facilities - 1950 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1736/B00C/Eaves Linings/S1					**Chrysotile (white asbestos)**

Interior

B00G - R0001 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	22m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Not able to be sampled due to height					

B00G - R0003 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Not able to be sampled due to height					

B00G - R0005 - Cleaning Supplies

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Not able to be sampled due to height					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00H - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00H - R0001 - Communal Space

No Asbestos

B00H - R0002 - P.E. Store

No Asbestos

B00H - R0003 - Communications Cupboard

No Asbestos

B00H - R0004 - Main Switch Board

No Asbestos

B00H - R0005 - External Movement

No Asbestos

B00H - R0006 - Covered Outdoor Learning Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00I - Electrical Services - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00I - R0001 - Main Switch Board

No Asbestos

B00I - R0002 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017