Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**East Hills Girls Technology High School (8187)**
Region :	**South Western Sydney**
State Electorate :	**East Hills**
Local Government Area :	**Bankstown**

Initial Survey :	**Noel Arnold & Associates : 04 - May - 2008**
Reviewed By :	**Parsons Brinckerhoff : 13 - Feb - 2017**

8187 - East Hills Girls Technology High School
Site Plan (11865)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B002 - Multi Purpose Facilities - 1954 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids					
Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	10m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B002/Eaves Linings/S30					**Chrysotile (white asbestos)**

Interior

B002 - R0001 - Cleaning Store - Distributed

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B002/R0003/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B002 - R0002 - Cleaning Store - Distributed

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B002/R0003/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B002 - R0004 - Sport Equipment Store

Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B002/R0003/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B002 - R0005 - Multi-Purpose Space

No Asbestos

B002 - R0006 - Sport Equipment Store

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B002/R0003/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B002 - R0007 - Sport Equipment Store

Ceiling Structures/Linings	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B002/R0003/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B002 - R0008 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B002/R0003/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B002 - R0009 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B002/R0003/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B002 - R0010 - Garden Store Room

Ceiling Structures/Linings	Flat AC Sheeting	16.13m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B002/R0010/Ceiling Structures/Linings/S28					**Chrysotile (white asbestos)**

B002 - R0011 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B002/R0003/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B002 - R0013 - Change

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Flat AC Sheeting	28.11m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B002/R0013/Ceiling Structures/Linings/S31					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B002 - R0014 - Plant						
Ceiling Structures/Linings	Flat AC Sheeting	1.28m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B002/R0013/Ceiling Structures/Linings/S31					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B002 - R0015 - Toilets-Girls						
Ceiling Structures/Linings	Flat AC Sheeting	17.67m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B002/R0013/Ceiling Structures/Linings/S31					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B002 - R0016 - Sport Equipment Store						
Ceiling Structures/Linings	Flat AC Sheeting	11.63m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B002/R0013/Ceiling Structures/Linings/S31					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B003 - General Learning - 1951 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B003 - R0001 - General Learning Space

Wall Linings Internal	Flat AC Sheeting	2m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B003/R0003/Wall Linings Internal/S21					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B003 - R0002 - General Learning Space

Wall Linings Internal	Flat AC Sheeting	2m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B003/R0003/Wall Linings Internal/S21					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B003 - R0003 - Design L.S.

Wall Linings Internal	Flat AC Sheeting	2m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B003/R0003/Wall Linings Internal/S21					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Floor Coverings Res/Textile	Vinyl Tiles	67m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B003/R0003/Floor Coverings Res/Textile/S22					**Chrysotile (white asbestos)**

B003 - R0004 - Resources Store

No Asbestos

B003 - R0005 - Resources Store

No Asbestos

B003 - R0006 - General Learning Space

Wall Linings Internal	Flat AC Sheeting	2m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B003/R0003/Wall Linings Internal/S21					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B003 - R0007 - Resources Store

No Asbestos

B003 - R0008 - General Storeroom

No Asbestos

B003 - R0009 - General Learning Space

Wall Linings Internal	Flat AC Sheeting	2m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B003/R0003/Wall Linings Internal/S21					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B003 - R0010 - Resources Store

Wall Linings Internal	Flat AC Sheeting	2m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B003/R0003/Wall Linings Internal/S21					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B003 - R0011 - Resources Store

No Asbestos

B003 - R0013 - Resources Store

No Asbestos

B003 - R0015 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	8187/B003/R0015/Ceiling Structures/Linings/S20					**No Asbestos Detected**

B003 - R0016 - Staff Study

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B003 - R0017 - Tea Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B004 - General Learning/Staff Facilities - 1954 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B004 - R0004 - General Learning Space

No Asbestos

B004 - R0005 - General Learning Space

No Asbestos

B004 - R0006 - Resources Store

No Asbestos

B004 - R0007 - Resources Store

No Asbestos

B004 - R0008 - General Learning Space

No Asbestos

B004 - R0009 - General Learning Space

No Asbestos

B004 - R0011 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	
	8187/B004/R0011/Ceiling Structures/Linings/S23	**No Asbestos Detected**

B004 - R0012 - Staff Study

No Asbestos

B004 - R0013 - Tea Room

No Asbestos

B004 - R0014 - Staff Study

No Asbestos

B004 - R0015 - Tea Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B005 - Science Learning/General Learning - 1954 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B005 - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	
	8187/B005/R0001/Ceiling Structures/Linings/S25	**No Asbestos Detected**

B005 - R0002 - Computer Resource

No Asbestos

B005 - R0003 - General Learning Space

No Asbestos

B005 - R0007 - Preparation - Science

No Asbestos

B005 - R0008 - Archive Store

No Asbestos

B005 - R0009 - Archive Store

Ceiling Structures/Linings	Flat AC Sheeting	
	8187/B005/R0001/Ceiling Structures/Linings/S25	**No Asbestos Detected**

B005 - R0010 - Computer Resource

No Asbestos

B005 - R0011 - Laboratory L.S.

No Asbestos

B005 - R0012 - General Learning Space

No Asbestos

B005 - R0013 - Science Laboratory

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B006 - General Learning - 1954 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B006 - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	8187/B006/R0011/Ceiling Structures/Linings/S12					**No Asbestos Detected**

B006 - R0002 - Laundry

No Asbestos

B006 - R0003 - General Learning Space

No Asbestos

B006 - R0004 - General Learning Space

No Asbestos

B006 - R0005 - Staff Study

Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B006/R0005/Floor Coverings Res/Textile/S13					**Chrysotile (white asbestos)**

B006 - R0006 - Staff Study

No Asbestos

B006 - R0007 - General Learning Space

No Asbestos

B006 - R0008 - General Learning Space

No Asbestos

B006 - R0009 - Staff Study

No Asbestos

B006 - R0010 - Resources Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B007 - General Learning/Computer Learning - 1951 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B007 - R0001 - General Assistants

Ceiling Structures/Linings	Flat AC Sheeting					
	8187/B007/R0001/Ceiling Structures/Linings/S14					**No Asbestos Detected**

B007 - R0003 - Computer Learning Space

Wall Linings Internal	Flat AC Sheeting	2m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B007/R0004/Wall Linings Internal/S15					**Chrysotile (white asbestos)**

B007 - R0004 - General Learning Space

Wall Linings Internal	Flat AC Sheeting	2m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B007/R0004/Wall Linings Internal/S15					**Chrysotile (white asbestos)**

B007 - R0005 - General Learning Space

Wall Linings Internal	Flat AC Sheeting	2m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B007/R0004/Wall Linings Internal/S15					**Chrysotile (white asbestos)**

B007 - R0006 - General Learning Space

Wall Linings Internal	Flat AC Sheeting	2m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B007/R0004/Wall Linings Internal/S15					**Chrysotile (white asbestos)**

B007 - R0008 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	8187/B007/R0001/Ceiling Structures/Linings/S14					**No Asbestos Detected**

B007 - R0009 - Staff Study

Wall Linings Internal	Flat AC Sheeting					
	8187/B007/R0009/Wall Linings Internal/S32					**No Asbestos Detected**

B007 - R0010 - Tea Room

Wall Linings Internal	Flat AC Sheeting					
	8187/B007/R0010/Wall Linings Internal/S33					**No Asbestos Detected**

B007 - R0011 - General Assistants

No Asbestos

B007 - R0012 - Handwashing Facilities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B008 - Art - 1951 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B008 - R0001 - Dark Room

No Asbestos

B008 - R0003 - Art Learning Space

No Asbestos

B008 - R0006 - Resources Store

No Asbestos

B008 - R0007 - Art Learning Space

No Asbestos

B008 - R0008 - Resources Store

No Asbestos

B008 - R0009 - Resources Store

No Asbestos

B008 - R0010 - Staff Lounge

No Asbestos

B008 - R0013 - Dark Room

No Asbestos

B008 - R0014 - Staff Study

No Asbestos

B008 - R0015 - External Movement

No Asbestos

B008 - R0016 - Darkroom Space

No Asbestos

B008 - R0017 - Resources Store

No Asbestos

B008 - R0018 - Art Learning Space

No Asbestos

B008 - R0019 - Staff Study

Ceiling Structures/Linings	Flat AC Sheeting	15.51m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B008/R0019/Ceiling Structures/Linings/S34					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B008 - R0020 - Tea Room

Ceiling Structures/Linings	Flat AC Sheeting	1.04m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B008/R0019/Ceiling Structures/Linings/S34					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

B009 - Technological & Applied Studies - 1951 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B009 - R0002 - Staff Study

No Asbestos

B009 - R0004 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting 8187/B009/R0004/Wall Linings Internal/S35	**No Asbestos Detected**
Wall Linings Internal	Flat AC Sheeting 8187/B009/R0004/Wall Linings Internal/S36	**No Asbestos Detected**

B009 - R0005 - Kitchen - Type 1

No Asbestos

B009 - R0006 - Design/Technology L.S.

No Asbestos

B009 - R0007 - Materials Technology L.S.

No Asbestos

B009 - R0008 - Food Technology L.S.

No Asbestos

B009 - R0009 - Preparation - Materials

No Asbestos

B009 - R0010 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 8187/B009/R0010/Ceiling Structures/Linings/S9	**No Asbestos Detected**

B009 - R0011 - Staff Study

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B010 - Computer Learning/Music - 1951 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B010 - R0001 - Music Learning Space

No Asbestos

B010 - R0002 - Computer Learning Space

No Asbestos

B010 - R0003 - Office/Store

No Asbestos

B010 - R0004 - General Learning Space

No Asbestos

B010 - R0006 - Staff Study

No Asbestos

B010 - R0007 - Resources Store

No Asbestos

B010 - R0009 - External Movement

No Asbestos

B010 - R0010 - Staff Study

No Asbestos

B010 - R0011 - Tea Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B011 - Pupil Facilities - 1957 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids

Interior

B011 - R0001 - Covered Area

No Asbestos

B011 - R0002 - Student Canteen

No Asbestos

B011 - R0003 - Office/Store

No Asbestos

B011 - R0004 - Staff - Toilet

No Asbestos

B011 - R0005 - General Storeroom

No Asbestos

B011 - R0006 - Pantry

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B012 - Library/Science Learning - 1970 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids					

Interior

B012 - M1001 - Senior Seminar

No Asbestos

B012 - M1002 - Plant

No Asbestos

B012 - M1003 - Study Space

No Asbestos

B012 - M1004 - Study Space

No Asbestos

B012 - M1005 - Stairs

No Asbestos

B012 - M1006 - Stairs

No Asbestos

B012 - M1007 - Plant

No Asbestos

B012 - M1008 - Plant

No Asbestos

B012 - M1009 - Plant

No Asbestos

B012 - R0001 - Computer Learning Space

Ceiling Structures/Linings	Vermiculite 8187/B012/R0008/Ceiling Structures/Linings/S7					**No Asbestos Detected**

B012 - R0002 - Laboratory L.S.

Ceiling Structures/Linings	Vermiculite 8187/B012/R0008/Ceiling Structures/Linings/S7					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 8187/B012/R0008/Floor Coverings Res/Textile/S6	91m2	Throughout	Good Condition (1)	Low (1) Low Priority (2-3)	**Chrysotile (white asbestos)**

B012 - R0003 - Preparation - Science

Ceiling Structures/Linings	Vermiculite 8187/B012/R0008/Ceiling Structures/Linings/S7					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 8187/B012/R0008/Floor Coverings Res/Textile/S6	45m2	Throughout	Good Condition (1)	Low (1) Low Priority (2-3)	**Chrysotile (white asbestos)**

B012 - R0004 - Chemical Store

Ceiling Structures/Linings	Vermiculite 8187/B012/R0008/Ceiling Structures/Linings/S7					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 8187/B012/R0008/Floor Coverings Res/Textile/S6	4m2	Throughout	Good Condition (1)	Low (1) Low Priority (2-3)	**Chrysotile (white asbestos)**

B012 - R0005 - Laboratory L.S.

Ceiling Structures/Linings	Vermiculite 8187/B012/R0008/Ceiling Structures/Linings/S7					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 8187/B012/R0008/Floor Coverings Res/Textile/S6	92m2	Throughout	Good Condition (1)	Low (1) Low Priority (2-3)	**Chrysotile (white asbestos)**

B012 - R0006 - Apparatus Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Floor Coverings Res/Textile	Vinyl Tiles	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B012/R0008/Floor Coverings Res/Textile/S6					**Chrysotile (white asbestos)**
B012 - R0007 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
No Asbestos						
B012 - R0008 - Laboratory L.S.						
Floor Coverings Res/Textile	Vinyl Tiles	92m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B012/R0008/Floor Coverings Res/Textile/S6					**Chrysotile (white asbestos)**
Ceiling Structures/Linings	Vermiculite					
	8187/B012/R0008/Ceiling Structures/Linings/S7					**No Asbestos Detected**
B012 - R0011 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles	41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B012/R0008/Floor Coverings Res/Textile/S6					**Chrysotile (white asbestos)**
B012 - R0012 - External Movement						
No Asbestos						
B012 - R0013 - Cleaning Store - Distributed						
No Asbestos						
B012 - R0014 - Plant						
No Asbestos						
B012 - R0015 - Lift						
No Asbestos						
B012 - R0016 - Movement						
No Asbestos						
B012 - R0017 - Plant						
No Asbestos						
B012 - R0018 - Stairs						
No Asbestos						
B012 - R0019 - Main Switchroom						
No Asbestos						
B012 - R0020 - Staff Study						
Ceiling Structures/Linings	Vermiculite					
	8187/B012/R0020/Recently Modified Space/S37					**No Asbestos Detected**
B012 - R0021 - Tea Room						
No Asbestos						
B012 - R1001 - Staff - Toilet						
No Asbestos						
B012 - R1002 - Seminar						
Ceiling Structures/Linings	Vermiculite					
	8187/B012/R0008/Ceiling Structures/Linings/S7					**No Asbestos Detected**
B012 - R1006 - Cleaning Store - Distributed						
No Asbestos						
B012 - R1007 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
No Asbestos						
B012 - R1008 - Senior Study						
No Asbestos						
B012 - R1009 - Senior Study						
No Asbestos						
B012 - R1010 - Audio Visual Workroom						
No Asbestos						
B012 - R1011 - Archive Store						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B012 - R1013 - Librarian

No Asbestos

B012 - R1014 - Staff - Toilet

No Asbestos

B012 - R1016 - Plant

No Asbestos

B012 - R1017 - Plant

No Asbestos

B012 - R1018 - External Movement

No Asbestos

B012 - R1020 - Movement

No Asbestos

B012 - R1021 - Stairs

No Asbestos

B012 - R1022 - Stairs

No Asbestos

B012 - R1023 - External Stairs

No Asbestos

B012 - R1025 - Computer Resource

Ceiling Structures/Linings	Vermiculite		
	8187/B012/R1028/Ceiling Structures/Linings/S38		**No Asbestos Detected**

B012 - R1026 - Computer Store

No Asbestos

B012 - R1027 - Main Entry

No Asbestos

B012 - R1028 - Main Area

Ceiling Structures/Linings	Vermiculite		
	8187/B012/R1028/Ceiling Structures/Linings/S38		**No Asbestos Detected**

B012 - R1029 - Movement

No Asbestos

B012 - R1030 - Handwashing Facilities

No Asbestos

B012 - R1031 - Library Administration

No Asbestos

B012 - R1032 - Tea Room

No Asbestos

B012 - R1033 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B013 - Pupil Facilities - 1957 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids					

Interior

B013 - R0001 - Toilets-Girls

Ceiling Structures/Linings	Flat AC Sheeting	136m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B013/R0004/Ceiling Structures/Linings/S26					**Chrysotile (white asbestos)**
Partition Walls (Cubicles)	Compressed AC Sheet					
	8187/B013/R0001/Partition Walls (Cubicles)/S27					**No Asbestos Detected**

B013 - R0002 - Toilets-Disabled

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B013/R0004/Ceiling Structures/Linings/S26					**Chrysotile (white asbestos)**

B013 - R0003 - Cleaning Store - Distributed

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B013/R0004/Ceiling Structures/Linings/S26					**Chrysotile (white asbestos)**

B013 - R0004 - Student Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B013/R0004/Ceiling Structures/Linings/S26					**Chrysotile (white asbestos)**

B013 - R0005 - Student Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B013/R0004/Ceiling Structures/Linings/S26					**Chrysotile (white asbestos)**

B013 - R0006 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B013/R0004/Ceiling Structures/Linings/S26					**Chrysotile (white asbestos)**

B013 - R0007 - Staff - Toilet

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B013/R0004/Ceiling Structures/Linings/S26					**Chrysotile (white asbestos)**

B013 - R0008 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B013/R0004/Ceiling Structures/Linings/S26					**Chrysotile (white asbestos)**

B013 - R0009 - Cleaning Supplies Store

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8187/B013/R0004/Ceiling Structures/Linings/S26					**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B014 - Computer Learning - 2007 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids
Ceiling Voids	No Asbestos Found

Interior

B014 - R0001 - Staff - Toilet

No Asbestos

B014 - R0002 - Computer Store

No Asbestos

B014 - R0003 - Computer Learning Space

No Asbestos

B014 - R0004 - Computer Learning Space

No Asbestos

B014 - R0005 - Movement

No Asbestos

B014 - R0006 - Staff Study

No Asbestos

B014 - R0007 - Staff Kitchen

No Asbestos

B014 - R0008 - Computer Room

No Asbestos

B014 - R0009 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B015 - Multi Purpose Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids
Ceiling Voids	No Asbestos Found

Interior

B015 - R0001 - Multi-Purpose Space

No Asbestos

B015 - R0002 - Plant

No Asbestos

B015 - R0003 - First Aid

No Asbestos

B015 - R0004 - Access Student Shower/Toilet/Change

No Asbestos

B015 - R0005 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B015 - R0006 - Cleaning Store - Distributed

No Asbestos

B015 - R0007 - External Movement

No Asbestos

B015 - R0008 - Change

No Asbestos

B015 - R0009 - Change

No Asbestos

B015 - R0010 - Large Equipment Store

No Asbestos

B015 - R0011 - Chair Store

No Asbestos

B015 - R0012 - External Movement

No Asbestos

B015 - R0013 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B016 - Technological & Applied Studies - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids
Ceiling Voids	No Asbestos Found

Interior

B016 - R0001 - Performance Workshop

No Asbestos

B016 - R0002 - Practice/Seminar

No Asbestos

B016 - R0003 - Performance Store

No Asbestos

B016 - R0004 - General Learning Space - Type 1

No Asbestos

B016 - R0005 - General Learning Space - Type 1

No Asbestos

B016 - R0006 - General Learning Space - Type 1

No Asbestos

B016 - R0007 - General Learning Space - Type 1

No Asbestos

B016 - R0008 - General Learning Space - Type 9

No Asbestos

B016 - R0009 - General Learning Space - Type 8

No Asbestos

B016 - R0010 - Dust Extraction Space

No Asbestos

B016 - R0011 - Materials Workshop - Type 2

No Asbestos

B016 - R0012 - Project Store - Type 1

No Asbestos

B016 - R0013 - Outdoor Workshop

No Asbestos

B016 - R0014 - Welding/Hot Metals Area

No Asbestos

B016 - R0015 - Kiln Space

No Asbestos

B016 - R0016 - Pottery Store

No Asbestos

B016 - R0017 - Materials Store - Type 1

No Asbestos

B016 - R0018 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B016 - R0019 - L.P.G. Store

No Asbestos

B016 - R0020 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B016 - R0021 - G.L.S. Store

No Asbestos

B016 - R0022 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B016 - R0023 - External Movement						
No Asbestos						
B016 - R0024 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B017 - Administration/Staff - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids
Ceiling Voids	No Asbestos Found

Interior

B017 - R0001 - Public Reception

No Asbestos

B017 - R0002 - Visitors Office

No Asbestos

B017 - R0003 - Interview/Meeting

No Asbestos

B017 - R0004 - Movement

No Asbestos

B017 - R0005 - Principal Office

No Asbestos

B017 - R0006 - Store

No Asbestos

B017 - R0007 - Staff Lounge

No Asbestos

B017 - R0008 - Staff - Toilet

No Asbestos

B017 - R0009 - Staff - Toilet

No Asbestos

B017 - R0010 - Staff Kitchen

No Asbestos

B017 - R0011 - Preparation/Printing

No Asbestos

B017 - R0012 - Cleaning Store - Distributed

No Asbestos

B017 - R0013 - Staff - Toilet

No Asbestos

B017 - R0014 - Tea Room

No Asbestos

B017 - R0015 - Administration - Executive

No Asbestos

B017 - R0016 - External Movement

No Asbestos

B017 - R0017 - Administration - Clerical

No Asbestos

B017 - R0018 - Movement

No Asbestos

B017 - R0019 - Deputy Principal Office

No Asbestos

B017 - R0020 - Deputy Principal Office

No Asbestos

B017 - R0021 - Interview/Office - Type 2

No Asbestos

B017 - R0022 - Student Reception

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B017 - R0023 - Access Staff Shower/Toilet

No Asbestos

B017 - R0024 - Access Staff Shower/Toilet

No Asbestos

B017 - R0025 - Clinic - Girls

No Asbestos

B017 - R0026 - Interview/Office - Type 1

No Asbestos

B017 - R0027 - Deputy Principal Office

No Asbestos

B017 - R0028 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B017 - R0029 - External Movement

No Asbestos

B017 - R0030 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 601 - D11197 - Learning Unit - Standard/Withdrawal : Placement Date - 2/02/2017

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

OS 601 - D11397 - Learning Unit - Standard/Withdrawal : Placement Date - 26/09/1996

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2

OS 601 - D11684 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2

OS 601 - D11687 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 601 - D14826 - Learning Unit - Standard/Withdrawal : Placement Date - 11/07/2013						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Store						
No Asbestos Found.						
OS 601 - D16279 - Learning Unit - Standard/Withdrawal : Placement Date - 22/02/2000						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 600 - D17420 - Learning Unit - Small : Placement Date - 4/01/2016						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - General Learning Space						
No Asbestos Found.						
OS 600 - D17421 - Learning Unit - Small : Placement Date - 4/01/2016						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Interior

R1 - General Learning Space

No Asbestos Found.

OS 601 - D17815 - Learning Unit - Standard/Withdrawal : Placement Date - 4/02/2015

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017