Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Glen Innes Public School (2005)**
Region :	**New England**
State Electorate :	**Northern Tablelands**
Local Government Area :	**Glen Innes Severn**

Initial Survey :	**Noel Arnold & Associates : 20 - May - 2008**
Reviewed By :	**Greencap-NAA : 01 - Apr - 2015**

2005 - Glen Innes Public School
Site Plan (12713)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - General Learning/Staff Facilities - 1929 - Brick/Block (Brick/Block)

Exterior

Gable Verge Lining	Flat AC Sheeting	30m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction					
Eaves Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00A/Eaves Linings/S31					**Chrysotile (white asbestos)**
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00A - R0001 - Staff Room Annexe

No Asbestos

B00A - R0002 - Movement

Wall Linings Internal	Flat AC Sheeting	8m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00A/R0002/Wall Linings Internal/S9					**Chrysotile (white asbestos)**

B00A - R0003 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 2005/B00A/R0003/Ceiling Structures/Linings/S8	**No Asbestos Detected**

B00A - R0004 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting	102m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction					
Wall Linings Internal	Flat AC Sheeting	8m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)

B00A - R0005 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 2005/B00A/R0003/Ceiling Structures/Linings/S8	**No Asbestos Detected**

B00A - R0006 - Movement

No Asbestos

B00A - R0007 - Home Base

No Asbestos

B00A - R0008 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles 2005/B00A/R0008/Floor Coverings Res/Textile/S18	**No Asbestos Detected**
Floor Coverings Res/Textile	Adhesive 2005/B00A/R0008/Floor Coverings Res/Textile/S19	**No Asbestos Detected**

B00A - R0009 - Duplicating Workroom

No Asbestos

B00A - R0010 - Special Programs Room

No Asbestos

B00A - R0011 - Movement

No Asbestos

B00A - R0013 - Cleaning Distributed Store

No Asbestos

B00A - R0014 - Personal Effects Storage

No Asbestos

B00A - R0018 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
B00A - R0019 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00A/R0019/Ceiling Structures/Linings/S28					**Chrysotile (white asbestos)**
B00A - R0020 - Stairs						
No Asbestos						
B00A - R0021 - Stairs						
No Asbestos						
B00A - R0022 - External Movement						
No Asbestos						
B00A - R0023 - Staff Toilet						
No Asbestos						
B00A - R1001 - Movement						
No Asbestos						
B00A - R1002 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00A/R1011/Ceiling Structures/Linings/S29					**Chrysotile (white asbestos)**
B00A - R1003 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00A/R1011/Ceiling Structures/Linings/S29					**Chrysotile (white asbestos)**
B00A - R1005 - Staff Room Annexe						
Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00A/R1011/Ceiling Structures/Linings/S29					**Chrysotile (white asbestos)**
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	2005/B00A/R0008/Floor Coverings Res/Textile/S18					**No Asbestos Detected**
Floor Coverings Res/Textile	Adhesive					
	2005/B00A/R0008/Floor Coverings Res/Textile/S19					**No Asbestos Detected**
B00A - R1006 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00A/R1011/Ceiling Structures/Linings/S29					**Chrysotile (white asbestos)**
B00A - R1010 - Stairs						
No Asbestos						
B00A - R1011 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00A/R1011/Ceiling Structures/Linings/S29					**Chrysotile (white asbestos)**
B00A - R1012 - Practical Activities - 1hb						
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00A/R1011/Ceiling Structures/Linings/S29					**Chrysotile (white asbestos)**
B00A - R1013 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00A/R1011/Ceiling Structures/Linings/S29					**Chrysotile (white asbestos)**
B00A - R1014 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00A/R1011/Ceiling Structures/Linings/S29					**Chrysotile (white asbestos)**
B00A - R1015 - Toilet - Lobby						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Floor Coverings Res/Textile	Adhesive					
	2005/B00A/R1016/Floor Coverings Res/Textile/S22					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles					
	2005/B00A/R1016/Floor Coverings Res/Textile/S21					**No Asbestos Detected**
Wall Linings Internal	Flat AC Sheeting					
	2005/B00A/R1017/Wall Linings Internal/S20					**No Asbestos Detected**
B00A - R1016 - Staff Toilet						
Floor Coverings Res/Textile	Adhesive					
	2005/B00A/R1016/Floor Coverings Res/Textile/S22					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles					
	2005/B00A/R1016/Floor Coverings Res/Textile/S21					**No Asbestos Detected**
Wall Linings Internal	Flat AC Sheeting					
	2005/B00A/R1017/Wall Linings Internal/S20					**No Asbestos Detected**
B00A - R1017 - General Storeroom						
Wall Linings Internal	Flat AC Sheeting					
	2005/B00A/R1017/Wall Linings Internal/S20					**No Asbestos Detected**
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00A/R1011/Ceiling Structures/Linings/S29					**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - Administration/General Learning - 1891 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids	Non Accessible Area - Area inaccessible

Interior

B00B - R0001 - Home Base

No Asbestos

B00B - R0002 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	89m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00B/R0002/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)

B00B - R0004 - Cleaning Distributed Store

No Asbestos

B00B - R0005 - General Storeroom

No Asbestos

B00B - R0006 - Interview

Floor Coverings Res/Textile	Vinyl Sheet under carpet	
	2005/B00B/R0006/Floor Coverings Res/Textile/S23	**No Asbestos Detected**
Floor Coverings Res/Textile	Adhesive	
	2005/B00B/R0006/Floor Coverings Res/Textile/S24	**No Asbestos Detected**

B00B - R0009 - Staff Room

Floor Coverings Res/Textile	Adhesive	
	2005/B00B/R0006/Floor Coverings Res/Textile/S24	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Sheet under carpet	
	2005/B00B/R0006/Floor Coverings Res/Textile/S23	**No Asbestos Detected**

B00B - R0010 - Entry Vestibule

No Asbestos

B00B - R0011 - Deputy Principal

No Asbestos

B00B - R0012 - Principal

No Asbestos

B00B - R0013 - Movement

No Asbestos

B00B - R0014 - Clerical Office

No Asbestos

B00B - R0015 - Duplicating Workroom

Floor Coverings Res/Textile	Adhesive	
	2005/B00B/R0006/Floor Coverings Res/Textile/S24	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Sheet under carpet	
	2005/B00B/R0006/Floor Coverings Res/Textile/S23	**No Asbestos Detected**

B00B - R0016 - Clerical Office

Floor Coverings Res/Textile	Adhesive	
	2005/B00B/R0006/Floor Coverings Res/Textile/S24	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Sheet under carpet	
	2005/B00B/R0006/Floor Coverings Res/Textile/S23	**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00B - R0017 - Movement

Floor Coverings Res/Textile	Vinyl Sheet	
	2005/B00C/R0002/Floor Coverings Res/Textile/S6	**No Asbestos Detected**

B00B - R0018 - Home Base

No Asbestos

B00B - R0019 - Withdrawal Space - 2hb

No Asbestos

B00B - R0020 - Practical Activities - 2hb

No Asbestos

B00B - R0021 - Home Base Store

No Asbestos

B00B - R0022 - Home Base Store

No Asbestos

B00B - R0023 - Toilet - Lobby

No Asbestos

B00B - R0024 - Staff Toilet

No Asbestos

B00B - R0025 - Staff Toilet

No Asbestos

B00B - R0026 - Toilet - Lobby

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00C - Pupil Facilities/General Learning - 1950 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	No Asbestos Found					

Interior

B00C - R0001 - Drinking Facilities

No Asbestos

B00C - R0002 - Home Base

Floor Coverings Res/Textile	Vinyl Sheet					
	2005/B00C/R0002/Floor Coverings Res/Textile/S6					**No Asbestos Detected**

B00C - R0003 - External Movement

Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					

B00C - R0004 - Canteen

Floor Coverings Res/Textile	Vinyl Sheet					
	2005/B00C/R0002/Floor Coverings Res/Textile/S6					**No Asbestos Detected**

B00C - R0005 - Canteen Office/Store

No Asbestos

B00C - R0006 - External Movement

No Asbestos

B00C - R0007 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00D - General Learning/Communal Facilities - 1947 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 2005/B00D/Eaves Linings/S32					**No Asbestos Detected**
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting **Assumed Asbestos - Height Restriction**	30m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
Roof Sealant	Resinous Membrane **Assumed Asbestos - Height Restriction over plant room**	34m2	South	Minimal Damage (2)	Low (1)	Low Priority (2-3)

Interior

B00D - R0001 - Raised Platform

No Asbestos

B00D - R0002 - Communal Space

Decorative Coating To Wall	Vermiculite 2005/B00D/R0002/Decorative Coating/S12	**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 2005/B00D/R0002/Decorative Coating/S12	**No Asbestos Detected**

B00D - R0003 - External Movement

No Asbestos

B00D - R0004 - Staff Kitchen

No Asbestos

B00D - R0005 - Movement

No Asbestos

B00D - R0007 - Movement

No Asbestos

B00D - R0008 - Cleaning Distributed Store

No Asbestos

B00D - R0009 - External Movement

No Asbestos

B00D - R0010 - Movement

No Asbestos

B00D - R0011 - External Movement

No Asbestos

B00D - R0012 - Hall Chair Store

No Asbestos

B00D - R0013 - Staff Toilet

No Asbestos

B00D - R0014 - Staff Room Annexe

No Asbestos

B00D - R0015 - Uniform Shop

No Asbestos

B00D - R0016 - Movement

No Asbestos

B00D - R0017 - External Movement

No Asbestos

B00D - R0018 - Plant

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00D - R0019 - Plant						
Electrical Backing Board	Resinous Board	2Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					
B00D - R0020 - Plant						
No Asbestos						
B00D - R0021 - Interview						
No Asbestos						
B00D - R0022 - Staff Toilet						
No Asbestos						
B00D - R0023 - General Storeroom						
No Asbestos						
B00D - R0024 - General Storeroom						
No Asbestos						
B00D - R0025 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles					
	2005/B00D/R0025/Floor Coverings Res/Textile/S13					**No Asbestos Detected**
B00D - R0026 - Distribution Board						Note: No inspection of live electrical installation.
No Asbestos						
B00D - R0027 - External Movement						
No Asbestos						
B00D - R0028 - External Movement						
No Asbestos						
B00D - R0029 - External Movement						
No Asbestos						
B00D - R0030 - Movement						
No Asbestos						
B00D - R0031 - Home Base						
No Asbestos						
B00D - R0033 - Home Base						
No Asbestos						
B00D - R0034 - Home Base						
No Asbestos						
B00D - R0036 - Home Base						
No Asbestos						
B00D - R0037 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	110m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00D/R0037/Floor Coverings Res/Textile/S26					**Chrysotile (white asbestos)**
Floor Coverings Res/Textile	Adhesive					
	2005/B00D/R0037/Floor Coverings Res/Textile/S27					**No Asbestos Detected**
B00D - R0038 - Practical Activities - 1hb						
No Asbestos						
B00D - R0039 - Home Base Store						
No Asbestos						
B00D - R0040 - Withdrawal Space - 2hb						
No Asbestos						
B00D - R0041 - Home Base Store						
No Asbestos						
B00D - R0042 - Practical Activities - 1hb						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00D - R0043 - Practical Activities - 1hb						
No Asbestos						
B00D - R0044 - Home Base Store						
No Asbestos						
B00D - R0045 - Withdrawal Space - 2hb						
No Asbestos						
B00D - R0046 - Home Base Store						
No Asbestos						
B00D - R0047 - Practical Activities - 1hb						
No Asbestos						
B00D - R0048 - Stairs						
No Asbestos						
B00D - R0049 - Stairs						
No Asbestos						
B00D - R0050 - External Movement						
No Asbestos						
B00D - R1001 - Practical Activities - 1hb						
No Asbestos						
B00D - R1002 - Personal Effects Storage						
No Asbestos						
B00D - R1003 - Staff Room Annexe						
No Asbestos						
B00D - R1004 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles					
	2005/B00D/R0025/Floor Coverings Res/Textile/S13					**No Asbestos Detected**
B00D - R1005 - Home Base						
Floor Coverings Res/Textile	Adhesive					
	2005/B00D/R0037/Floor Coverings Res/Textile/S27					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00D/R0037/Floor Coverings Res/Textile/S26					**Chrysotile (white asbestos)**
B00D - R1007 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00D/R0037/Floor Coverings Res/Textile/S26					**Chrysotile (white asbestos)**
Floor Coverings Res/Textile	Adhesive					
	2005/B00D/R0037/Floor Coverings Res/Textile/S27					**No Asbestos Detected**
B00D - R1008 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00D/R0037/Floor Coverings Res/Textile/S26					**Chrysotile (white asbestos)**
Floor Coverings Res/Textile	Adhesive					
	2005/B00D/R0037/Floor Coverings Res/Textile/S27					**No Asbestos Detected**
B00D - R1010 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00D/R0037/Floor Coverings Res/Textile/S26					**Chrysotile (white asbestos)**
Floor Coverings Res/Textile	Adhesive					
	2005/B00D/R0037/Floor Coverings Res/Textile/S27					**No Asbestos Detected**
B00D - R1011 - Sick Bay						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
No Asbestos						
B00D - R1012 - Staff Toilet						
No Asbestos						
B00D - R1013 - Staff Toilet						
Partition Walls (Cubicles)	Flat AC Sheeting	4m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00D/R1013/Partition Walls (Cubicles)/S14					**Chrysotile (white asbestos)**
B00D - R1014 - Movement						
No Asbestos						
B00D - R1015 - Home Base - M						
No Asbestos						
B00D - R1016 - Practical Activities - M - 1hb						
No Asbestos						
B00D - R1017 - Movement						
No Asbestos						
B00D - R1018 - Stairs						
No Asbestos						
B00D - R1019 - Practical Activities - 1hb						
No Asbestos						
B00D - R1020 - Home Base Store						
No Asbestos						
B00D - R1021 - Withdrawal Space - 2hb						
No Asbestos						
B00D - R1022 - Practical Activities - 1hb						
No Asbestos						
B00D - R1023 - Home Base Store						
No Asbestos						
B00D - R1024 - Practical Activities - 1hb						
No Asbestos						
B00D - R1025 - Home Base Store						
No Asbestos						
B00D - R1026 - Withdrawal Space - 2hb						
No Asbestos						
B00D - R1027 - Home Base Store						
No Asbestos						
B00D - R1028 - Practical Activities - 1hb						
No Asbestos						
B00D - R1029 - Stairs						
No Asbestos						
B00D - R9001 - General Assistant/Bulk Store						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00E - Library/Tiered Learning - 1950 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

Interior

B00E - R0001 - Plant

No Asbestos

B00E - R0002 - Special Programs Store

No Asbestos

B00E - R0006 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	8m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00E/R0006/Electrical Mounting Board/S15					**Chrysotile (white asbestos)**

B00E - R0007 - Reading Area

Floor Coverings Res/Textile	Vinyl Tiles					
	2005/B00D/R0025/Floor Coverings Res/Textile/S13					**No Asbestos Detected**

B00E - R0008 - Seminar/Study

No Asbestos

B00E - R0009 - Communications Room

No Asbestos

B00E - R0010 - External Movement

No Asbestos

B00E - R0011 - Toilets-Disabled

No Asbestos

B00E - R0012 - Home Base

No Asbestos

B00E - R0013 - Laundry

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00F - Pupil Facilities - 1930 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	15m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00F/Eaves Linings/S17					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

Interior

B00F - R0001 - Plant

No Asbestos

B00F - R0002 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00F/R0006/Partition Walls (Cubicles)/S16					Chrysotile (white asbestos)

B00F - R0003 - Drinking Facilities

No Asbestos

B00F - R0004 - Plant

No Asbestos

B00F - R0005 - Drinking Facilities

No Asbestos

B00F - R0006 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00F/R0006/Partition Walls (Cubicles)/S16					Chrysotile (white asbestos)

B00F - R0007 - Cleaning Distributed Store

No Asbestos

B00F - R0008 - Movement

No Asbestos

B00F - R0009 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00G - Building Services - 1935 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

Interior

B00G - R0001 - General Assistant/Bulk Store

Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00G/R0001/Ceiling Structures/Linings/S2					**Chrysotile (white asbestos)**

B00G - R0002 - General Assistant/Bulk Store

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00G/R0001/Ceiling Structures/Linings/S2					**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00H - Communal Facilities - 1935 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Extreme Access Issue - No Access Point into ceiling void identified					
Wall Cladding	Flat AC Sheeting	30m2	North, South, East	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2005/B00H/Wall Cladding/S3				**Chrysotile (white asbestos)**	
Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction - Extreme Access Issue - No Access Point into ceiling void identified					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00H - R0001 - P.E. Store

Wall Linings Internal	Flat AC Sheeting	30m2	North, South, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00H/Wall Cladding/S3				**Chrysotile (white asbestos)**	

B00H - R0002 - P.E. Store

No Asbestos

B00H - R0003 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00I - Special Purpose/General Learning - 1950 - Timber (Timber)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids	No Asbestos Found

Interior

B00I - R0002 - Craft Store

No Asbestos

B00I - R0006 - Practical Activities - 1hb

No Asbestos

B00I - R0007 - Home Base

No Asbestos

B00I - R0008 - Home Base

No Asbestos

B00I - R0009 - Home Base Store

No Asbestos

B00I - R0010 - Practical Activities - 2hb

No Asbestos

B00I - R0011 - Withdrawal Space - 2hb

No Asbestos

B00I - R0012 - External Movement

No Asbestos

B00I - R0013 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00J - Administration/Building Services - 1935 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found	
Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction	
Underfloor Voids	Non Accessible Area - Area inaccessible	

Interior

B00J - R0001 - Cleaning Supplies

No Asbestos

B00J - R0002 - Garden Store

Wall Linings Internal	Flat AC Sheeting 2005/B00J/R0002/Wall Linings Internal/S25	**No Asbestos Detected**

B00J - R0003 - General Storeroom

In-fill-panel	Flat AC Sheeting 2005/B00J/R0002/Wall Linings Internal/S25	**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00K - Pupil Facilities/Staff Facilities - 1950 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00K/Eaves Linings/S4					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

Interior

B00K - R0002 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00K/R0002/Ceiling Structures/Linings/S5					**Chrysotile (white asbestos)**

B00K - R0003 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00K/R0002/Ceiling Structures/Linings/S5					**Chrysotile (white asbestos)**

B00K - R0004 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00K/R0002/Ceiling Structures/Linings/S5					**Chrysotile (white asbestos)**
Partition Walls (Cubicles)	Flat AC Sheeting	30m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00K/R0004/Partition Walls (Cubicles)/S11					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00K - R0005 - External Movement

No Asbestos

B00K - R0006 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00K/R0002/Ceiling Structures/Linings/S5					**Chrysotile (white asbestos)**
Partition Walls (Cubicles)	Flat AC Sheeting	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00K/R0004/Partition Walls (Cubicles)/S11					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00K - R0007 - Toilet - Lobby

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2005/B00K/R0002/Ceiling Structures/Linings/S5					**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00L - Building Services - 2011 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00L - R0001 - Garage/Carport

No Asbestos

B00L - R0002 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00M - Communal Facilities - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Extreme Access Issue - No Access Point into ceiling void identified
Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00M - R0001 - Communal Space

No Asbestos

B00M - R0002 - Raised Platform

No Asbestos

B00M - R0003 - Communal/Performance Store

No Asbestos

B00M - R0004 - P.E. Store

No Asbestos

B00M - R0005 - Hall Chair Store

No Asbestos

B00M - R0006 - Toilet - Lobby

No Asbestos

B00M - R0007 - Toilets - Girls

No Asbestos

B00M - R0008 - Sound Cupboard

No Asbestos

B00M - R0009 - Toilet - Lobby

No Asbestos

B00M - R0010 - Toilets - Boys

No Asbestos

B00M - R0011 - Cleaning Distributed Store

No Asbestos

B00M - R0012 - Plant

No Asbestos

B00M - R0013 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00M - R0014 - Access Shower/Toilet/Change

No Asbestos

B00M - R0015 - Covered Outdoor Learning Area

No Asbestos

B00M - R0016 - Movement

No Asbestos

B00M - R0017 - Ramp

No Asbestos

B00M - R0018 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017