Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Hurstville Grove Infants School (5195)**
Region :	**Sydney**
State Electorate :	**Oatley**
Local Government Area :	**Kogarah**

Initial Survey :	**Noel Arnold & Associates : 30 - Mar - 2008**
Register Issue Date :	**23 - Mar - 2017**

5195 - Hurstville Grove Infants School
Site Plan (12661)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - General Learning/Staff Facilities - 1952 - Steel (Steel)

Exterior

Wall Cladding	Flat AC Sheeting	12m2	East facing, Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	5195/B00E/Wall Cladding/S2					Chrysotile (white asbestos)
Wall Cladding	Flat AC Sheeting	6m2	North facing, South facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Eaves Linings	Flat AC Sheeting	14m2	North facing, South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00A - R0001 - Home Base Store

Wall Linings Internal	Flat AC Sheeting	6m2	North facing, South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	5195/B00E/R0001/Wall Linings Internal/S1					Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5195/B00E/R0001/Wall Linings Internal/S1					Chrysotile (white asbestos)

B00A - R0002 - Practical Activities - 1hb

Wall Linings Internal	Flat AC Sheeting	7m2	West facing, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	5195/B00E/R0001/Wall Linings Internal/S1					Chrysotile (white asbestos)

B00A - R0003 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	12m2	North facing, South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	5195/B00E/R0001/Wall Linings Internal/S1					Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5195/B00E/R0001/Wall Linings Internal/S1					Chrysotile (white asbestos)

B00A - R0004 - Home Base

No Asbestos

B00A - R0005 - Home Base

No Asbestos

B00A - R0006 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00B - Pupil Facilities - 1952 - Timber (Timber)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Drinking Facilities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00C - Pupil Facilities - 1952 - Brick/Veneer (Brick/Veneer)

Exterior

Wall Cladding	Flat AC Sheeting 5195/B00C/Wall Cladding/S3	**No Asbestos Detected**
Eaves Linings	Flat AC Sheeting 5195/B00C/R0002/Ceiling Structures/Linings/S5	**No Asbestos Detected**
Ceiling Voids	Requires Inspection	
Underfloor Voids	Requires Inspection	

Interior

B00C - R0002 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 5195/B00C/R0002/Ceiling Structures/Linings/S5	**No Asbestos Detected**

B00C - R0003 - Disabled Toilet

Ceiling Structures/Linings	Flat AC Sheeting 5195/B00C/R0003/Ceiling Structures/Linings/S4	**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00E - General Learning/Library - 1952 - Steel (Steel)

Exterior

Wall Cladding	Flat AC Sheeting	12m2	East facing, Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	5195/B00E/Wall Cladding/S2				Chrysotile (white asbestos)	
Wall Cladding	Flat AC Sheeting	6m2	North facing, South facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	5195/B00E/Wall Cladding/S2				Chrysotile (white asbestos)	
Wall Cladding	Flat AC Sheeting	6m2	North facing, South facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Eaves Linings	Flat AC Sheeting	14m2	North facing, South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00E - R0001 - Home Base Store

Wall Linings Internal	Flat AC Sheeting	12m2	North facing, South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	5195/B00E/R0001/Wall Linings Internal/S1				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5195/B00E/R0001/Wall Linings Internal/S1				Chrysotile (white asbestos)	

B00E - R0002 - Practical Activities - 1hb

Wall Linings Internal	Flat AC Sheeting	7m2	North facing, West facing, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	5195/B00E/R0001/Wall Linings Internal/S1				Chrysotile (white asbestos)	

B00E - R0003 - General Storeroom

Wall Linings Internal	Flat AC Sheeting	4m2	South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	5195/B00E/R0001/Wall Linings Internal/S1				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5195/B00E/R0001/Wall Linings Internal/S1				Chrysotile (white asbestos)	

B00E - R0004 - Reading Area

No Asbestos

B00E - R0005 - Home Base

No Asbestos

B00E - R0006 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00F - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - Communal Space

No Asbestos

B00F - R0002 - P.E. Store

No Asbestos

B00F - R0003 - Covered Outdoor Learning Area

No Asbestos

B00F - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00G - Pupil Facilities/Staff Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - External Movement

No Asbestos

B00G - R0002 - Toilets - Boys

No Asbestos

B00G - R0003 - Toilets - Girls

No Asbestos

B00G - R0004 - Staff Toilet

No Asbestos

B00G - R0005 - Staff Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 505 - D13634 - Admin Staff/Principal/Secure Store : Placement Date - 5/06/2001

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2

R2 - Principal

Ceiling	Flat AC Sheet	Assumed Asbestos	16 m2

R3 - Staff Room

Ceiling	Flat AC Sheet	Assumed Asbestos	20 m2

R4 - Security Store

Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R5 - Clerical Office

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	18 m2

OS 601 - D70084 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/2003

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017