Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Hunter River High School (8219)**
Region :	**Hunter/Central Coast**
State Electorate :	**Port Stephens**
Local Government Area :	**Port Stephens**

Initial Survey :	**Noel Arnold & Associates : 27 - May - 2008**
Reviewed By :	**Greencap-NAA : 10 - Feb - 2015**

8219 - Hunter River High School
Site Plan (11236)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00A - Administration - 1956 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting 8219/B00A/Eaves Linings/S8	**No Asbestos Detected**
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	

Interior

B00A - R0001 - Leading Teacher

No Asbestos

B00A - R0002 - Administration - Clerical

No Asbestos

B00A - R0004 - Staff - Toilet

Ceiling Structures/Linings	Flat AC Sheeting 8219/B00A/R0004/Ceiling Structures/Linings/S10	**No Asbestos Detected**

B00A - R0006 - Administration - Clerical

No Asbestos

B00A - R0007 - Interview/Office - Type 1

No Asbestos

B00A - R0008 - Leading Teacher

No Asbestos

B00A - R0009 - Deputy Principal Office

No Asbestos

B00A - R0010 - Staff - Toilet

No Asbestos

B00A - R0011 - Clinic-Toilets

No Asbestos

B00A - R0012 - Clinic - Boys

No Asbestos

B00A - R0013 - General Storeroom

No Asbestos

B00A - R0014 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)

Assumed Asbestos - Electrical Hazard

B00A - R0015 - Staff - Toilet

Wall Linings Internal	Flat AC Sheeting 8219/B00A/R0015/Wall Linings Internal/S6	**No Asbestos Detected**
Ceiling Structures/Linings	Flat AC Sheeting 8219/B00A/R0004/Ceiling Structures/Linings/S10	**No Asbestos Detected**

B00A - R0016 - Cleaning Store - Distributed

No Asbestos

B00A - R0017 - Duplicating Workroom

Wall Linings Internal	Flat AC Sheeting 8219/B00A/R0017/Wall Linings Internal/S7	**No Asbestos Detected**
Ceiling Structures/Linings	Flat AC Sheeting 8219/B00A/R0004/Ceiling Structures/Linings/S10	**No Asbestos Detected**

B00A - R0018 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 8219/B00A/R0004/Ceiling Structures/Linings/S10	**No Asbestos Detected**

B00A - R0019 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 8219/B00A/R0004/Ceiling Structures/Linings/S10	**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

B00A - R0021 - Principal Office

No Asbestos

B00A - R0022 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - General Learning - 1956 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	15m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/Eaves Linings/S11					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00B - R0004 - Interview/Office - Type 1

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	2m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0007/Floor Coverings Res/Textile/S27					Chrysotile (white asbestos)

B00B - R0005 - General Learning Space

Ceiling Structures/Linings	Flat AC Sheeting	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00B - R0006 - General Learning Space

Ceiling Structures/Linings	Flat AC Sheeting	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00B - R0007 - Office/Store

Floor Coverings Res/Textile	Vinyl Sheet	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0007/Floor Coverings Res/Textile/S27					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	8219/B00B/R0007/Floor Coverings Res/Textile/S28					**No Asbestos Detected**

B00B - R0008 - Cleaning Store - Distributed

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00B - R0009 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00B - R0010 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	85m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00B - R0014 - Interview/Office - Type 1

Ceiling Structures/Linings	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00B - R0015 - General Learning Space

Ceiling Structures/Linings	Flat AC Sheeting	55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00B - R0016 - Store						
Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00B - R0017 - Staff Study						
Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00C - Technological & Applied Studies - 1956 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Electrical Backing Board	Resinous Board	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00C - R0001 - Secure Storeroom

No Asbestos

B00C - R0002 - Materials Store

No Asbestos

B00C - R0003 - Materials Store

No Asbestos

B00C - R0006 - Pantry

No Asbestos

B00C - R0007 - Food/Research Space

No Asbestos

B00C - R0008 - Food Technology L.S.

No Asbestos

B00C - R0009 - Laundry

No Asbestos

B00C - R0010 - Materials Store

No Asbestos

B00C - R0011 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	90m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00C - R0012 - Staff Study

No Asbestos

B00C - R0013 - General Learning Space - Type 1

No Asbestos

B00C - R0014 - Movement

No Asbestos

B00C - Room+1 - Added Room

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00D - Technological & Applied Studies - 1956 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/Eaves Linings/S11					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00D - R0001 - Design L.S.

No Asbestos

B00D - R0002 - Materials Technology L.S.

No Asbestos

B00D - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00N/R0001/Ceiling Structures/Linings/S19					**Chrysotile (white asbestos)**

B00D - R0010 - Computer Room

No Asbestos

B00D - R0011 - Store

No Asbestos

B00D - R0012 - Design L.S.

No Asbestos

B00D - R0013 - Wood Technology Bay

No Asbestos

B00D - R0014 - Project Store - Type 1

No Asbestos

B00D - R0015 - Materials Store

No Asbestos

B00D - R0016 - Materials Store

No Asbestos

B00D - R0017 - Dust Extraction Space

No Asbestos

B00D - R0018 - Covered Outdoor Space

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00E - Technological & Applied Studies - 1956 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/Eaves Linings/S11				**Chrysotile (white asbestos) , Amosite (brown asbestos)**	
Electrical Backing Board	Resinous Board	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00E - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12				**Chrysotile (white asbestos) , Amosite (brown asbestos)**	

B00E - R0002 - Commonroom

No Asbestos

B00E - R0003 - Cleaning Store - Distributed

No Asbestos

B00E - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12				**Chrysotile (white asbestos) , Amosite (brown asbestos)**	

B00E - R0005 - Staff - Toilet

No Asbestos

B00E - R0006 - Staff - Toilet

No Asbestos

B00E - R0007 - Staff Study

No Asbestos

B00E - R0008 - Materials Technology L.S.

No Asbestos

B00E - R0009 - Materials Store

No Asbestos

B00E - R0010 - Resource/Project Store

No Asbestos

B00E - R0011 - Staff Study

No Asbestos

B00E - R0012 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12				**Chrysotile (white asbestos) , Amosite (brown asbestos)**	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00F - General Learning - 1956 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/Eaves Linings/S11				**Chrysotile (white asbestos) , Amosite (brown asbestos)**	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00F - R0001 - General Learning Space

No Asbestos

B00F - R0002 - General Learning Space

No Asbestos

B00F - R0003 - Movement

Infil panel	Flat AC Sheeting	
	8219/B00F/R0011/Infil panel/S29	**No Asbestos Detected**

B00F - R0005 - General Learning Space

No Asbestos

B00F - R0009 - Administration - Clerical

No Asbestos

B00F - R0010 - Security Store

No Asbestos

B00F - R0011 - Staff - Toilet

Infil panel	Flat AC Sheeting	
	8219/B00F/R0011/Infil panel/S29	**No Asbestos Detected**

B00F - R0012 - Deputy Principal Office

No Asbestos

B00F - R0013 - Interview/Office - Type 1

No Asbestos

B00F - R0014 - Interview/Office - Type 1

No Asbestos

B00F - R0015 - Interview/Office - Type 1

No Asbestos

B00F - R0016 - Pupil Entry

Infil panel	Flat AC Sheeting	
	8219/B00F/R0011/Infil panel/S29	**No Asbestos Detected**

B00F - R0017 - Movement

No Asbestos

B00F - Room+1 - Added Room

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/Eaves Linings/S11				**Chrysotile (white asbestos) , Amosite (brown asbestos)**	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00G - Various - 1969 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	50m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8219/B00B/Eaves Linings/S11					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00G - R0001 - Cleaning Store - Distributed

No Asbestos

B00G - R0002 - Resources Store

No Asbestos

B00G - R0003 - Resources Store

Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00I/R0004/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)

B00G - R0004 - Art Learning Space

Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					No Asbestos Detected
Ceiling Structures/Linings	Vermiculite					
	8219/B00I/R0002/Ceiling Structures/Linings/S1					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles	61m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00I/R0004/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)

B00G - R0005 - Art Learning Space

Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					No Asbestos Detected
Ceiling Structures/Linings	Vermiculite					
	8219/B00I/R0002/Ceiling Structures/Linings/S1					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00I/R0004/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)

B00G - R0006 - Resources Store

Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00I/R0004/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00G/R1013/Ceiling Structures/Linings/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00G - R0007 - Kiln Space

Ceiling Structures/Linings	Vermiculite					
	8219/B00I/R0002/Ceiling Structures/Linings/S1					No Asbestos Detected

B00G - R0008 - Laboratory L.S.

No Asbestos

B00G - R0009 - Apparatus Store

Ceiling Structures/Linings	Vermiculite					
	8219/B00I/R0002/Ceiling Structures/Linings/S1					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00I/R0004/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)

B00G - R0010 - Preparation

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Window Sill	Compressed AC Sheet 8219/B00I/R0003/Window Sill/S3					**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 8219/B00I/R0004/Floor Coverings Res/Textile/S2	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) **Chrysotile (white asbestos)**
B00G - R0011 - Cleaning Store - Distributed						
No Asbestos						
B00G - R0012 - External Movement						
No Asbestos						
B00G - R0013 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
Electrical Backing Board	Resinous Board **Assumed Asbestos - Electrical Hazard**	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
Wall Linings Internal	Flat AC Sheeting 8219/B00G/R0013/Wall Linings Internal/S30	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) **Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
B00G - R0014 - Stairs						
No Asbestos						
B00G - R0015 - Stairs						
No Asbestos						
B00G - R1001 - Cleaning Store - Distributed						
Ceiling Structures/Linings	Flat AC Sheeting 8219/B00G/R1013/Ceiling Structures/Linings/S15	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) **Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00G - R1002 - Staff Study						
Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1					**No Asbestos Detected**
Window Sill	Compressed AC Sheet 8219/B00I/R0003/Window Sill/S3					**No Asbestos Detected**
B00G - R1003 - General Learning Space						
Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1					**No Asbestos Detected**
Window Sill	Compressed AC Sheet 8219/B00I/R0003/Window Sill/S3					**No Asbestos Detected**
B00G - R1004 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
Electrical Backing Board	Resinous Board **Assumed Asbestos - Electrical Hazard**	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
B00G - R1005 - General Storeroom						
Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00G - R1006 - General Storeroom						
Window Sill	Compressed AC Sheet 8219/B00I/R0003/Window Sill/S3					**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00G - R1007 - General Learning Space						
Window Sill	Compressed AC Sheet 8219/B00I/R0003/Window Sill/S3					**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00G - R1008 - General Learning Space						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Window Sill	Compressed AC Sheet 8219/B00I/R0003/Window Sill/S3					**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00G - R1009 - General Storeroom						
Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00G - R1010 - General Storeroom						
Window Sill	Compressed AC Sheet 8219/B00I/R0003/Window Sill/S3					**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00G - R1011 - General Learning Space						
Window Sill	Compressed AC Sheet 8219/B00I/R0003/Window Sill/S3					**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00G - R1012 - Cleaning Store - Distributed						
No Asbestos						
B00G - R1013 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting 8219/B00G/R1013/Ceiling Structures/Linings/S15	97m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) **Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00G - R1014 - Stairs						
No Asbestos						
B00G - R1015 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00H - Various - 1969 - Brick/Block (Brick/Block)

Exterior

In-fill-panel	Flat AC Sheeting	30m2	South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00H/In-fill-panel/S16					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00H - R0001 - Garden Store Room

No Asbestos

B00H - R0002 - Laboratory L.S.

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**
Window Sill	Compressed AC Sheet	
	8219/B00I/R0003/Window Sill/S3	**No Asbestos Detected**

B00H - R0006 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0008 - Staff Study

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**
Window Sill	Compressed AC Sheet	
	8219/B00I/R0003/Window Sill/S3	**No Asbestos Detected**

B00H - R0009 - Cleaning Store - Distributed

No Asbestos

B00H - R0010 - Main Switchroom

No Asbestos

B00H - R0011 - External Movement

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00H - R0012 - Stairs

No Asbestos

B00H - R0013 - Stairs

No Asbestos

B00H - R0014 - Food/Research Space

No Asbestos

B00H - R0015 - Food Technology L.S.

No Asbestos

B00H - R0016 - Preparation - Materials

No Asbestos

B00H - R0017 - Pantry

No Asbestos

B00H - R0018 - Laundry

No Asbestos

B00H - R1001 - Music Store

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00G/R1013/Ceiling Structures/Linings/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00H - R1002 - Staff - Toilet

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00G/R1013/Ceiling Structures/Linings/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00H - R1003 - General Storeroom						
No Asbestos						
B00H - R1007 - Computer Learning Space						
Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					No Asbestos Detected
B00H - R1008 - Computer Learning Space						
Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					No Asbestos Detected
B00H - R1009 - Computer Store						
Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					No Asbestos Detected
B00H - R1010 - Computer Resource						
Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					No Asbestos Detected
B00H - R1011 - General Learning Space						
Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					No Asbestos Detected
B00H - R1012 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					
B00H - R1013 - General Storeroom						
No Asbestos						
B00H - R1014 - General Storeroom						
Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					No Asbestos Detected
B00H - R1015 - General Learning Space						
Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					No Asbestos Detected
B00H - R1016 - General Storeroom						
Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					No Asbestos Detected
B00H - R1017 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting	92m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00G/R1013/Ceiling Structures/Linings/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00H - R1018 - Staff Study						
Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					No Asbestos Detected
B00H - R1019 - Stairs						
No Asbestos						
B00H - R1020 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00I - Various - 1969 - Brick/Block (Brick/Block)

Exterior

In-fill-panel	Flat AC Sheeting	30m2	South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00H/In-fill-panel/S16					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00I - R0001 - Cleaning Store - Distributed

No Asbestos

B00I - R0002 - General Storeroom

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00I - R0003 - General Learning Space

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**
Window Sill	Compressed AC Sheet	
	8219/B00I/R0003/Window Sill/S3	**No Asbestos Detected**

B00I - R0004 - General Learning Space

Floor Coverings Res/Textile	Vinyl Tiles	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00I/R0004/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite					
	8219/B00I/R0002/Ceiling Structures/Linings/S1					**No Asbestos Detected**

B00I - R0005 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					

B00I - R0006 - General Storeroom

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00I - R0007 - General Storeroom

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00I - R0008 - General Learning Space

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00I - R0009 - Art Learning Space

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00I - R0010 - General Learning Space

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00I - R0011 - Cleaning Store - Distributed

No Asbestos

B00I - R0012 - Staff - Toilet

No Asbestos

B00I - R0013 - Staff Change

No Asbestos

B00I - R0014 - External Movement

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00I - R0015 - Stairs

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
No Asbestos						
B00I - R0016 - Stairs						
No Asbestos						
B00I - R1001 - Music Store						
No Asbestos						
B00I - R1002 - Music Learning Space						
Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					**No Asbestos Detected**
B00I - R1003 - General Learning Space						
Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					**No Asbestos Detected**
B00I - R1004 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
Electrical Backing Board	Resinous Board	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					
B00I - R1005 - General Storeroom						
Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Sheet					
	8219/B00I/R1005/Floor Coverings Res/Textile/S32					**No Asbestos Detected**
Floor Coverings Res/Textile	Backing					
	8219/B00I/R1005/Floor Coverings Res/Textile/S33					**No Asbestos Detected**
Infil panel	Flat AC Sheeting	2m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00P/In-fill-panel/S21					**Chrysotile (white asbestos)**
B00I - R1006 - General Learning Space						
No Asbestos						
B00I - R1007 - General Learning Space						
No Asbestos						
B00I - R1008 - Staff Study						
No Asbestos						
B00I - R1009 - Staff - Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00G/R1013/Ceiling Structures/Linings/S15					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00I - R1010 - Staff Change						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00G/R1013/Ceiling Structures/Linings/S15					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00I - R1011 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting	98m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00G/R1013/Ceiling Structures/Linings/S15					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00I - R1012 - Stairs						
No Asbestos						
B00I - R1013 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00J - Various - 1969 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	

Interior

B00J - R0001 - General Learning Space

Window Sill	Compressed AC Sheet 8219/B00I/R0003/Window Sill/S3	**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00J - R0002 - General Storeroom

Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**
Window Sill	Compressed AC Sheet 8219/B00I/R0003/Window Sill/S3	**No Asbestos Detected**

B00J - R0003 - General Storeroom

Window Sill	Compressed AC Sheet 8219/B00I/R0003/Window Sill/S3	**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00J - R0004 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board **Assumed Asbestos - Electrical Hazard**	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)

B00J - R0005 - General Learning Space

Window Sill	Compressed AC Sheet 8219/B00I/R0003/Window Sill/S3	**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00J - R0006 - Staff Study

Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**
Window Sill	Compressed AC Sheet 8219/B00I/R0003/Window Sill/S3	**No Asbestos Detected**

B00J - R0007 - Staff - Toilet

Window Sill	Compressed AC Sheet 8219/B00I/R0003/Window Sill/S3	**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

Partition Walls (Cubicles)	Compressed AC Sheet 8219/B00O/R1003/Partition Walls (Cubicles)/S22	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3) **Chrysotile (white asbestos)**

B00J - R0008 - Staff - Toilet

Window Sill	Compressed AC Sheet 8219/B00I/R0003/Window Sill/S3	**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

Partition Walls (Cubicles)	Compressed AC Sheet 8219/B00O/R1003/Ceiling Structures/Linings/S23	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3) **Chrysotile (white asbestos)**

B00J - R0009 - General Storeroom

Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					**No Asbestos Detected**
B00J - R0010 - Cleaning Supplies Store						
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00I/R0004/Floor Coverings Res/Textile/S2					**Chrysotile (white asbestos)**
Ceiling Structures/Linings	Vermiculite					
	8219/B00I/R0002/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00J - R0011 - External Movement						
Ceiling Structures/Linings	Vermiculite					
	8219/B00I/R0002/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00J - R1001 - Seminar						
Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					**No Asbestos Detected**
B00J - R1004 - Performing Arts Store						
No Asbestos						
B00J - R1005 - Performance Workspace						
In-fill-panel	Flat AC Sheeting					
	8219/B00J/R1005/In-fill-panel/S4					**No Asbestos Detected**
Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					**No Asbestos Detected**
B00J - R1008 - Staff Study						
Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					**No Asbestos Detected**
B00J - R1009 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
	8219/B00I/R0002/Ceiling Structures/Linings/S1					**No Asbestos Detected**
In-fill-panel	Flat AC Sheeting					
	8219/B00J/R1005/In-fill-panel/S4					**No Asbestos Detected**
B00J - R1010 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
Electrical Backing Board	Resinous Board	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					
B00J - R1011 - General Storeroom						
No Asbestos						
B00J - R1012 - Plant						
Window Sill	Compressed AC Sheet					
	8219/B00I/R0003/Window Sill/S3					**No Asbestos Detected**
B00J - R1013 - Performance Workshop						
Infil panel	Flat AC Sheeting					
	8219/B00J/R1005/In-fill-panel/S4					**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00K - Library/Science Learning - 1970 - Brick/Block (Brick/Block)

Exterior

Gable Verge Lining	Flat AC Sheeting 8219/B00A/Eaves Linings/S8	**No Asbestos Detected**
Eaves Linings	Flat AC Sheeting 8219/B00A/Eaves Linings/S8	**No Asbestos Detected**
Ceiling Voids - Flat Roof	No Asbestos Found	
Underfloor Voids	No Asbestos Found	

Interior

B00K - M1001 - General Storeroom

No Asbestos

B00K - M1002 - Plant

No Asbestos

B00K - M1005 - System Administrators Office

No Asbestos

B00K - M1006 - System Administrators Office

No Asbestos

B00K - M1007 - Garden Store Room

No Asbestos

B00K - M1008 - Computer Learning Space

No Asbestos

B00K - R0001 - Laboratory L.S.

No Asbestos

B00K - R0002 - External Movement

No Asbestos

B00K - R0003 - Movement

Floor Coverings Res/Textile	Vinyl Tiles 8219/B00K/R0007/Floor Coverings Res/Textile/S5	**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00K - R0004 - Laboratory L.S.

No Asbestos

B00K - R0005 - Preparation

No Asbestos

B00K - R0006 - Laboratory L.S.

No Asbestos

B00K - R0007 - Apparatus Store

Floor Coverings Res/Textile	Vinyl Tiles 8219/B00K/R0007/Floor Coverings Res/Textile/S5	**No Asbestos Detected**

B00K - R0008 - Main Switchroom

Electrical Backing Board	Resinous Board **Assumed Asbestos - Electrical Hazard**	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)

B00K - R0009 - Laboratory L.S.

No Asbestos

B00K - R0010 - Preparation

Floor Coverings Res/Textile	Vinyl Tiles 8219/B00K/R0007/Floor Coverings Res/Textile/S5	**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00K - R0011 - Distribution Board Cupboard Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)

Assumed Asbestos - Electrical Hazard

B00K - R0012 - General Storeroom

No Asbestos

B00K - R0013 - External Stairs

No Asbestos

B00K - R1001 - Movement

No Asbestos

B00K - R1002 - Staff - Toilet

No Asbestos

B00K - R1003 - Staff Change

No Asbestos

B00K - R1004 - Main Area

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00K - R1005 - Seminar

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00K - R1006 - Seminar

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00K - R1007 - Distribution Board Cupboard Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	2Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)

Assumed Asbestos - Electrical Hazard

B00K - R1008 - Cleaning Store - Distributed

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00K - R1009 - Seminar

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00K - R1010 - Seminar

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00K - R1011 - Audio Visual Workroom

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00K - R1012 - Librarian

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00K - R1013 - Workroom

Ceiling Structures/Linings	Vermiculite	
	8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00K - R1014 - Staff Change

No Asbestos

B00K - R1015 - Staff - Toilet

No Asbestos

B00K - R1016 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00L - Pupil Facilities - 1956 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found	
Underfloor Voids	No Asbestos Found	

Interior

B00L - R0001 - External Movement

No Asbestos

B00L - R0002 - Student Drinking Facilities

No Asbestos

B00L - R0003 - External Movement

No Asbestos

B00L - R0004 - Student Drinking Facilities

No Asbestos

B00L - R0005 - Toilets-Boys

Ceiling Structures/Linings	Flat AC Sheeting 8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**
Partition Walls (Cubicles)	Compressed AC Sheet 8219/B00L/R0005/Partition Walls (Cubicles)/S20	**No Asbestos Detected**

B00L - R0006 - Plant

No Asbestos

B00L - R0007 - Toilets-Girls

Ceiling Structures/Linings	Flat AC Sheeting 8219/B00I/R0002/Ceiling Structures/Linings/S1	**No Asbestos Detected**
Partition Walls (Cubicles)	Compressed AC Sheet 8219/B00L/R0005/Partition Walls (Cubicles)/S20	**No Asbestos Detected**

B00L - R0008 - Plant

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00M - Various - 1956 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/Eaves Linings/S11					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00M - R0001 - General Learning Space

Ceiling Structures/Linings	Flat AC Sheeting	47m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00M - R0002 - General Learning Space

Ceiling Structures/Linings	Flat AC Sheeting	55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00M - R0003 - Darkroom Space

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00M - R0004 - No Access

Ceiling Structures/Linings	Flat AC Sheeting	55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00M - R0005 - Performing Arts Store

Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00M - R0006 - Performance Workspace

Ceiling Structures/Linings	Flat AC Sheeting	90m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00M - R0007 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	88m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00N - Agricultural Science - 1956 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00N - R0001 - Office/Store

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00N/R0001/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8219/B00N/R0001/Wall Linings Internal/S34					Chrysotile (white asbestos)

B00N - R0002 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00N/R0001/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)

B00N - R0003 - Class Tools Storage

Wall Linings Internal	Flat AC Sheeting	30m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8219/B00N/R0001/Wall Linings Internal/S34					Chrysotile (white asbestos)

B00N - R0004 - Machine Storage

Wall Linings Internal	Flat AC Sheeting	12m2	West	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8219/B00N/R0001/Wall Linings Internal/S34					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00O - Pupil Facilities - 1969 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00O - R0001 - Cleaning Store - Distributed

No Asbestos

B00O - R0002 - Sport Equipment Store

No Asbestos

B00O - R0003 - Garden Store Room

No Asbestos

B00O - R0004 - Staff - Toilet

No Asbestos

B00O - R0005 - Pantry

No Asbestos

B00O - R0006 - Student Canteen

No Asbestos

B00O - R0007 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	2Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					

B00O - R0008 - General Storeroom

No Asbestos

B00O - R0009 - Cleaning Store - Distributed

No Asbestos

B00O - R0010 - Movement

No Asbestos

B00O - R0011 - External Movement

No Asbestos

B00O - R0012 - Stairs

No Asbestos

B00O - R0013 - Stairs

No Asbestos

B00O - R1001 - Movement

No Asbestos

B00O - R1002 - Plant

Toilet Cistern	Fibre Cement Casting (Monocrete)	10Unit(s)	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00O/R1003/Partition Walls (Cubicles)/S22				**Chrysotile (white asbestos)**	

B00O - R1003 - Toilets-Girls

Ceiling Structures/Linings	Flat AC Sheeting	61m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00O/R1003/Ceiling Structures/Linings/S23				**Chrysotile (white asbestos)**	
Partition Walls (Cubicles)	Compressed AC Sheet	20m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00O/R1003/Ceiling Structures/Linings/S23				**Chrysotile (white asbestos)**	

B00O - R1004 - Plant

No Asbestos

B00O - R1005 - Toilets-Boys

Ceiling Structures/Linings	Flat AC Sheeting	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00O/R1003/Ceiling Structures/Linings/S23				**Chrysotile (white asbestos)**	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Partition Walls (Cubicles)	Compressed AC Sheet	20m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00O/R1003/Partition Walls (Cubicles)/S22					**Chrysotile (white asbestos)**

B00O - R1006 - Movement

No Asbestos

B00O - R1007 - Stairs

No Asbestos

B00O - R1008 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00P - Various - 1984 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/Eaves Linings/S11					Chrysotile (white asbestos) , Amosite (brown asbestos)
In-fill-panel	Flat AC Sheeting	50m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00P/In-fill-panel/S21					Chrysotile (white asbestos)
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00P - R0001 - Staff Shower

No Asbestos

B00P - R0002 - Staff - Toilet

No Asbestos

B00P - R0003 - Staff Change

No Asbestos

B00P - R0005 - Plant

No Asbestos

B00P - R0010 - Materials Technology L.S.

No Asbestos

B00P - R0011 - T.A.S. Outdoor Area

Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00O/R1003/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)

B00P - R0014 - Welding Area

No Asbestos

B00P - R0015 - Materials Store

No Asbestos

B00P - R0016 - Project Store - Type 1

No Asbestos

B00P - R0017 - Welding Area

No Asbestos

B00P - R0018 - Materials Store

No Asbestos

B00P - R0019 - Materials Store

No Asbestos

B00P - R0020 - Workshop Area

No Asbestos

B00P - R0021 - Workshop

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00Q - Pupil Facilities - 1969 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	15m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00O/R1003/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00Q - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00O/R1003/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)

B00Q - R0002 - Shower/Change

Ceiling Structures/Linings	Flat AC Sheeting	43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00O/R1003/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00O/R1003/Partition Walls (Cubicles)/S22					Chrysotile (white asbestos)

B00Q - R0003 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00O/R1003/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)

B00Q - R0004 - No Access

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00O/R1003/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Sheet	4m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8219/B00Q/R0004/Floor Coverings Res/Textile/S25					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	8219/B00Q/R0004/Floor Coverings Res/Textile/S26					No Asbestos Detected

B00Q - R0005 - No Access

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00O/R1003/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)

B00Q - R0006 - Sport Equipment Store

No Asbestos

B00Q - R0007 - Plant

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00O/R1003/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8219/B00Q/R0004/Floor Coverings Res/Textile/S25					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	8219/B00Q/R0004/Floor Coverings Res/Textile/S26					No Asbestos Detected

B00Q - R0008 - Shower/Change

Ceiling Structures/Linings	Flat AC Sheeting	42m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00O/R1003/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00O/R1003/Partition Walls (Cubicles)/S22					Chrysotile (white asbestos)

B00Q - R0009 - External Movement

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00O/R1003/Ceiling Structures/Linings/S23					**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00R - Multi Purpose Facilities - 1971 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting					
	8219/B00A/Eaves Linings/S8					**No Asbestos Detected**
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00R - M0001 - Control Room

No Asbestos

B00R - M0002 - Staff - Toilet

No Asbestos

B00R - M0003 - Staff - Toilet

No Asbestos

B00R - M0004 - Control Room

Electrical Backing Board	Resinous Board	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					

B00R - R0001 - External Movement

No Asbestos

B00R - R0002 - Movement

No Asbestos

B00R - R0003 - Movement

No Asbestos

B00R - R0004 - Stage

No Asbestos

B00R - R0005 - Movement

No Asbestos

B00R - R0006 - Movement

No Asbestos

B00R - R0007 - External Movement

No Asbestos

B00R - R0008 - Multi-Purpose Space

No Asbestos

B00R - R0009 - External Movement

No Asbestos

B00R - R0010 - Staff - Toilet

No Asbestos

B00R - R0011 - Cleaning Store - Distributed

No Asbestos

B00R - R0012 - Staff - Toilet

No Asbestos

B00R - R0013 - Entry

Electrical Backing Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					

B00R - R0014 - External Movement

No Asbestos

B00R - R0015 - Staff Kitchen

Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00R/R0015/Floor Coverings Res/Textile/S24					**Chrysotile (white asbestos)**

B00R - R0016 - External Movement

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

No Asbestos

B00R - R9001 - Movement

No Asbestos

B00R - R9002 - General Storeroom

No Asbestos

B00R - R9003 - Performing Arts Changeroom

No Asbestos

B00R - R9004 - Performing Arts Changeroom

No Asbestos

B00R - R9005 - General Storeroom

No Asbestos

B00R - R9006 - Movement

No Asbestos

B00R - R9007 - Performing Arts Chair Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00S - Agricultural Science - 1956 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00S - R0001 - Garden Store Room

No Asbestos

B00S - R0002 - Class Tools Storage

No Asbestos

B00S - R0003 - Machine Storage

No Asbestos

B00S - R0004 - Materials Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00T - Technological & Applied Studies - 2006 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00T - R0001 - Kiln Space

Kiln outer shell	Encapsulated Insulation material within unit	
	8219/B00T/R0001/Kiln outer shell/S31	**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00U - Technological & Applied Studies - 2009 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00U - R0001 - Entry

No Asbestos

B00U - R0002 - Store

No Asbestos

B00U - R0003 - Toilets-Disabled

No Asbestos

B00U - R0004 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B00U - R0005 - Materials Technology L.S.

No Asbestos

B00U - R0006 - Store

No Asbestos

B00U - R0007 - Teachers Aides

No Asbestos

B00U - R0008 - Workshop Area

No Asbestos

B00U - R0009 - External Movement

No Asbestos

B00U - R0010 - Outdoor Workshop

No Asbestos

B00U - R0011 - Plant

No Asbestos

B00U - R0012 - Plant

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00V - Other - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00V - R0001 - Movement

No Asbestos

B00V - R0002 - Lift

No Asbestos

B00V - R1001 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Build+1 - Added Building

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

Build+1 - Room+1 - Added Room

Ceiling Structures/Linings	Flat AC Sheeting	100m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8219/B00B/R0011/Ceiling Structures/Linings/S12					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 711 - D10619 - Home Science/Art/Science Dem/Computer : Placement Date - 20/03/2002

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	14.4 m2

Interior

R1 - Computer Room

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	

R2 - Food Technology L.S.

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	73 m2

R3 - Storeroom

Ceiling	Flat AC Sheet	Assumed Asbestos	

OS 837 - D14954 - Hcap Shower/Change/Toilet : Placement Date - 10/02/2012

Exterior

No Asbestos Found.

Interior

R1 - Disabled Shower/Toilet

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017