Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Kanwal Public School (2259)**
Region :	**Hunter/Central Coast**
State Electorate :	**Wyong**
Local Government Area :	**Wyong**

Initial Survey :	**Noel Arnold & Associates : 29 - Mar - 2008**
Reviewed By :	**Greencap-NAA : 20 - Mar - 2015**

2259 - Kanwal Public School
Site Plan (11657)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00A - Administration - 1965 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	

Interior

B00A - R0001 - Staff Toilet

Ceiling Structures/Linings	Vermiculite 2259/B00A/R0001/Ceiling Structures/Linings/S23	**No Asbestos Detected**

B00A - R0002 - Staff Toilet

Ceiling Structures/Linings	Vermiculite 2259/B00A/R0001/Ceiling Structures/Linings/S23	**No Asbestos Detected**

B00A - R0003 - Entry Vestibule

Panels Under Windows	Flat AC Sheeting 2259/B00A/R0012/Panels Under Windows/S2	**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 2259/B00A/R0001/Ceiling Structures/Linings/S23	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 2259/B00A/R0017/Floor Coverings Res/Textile/S22	**No Asbestos Detected**

B00A - R0004 - Clerical Office

Panels Under Windows	Flat AC Sheeting 2259/B00A/R0006/Infill panel above & below windows/S31	**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 2259/B00A/R0001/Ceiling Structures/Linings/S23	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 2259/B00A/R0017/Floor Coverings Res/Textile/S22	**No Asbestos Detected**

B00A - R0005 - Plant

Ceiling Structures/Linings	Vermiculite 2259/B00A/R0001/Ceiling Structures/Linings/S23	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 2259/B00A/R0017/Floor Coverings Res/Textile/S22	**No Asbestos Detected**

B00A - R0006 - Sick Bay

Ceiling Structures/Linings	Vermiculite 2259/B00A/R0001/Ceiling Structures/Linings/S23	**No Asbestos Detected**
Wall Linings Internal	Flat AC Sheeting 2259/B00A/R0008/Wall Linings Internal/S30	**No Asbestos Detected**
Infill panel above & below windows	Compressed AC Sheet 2259/B00A/R0006/Infill panel above & below windows/S31	**No Asbestos Detected**

B00A - R0007 - Staff Shower/Change

Ceiling Structures/Linings	Vermiculite 2259/B00A/R0001/Ceiling Structures/Linings/S23	**No Asbestos Detected**
Wall Linings Internal	Flat AC Sheeting 2259/B00A/R0008/Wall Linings Internal/S30	**No Asbestos Detected**

B00A - R0008 - Staff Toilet

Ceiling Structures/Linings	Vermiculite 2259/B00A/R0001/Ceiling Structures/Linings/S23	**No Asbestos Detected**
Wall Linings Internal	Flat AC Sheeting 2259/B00A/R0008/Wall Linings Internal/S30	**No Asbestos Detected**

B00A - R0009 - Interview

Panels Under Windows	Flat AC Sheeting 2259/B00A/R0006/Infill panel above & below windows/S31	**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result
Ceiling Structures/Linings	Vermiculite 2259/B00A/R0001/Ceiling Structures/Linings/S23	**No Asbestos Detected**
B00A - R0010 - Principal		
Ceiling Structures/Linings	Vermiculite 2259/B00A/R0001/Ceiling Structures/Linings/S23	**No Asbestos Detected**
Panels Under Windows	Flat AC Sheeting 2259/B00A/R0006/Infill panel above & below windows/S31	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2259/B00A/R0017/Floor Coverings Res/Textile/S22	**No Asbestos Detected**
B00A - R0011 - Staff Room		
Panels Under Windows	Flat AC Sheeting 2259/B00A/R0006/Infill panel above & below windows/S31	**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 2259/B00A/R0001/Ceiling Structures/Linings/S23	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2259/B00A/R0017/Floor Coverings Res/Textile/S22	**No Asbestos Detected**
B00A - R0012 - Staff Room Annexe		
Panels Under Windows	Flat AC Sheeting 2259/B00A/R0006/Infill panel above & below windows/S31	**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 2259/B00A/R0001/Ceiling Structures/Linings/S23	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2259/B00A/R0017/Floor Coverings Res/Textile/S22	**No Asbestos Detected**
B00A - R0013 - Interview		
Panels Under Windows	Flat AC Sheeting 2259/B00A/R0006/Infill panel above & below windows/S31	**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 2259/B00A/R0001/Ceiling Structures/Linings/S23	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2259/B00A/R0017/Floor Coverings Res/Textile/S22	**No Asbestos Detected**
B00A - R0014 - Deputy Principal		
Panels Under Windows	Flat AC Sheeting 2259/B00A/R0006/Infill panel above & below windows/S31	**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 2259/B00A/R0001/Ceiling Structures/Linings/S23	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2259/B00A/R0017/Floor Coverings Res/Textile/S22	**No Asbestos Detected**
B00A - R0015 - Duplicating Workroom		
Panels Under Windows	Flat AC Sheeting 2259/B00A/R0006/Infill panel above & below windows/S31	**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 2259/B00A/R0001/Ceiling Structures/Linings/S23	**No Asbestos Detected**
B00A - R0016 - Distribution Board	Note: No inspection of live electrical installation.	
Ceiling Structures/Linings	Vermiculite 2259/B00A/R0001/Ceiling Structures/Linings/S23	**No Asbestos Detected**
B00A - R0017 - Cleaning Distributed Store		
Ceiling Structures/Linings	Vermiculite 2259/B00A/R0001/Ceiling Structures/Linings/S23	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 2259/B00A/R0017/Floor Coverings Res/Textile/S22	**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result
B00A - R0018 - Security Store		
No Asbestos		
B00A - R0019 - Movement		
Ceiling Structures/Linings	Vermiculite	
	2259/B00A/R0001/Ceiling Structures/Linings/S23	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles	
	2259/B00A/R0017/Floor Coverings Res/Textile/S22	**No Asbestos Detected**
B00A - R0020 - External Movement		
Panels Under Windows	Flat AC Sheeting	
	2259/B00A/R0020/Panels Under Windows/S1	**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - Pupil Facilities - 1969 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	10m2	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00B/R0009/Ceiling Structures/Linings/S32					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting					
	2259/B00B/Gable Verge Lining/S33					No Asbestos Detected
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Interior

B00B - R0001 - Uniform Shop

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00B/R0009/Ceiling Structures/Linings/S32					Chrysotile (white asbestos)

B00B - R0002 - General Assistant/Bulk Store

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00B/R0007/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)

B00B - R0003 - Canteen

Floor Coverings Res/Textile	Vinyl Tiles					
	2259/B00B/R0003/Floor Coverings Res/Textile/S34					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00B/R0007/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)

B00B - R0005 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00B/R0007/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)

B00B - R0006 - Handwashing Facilities

Floor Coverings Res/Textile	Vinyl Tiles					
	2259/B00B/R0003/Floor Coverings Res/Textile/S5					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00B/R0009/Ceiling Structures/Linings/S32					Chrysotile (white asbestos)

B00B - R0007 - Movement

Floor Coverings Res/Textile	Vinyl Tiles					
	2259/B00B/R0003/Floor Coverings Res/Textile/S5					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00B/R0007/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)

B00B - R0008 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00B/R0007/Ceiling Structures/Linings/S24					Chrysotile (white asbestos)

B00B - R0009 - External Movement

Wall Linings Internal	Flat AC Sheeting					
	2259/B00B/R0009/Wall Linings Internal/S4					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00B/R0009/Ceiling Structures/Linings/S32					Chrysotile (white asbestos)

B00B - R0010 - Toilets - Boys

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00B/R0009/Ceiling Structures/Linings/S32					**Chrysotile (white asbestos)**
B00B - R0011 - Toilets - Girls						
Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00B/R0009/Ceiling Structures/Linings/S32					**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00C - General Learning - 1973 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00C/Eaves Linings/S9					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00C - R0001 - Home Base Store

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00C/R0001/Ceiling Structures/Linings/S35					Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00C/R0008/Wall Linings Internal/S11					Chrysotile (white asbestos)

B00C - R0002 - Home Base

Panels Around Heater	Flat AC Sheeting	2m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00C/R0007/Panels Around Heater/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00C - R0003 - Home Base

No Asbestos

B00C - R0004 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Sheet					
	2259/B00C/R0005/Floor Coverings Res/Textile/S13					No Asbestos Detected

B00C - R0005 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Sheet					
	2259/B00C/R0005/Floor Coverings Res/Textile/S13					No Asbestos Detected

B00C - R0006 - Home Base

Panels Around Heater	Flat AC Sheeting	2m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00C/R0007/Panels Around Heater/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00C - R0007 - Home Base

Panels Around Heater	Flat AC Sheeting	2m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00C/R0007/Panels Around Heater/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00C - R0008 - Practical Activities - 1hb

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00C/R0001/Ceiling Structures/Linings/S35					Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00C/R0008/Wall Linings Internal/S11					Chrysotile (white asbestos)

B00C - R0009 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	61m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00C/R0009/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00D - General Learning - 1965 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/Eaves Linings/S41					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/Eaves Linings/S41					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00D - R0001 - Home Base

Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/R0001/Floor Coverings Res/Textile/S40					Chrysotile (white asbestos)

B00D - R0002 - Practical Activities - 1hb

Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/R0001/Floor Coverings Res/Textile/S40					Chrysotile (white asbestos)

B00D - R0003 - Practical Activities - 1hb

Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/R0001/Floor Coverings Res/Textile/S40					Chrysotile (white asbestos)

B00D - R0004 - Home Base

Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/R0001/Floor Coverings Res/Textile/S40					Chrysotile (white asbestos)

B00D - R0005 - Cleaning Supplies

No Asbestos

B00D - R0006 - Home Base

Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/R0001/Floor Coverings Res/Textile/S40					Chrysotile (white asbestos)

B00D - R0007 - Practical Activities - 1hb

Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00E/R0009/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)

B00D - R0008 - Distribution Board

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	2Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					

B00D - R0009 - Practical Activities - 1hb

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
B00D - R0010 - Home Base						
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/R0001/Floor Coverings Res/Textile/S40					**Chrysotile (white asbestos)**
B00D - R0011 - External Movement						
No Asbestos						
B00D - R0012 - External Stairs						
No Asbestos						
B00D - R1001 - Home Base						
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/R0001/Floor Coverings Res/Textile/S40					**Chrysotile (white asbestos)**
B00D - R1002 - Practical Activities - 1hb						
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00E/R0009/Floor Coverings Res/Textile/S14					**Chrysotile (white asbestos)**
B00D - R1003 - Practical Activities - 1hb						
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/R0001/Floor Coverings Res/Textile/S40					**Chrysotile (white asbestos)**
B00D - R1004 - Home Base						
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/R0001/Floor Coverings Res/Textile/S40					**Chrysotile (white asbestos)**
B00D - R1005 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/R1005/Ceiling Structures/Linings/S26					**Chrysotile (white asbestos)**
B00D - R1006 - Home Base						
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/R0001/Floor Coverings Res/Textile/S40					**Chrysotile (white asbestos)**
B00D - R1007 - Practical Activities - 1hb						
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
B00D - R1008 - Practical Activities - 1hb						
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00E/R0009/Floor Coverings Res/Textile/S14					**Chrysotile (white asbestos)**
B00D - R1009 - Home Base						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/R0001/Floor Coverings Res/Textile/S40					**Chrysotile (white asbestos)**
B00D - R1010 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/R1005/Ceiling Structures/Linings/S26					**Chrysotile (white asbestos)**
B00D - R1011 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/R1005/Ceiling Structures/Linings/S26					**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00E - General Learning/Pupil Facilities - 1965 - Brick/Block (Brick/Block)

Exterior

Gable Verge Lining	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/Eaves Linings/S41				Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/Eaves Linings/S41				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00E - R0001 - Toilets - Boys

No Asbestos

B00E - R0002 - Cleaning Distributed Store

No Asbestos

B00E - R0003 - Toilets - Girls

No Asbestos

B00E - R0004 - Cleaning Distributed Store

No Asbestos

B00E - R0005 - Home Base

Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25				No Asbestos Detected	

B00E - R0006 - Practical Activities - 1hb

Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25				No Asbestos Detected	
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00E/R0009/Floor Coverings Res/Textile/S14				Chrysotile (white asbestos)	

B00E - R0007 - Home Base Store

No Asbestos

B00E - R0008 - Home Base

Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25				No Asbestos Detected	

B00E - R0009 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00E/R0009/Floor Coverings Res/Textile/S14				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25				No Asbestos Detected	

B00E - R0010 - Home Base Store

No Asbestos

B00E - R0011 - Distribution Board

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25				No Asbestos Detected	

B00E - R0012 - General Assistant/Bulk Store

Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25				No Asbestos Detected	

B00E - R0013 - General Storeroom

Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25				No Asbestos Detected	

B00E - R0014 - General Storeroom

Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25				No Asbestos Detected	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00E - R0015 - Sports Store						
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
B00E - R0016 - Garden Store						
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
B00E - R0017 - External Movement						
No Asbestos						
B00E - R0018 - P.E. Store						
No Asbestos						
B00E - R0019 - Kiln Room						
No Asbestos						
B00E - R0020 - External Stairs						
No Asbestos						
B00E - R0021 - External Stairs						
No Asbestos						
B00E - R1001 - Home Base						
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
B00E - R1002 - Practical Activities - 1hb						
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
B00E - R1003 - Practical Activities - 1hb						
Floor Coverings Res/Textile	Vinyl Tiles	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00E/R0009/Floor Coverings Res/Textile/S14					**Chrysotile (white asbestos)**
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
B00E - R1004 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00E/R0009/Floor Coverings Res/Textile/S14					**Chrysotile (white asbestos)**
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
B00E - R1005 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/Eaves Linings/S41					**Chrysotile (white asbestos)**
B00E - R1006 - Home Base						
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
B00E - R1007 - Practical Activities - 1hb						
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
B00E - R1008 - Practical Activities - 1hb						
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00E/R0009/Floor Coverings Res/Textile/S14					**Chrysotile (white asbestos)**
B00E - R1009 - Home Base						
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Floor Coverings Res/Textile	Vinyl Tiles	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00E/R0009/Floor Coverings Res/Textile/S14					**Chrysotile (white asbestos)**
B00E - R1010 - Toilets - Girls						
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/Eaves Linings/S41					**Chrysotile (white asbestos)**
B00E - R1011 - Cleaning Distributed Store						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00E/R0009/Floor Coverings Res/Textile/S14					**Chrysotile (white asbestos)**
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/Eaves Linings/S41					**Chrysotile (white asbestos)**
B00E - R1012 - Interview						
Floor Coverings Res/Textile	Vinyl Tiles	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00E/R0009/Floor Coverings Res/Textile/S14					**Chrysotile (white asbestos)**
Ceiling Structures/Linings	Vermiculite					
	2259/B00D/R0010/Ceiling Structures/Linings/S25					**No Asbestos Detected**
B00E - R1013 - Toilets - Boys						
Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/Eaves Linings/S41					**Chrysotile (white asbestos)**
B00E - R1014 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/Eaves Linings/S41					**Chrysotile (white asbestos)**
B00E - R1015 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/Eaves Linings/S41					**Chrysotile (white asbestos)**
B00E - R1016 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00D/Eaves Linings/S41					**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00M - Other-Community Use - 1965 - Timber (Timber)

Exterior

Underfloor Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Interior

B00M - R0001 - Plant

Panels Behind Heater	Flat AC Sheeting	2m2	North, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00M/R0001/Panels Behind Heater/S21					**Chrysotile (white asbestos)**

B00M - R0002 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	2259/B00M/R0002/Ceiling Structures/Linings/S18					**No Asbestos Detected**

B00M - R0003 - Toilets - Boys/Girls

Floor Coverings Res/Textile	Vinyl Sheet					
	2259/B00M/R0003/Floor Coverings Res/Textile/S19					**No Asbestos Detected**
Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00M/R0003/Wall Linings Internal/S20					**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00N - Communal Facilities - 1965 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Wall Cladding	Flat AC Sheeting 2259/B00N/Wall Cladding/S15	**No Asbestos Detected**
Gable Ends	Flat AC Sheeting 2259/B00N/Wall Cladding/S15	**No Asbestos Detected**
Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	No Asbestos Found	

Interior

B00N - R0001 - Communal Space

Wall Linings Internal	Flat AC Sheeting 2259/B00N/R0001/Wall Linings Internal/S16	**No Asbestos Detected**
Ceiling Structures/Linings	Flat AC Sheeting 2259/B00N/R0001/Ceiling Structures/Linings/S17	**No Asbestos Detected**

B00N - R0002 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 2259/B00N/R0001/Ceiling Structures/Linings/S17	**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00Q - General Learning - 1965 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 2259/B00R/Eaves Linings/S38					**No Asbestos Detected**
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00Q - R0001 - Home Base Store

Electrical Backing Board	Resinous Board **Assumed Asbestos - Electrical Hazard**	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)

B00Q - R0002 - Home Base

No Asbestos

B00Q - R0003 - Home Base

Infill panels behind heater	Compressed AC Sheet 2259/B00Q/R0003/Infill panels behind heater/S39	2m2	North west	Good Condition (1)	Low (1) **Chrysotile (white asbestos)**	Low Priority (2-3)

B00Q - R0005 - Practical Activities - 1hb

No Asbestos

B00Q - R0006 - Practical Activities - 1hb

No Asbestos

B00Q - R0007 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00R - General Learning - 1965 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 2259/B00R/Eaves Linings/S38	**No Asbestos Detected**
Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	

Interior

B00R - R0001 - Home Base

Electrical Backing Board	Resinous Board **Assumed Asbestos - Electrical Hazard**	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)

B00R - R0003 - Home Base Store

No Asbestos

B00R - R0004 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00S - General Learning - 1965 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	6m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00S/R0006/Ceiling Structures/Linings/S37					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Underfloor Voids	Debris	2m2	Variable positions	Minimal Damage (2)	Medium (2)	Medium Priority (4-5)
	2259/B00S/Underfloor Voids/S36					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Ceiling Voids	No Asbestos Found					

Interior

B00S - R0001 - Home Base

Panels Behind Heater	Flat AC Sheeting	2m2	North, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00S/R0001/Panels Behind Heater/S6					**Chrysotile (white asbestos)**

B00S - R0006 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00S/R0006/Ceiling Structures/Linings/S37					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Electrical Backing Board	Resinous Board	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - No access live electrical equipment					

B00S - R0007 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2259/B00S/R0006/Ceiling Structures/Linings/S37					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00S - R0008 - Practical Activities - 1hb

No Asbestos

B00S - R0009 - Home Base Store

No Asbestos

B00S - R0010 - Special Programs Room - Type 1

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00T - Library - 1993 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00T - R0001 - Reading Area

No Asbestos

B00T - R0002 - Communications Room

No Asbestos

B00T - R0003 - Library Office/Workroom

No Asbestos

B00T - R0004 - Movement

No Asbestos

B00T - R0005 - External Movement

No Asbestos

B00T - R0006 - Special Programs Room

No Asbestos

B00T - R0007 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00T - R0008 - Security Store

No Asbestos

B00T - R0009 - Plant

No Asbestos

B00T - R0010 - External Movement

No Asbestos

B00T - R0011 - Disabled Toilet

No Asbestos

B00T - R0012 - Cleaning Distributed Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00U - Communal Facilities - 1993 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	

Interior

B00U - R0001 - External Movement

No Asbestos

B00U - R0002 - Communal Space

No Asbestos

B00U - R0003 - Plant

Ceiling Structures/Linings	Flat AC Sheeting 2259/B00U/R0006/Ceiling Structures/Linings/S29	**No Asbestos Detected**

B00U - R0004 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting 2259/B00U/R0006/Ceiling Structures/Linings/S29	**No Asbestos Detected**

B00U - R0005 - Raised Platform

No Asbestos

B00U - R0006 - P.E. Store

Ceiling Structures/Linings	Flat AC Sheeting 2259/B00U/R0006/Ceiling Structures/Linings/S29	**No Asbestos Detected**

B00U - R0007 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00U - R0008 - External Movement

No Asbestos

B00U - R0009 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00V - General Learning - 2006 - Concrete (Concrete)

Exterior

Underfloor Voids	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00V - R0001 - Seminar/Study

No Asbestos

B00V - R0002 - Seminar/Study

No Asbestos

B00V - R0003 - Movement

No Asbestos

B00V - R0004 - Staff Toilet

No Asbestos

B00V - R0005 - Special Programs Room

No Asbestos

B00V - R0006 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00W - Building Services - 2007 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00W - R0001 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00X - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00X - R0001 - Practical Activities - 1hb

No Asbestos

B00X - R0002 - Personal Effects Storage

No Asbestos

B00X - R0003 - Home Base Store

No Asbestos

B00X - R0004 - Home Base

No Asbestos

B00X - R0005 - Withdrawal Space - 2hb

No Asbestos

B00X - R0006 - Practical Activities - 1hb

No Asbestos

B00X - R0007 - Personal Effects Storage

No Asbestos

B00X - R0008 - Home Base Store

No Asbestos

B00X - R0009 - Home Base

No Asbestos

B00X - R0010 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

B00Y - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00Y - R0001 - Practical Activities - 1hb

No Asbestos

B00Y - R0002 - Personal Effects Storage

No Asbestos

B00Y - R0003 - Home Base Store

No Asbestos

B00Y - R0004 - Home Base

No Asbestos

B00Y - R0005 - Withdrawal Space - 2hb

No Asbestos

B00Y - R0006 - Practical Activities - 1hb

No Asbestos

B00Y - R0007 - Personal Effects Storage

No Asbestos

B00Y - R0008 - Home Base Store

No Asbestos

B00Y - R0009 - Home Base

No Asbestos

B00Y - R0010 - External Movement

No Asbestos

B00Y - R0011 - Movement

No Asbestos

B00Y - R0012 - Special Programs Store

No Asbestos

B00Y - R0013 - Practical Activities

No Asbestos

B00Y - R0014 - Special Programs Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10204 - Learning Unit - Standard With P.A.A. : Placement Date - 13/05/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11480 - Learning Unit - Standard With P.A.A. : Placement Date - 28/03/2001

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

NS 020 - D12165 - Staff Study/Store : Placement Date - 10/08/1999

Exterior

No Asbestos Found.

Interior

R1 - Staff Room

No Asbestos Found.

R2 - Store

No Asbestos Found.

R3 - Entry

No Asbestos Found.

OS 602 - D14927 - Learning Unit - Standard With P.A.A. : Placement Date - 18/01/2001

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017