Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Kellyville Public School (2274)**
Region :	**Western Sydney**
State Electorate :	**Castle Hill**
Local Government Area :	**The Hills**

Initial Survey :	**Noel Arnold & Associates : 20 - May - 2008**
Reviewed By :	**Parsons Brinckerhoff : 14 - May - 2015**

2274 - Kellyville Public School
Site Plan (12569)

1:938 Printed: 04-Feb-2017

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00A - Staff Facilities - 1898 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00A - R0002 - Staff Room

No Asbestos

B00A - R0003 - External Movement

In-fill-panel	Flat AC Sheeting	6m	North, West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00A/R0003/In-fill-panel/S1					**Chrysotile (white asbestos)**
Ceiling Structures/Linings	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00A/R0003/In-fill-panel/S1					**Chrysotile (white asbestos)**

B00A - R0004 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0005 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00B - Music - 1912 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00B - R0001 - External Movement

No Asbestos

B00B - R0002 - Special Programs Room

Ceiling Hatch	Flat AC Sheeting	1m2	East	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2274/B00B/R0002/Ceiling Hatch/S19					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00C - Administration/General Learning - 1971 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	50m2	North, South, East, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00I/Eaves Linings/S25					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00I/Gable Verge Lining/S26					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - No access into Underfloor Void - No hatch located					

Interior

B00C - R0001 - External Movement

No Asbestos

B00C - R0003 - Clerical Office

Ceiling Structures/Linings	Vermiculite	
	2274/B00C/R0021/Ceiling Structures/Linings/S2	No Asbestos Detected

B00C - R0009 - Main Switch Board

No Asbestos

B00C - R0010 - Staff Toilet

Ceiling Structures/Linings	Vermiculite	
	2274/B00C/R0021/Ceiling Structures/Linings/S2	No Asbestos Detected

B00C - R0013 - Security Store

No Asbestos

B00C - R0014 - Communications Room

No Asbestos

B00C - R0019 - Principal

Ceiling Structures/Linings	Vermiculite	
	2274/B00C/R0021/Ceiling Structures/Linings/S2	No Asbestos Detected

B00C - R0020 - Entry Vestibule

Ceiling Structures/Linings	Vermiculite	
	2274/B00C/R0021/Ceiling Structures/Linings/S2	No Asbestos Detected

B00C - R0021 - Movement

Ceiling Structures/Linings	Vermiculite	
	2274/B00C/R0021/Ceiling Structures/Linings/S2	No Asbestos Detected

B00C - R0022 - Sick Bay - Shower/Toilet

No Asbestos

B00C - R0023 - Sick Bay

Ceiling Structures/Linings	Vermiculite	
	2274/B00C/R0021/Ceiling Structures/Linings/S2	No Asbestos Detected

B00C - R0024 - Duplicating Workroom

Ceiling Structures/Linings	Vermiculite	
	2274/B00C/R0021/Ceiling Structures/Linings/S2	No Asbestos Detected

B00C - R0025 - Staff Toilet

Decorative Coating	Vermiculite	
	2274/B00C/R0025/Decorative Coating/S20	No Asbestos Detected

B00C - R0026 - Handwashing Facilities

Decorative Coating	Vermiculite	
	2274/B00C/R0025/Decorative Coating/S20	No Asbestos Detected

B00C - R0027 - Stairs

No Asbestos

B00C - R1002 - Home Base

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
No Asbestos						
B00C - R1003 - Personal Effects Storage						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00C/R1003/Floor Coverings Res/Textile/S4					**Chrysotile (white asbestos)**
B00C - R1004 - Home Base Store						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00C/R1003/Floor Coverings Res/Textile/S4					**Chrysotile (white asbestos)**
B00C - R1006 - Home Base Store						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00C/R1001/Ceiling Structures/Linings/S3					**Chrysotile (white asbestos)**
B00C - R1007 - Home Base Store						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00C/R1003/Floor Coverings Res/Textile/S4					**Chrysotile (white asbestos)**
B00C - R1008 - Personal Effects Storage						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00C/R1003/Floor Coverings Res/Textile/S4					**Chrysotile (white asbestos)**
B00C - R1009 - Home Base						
No Asbestos						
B00C - R1010 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00C/R1011/Ceiling Structures/Linings/S17					**Chrysotile (white asbestos)**
B00C - R1011 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00C/R1011/Ceiling Structures/Linings/S17					**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00D - General Learning/Administration - 1972 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	45m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00I/Eaves Linings/S25					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00I/Gable Verge Lining/S26					Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting	24m2	East, Upper portion, Lower portion, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00D/Panels under Windows/S5					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - No access - No hatch located					

Interior

B00D - R0001 - External Movement

In-fill-panel	Flat AC Sheeting	12m	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00D/Panels under Windows/S5					Chrysotile (white asbestos)

B00D - R0002 - Home Base

Ceiling Structures/Linings	Vermiculite	
	2274/B00D/R0018/Ceiling Structures/Linings/S6	**No Asbestos Detected**

B00D - R0003 - Home Base Store

Floor Coverings Res/Textile	Vinyl Sheet (Under Carpet)	
	2274/B00D/R0003/Floor Coverings Res/Textile/S21	**No Asbestos Detected**
Decorative Coating	Vermiculite	
	2274/B00C/R0025/Decorative Coating/S20	**No Asbestos Detected**

B00D - R0004 - Personal Effects Storage

Ceiling Structures/Linings	Vermiculite	
	2274/B00D/R0018/Ceiling Structures/Linings/S6	**No Asbestos Detected**

B00D - R0005 - Movement

No Asbestos

B00D - R0006 - Movement

No Asbestos

B00D - R0007 - Uniform Shop

No Asbestos

B00D - R0008 - Personal Effects Storage

Ceiling Structures/Linings	Vermiculite	
	2274/B00D/R0018/Ceiling Structures/Linings/S6	**No Asbestos Detected**

B00D - R0009 - Distribution Board

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Vermiculite	
	2274/B00D/R0018/Ceiling Structures/Linings/S6	**No Asbestos Detected**

B00D - R0010 - Home Base Store

Ceiling Structures/Linings	Vermiculite	
	2274/B00D/R0018/Ceiling Structures/Linings/S6	**No Asbestos Detected**

B00D - R0011 - Home Base

Ceiling Structures/Linings	Vermiculite	
	2274/B00D/R0018/Ceiling Structures/Linings/S6	**No Asbestos Detected**

B00D - R0015 - Interview

Ceiling Structures/Linings	Vermiculite	
	2274/B00D/R0018/Ceiling Structures/Linings/S6	**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00D - R0016 - Interview						
Ceiling Structures/Linings	Vermiculite					
	2274/B00D/R0018/Ceiling Structures/Linings/S6					**No Asbestos Detected**
B00D - R0017 - Movement						
Ceiling Structures/Linings	Vermiculite					
	2274/B00D/R0018/Ceiling Structures/Linings/S6					**No Asbestos Detected**
B00D - R0018 - Interview						
Ceiling Structures/Linings	Vermiculite					
	2274/B00D/R0018/Ceiling Structures/Linings/S6					**No Asbestos Detected**
B00D - R0019 - General Storeroom						
Ceiling Structures/Linings	Vermiculite					
	2274/B00D/R0018/Ceiling Structures/Linings/S6					**No Asbestos Detected**
B00D - R0020 - Stairs						
No Asbestos						
B00D - R0021 - Stairs						
No Asbestos						
B00D - R1001 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00C/R1001/Ceiling Structures/Linings/S3					**Chrysotile (white asbestos)**
In-fill-panel	Flat AC Sheeting	12m	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00D/Panels under Windows/S5					**Chrysotile (white asbestos)**
B00D - R1002 - Home Base						
No Asbestos						
B00D - R1003 - Home Base Store						
No Asbestos						
B00D - R1004 - Personal Effects Storage						
No Asbestos						
B00D - R1005 - Movement						
No Asbestos						
B00D - R1006 - General Storeroom						
No Asbestos						
B00D - R1007 - Personal Effects Storage						
No Asbestos						
B00D - R1008 - Distribution Board						Note: No inspection of live electrical installation.
No Asbestos						
B00D - R1009 - Home Base Store						
No Asbestos						
B00D - R1010 - Home Base						
No Asbestos						
B00D - R1011 - Home Base						
No Asbestos						
B00D - R1012 - Home Base Store						
No Asbestos						
B00D - R1013 - Personal Effects Storage						
No Asbestos						
B00D - R1014 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00C/R1011/Ceiling Structures/Linings/S17					**Chrysotile (white asbestos)**
B00D - R9001 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00D - R9002 - Toilets - Boys						
Partition Walls (Cubicles)	Compressed AC Sheet	24m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00D/R9003/Partition Walls (Cubicles)/S13					**Chrysotile (white asbestos)**
B00D - R9003 - Toilets - Girls						
Partition Walls (Cubicles)	Compressed AC Sheet	40m2	North, South, East, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00D/R9003/Partition Walls (Cubicles)/S13					**Chrysotile (white asbestos)**
B00D - R9004 - Cleaning Distributed Store						
No Asbestos						
B00D - R9005 - Movement						
No Asbestos						
B00D - R9006 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00E - General Learning - 1955 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00E/Eaves Linings/S23				**Chrysotile (white asbestos) , Amosite (brown asbestos)**	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00E - R0002 - Home Base

In-fill-panel	Flat AC Sheeting					
	2274/B00E/R0002/In-fill-panel/S8				**No Asbestos Detected**	

B00E - R0003 - Home Base

No Asbestos

B00E - R0004 - Other-Community Use

No Asbestos

B00E - R0005 - Other-Community Use

No Asbestos

B00E - R0006 - Home Base Store

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00E/R0006/Ceiling Structures/Linings/S18				**Chrysotile (white asbestos) , Amosite (brown asbestos)**	

B00E - R0007 - Practical Activities - 2hb

Ceiling Structures/Linings	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00E/R0006/Ceiling Structures/Linings/S18				**Chrysotile (white asbestos) , Amosite (brown asbestos)**	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00H - General Learning - 1969 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00I/Gable Verge Lining/S26					Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	25m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00I/Eaves Linings/S25					Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting	10m2	East, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00H/R0001/Panel under Windows/S11					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00H - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00H/R0001/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting	10m	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00H/R0001/Panel under Windows/S11					Chrysotile (white asbestos)

B00H - R0002 - Personal Effects Storage

No Asbestos

B00H - R0003 - Home Base Store

No Asbestos

B00H - R0004 - Home Base

No Asbestos

B00H - R0005 - Home Base

No Asbestos

B00H - R0006 - Toilets - Boys/Girls

Wall Linings Internal	Flat AC Sheeting	8m2	North, South, East, West, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00H/R0006/Wall Linings Internal/S9					Chrysotile (white asbestos)

B00H - R0007 - Home Base Store

No Asbestos

B00H - R0008 - Personal Effects Storage

No Asbestos

B00H - R9001 - P.E. Store

Ceiling Structures/Linings	Flat AC Sheeting	29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00H/R0001/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00I - General Learning/Pupil Facilities - 1962 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	80m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00I/Eaves Linings/S25				Chrysotile (white asbestos)	
Gable Verge Lining	Flat AC Sheeting	10m2	East & West	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2274/B00I/Gable Verge Lining/S26				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00I - R0001 - Home Base Store

No Asbestos

B00I - R0002 - Personal Effects Storage

No Asbestos

B00I - R0003 - External Movement

No Asbestos

B00I - R0004 - Home Base

No Asbestos

B00I - R0005 - Home Base

No Asbestos

B00I - R0006 - External Movement

No Asbestos

B00I - R0007 - Personal Effects Storage

No Asbestos

B00I - R0008 - Home Base Store

No Asbestos

B00I - R0009 - Toilets - Boys/Girls

Wall Linings Internal	Flat AC Sheeting	15m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00I/R0009/Wall Linings Internal/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00I - R0010 - Toilets - Girls

No Asbestos

B00I - R0011 - Disabled Toilet

No Asbestos

B00I - R0012 - Toilets - Boys

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00J - General Learning - 1969 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00I/Gable Verge Lining/S26					Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	35m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00I/Eaves Linings/S25					Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting	17m2	South, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00H/R0001/Panel under Windows/S11					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00J - R0001 - External Movement

In-fill-panel	Flat AC Sheeting	8m	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00J/R0001/Panel under Windows/S15					Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00H/R0001/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)

B00J - R0002 - Personal Effects Storage

No Asbestos

B00J - R0003 - Home Base Store

No Asbestos

B00J - R0004 - Home Base

No Asbestos

B00J - R0005 - Home Base

No Asbestos

B00J - R0006 - Home Base Store

No Asbestos

B00J - R0007 - Personal Effects Storage

No Asbestos

B00J - R0008 - Withdrawal Space - 2hb

No Asbestos

B00J - R0009 - General Storeroom

No Asbestos

B00J - R0016 - Cleaning Distributed Store

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00J/R0016/Floor Coverings Res/Textile/S16					Chrysotile (white asbestos)

B00J - R0017 - Practical Activities - 1hb

No Asbestos

B00J - R0018 - Home Base

No Asbestos

B00J - R9001 - General Assistant/Bulk Store

Ceiling Structures/Linings	Flat AC Sheeting	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2274/B00J/R9001/Ceiling Structures/Linings/S14					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00J - R9002 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00K - Other-After School Care - 1995 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00K - R0001 - Withdrawal - Pre

No Asbestos

B00K - R0002 - Other-Community Use

No Asbestos

B00K - R0003 - Kitchen - Pre

No Asbestos

B00K - R0004 - Toilets - Boys/Girls - Pre

No Asbestos

B00K - R0005 - Toilets - Boys/Girls - Pre

No Asbestos

B00K - R0006 - Withdrawal - Pre

No Asbestos

B00K - R0007 - Practical Activities - Pre

No Asbestos

B00K - R0008 - Staff Room - Pre

No Asbestos

B00K - R0009 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00L - Communal Facilities/Pupil Facilities - 1997 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Eaves Linings	Flat AC Sheeting 2274/B00L/Eaves Linings/S24	**No Asbestos Detected**

Interior

B00L - R0001 - Canteen

No Asbestos

B00L - R0002 - Canteen Office/Store

No Asbestos

B00L - R0003 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 2274/B00L/Eaves Linings/S24	**No Asbestos Detected**

B00L - R0004 - Cleaning Distributed Store

No Asbestos

B00L - R0005 - Disabled Toilet

No Asbestos

B00L - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0007 - P.E. Store

No Asbestos

B00L - R0008 - Plant

No Asbestos

B00L - R0009 - Hall Chair Store

No Asbestos

B00L - R0010 - Toilets - Boys

No Asbestos

B00L - R0011 - Shower/Change

No Asbestos

B00L - R0012 - Toilets - Girls

No Asbestos

B00L - R0013 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 2274/B00L/Eaves Linings/S24	**No Asbestos Detected**

B00L - R0014 - Community Clinic

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00L - R0015 - Community Clinic

No Asbestos

B00L - R0016 - Community Clinic

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00L - R0017 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 2274/B00L/Eaves Linings/S24	**No Asbestos Detected**

B00L - R0018 - Raised Platform

No Asbestos

B00L - R0019 - Communal Space

No Asbestos

B00L - R0020 - External Movement

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Wall Linings Internal	Flat AC Sheeting					
	2274/B00L/Eaves Linings/S24					**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00M - Library/Staff Facilities - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found	
Underfloor Voids	No Asbestos Found	
Eaves Linings	Flat AC Sheeting 2274/B00M/Eaves Linings/S22	**No Asbestos Detected**

Interior

B00M - R0001 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00M - R0002 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00M - R0003 - Staff Toilet

No Asbestos

B00M - R0004 - No Access

No Asbestos

B00M - R0005 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00M - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00M - R0007 - External Movement

No Asbestos

B00M - R0008 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00N - General Learning - 2007 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00N - R0005 - External Movement

No Asbestos

B00N - R0006 - Practical Activities - 1hb

No Asbestos

B00N - R0007 - Home Base Store

No Asbestos

B00N - R0008 - Home Base

No Asbestos

B00N - R0009 - Withdrawal Space - 2hb

No Asbestos

B00N - R0010 - Home Base

No Asbestos

B00N - R0011 - Home Base Store

No Asbestos

B00N - R0012 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00O - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00O - R0001 - External Movement

No Asbestos

B00O - R0002 - Practical Activities - 1hb

No Asbestos

B00O - R0003 - Home Base Store

No Asbestos

B00O - R0004 - Home Base

No Asbestos

B00O - R0005 - Withdrawal Space - 2hb

No Asbestos

B00O - R0006 - Home Base

No Asbestos

B00O - R0007 - Home Base Store

No Asbestos

B00O - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00P - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00P - R0001 - External Movement

No Asbestos

B00P - R0002 - Practical Activities - 1hb

No Asbestos

B00P - R0003 - Home Base Store

No Asbestos

B00P - R0004 - Home Base

No Asbestos

B00P - R0005 - Withdrawal Space - 2hb

No Asbestos

B00P - R0006 - Home Base

No Asbestos

B00P - R0007 - Home Base Store

No Asbestos

B00P - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00Q - General Learning/Other - 2007 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00Q - R0001 - External Movement

No Asbestos

B00Q - R0002 - Special Programs Room

No Asbestos

B00Q - R0003 - Special Programs Store

No Asbestos

B00Q - R0004 - Withdrawal Space - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10268 - Learning Unit - Standard With P.A.A. : Placement Date - 10/02/2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12616 - Learning Unit - Standard With P.A.A. : Placement Date - 17/11/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12770 - Learning Unit - Standard With P.A.A. : Placement Date - 28/11/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

- D13143 - : Placement Date - 6/10/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found.

2017

OS 602 - D14457 - Learning Unit - Standard With P.A.A. : Placement Date - 30/11/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D15012 - Learning Unit - Standard With P.A.A. : Placement Date - 6/10/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D15285 - Learning Unit - Standard With P.A.A. : Placement Date - 2/12/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017