Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Katoomba High School (8150)**
Region :	**Western Sydney**
State Electorate :	**Blue Mountains**
Local Government Area :	**Blue Mountains**

Initial Survey :	**Noel Arnold & Associates : 23 - May - 2008**
Reviewed By :	**Parsons Brinckerhoff : 06 - Mar - 2015**

8150 - Katoomba High School
Site Plan (11533)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00A - Library/Science - 1978 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00A - M1001 - Main Area

No Asbestos

B00A - M1002 - Lift

No Asbestos

B00A - M1003 - Stairs

No Asbestos

B00A - R0001 - Laboratory L.S.

Floor Coverings Res/Textile	Vinyl Tiles	
	8150/B00A/R0001/Floor Coverings Res/Textile/S7	**No Asbestos Detected**

B00A - R0002 - Preparation

Floor Coverings Res/Textile	Vinyl Tiles	
	8150/B00A/R0001/Floor Coverings Res/Textile/S7	**No Asbestos Detected**

B00A - R0003 - Laboratory L.S.

Floor Coverings Res/Textile	Vinyl Tiles	
	8150/B00A/R0001/Floor Coverings Res/Textile/S7	**No Asbestos Detected**

B00A - R0004 - Laboratory L.S.

Floor Coverings Res/Textile	Vinyl Tiles	
	8150/B00A/R0001/Floor Coverings Res/Textile/S7	**No Asbestos Detected**

B00A - R0006 - Laboratory L.S.

Floor Coverings Res/Textile	Vinyl Tiles	
	8150/B00A/R0001/Floor Coverings Res/Textile/S7	**No Asbestos Detected**

B00A - R0007 - Apparatus Store

No Asbestos

B00A - R0008 - Main Switchroom

No Asbestos

B00A - R0009 - Movement

No Asbestos

B00A - R0010 - Preparation

Floor Coverings Res/Textile	Vinyl Tiles	
	8150/B00A/R0001/Floor Coverings Res/Textile/S7	**No Asbestos Detected**

B00A - R0011 - Chemical Store

Floor Coverings Res/Textile	Vinyl Tiles	
	8150/B00A/R0001/Floor Coverings Res/Textile/S7	**No Asbestos Detected**

B00A - R0012 - Stairs

No Asbestos

B00A - R1001 - Movement

No Asbestos

B00A - R1002 - Staff Study

No Asbestos

B00A - R1003 - Staff - Toilet

No Asbestos

B00A - R1004 - Cleaning Store - Distributed

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

No Asbestos

B00A - R1005 - Staff - Toilet

No Asbestos

B00A - R1006 - Staff - Toilet

No Asbestos

B00A - R1007 - Workroom

No Asbestos

B00A - R1008 - Workroom

No Asbestos

B00A - R1009 - Administration - Clerical

No Asbestos

B00A - R1010 - Librarian

No Asbestos

B00A - R1011 - Computer Learning Space

No Asbestos

B00A - R1012 - Workroom

No Asbestos

B00A - R1013 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B00A - R1014 - Seminar

No Asbestos

B00A - R1015 - Seminar

No Asbestos

B00A - R1016 - Seminar

No Asbestos

B00A - R1018 - Lift

No Asbestos

B00A - R1019 - Stairs

No Asbestos

B00A - R1020 - Main Area

No Asbestos

B00A - R1021 - Stairs

No Asbestos

B00A - R9001 - General Storeroom

No Asbestos

B00A - R9002 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00B - Administration/Various - 1962 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids	No Asbestos Found	
Ceiling Voids	Vermiculite 8150/B00B/Ceiling Voids/S12	**No Asbestos Detected**

Interior

B00B - R0001 - Music Store

No Asbestos

B00B - R0002 - Practice/Seminar

No Asbestos

B00B - R0003 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00B - R0004 - Music Learning Space

Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00B - R0005 - Music Learning Space

Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00B - R0006 - Music Store

Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00B - R0007 - Self Help Toilet

Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00B - R0008 - Movement

Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00B - R0009 - Staff - Toilet

Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00B - R0010 - Laboratory L.S.

Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00B - R0011 - Preparation

Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00B - R0012 - Apparatus Store

Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00B - R0013 - Materials Technology L.S.

No Asbestos

B00B - R0014 - Materials Store

No Asbestos

B00B - R0015 - Dust Extraction Space

No Asbestos

B00B - R0016 - Materials Store

No Asbestos

B00B - R0017 - Materials Technology L.S.

No Asbestos

B00B - R0018 - Movement

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 8150/B00B/R0018/Floor Coverings Res/Textile/S2	**No Asbestos Detected**

B00B - R0019 - Movement

Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 8150/B00B/R0018/Floor Coverings Res/Textile/S2	**No Asbestos Detected**

B00B - R0020 - Materials Technology L.S.

No Asbestos

B00B - R0021 - Welding Area

No Asbestos

B00B - R0023 - Materials Store

No Asbestos

B00B - R0025 - Materials Technology L.S.

No Asbestos

B00B - R0026 - Movement

Floor Coverings Res/Textile	Vinyl Tiles 8150/B00B/R0018/Floor Coverings Res/Textile/S2	**No Asbestos Detected**

B00B - R0027 - Cleaning Store - Distributed

No Asbestos

B00B - R0028 - Movement

No Asbestos

B00B - R0029 - General Storeroom

No Asbestos

B00B - R0030 - Maintenance Bulk Store

No Asbestos

B00B - R0031 - Movement

No Asbestos

B00B - R0032 - Materials Store

No Asbestos

B00B - R0033 - Cleaning Supplies Store

No Asbestos

B00B - R0034 - Toilets-Boys

Partition Walls (Cubicles)	Compressed AC Sheet 8150/B00B/R0034/Partition Walls (Cubicles)/S4	**No Asbestos Detected**

B00B - R0035 - Movement

No Asbestos

B00B - R0036 - Toilets-Girls

Partition Walls (Cubicles)	Compressed AC Sheet 8150/B00B/R0034/Partition Walls (Cubicles)/S4	**No Asbestos Detected**

B00B - R0038 - Movement

No Asbestos

B00B - R0039 - Movement

No Asbestos

B00B - R0040 - General Storeroom

No Asbestos

B00B - R0041 - General Assistants

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00B - R0042 - Cleaning Supplies Store

No Asbestos

B00B - R0043 - Main Switchroom

No Asbestos

B00B - R0044 - General Storeroom

No Asbestos

B00B - R0045 - Sport Equipment Store

No Asbestos

B00B - R0046 - Cleaning Store - Distributed

No Asbestos

B00B - R0048 - Shower/Change

No Asbestos

B00B - R0049 - Sport Equipment Store

No Asbestos

B00B - R0050 - Movement

No Asbestos

B00B - R0051 - Sport Equipment Store

No Asbestos

B00B - R0052 - Shower/Change

No Asbestos

B00B - R0053 - Sport Equipment Store

No Asbestos

B00B - R0054 - Student Canteen

Floor Coverings Res/Textile	Vinyl Tiles		
	8150/B00B/R0053/Floor Coverings Res/Textile/S5		**No Asbestos Detected**

B00B - R0055 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles		
	8150/B00B/R0053/Floor Coverings Res/Textile/S5		**No Asbestos Detected**

B00B - R0056 - Staff - Toilet

Floor Coverings Res/Textile	Vinyl Tiles		
	8150/B00B/R0053/Floor Coverings Res/Textile/S5		**No Asbestos Detected**

B00B - R0057 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B00B - R0058 - Lift

No Asbestos

B00B - R0059 - Plant

No Asbestos

B00B - R0060 - Movement

No Asbestos

B00B - R0061 - Other-Vacant

No Asbestos

B00B - R0062 - Movement

No Asbestos

B00B - R0063 - Movement

No Asbestos

B00B - R0064 - Movement

No Asbestos

B00B - R0065 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00B - R0066 - Plant						
No Asbestos						
B00B - R0067 - Stairs						
No Asbestos						
B00B - R0068 - Stairs						
No Asbestos						
B00B - R0069 - General Storeroom						
No Asbestos						
B00B - R0070 - General Storeroom						
Electrical Backing Board	Resinous Board	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R0070/Electrical Backing Board/S15					**Chrysotile (white asbestos)**
B00B - R0071 - Stairs						
No Asbestos						
B00B - R0072 - Stairs						
No Asbestos						
B00B - R0073 - Stairs						
No Asbestos						
B00B - R0074 - Stairs						
No Asbestos						
B00B - R0075 - Materials Technology L.S.						
No Asbestos						
B00B - R0076 - Welding/Hot Metals Area						
No Asbestos						
B00B - R0077 - Welding/Hot Metals Area						
No Asbestos						
B00B - R1004 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1006 - Design L.S.						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1007 - Staff Study						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1008 - Design L.S.						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1009 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1010 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1011 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1012 - Staff Study						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1013 - General Storeroom						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result
B00B - R1014 - Commonroom		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R1015 - Cleaning Store - Distributed		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R1017 - Administration - Clerical		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R1018 - Movement		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R1019 - Careers Advisers Office		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R1020 - Staff - Toilet		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R1021 - Clinic - Boys		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R1024 - General Storeroom		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R1025 - Staff - Toilet		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R1026 - Principal Office		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R1027 - Public Entry		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R1033 - Bulk Store		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R1034 - Darkroom Space		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R1035 - Art Learning Space		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R1036 - Preparation		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R1037 - Preparation		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R1038 - Performance Workshop		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R1039 - Laboratory L.S.		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00B - R1040 - Preparation						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1050 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1051 - Cleaning Store - Distributed						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1052 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1053 - Resources Store						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1054 - General Storeroom						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1058 - Computer Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1059 - Movement						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1060 - Computer Resource						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1061 - General Storeroom						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1062 - Leading Teacher						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1063 - Deputy Principal Office						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1064 - Pupil Entry						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1065 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
Wall Linings Internal	Flat AC Sheeting	3m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	8150/B00B/R1065/Wall Linings Internal/S6					**Chrysotile (white asbestos)**
B00B - R1066 - Lift						
No Asbestos						
B00B - R1068 - Toilets-Disabled						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1069 - Toilets-Disabled						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R1070 - Main Entry						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Flat AC Sheeting					
	8150/B00B/R1070/Ceiling Structures/Linings/S16					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R1070/Floor Coverings Res/Textile/S17					**Chrysotile (white asbestos)**
B00B - R1071 - Administration - Clerical						
Floor Coverings Res/Textile	Vinyl Tiles	103m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R1071/Floor Coverings Res/Textile/S18					**Chrysotile (white asbestos)**
B00B - R1072 - Administration - Executive						
Floor Coverings Res/Textile	Vinyl Tiles	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R1072/Floor Coverings Res/Textile/S19					**Chrysotile (white asbestos)**
B00B - R1073 - Duplicating Workroom						
Floor Coverings Res/Textile	Vinyl Tiles	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R1073/Floor Coverings Res/Textile/S20					**Chrysotile (white asbestos)**
B00B - R1074 - Secure Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R1074/Floor Coverings Res/Textile/S21					**Chrysotile (white asbestos)**
B00B - R1075 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R1075/Floor Coverings Res/Textile/S22					**Chrysotile (white asbestos)**
B00B - R1076 - Clinic						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R1076/Floor Coverings Res/Textile/S23					**Chrysotile (white asbestos)**
B00B - R1077 - Clinic						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R1077/Floor Coverings Res/Textile/S24					**Chrysotile (white asbestos)**
B00B - R1078 - Toilets-Boys/Girls						
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R1078/Floor Coverings Res/Textile/S25					**Chrysotile (white asbestos)**
B00B - R1079 - Toilets-Boys/Girls						
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R1079/Floor Coverings Res/Textile/S26					**Chrysotile (white asbestos)**
B00B - R1080 - Toilets-Disabled						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R1080/Floor Coverings Res/Textile/S27					**Chrysotile (white asbestos)**
B00B - R1081 - Plant						
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R1081/Floor Coverings Res/Textile/S28					**Chrysotile (white asbestos)**
B00B - R1083 - Office/Store						
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R1083/Floor Coverings Res/Textile/S30					**Chrysotile (white asbestos)**
B00B - R1084 - Uniform Shop						
Floor Coverings Res/Textile	Vinyl Tiles	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R1084/Floor Coverings Res/Textile/S31					**Chrysotile (white asbestos)**
B00B - R1085 - Careers Advisers Office						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R1085/Floor Coverings Res/Textile/S32					Chrysotile (white asbestos)
B00B - R1086 - Careers Advisers Office						
Floor Coverings Res/Textile	Vinyl Tiles	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R1086/Floor Coverings Res/Textile/S33					Chrysotile (white asbestos)
B00B - R1087 - Stairs						
Floor Coverings Res/Textile	Vinyl Tiles	29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R1087/Floor Coverings Res/Textile/S34					Chrysotile (white asbestos)
B00B - R1088 - Stairs						
Floor Coverings Res/Textile	Vinyl Tiles	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R1088/Floor Coverings Res/Textile/S35					Chrysotile (white asbestos)
B00B - R1089 - Stairs						
Floor Coverings Res/Textile	Vinyl Tiles	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8150/B00B/R1089/Floor Coverings Res/Textile/S36					Chrysotile (white asbestos)
B00B - R1091 - Stairs						
No Asbestos						
B00B - R1092 - Hospitality Space						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R1094/Ceiling Structures/Linings/S43					No Asbestos Detected
B00B - R1093 - Preparation/Printing						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R1094/Ceiling Structures/Linings/S43					No Asbestos Detected
B00B - R1094 - Food Technology L.S.						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R1094/Ceiling Structures/Linings/S43					No Asbestos Detected
B00B - R1095 - Movement						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R1094/Ceiling Structures/Linings/S43					No Asbestos Detected
B00B - R1096 - Toilets-Girls						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R1094/Ceiling Structures/Linings/S43					No Asbestos Detected
B00B - R1097 - Toilets-Boys						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R1094/Ceiling Structures/Linings/S43					No Asbestos Detected
B00B - R1098 - Pantry						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R1094/Ceiling Structures/Linings/S43					No Asbestos Detected
B00B - R1099 - Laundry						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R1094/Ceiling Structures/Linings/S43					No Asbestos Detected
B00B - R1100 - Movement						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R1094/Ceiling Structures/Linings/S43					No Asbestos Detected
B00B - R1101 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	297m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8150/B00B/R1101/Floor Coverings Res/Textile/S42					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R1094/Ceiling Structures/Linings/S43					No Asbestos Detected
B00B - R1102 - Kitchen - Type 1						
Recently Modified Space	Requires Inspection					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result
B00B - R1103 - Movement		
Recently Modified Space	Requires Inspection	
B00B - R1104 - Movement		
Recently Modified Space	Requires Inspection	
B00B - R2001 - Stage		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2002 - Performance Workspace		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2003 - Secure Storeroom		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2004 - General Storeroom		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2005 - General Learning Space		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2006 - General Learning Space		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2007 - General Learning Space		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2008 - General Learning Space		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2009 - General Learning Space		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2010 - General Learning Space		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2011 - Staff Study		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2012 - General Learning Space		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2013 - General Learning Space		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2014 - General Learning Space		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2015 - Cleaning Store - Distributed		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2016 - General Learning Space		
Ceiling Structures/Linings	Vermiculite	
	8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2017 - General Storeroom		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2018 - General Learning Space		
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2019 - Sport Equipment Store		
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2020 - Interview/Office - Type 1		
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2021 - Administration - Clerical		
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2022 - Administration - Clerical		
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2023 - Staff - Toilet		
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2024 - Ancillary Staff		
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2025 - Staff - Toilet		
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2026 - Duplicating Workroom		
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2027 - Duplicating Workroom		
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2030 - Distribution Board Cupboard		Note: No inspection of live electrical installation.
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2033 - Kiln Space		
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2035 - General Storeroom		
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2036 - Resources Store		
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2037 - Art Learning Space		
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2038 - Resources Store		
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2039 - Art Learning Space		
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1	**No Asbestos Detected**
B00B - R2040 - Movement		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2041 - Staff Study						
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2042 - General Storeroom						
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2043 - General Learning Space						
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2044 - General Learning Space						
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2045 - General Storeroom						
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2046 - General Storeroom						
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2047 - Computer Resource						
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2048 - Staff Study						
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2049 - Staff Study						
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2050 - Movement						
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2051 - General Learning Space						
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2052 - General Learning Space						
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2053 - General Storeroom						
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2054 - Interview/Office - Type 1						
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2055 - Staff Study						
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2056 - General Learning Space						
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2057 - General Storeroom						
Ceiling Structures/Linings	Vermiculite 8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2058 - Computer Learning Space						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2059 - Movement						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00B - R2060 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R0018/Ceiling Structures/Linings/S1					**No Asbestos Detected**
Wall Linings Internal	Flat AC Sheeting	3m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	8150/B00B/R1065/Wall Linings Internal/S6					**Chrysotile (white asbestos)**
B00B - R2061 - Lift						
No Asbestos						
B00B - R2062 - Stairs						
Ceiling Structures/Linings	Vermiculite	6m2	Throughout	Friable Asbestos (5)	Medium (2)	High Priority (6-8)
	8150/B00B/R2062/Ceiling Structures/Linings/S37					**Chrysotile (white asbestos)**
B00B - R2063 - Stairs						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R2063/Ceiling Structures/Linings/S38					**No Asbestos Detected**
B00B - R2064 - Stairs						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R2064/Ceiling Structures/Linings/S39					**No Asbestos Detected**
B00B - R2065 - Stairs						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R2065/Ceiling Structures/Linings/S40					**No Asbestos Detected**
B00B - R2066 - Stairs						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R2066/Ceiling Structures/Linings/S41					**No Asbestos Detected**
B00B - R2067 - Stairs						
Ceiling Structures/Linings	Vermiculite					
	8150/B00B/R2067/Ceiling Structures/Linings/S11					**No Asbestos Detected**
B00B - R2068 - Staff Study						
Recently Modified Space	Requires Inspection					
B00B - R2069 - General Learning Space						
Recently Modified Space	Requires Inspection					
B00B - R2070 - General Learning Space						
Recently Modified Space	Requires Inspection					
B00B - R2071 - General Learning Space						
Recently Modified Space	Requires Inspection					
B00B - R2072 - General Learning Space						
Recently Modified Space	Requires Inspection					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00C - Physical Education - 1962 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting 8150/B00C/Eaves Linings/S43					**No Asbestos Detected**
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Window putty	Mastic 8150/B00C/Window putty/S44	400m	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3) **Chrysotile (white asbestos)**

Interior

B00C - R0001 - Movement

No Asbestos

B00C - R0002 - Staff - Toilet

No Asbestos

B00C - R0003 - Sport Equipment Store

No Asbestos

B00C - R0004 - Gymnasium

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00D - Performing Arts - 1962 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00D - M0001 - Control Room

No Asbestos

B00D - M0002 - Chair Store

No Asbestos

B00D - R0001 - Cleaning Store - Distributed

No Asbestos

B00D - R0002 - Chair Store

No Asbestos

B00D - R0004 - Staff Kitchen

No Asbestos

B00D - R0005 - General Storeroom

No Asbestos

B00D - R0007 - Performing Arts Store

No Asbestos

B00D - R0011 - Stairs

No Asbestos

B00D - R0012 - Stairs

No Asbestos

B00D - R0013 - Stage

No Asbestos

B00D - R0014 - Multi-Purpose Space

No Asbestos

B00D - R0015 - Movement

No Asbestos

B00D - R0016 - Lift

No Asbestos

B00D - R9001 - General Storeroom

No Asbestos

B00D - R9002 - Shower/Change

No Asbestos

B00D - R9003 - Gymnasium

No Asbestos

B00D - R9004 - Shower/Change

No Asbestos

B00D - R9005 - General Storeroom

No Asbestos

B00D - R9006 - Stairs

No Asbestos

B00D - R9007 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00E - Building Services - 2001 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00E - R0001 - General Assistants

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00F - Building Services - 2001 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00F - R0001 - Cleaning Supplies Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00G - Pupil Facilities - 2003 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00G - R0001 - Covered Area

No Asbestos

B00G - R0002 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00H - Support Unit - 1962 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00H - R0001 - Practical Activity Area

No Asbestos

B00H - R0002 - General Learning Space - S/P

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0003 - Seminar - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0004 - Home Base Store - S

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0005 - Practical Activity Area

No Asbestos

B00H - R0006 - Practical Activity Area

No Asbestos

B00H - R0007 - General Learning Space - S/P

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0008 - Seminar - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0009 - Home Base Store - S

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0010 - Staff - Toilet

No Asbestos

B00H - R0011 - Wheelchair Store-Special Ed

No Asbestos

B00H - R0012 - Covered Vehicle Area/Porte Cochere

No Asbestos

B00H - R0013 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0014 - Commonroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0015 - Cleaning Store - Distributed

No Asbestos

B00H - R0016 - Practical Activity Area

No Asbestos

B00H - R0017 - General Learning Space - S/P

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0018 - Toilets-Disabled

No Asbestos

B00H - R0019 - Student Laundry - Type 3

No Asbestos

B00H - R0020 - Toilets-Disabled

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00H - R0021 - Practical Activity Area

No Asbestos

B00H - R0022 - General Learning Space - S/P

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00H - R0023 - Home Base Store - S

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00H - R0024 - Seminar - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00H - R0025 - Movement

No Asbestos

B00H - R0026 - Movement

No Asbestos

B00H - R0027 - Outdoor Learning Area

No Asbestos

B00H - R0028 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B00H - R0029 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

8150_ASB_100913_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017