Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Leumeah High School (8532)**
Region :	**South Western Sydney**
State Electorate :	**Macquarie Fields**
Local Government Area :	**Campbelltown**

Initial Survey :	**Noel Arnold & Associates : 19 - May - 2008**
Reviewed By :	**Greencap-NAA : 26 - Aug - 2014**

8532 - Leumeah High School
Site Plan (11631)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00A - Science/General Learning - 1976 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00A - R0001 - General Learning Space

No Asbestos

B00A - R0002 - General Learning Space

No Asbestos

B00A - R0003 - Chemical Store

Floor Coverings Res/Textile — Vinyl Tiles

8532/B00A/R0014/Floor Coverings Res/Textile/S3 — **No Asbestos Detected**

B00A - R0004 - Cleaning Store - Distributed

No Asbestos

B00A - R0005 - Laboratory L.S.

Floor Coverings Res/Textile — Vinyl Tiles

8532/B00A/R0014/Floor Coverings Res/Textile/S3 — **No Asbestos Detected**

B00A - R0006 - Preparation

Floor Coverings Res/Textile — Vinyl Tiles

8532/B00A/R0014/Floor Coverings Res/Textile/S3 — **No Asbestos Detected**

B00A - R0007 - Lift

Floor Coverings Res/Textile — Vinyl Tiles

8532/B00A/R0014/Floor Coverings Res/Textile/S3 — **No Asbestos Detected**

B00A - R0008 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board	2Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)

8532/B0B1/R0003/Electrical Mounting Board/S24 — **Chrysotile (white asbestos)**

B00A - R0009 - Laboratory L.S.

Floor Coverings Res/Textile — Vinyl Tiles

8532/B00A/R0014/Floor Coverings Res/Textile/S3 — **No Asbestos Detected**

B00A - R0010 - Secure Storeroom

Floor Coverings Res/Textile — Vinyl Tiles

8532/B00A/R0014/Floor Coverings Res/Textile/S3 — **No Asbestos Detected**

B00A - R0011 - General Learning Space

No Asbestos

B00A - R0012 - Cleaning Store - Distributed

No Asbestos

B00A - R0013 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Electrical Mounting Board — Resinous Board

8532/B0B1/R1009/Floor Coverings Res/Textile/S5 — **No Asbestos Detected**

B00A - R0014 - Secure Storeroom

Floor Coverings Res/Textile — Vinyl Tiles

8532/B00A/R0014/Floor Coverings Res/Textile/S3 — **No Asbestos Detected**

B00A - R0015 - Staff Study

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00A - R0016 - Computer Learning Space						
No Asbestos						
B00A - R0017 - Movement						
No Asbestos						
B00A - R0018 - Toilets-Boys						
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B00C/R0016/Partition Walls (Cubicles)/S2					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00A - R0019 - Cleaning Store - Distributed						
No Asbestos						
B00A - R0023 - Movement						
Recently Modified Space	Requires Inspection					
B00A - R0024 - Stairs						
Recently Modified Space	Requires Inspection					
B00A - R0025 - Movement						
Recently Modified Space	Requires Inspection					
B00A - R0026 - Stairs						
Recently Modified Space	Requires Inspection					
B00A - R1001 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00A - R1002 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00A - R1003 - Toilets-Girls						
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B00C/R0016/Partition Walls (Cubicles)/S2					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00A - R1004 - Laboratory L.S.						
Floor Coverings Res/Textile	Vinyl Tiles					
	8532/B00A/R0014/Floor Coverings Res/Textile/S3					**No Asbestos Detected**
B00A - R1005 - Cleaning Store - Distributed						
No Asbestos						
B00A - R1006 - Preparation						
Floor Coverings Res/Textile	Vinyl Tiles					
	8532/B00A/R0014/Floor Coverings Res/Textile/S3					**No Asbestos Detected**
B00A - R1007 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
Electrical Mounting Board	Resinous Board	2Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B0B1/R0003/Electrical Mounting Board/S24					**Chrysotile (white asbestos)**
B00A - R1008 - Laboratory L.S.						
Floor Coverings Res/Textile	Vinyl Tiles					
	8532/B00A/R0014/Floor Coverings Res/Textile/S3					**No Asbestos Detected**
B00A - R1009 - Computer Resource						
No Asbestos						
B00A - R1010 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00A - R1011 - Cleaning Store - Distributed						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00A - R1012 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
Electrical Mounting Board	Resinous Board	2Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B0B1/R0003/Electrical Mounting Board/S24					**Chrysotile (white asbestos)**
B00A - R1013 - Staff Study						
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00A - R1014 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00A - R1017 - Toilets-Girls						
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B00C/R0016/Partition Walls (Cubicles)/S2					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00A - R1019 - Stairs						
Recently Modified Space	Requires Inspection					
B00A - R1020 - Stairs						
Recently Modified Space	Requires Inspection					
B00A - R1021 - Stairs						
Recently Modified Space	Requires Inspection					
B00A - R1022 - Movement						
Recently Modified Space	Requires Inspection					
B00A - R1023 - Movement						
Recently Modified Space	Requires Inspection					
B00A - R2001 - Laboratory L.S.						
Floor Coverings Res/Textile	Vinyl Tiles					
	8532/B00A/R0014/Floor Coverings Res/Textile/S3					**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00A - R2002 - Cleaning Store - Distributed						
No Asbestos						
B00A - R2003 - Preparation						
Floor Coverings Res/Textile	Vinyl Tiles					
	8532/B00A/R0014/Floor Coverings Res/Textile/S3					**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00A - R2004 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
Electrical Mounting Board	Resinous Board	2Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B0B1/R0003/Electrical Mounting Board/S24					**Chrysotile (white asbestos)**
B00A - R2005 - Laboratory L.S.						
Floor Coverings Res/Textile	Vinyl Tiles					
	8532/B00A/R0014/Floor Coverings Res/Textile/S3					**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00A - R2006 - Dust Extraction Space						
No Asbestos						
B00A - R2007 - Growing/Breeding						
Floor Coverings Res/Textile	Vinyl Tiles					
	8532/B00A/R0014/Floor Coverings Res/Textile/S3					**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00A - R2008 - Staff - Toilet						
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00A - R2009 - Staff - Toilet						
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00A - R2010 - Movement						
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00A - R2011 - Stairs						
Recently Modified Space	Requires Inspection					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00C - Multi Purpose Facilities - 1976 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Telecommunication pit	Moulded fibre cement	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B00C/Telecommunication pit/S20					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

Interior

B00C - R0001 - Canteen

No Asbestos

B00C - R0002 - Staff Toilet

No Asbestos

B00C - R0003 - Office/Store

No Asbestos

B00C - R0004 - Chair Store

No Asbestos

B00C - R0005 - Main Switchroom

Electrical Mounting Board	Resinous Board	3Unit	South & East	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B00C/R0005/Electrical Mounting Board/S21					**Chrysotile (white asbestos)**
Sheet Lining	Compressed AC Sheet	2m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B00C/R0005/Sheet Lining/S22					**Chrysotile (white asbestos)**

B00C - R0006 - Garden Store Room

No Asbestos

B00C - R0007 - Multi-Purpose Space

Ceiling Structures/Linings	Vermiculite	
	8532/B00D/R1017/Ceiling Structures/Linings/S15	**No Asbestos Detected**

B00C - R0008 - Shower/Change

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B00C/R0016/Partition Walls (Cubicles)/S2					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00C - R0009 - General Storeroom

Flue	Moulded fibre cement	4m	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B00C/R0009/Flue/S23					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00C - R0010 - Staff Study

Floor Coverings Res/Textile	Vinyl Tiles	
	8532/B00D/R0004/Floor Coverings Res/Textile/S4	**No Asbestos Detected**

B00C - R0011 - Sport Equipment Store

No Asbestos

B00C - R0012 - Secure Storeroom

No Asbestos

B00C - R0013 - Staff Shower

No Asbestos

B00C - R0014 - Movement

No Asbestos

B00C - R0015 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
No Asbestos						
B00C - R0016 - Shower/Change						
Partition Walls (Cubicles)	Compressed AC Sheet	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B00C/R0016/Partition Walls (Cubicles)/S2					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00C - R0017 - Cleaning Distributed Store						
Flue	Moulded fibre cement	4m	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B00C/R0009/Flue/S23					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00C - R0018 - Movement						
No Asbestos						
B00C - R0019 - Movement						
No Asbestos						
B00C - R0020 - Movement						
No Asbestos						
B00C - R0021 - Movement						
No Asbestos						
B00C - R0022 - Movement						
No Asbestos						
B00C - R0023 - Movement						
No Asbestos						
B00C - R0024 - Movement						
No Asbestos						
B00C - R0025 - Covered Area						
No Asbestos						
B00C - R0026 - Movement						
No Asbestos						
B00C - R0027 - Movement						
No Asbestos						
B00C - R0028 - No Access						
No Asbestos						
B00C - R1001 - Toilets-Girls						
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B00C/R0016/Partition Walls (Cubicles)/S2					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B00C - R1002 - Cleaning Store - Distributed						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B00C - R1003 - Staff - Toilet						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B00C - R1004 - Staff Shower						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B00C - R1005 - Staff Shower						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B00C - R1006 - Cleaning Supplies Store						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Floor Coverings Res/Textile	Vinyl Tiles					
	8532/B00D/R0004/Floor Coverings Res/Textile/S4					**No Asbestos Detected**
B00C - R1007 - Staff Study						
Floor Coverings Res/Textile	Vinyl Tiles					
	8532/B00D/R0004/Floor Coverings Res/Textile/S4					**No Asbestos Detected**
B00C - R1008 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00D - Administration - 1986 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Underfloor Voids	Flat AC Sheeting	20m2	Southwest corner	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8532/B00D/Underfloor Voids/S18					**Chrysotile (white asbestos)**

Interior

B00D - R0001 - General Storeroom

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 8532/B00D/R0004/Floor Coverings Res/Textile/S4	**No Asbestos Detected**

B00D - R0002 - Cleaning Supplies Store

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 8532/B00D/R0004/Floor Coverings Res/Textile/S4	**No Asbestos Detected**

B00D - R0003 - General Assistants

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 8532/B00D/R0004/Floor Coverings Res/Textile/S4	**No Asbestos Detected**

B00D - R0004 - Movement

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 8532/B00D/R0004/Floor Coverings Res/Textile/S4	**No Asbestos Detected**

B00D - R0005 - Movement

No Asbestos

B00D - R1001 - General Storeroom

No Asbestos

B00D - R1002 - Principal Office

No Asbestos

B00D - R1003 - Deputy Principal Office

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15	**No Asbestos Detected**

B00D - R1004 - Leading Teacher

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15	**No Asbestos Detected**

B00D - R1005 - Staff - Toilet

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15	**No Asbestos Detected**

B00D - R1006 - Staff - Toilet

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15	**No Asbestos Detected**

B00D - R1007 - Cleaning Store - Distributed

No Asbestos

B00D - R1008 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Electrical Mounting Board	Resinous Board	2Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B00D/R1008/Electrical Mounting Board/S17					**Chrysotile (white asbestos)**
B00D - R1010 - Administration - Clerical						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B00D - R1011 - Duplicating Workroom						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B00D - R1012 - Ancillary Staff						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B00D - R1014 - Movement						
No Asbestos						
B00D - R1016 - Administration - Clerical						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8532/B00D/R1016/Floor Coverings Res/Textile/S16					**No Asbestos Detected**
Floor Coverings Res/Textile	Adhesive					
	8532/B00D/R1016/Floor Coverings Res/Textile/S19					**No Asbestos Detected**
B00D - R1018 - Stairs						
No Asbestos						
B00D - R1019 - Movement						
Recently Modified Space	Requires Inspection					
B00D - R1020 - Staff Study						
Recently Modified Space	Requires Inspection					
B00D - R2001 - Interview/Office - Type 1						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B00D - R2002 - Interview/Office - Type 1						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B00D - R2003 - Clinic-Toilets						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B00D - R2004 - Clinic - Girls						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B00D - R2005 - Clinic - Boys						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B00D - R2006 - Commonroom						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles					
	8532/B00D/R0004/Floor Coverings Res/Textile/S4					**No Asbestos Detected**
B00D - R2007 - Movement						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B00D - R2008 - Staff - Toilet						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B00D - R2009 - Staff - Toilet						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B00D - R2010 - Cleaning Store - Distributed						
No Asbestos						
B00D - R2011 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
Electrical Mounting Board	Resinous Board	2Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B00D/R1008/Electrical Mounting Board/S17					**Chrysotile (white asbestos)**
B00D - R2012 - Movement						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles					
	8532/B00D/R0004/Floor Coverings Res/Textile/S4					**No Asbestos Detected**
B00D - R2013 - Movement						
No Asbestos						
B00D - R2014 - Movement						
No Asbestos						
B00D - R2015 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00E - Library - 1976 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible	
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible	

Interior

B00E - M0002 - Stairs

Ceiling Structures/Linings	Vermiculite	
	8532/B00E/R0015/Ceiling Structures/Linings/S29	**No Asbestos Detected**

B00E - M0003 - Stairs

Ceiling Structures/Linings	Vermiculite	
	8532/B00E/R0015/Ceiling Structures/Linings/S29	**No Asbestos Detected**

B00E - M0004 - Computer Room

Ceiling Structures/Linings	Vermiculite	
	8532/B00E/R0015/Ceiling Structures/Linings/S29	**No Asbestos Detected**

B00E - M0005 - Study Space

Ceiling Structures/Linings	Vermiculite	
	8532/B00E/R0015/Ceiling Structures/Linings/S29	**No Asbestos Detected**

B00E - M0006 - Study Space

Ceiling Structures/Linings	Vermiculite	
	8532/B00E/R0015/Ceiling Structures/Linings/S29	**No Asbestos Detected**

B00E - R0001 - Computer Resource

Ceiling Structures/Linings	Vermiculite	
	8532/B00E/R0015/Ceiling Structures/Linings/S29	**No Asbestos Detected**

B00E - R0002 - Audio Visual Workroom

Ceiling Structures/Linings	Vermiculite	
	8532/B00E/R0015/Ceiling Structures/Linings/S29	**No Asbestos Detected**

B00E - R0003 - Seminar

Ceiling Structures/Linings	Vermiculite	
	8532/B00E/R0015/Ceiling Structures/Linings/S29	**No Asbestos Detected**

B00E - R0004 - Seminar

Ceiling Structures/Linings	Vermiculite	
	8532/B00E/R0015/Ceiling Structures/Linings/S29	**No Asbestos Detected**

B00E - R0005 - Main Area

Ceiling Structures/Linings	Vermiculite	
	8532/B00E/R0015/Ceiling Structures/Linings/S29	**No Asbestos Detected**

B00E - R0006 - General Storeroom

No Asbestos

B00E - R0007 - Workroom

Ceiling Structures/Linings	Vermiculite	
	8532/B00E/R0015/Ceiling Structures/Linings/S29	**No Asbestos Detected**

B00E - R0008 - Librarian

Ceiling Structures/Linings	Vermiculite	
	8532/B00E/R0015/Ceiling Structures/Linings/S29	**No Asbestos Detected**

B00E - R0009 - Workroom

Ceiling Structures/Linings	Vermiculite	
	8532/B00E/R0015/Ceiling Structures/Linings/S29	**No Asbestos Detected**

B00E - R0010 - Staff - Toilet

No Asbestos

B00E - R0011 - Main Area

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00E - R0012 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
Electrical Mounting Board	Resinous Board	2Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B0B1/R0003/Electrical Mounting Board/S24					**Chrysotile (white asbestos)**
B00E - R0013 - Staff - Toilet						
No Asbestos						
B00E - R0014 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
Electrical Mounting Board	Resinous Board	21Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B0B1/R0003/Electrical Mounting Board/S24					**Chrysotile (white asbestos)**
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B0B1/R0003/Ceiling Structures/Linings/S25					**Chrysotile (white asbestos)**
B00E - R0015 - Movement						
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00E - R0017 - Movement						
No Asbestos						
B00E - R0018 - Movement						
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00E - R0019 - Stairs						
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00E - R0020 - Stairs						
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00E - R1002 - Staff Study						
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00E - R1003 - General Storeroom						
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00E - R1004 - Staff Study						
Ceiling Structures/Linings	Vermiculite					
	8532/B00E/R0015/Ceiling Structures/Linings/S29					**No Asbestos Detected**
B00E - R1005 - Toilets-Boys						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B00C/R0016/Partition Walls (Cubicles)/S2					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R1007 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00F - General Learning - 1977 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00F - R0001 - General Learning Space

Ceiling Structures/Linings — Vermiculite
8532/B00F/R0020/Ceiling Structures/Linings/S28 — **No Asbestos Detected**

B00F - R0002 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0003 - General Learning Space

Ceiling Structures/Linings — Vermiculite
8532/B00F/R0020/Ceiling Structures/Linings/S28 — **No Asbestos Detected**

B00F - R0004 - Staff Study

Ceiling Structures/Linings — Vermiculite
8532/B00F/R0020/Ceiling Structures/Linings/S28 — **No Asbestos Detected**

B00F - R0005 - General Learning Space

Ceiling Structures/Linings — Vermiculite
8532/B00F/R0020/Ceiling Structures/Linings/S28 — **No Asbestos Detected**

B00F - R0006 - General Learning Space

Ceiling Structures/Linings — Vermiculite
8532/B00F/R0020/Ceiling Structures/Linings/S28 — **No Asbestos Detected**

B00F - R0007 - General Learning Space

Ceiling Structures/Linings — Vermiculite
8532/B00F/R0020/Ceiling Structures/Linings/S28 — **No Asbestos Detected**

B00F - R0008 - General Storeroom

Ceiling Structures/Linings — Vermiculite
8532/B00F/R0020/Ceiling Structures/Linings/S28 — **No Asbestos Detected**

B00F - R0009 - General Storeroom

No Asbestos

B00F - R0010 - Toilets-Boys

No Asbestos

B00F - R0011 - Cleaning Store - Distributed

No Asbestos

B00F - R0012 - Staff - Toilet

No Asbestos

B00F - R0013 - General Storeroom

No Asbestos

B00F - R0014 - Careers Advisers Office

Ceiling Structures/Linings — Vermiculite
8532/B00F/R0020/Ceiling Structures/Linings/S28 — **No Asbestos Detected**

B00F - R0015 - General Storeroom

No Asbestos

B00F - R0016 - General Learning Space

Ceiling Structures/Linings — Vermiculite
8532/B00F/R0020/Ceiling Structures/Linings/S28 — **No Asbestos Detected**

B00F - R0017 - General Learning Space

Ceiling Structures/Linings — Vermiculite
8532/B00F/R0020/Ceiling Structures/Linings/S28 — **No Asbestos Detected**

B00F - R0018 - General Learning Space

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R0019 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R0020 - Movement						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R0021 - Movement						
No Asbestos						
B00F - R0022 - No Access						
No Asbestos						
B00F - R0023 - Stairs						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R0024 - Stairs						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R1001 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R1002 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R1003 - Staff Study						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R1004 - Computer Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R1005 - Computer Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R1006 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R1007 - Interview/Office - Type 1						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R1008 - Toilets-Girls						
No Asbestos						
B00F - R1009 - Cleaning Store - Distributed						
No Asbestos						
B00F - R1010 - Staff - Toilet						
No Asbestos						
B00F - R1011 - General Storeroom						
No Asbestos						
B00F - R1012 - General Storeroom						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R1013 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00F - R1014 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R1015 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R1016 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R1017 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
No Asbestos						
B00F - R1018 - Movement						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R1019 - Movement						
No Asbestos						
B00F - R1020 - Stairs						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R1021 - Stairs						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R2001 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R2002 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
No Asbestos						
B00F - R2003 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R2004 - Staff Study						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R2005 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R2006 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R2007 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R2008 - Toilets-Boys						
No Asbestos						
B00F - R2009 - Cleaning Store - Distributed						
No Asbestos						
B00F - R2010 - Staff - Toilet						
No Asbestos						
B00F - R2011 - General Storeroom						
No Asbestos						
B00F - R2012 - General Storeroom						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00F - R2013 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R2014 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R2016 - Movement						
No Asbestos						
B00F - R2017 - Stairs						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R2018 - Staff Study						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R2019 - Stairs						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**
B00F - R2020 - Movement						
Ceiling Structures/Linings	Vermiculite					
	8532/B00F/R0020/Ceiling Structures/Linings/S28					**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00G - Agricultural Science - 1986 - Timber (Timber)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00G - R0001 - Plant Space

No Asbestos

B00G - R0006 - Machine Storage

No Asbestos

B00G - R0007 - Movement

No Asbestos

B00G - R0008 - Staff - Toilet

No Asbestos

B00G - R0009 - Staff Study

No Asbestos

B00G - R0010 - General Learning Space

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B0B1 - Technological & Applied Studies - 1976 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Underfloor Voids	Non Accessible Area - Non accessible					

Interior

B0B1 - R0001 - Wood Technology L.S.

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B0B1 - R0002 - Resource/Project Store

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B0B1 - R0003 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board 8532/B0B1/R0003/Electrical Mounting Board/S24	2Unit	North & West	Good Condition (1)	Low (1)	Low Priority (2-3) **Chrysotile (white asbestos)**
Ceiling Structures/Linings	Flat AC Sheeting 8532/B0B1/R0003/Ceiling Structures/Linings/S25	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) **Chrysotile (white asbestos)**

B0B1 - R0004 - Movement

No Asbestos

B0B1 - R0005 - Cleaning Supplies Store

No Asbestos

B0B1 - R0006 - Cleaning Store - Distributed

No Asbestos

B0B1 - R0007 - Movement

No Asbestos

B0B1 - R0008 - Stairs

No Asbestos

B0B1 - R0009 - Stairs

No Asbestos

B0B1 - R1001 - Music Learning Space

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B0B1 - R1003 - Cleaning Store - Distributed

No Asbestos

B0B1 - R1004 - Music Learning Space

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B0B1 - R1005 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board 8532/B0B1/R0003/Electrical Mounting Board/S24	2Unit	North & West	Good Condition (1)	Low (1)	Low Priority (2-3) **Chrysotile (white asbestos)**
Ceiling Structures/Linings	Flat AC Sheeting 8532/B0B1/R0003/Ceiling Structures/Linings/S25	2m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5) **Chrysotile (white asbestos)**
Debris	Flat AC Sheeting 8532/B0B1/R0003/Ceiling Structures/Linings/S25	2m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5) **Chrysotile (white asbestos)**

B0B1 - R1006 - Staff Study

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B0B1 - R1007 - General Storeroom

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles					
	8532/B0B1/R1009/Floor Coverings Res/Textile/S5					**No Asbestos Detected**
B0B1 - R1008 - Movement						
No Asbestos						
B0B1 - R1009 - Movement						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles					
	8532/B0B1/R1009/Floor Coverings Res/Textile/S5					**No Asbestos Detected**
B0B1 - R1010 - Movement						
No Asbestos						
B0B1 - R1011 - Music Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B0B1 - R1012 - Music Store						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B0B1 - R1013 - Stairs						
No Asbestos						
B0B1 - R1014 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B0B2 - Technological & Applied Studies - 1976 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

Interior

B0B2 - R0001 - Metal Technology L.S.

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B0B2 - R0002 - Welding Area

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B0B2 - R0003 - Resource/Project Store

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B0B2 - R0004 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board 8532/B0B1/R0003/Electrical Mounting Board/S24	1Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) **Chrysotile (white asbestos)**
Ceiling Structures/Linings	Flat AC Sheeting 8532/B0B1/R0003/Ceiling Structures/Linings/S25	2m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5) **Chrysotile (white asbestos)**

B0B2 - R0005 - Staff Study

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B0B2 - R0006 - Materials Store

No Asbestos

B0B2 - R0007 - Movement

No Asbestos

B0B2 - R1001 - Food Technology L.S.

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 8532/B0B2/R1002/Floor Coverings Res/Textile/S26					**No Asbestos Detected**

B0B2 - R1002 - Laundry

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 8532/B0B2/R1002/Floor Coverings Res/Textile/S26					**No Asbestos Detected**

B0B2 - R1003 - Food/Research Space

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B0B2 - R1004 - Seminar/Technology Space

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B0B2 - R1005 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board 8532/B0B1/R0003/Electrical Mounting Board/S24	1Unit	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5) **Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Flat AC Sheeting	.64m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
	8532/B0B1/R0003/Ceiling Structures/Linings/S25					**Chrysotile (white asbestos)**
Debris	Flat AC Sheeting	2m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
	8532/B0B1/R0003/Ceiling Structures/Linings/S25					**Chrysotile (white asbestos)**
B0B2 - R1006 - Food Technology L.S.						
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles					
	8532/B0B2/R1002/Floor Coverings Res/Textile/S26					**No Asbestos Detected**
B0B2 - R1007 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B0B3 - Technological & Applied Studies - 1976 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

Interior

B0B3 - R0001 - Design L.S.

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B0B3 - R0002 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board 8532/B0B1/R0003/Electrical Mounting Board/S24	2Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) **Chrysotile (white asbestos)**
Ceiling Structures/Linings	Flat AC Sheeting 8532/B0B1/R0003/Ceiling Structures/Linings/S25	2m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5) **Chrysotile (white asbestos)**

B0B3 - R0003 - Study Space

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B0B3 - R0004 - General Storeroom

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 8532/B00D/R0004/Floor Coverings Res/Textile/S4					**No Asbestos Detected**

B0B3 - R0005 - Design L.S.

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B0B3 - R0006 - Movement

No Asbestos

B0B3 - R0007 - Storage Room

Wall Lining - Exterior	Moulded fibre cement 8532/B0B3/R0007/Wall Lining - Exterior/S27					**No Asbestos Detected**
Wall Linings Internal	Profiled fibre cement 8532/B0B3/R0007/Wall Lining - Exterior/S27					**No Asbestos Detected**

B0B3 - R1001 - Textiles Technology L.S.

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B0B3 - R1002 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board 8532/B0B1/R0003/Electrical Mounting Board/S24	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3) **Chrysotile (white asbestos)**

B0B3 - R1003 - Cleaning Store - Distributed

Ceiling Structures/Linings	Flat AC Sheeting 8532/B0B1/R0003/Ceiling Structures/Linings/S25	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) **Chrysotile (white asbestos)**

B0B3 - R1004 - General Storeroom

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B0B3 - R1005 - Laundry

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B0B3 - R1006 - Textiles Technology L.S.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B0B3 - R1007 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B0B4 - Art - 1976 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible	

Interior

B0B4 - R0001 - Art Learning Space

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 8532/B00D/R0004/Floor Coverings Res/Textile/S4	**No Asbestos Detected**

B0B4 - R0004 - Art Learning Space

Floor Coverings Res/Textile	Vinyl Tiles 8532/B00D/R0004/Floor Coverings Res/Textile/S4	**No Asbestos Detected**
Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15	**No Asbestos Detected**

B0B4 - R0005 - Resources Store

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15	**No Asbestos Detected**

B0B4 - R0006 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B0B1/R0003/Electrical Mounting Board/S24					**Chrysotile (white asbestos)**
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8532/B0B1/R0003/Ceiling Structures/Linings/S25					**Chrysotile (white asbestos)**

B0B4 - R0007 - Art Learning Space

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15	**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles 8532/B00D/R0004/Floor Coverings Res/Textile/S4	**No Asbestos Detected**

B0B4 - R0008 - Cleaning Store - Distributed

No Asbestos

B0B4 - R0009 - Movement

No Asbestos

B0B4 - R0010 - Stairs

No Asbestos

B0B4 - R0011 - Dark Room

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15	**No Asbestos Detected**

B0B4 - R0012 - Darkroom Space

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15	**No Asbestos Detected**

B0B4 - R0013 - Darkroom Space

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15	**No Asbestos Detected**

B0B4 - R0014 - Darkroom Space

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15	**No Asbestos Detected**

B0B4 - R0015 - Darkroom Space

Ceiling Structures/Linings	Vermiculite 8532/B00D/R1017/Ceiling Structures/Linings/S15	**No Asbestos Detected**

B0B4 - R0016 - Darkroom Space

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Vermiculite					
	8532/B00D/R1017/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B0B4 - R0017 - External Movement						
Recently Modified Space	Requires Inspection					
B0B4 - R0018 - External Movement						
Recently Modified Space	Requires Inspection					
B0B4 - R1001 - Movement						
No Asbestos						
B0B4 - R1002 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 971 - D80038 - Shed - Container (Garden/Sports/Bulk) : Placement Date - 30/06/1995

Exterior

No Asbestos Found.

Interior

R1 - Garden Store

No Asbestos Found.

OS 971 - D80039 - Shed - Container (Garden/Sports/Bulk) : Placement Date - 30/06/1995

Exterior

No Asbestos Found.

Interior

R1 - Garden Store

No Asbestos Found.

OS 971 - D80040 - Shed - Container (Garden/Sports/Bulk) : Placement Date - 30/06/1995

Exterior

No Asbestos Found.

Interior

R1 - Garden Store

No Asbestos Found.

OS 971 - D80041 - Shed - Container (Garden/Sports/Bulk) : Placement Date - 30/06/1995

Exterior

No Asbestos Found.

Interior

R1 - Garden Store

No Asbestos Found.

OS 971 - D80042 - Shed - Container (Garden/Sports/Bulk) : Placement Date - 30/06/1995

Exterior

No Asbestos Found.

Interior

R1 - Garden Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017