Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Mount Terry Public School (4610)**
Region :	**Illawarra and South East**
State Electorate :	**Kiama**
Local Government Area :	**Shellharbour**

Initial Survey :	**Noel Arnold & Associates : 30 - Mar - 2008**
Register Issue Date :	**23 - Mar - 2017**



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00A - Administration/Staff Facilities - 1993 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00A - R0001 - Movement

No Asbestos

B00A - R0002 - Garden Store

No Asbestos

B00A - R0003 - Cleaning Supplies

No Asbestos

B00A - R0004 - Cleaning Supplies

No Asbestos

B00A - R0005 - Sports Store

No Asbestos

B00A - R0007 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0009 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0010 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0011 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0012 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0013 - Sick Bay - Shower/Toilet

No Asbestos

B00A - R0014 - Sick Bay

No Asbestos

B00A - R0015 - Clerical Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0016 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0017 - Duplicating Workroom

No Asbestos

B00A - R0018 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0019 - Security Store

No Asbestos

B00A - R0020 - Staff Toilet

No Asbestos

B00A - R0021 - Staff Toilet

No Asbestos

B00A - R0022 - Staff Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00A - R0023 - Cleaning Distributed Store						
No Asbestos						
B00A - R0024 - Main Switch Board						
No Asbestos						
B00A - R0025 - Interview						
No Asbestos						
B00A - R0026 - Interview						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0027 - Staff Room						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0028 - Staff Kitchen						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00B - General Learning/Pupil Facilities - 1993 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00B - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00B - R0003 - Practical Activities - 1hb

No Asbestos

B00B - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00B - R0005 - Movement

No Asbestos

B00B - R0006 - Practical Activities - 1hb

No Asbestos

B00B - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00B - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00B - R0009 - Withdrawal Space - 1hb

No Asbestos

B00B - R0010 - Practical Activities - 1hb

No Asbestos

B00B - R0011 - Home Base Store

No Asbestos

B00B - R0012 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00B - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00B - R0014 - Practical Activities - 1hb

No Asbestos

B00B - R0015 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00B - R0016 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00B - R0017 - Home Base Store

No Asbestos

B00B - R0018 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0019 - Toilets - Girls

No Asbestos

B00B - R0020 - Kiln Room

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

No Asbestos

B00B - R0021 - Toilets - Boys

No Asbestos

B00B - R0022 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00C - General Learning/Pupil Facilities - 1993 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0002 - Home Base Store

No Asbestos

B00C - R0003 - Practical Activities - 1hb

No Asbestos

B00C - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0005 - Movement

No Asbestos

B00C - R0006 - Practical Activities - 1hb

No Asbestos

B00C - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0008 - Home Base Store

No Asbestos

B00C - R0009 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0010 - Practical Activities - 1hb

No Asbestos

B00C - R0011 - Home Base Store

No Asbestos

B00C - R0012 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0014 - Practical Activities - 1hb

No Asbestos

B00C - R0015 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0016 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0017 - Home Base Store

No Asbestos

B00C - R0018 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0019 - Toilets - Girls

No Asbestos

B00C - R0020 - Disabled Shower/Toilet

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00C - R0021 - Toilets - Boys						
No Asbestos						
B00C - R0022 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00D - Library/General Learning - 1993 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - External Movement

No Asbestos

B00D - R0002 - Practical Activities - 1hb

No Asbestos

B00D - R0003 - Home Base Store

No Asbestos

B00D - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00D - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00D - R0006 - Home Base Store

No Asbestos

B00D - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00D - R0008 - Withdrawal Space - 1hb

No Asbestos

B00D - R0009 - Practical Activities - 1hb

No Asbestos

B00D - R0010 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00D - R0011 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00D - R0012 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00D - R0013 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0014 - External Movement

No Asbestos

B00D - R0015 - Special Programs Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00E - Tiered Learning - 1993 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00E - R0002 - Plant

No Asbestos

B00E - R0003 - Cleaning Distributed Store

No Asbestos

B00E - R0004 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00E - R0005 - Movement

No Asbestos

B00E - R0006 - Movement

No Asbestos

B00E - R0007 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00F - General Learning/Pupil Facilities - 1993 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0002 - Practical Activities - 1hb

No Asbestos

B00F - R0003 - Home Base Store

No Asbestos

B00F - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0006 - Practical Activities - 1hb

No Asbestos

B00F - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0008 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0009 - Home Base Store

No Asbestos

B00F - R0010 - Practical Activities - 1hb

No Asbestos

B00F - R0011 - Home Base Store

No Asbestos

B00F - R0012 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0014 - Practical Activities - 1hb

No Asbestos

B00F - R0015 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0016 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0017 - Home Base Store

No Asbestos

B00F - R0018 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0019 - Canteen

No Asbestos

B00F - R0020 - Canteen Office/Store

No Asbestos

B00F - R0021 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00G - Communal Facilities - 1993 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Movement

No Asbestos

B00G - R0002 - Disabled Toilet

No Asbestos

B00G - R0003 - Cleaning Supplies

No Asbestos

B00G - R0004 - Plant

No Asbestos

B00G - R0005 - P.E. Store

No Asbestos

B00G - R0006 - Hall Chair Store

No Asbestos

B00G - R0007 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0008 - Toilets - Boys

No Asbestos

B00G - R0009 - Communal Space

No Asbestos

B00G - R0010 - Toilets - Girls

No Asbestos

B00G - R0011 - Plant

No Asbestos

B00G - R0012 - Communal Space

No Asbestos

B00G - R0013 - Other

No Asbestos

B00G - R0014 - Other

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0015 - Disabled Toilet

No Asbestos

B00G - R0016 - Disabled Toilet

No Asbestos

B00G - R0017 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0018 - Other

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0019 - Other

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0020 - General Storeroom

No Asbestos

B00G - R0021 - General Storeroom

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00G - R0022 - General Storeroom						
No Asbestos						
B00G - R0023 - Covered Outdoor Learning Area						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00H - General Learning - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - R0001 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0003 - Practical Activities - 1hb

No Asbestos

B00H - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0006 - Practical Activities - 1hb

No Asbestos

B00H - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0010 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0011 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0012 - Practical Activities - 1hb

No Asbestos

B00H - R0013 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0014 - Practical Activities - 1hb

No Asbestos

B00H - R0015 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0017 - Home Base

No Asbestos

B00H - R0018 - Home Base Store

No Asbestos

B00H - R0019 - Practical Activities - 1hb

No Asbestos

B00H - R0020 - Withdrawal Space - 2hb

No Asbestos

B00H - R0021 - Home Base

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

No Asbestos

B00H - R0022 - Home Base Store

No Asbestos

B00H - R0023 - Practical Activities - 1hb

No Asbestos

B00H - R0024 - Movement

No Asbestos

B00H - R0025 - Special Programs Room

No Asbestos

B00H - R0026 - Special Programs Store

No Asbestos

B00H - R0027 - Special Programs Store

No Asbestos

B00H - R0028 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00I - General Learning/Building Services - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00I - R0001 - Home Base

No Asbestos

B00I - R0002 - Home Base Store

No Asbestos

B00I - R0003 - Practical Activities - 1hb

No Asbestos

B00I - R0004 - Withdrawal Space - 2hb

No Asbestos

B00I - R0005 - Home Base

No Asbestos

B00I - R0006 - Home Base Store

No Asbestos

B00I - R0007 - Practical Activities - 1hb

No Asbestos

B00I - R0008 - External Movement

No Asbestos

B00I - R0009 - Sports Store

No Asbestos

B00I - R0010 - General Assistant/Bulk Store

No Asbestos

B00I - R0011 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 520 - D11519 - Staff Study : Placement Date - 30/06/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Staff Room

No Asbestos Found.

OS 602 - D11846 - Learning Unit - Standard With P.A.A. : Placement Date - 5/02/1997

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 602 - D11990 - Learning Unit - Standard With P.A.A. : Placement Date - 26/07/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 841 - D12399 - Boys Toilet : Placement Date - 29/07/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Toilets-Boys

No Asbestos Found.

OS 603 - D12964 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 6/01/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

OS 601 - D13107 - Learning Unit - Standard/Withdrawal : Placement Date - 5/02/1997

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

OS 840 - D14447 - Girls Toilet : Placement Date - 29/07/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Toilets-Girls

No Asbestos Found.

OS 603 - D15509 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 24/10/2005

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D15731 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 6/12/2012

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D15751 - Learning Unit - Standard With P.A.A. : Placement Date - 3/11/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D15985 - Learning Unit - Standard With P.A.A. : Placement Date - 19/01/2017

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017