Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Mount Annan High School (8286)**
Region :	**South Western Sydney**
State Electorate :	**Camden**
Local Government Area :	**Camden**

Initial Survey :	**Noel Arnold & Associates : 21 - May - 2008**
Register Issue Date :	**24 - Mar - 2017**

8286 - Mount Annan High School
Site Plan (13451)

1:1,454

Printed: 05-Feb-2017

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00A - General Learning - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00A - R0001 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0002 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0003 - Movement

No Asbestos

B00A - R0004 - Stairs

No Asbestos

B00A - R0005 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0006 - Shared Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0007 - General Learning Space - Type 2

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0008 - Stairs

No Asbestos

B00A - R0009 - Movement

No Asbestos

B00A - R0010 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0011 - Cleaning Store - Distributed

No Asbestos

B00A - R0012 - G.L.S. Store

No Asbestos

B00A - R0013 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0014 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0015 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0016 - Seminar - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0017 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R1001 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R1002 - Movement

No Asbestos

B00A - R1003 - Stairs

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result
No Asbestos		
B00A - R1004 - General Learning Space - Type 1		
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	
B00A - R1005 - Shared Learning Space		
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	
B00A - R1006 - Communications Cupboard		
No Asbestos		
B00A - R1007 - General Learning Space - Type 2		
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	
B00A - R1008 - Stairs		
No Asbestos		
B00A - R1009 - Movement		
No Asbestos		
B00A - R1010 - Cleaning Store - Distributed		
No Asbestos		
B00A - R1011 - G.L.S. Store		
No Asbestos		
B00A - R1012 - General Learning Space - Type 1		
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	
B00A - R1013 - General Learning Space - Type 1		
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	
B00A - R1014 - Distribution Board Cupboard		Note: No inspection of live electrical installation.
No Asbestos		
B00A - R1015 - Seminar - Type 1		
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	
B00A - R1016 - General Learning Space - Type 1		
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00B - Technological & Applied Studies/Art - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Movement

No Asbestos

B00B - R0002 - Cleaning Supplies Store

No Asbestos

B00B - R0003 - Wood Technology Bay

No Asbestos

B00B - R0004 - Dust Extraction Space

No Asbestos

B00B - R0005 - General Learning Space - Type 9

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00B - R0006 - General Learning Space - Type 8

No Asbestos

B00B - R0007 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0008 - Project Store - Type 1

No Asbestos

B00B - R0009 - General Learning Space - Type 5

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00B - R0010 - General Learning Space - Type 4

No Asbestos

B00B - R0011 - Movement

No Asbestos

B00B - R0012 - Movement

No Asbestos

B00B - R0013 - Dark Room

No Asbestos

B00B - R0014 - Visual Arts Store

No Asbestos

B00B - R0015 - Visual Arts Workshop

No Asbestos

B00B - R0016 - Movement

No Asbestos

B00B - R0017 - Outdoor Workshop

No Asbestos

B00B - R0018 - Kiln Space

No Asbestos

B00B - R0019 - Pottery Store

No Asbestos

B00B - R0020 - Welding/Hot Metals Area

No Asbestos

B00B - R0021 - L.P.G. Store

No Asbestos

B00B - R0022 - Materials Store - Type 2

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00B - R0023 - Materials Workshop - Type 2

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

B00C - General Learning - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Stairs

No Asbestos

B00C - R0002 - Movement

No Asbestos

B00C - R0003 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0004 - Shared Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0005 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0006 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0007 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0008 - Seminar - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0009 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0010 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0011 - G.L.S. Store

No Asbestos

B00C - R0012 - Cleaning Store - Distributed

No Asbestos

B00C - R0013 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0014 - Movement

No Asbestos

B00C - R0015 - Stairs

No Asbestos

B00C - R0016 - General Learning Space - Type 2

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0017 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0018 - Movement

No Asbestos

B00C - R1001 - Stairs

No Asbestos

B00C - R1002 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00C - R1003 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00C - R1004 - Communications Cupboard

No Asbestos

B00C - R1005 - Shared Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00C - R1006 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00C - R1007 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00C - R1008 - Seminar - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00C - R1009 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B00C - R1010 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00C - R1011 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00C - R1012 - G.L.S. Store

No Asbestos

B00C - R1013 - Cleaning Store - Distributed

No Asbestos

B00C - R1014 - Movement

No Asbestos

B00C - R1015 - Stairs

No Asbestos

B00C - R1016 - General Learning Space - Type 2

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00D - Technological & Applied Studies - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Movement

No Asbestos

B00D - R0002 - General Learning Space - Type 7

No Asbestos

B00D - R0003 - Materials Store - Type 1

No Asbestos

B00D - R0004 - Kitchen - Type 1

No Asbestos

B00D - R0005 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0006 - Preparation - Materials

No Asbestos

B00D - R0007 - Laundry

No Asbestos

B00D - R0008 - Pantry

No Asbestos

B00D - R0009 - Cleaning Store - Distributed

No Asbestos

B00D - R0010 - Kitchen - Type 1

No Asbestos

B00D - R0011 - Materials Store - Type 1

No Asbestos

B00D - R0012 - General Learning Space - Type 6

No Asbestos

B00D - R0013 - General Learning Space - Type 7

No Asbestos

B00D - R0014 - Seminar - Type 2

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00D - R0015 - Seminar - Type 2

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00D - R0016 - General Learning Space - Type 6

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00E - Science/Staff Facilities - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Science Laboratory

No Asbestos

B00E - R0002 - General Learning Space - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00E - R0003 - Movement

No Asbestos

B00E - R0004 - Seminar - Type 2

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00E - R0005 - Botany/Zoology

No Asbestos

B00E - R0006 - General Learning Space - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00E - R0007 - Chemical Store

No Asbestos

B00E - R0008 - Cleaning Store - Distributed

No Asbestos

B00E - R0009 - Apparatus Store

No Asbestos

B00E - R0010 - Apparatus Storage

No Asbestos

B00E - R0011 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0012 - General Learning Space - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00E - R0013 - General Learning Space - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00E - R0014 - General Learning Space - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00E - R0015 - General Learning Space - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00E - R0016 - Movement

No Asbestos

B00E - R0017 - Stairs

No Asbestos

B00E - R0018 - Science Laboratory

No Asbestos

B00E - R0019 - Science Laboratory

No Asbestos

B00E - R0020 - Preparation - Science

No Asbestos

B00E - R1001 - Staff Study

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00E - R1002 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00E - R1003 - Communications Cupboard

No Asbestos

B00E - R1004 - Staff - Toilet

No Asbestos

B00E - R1005 - Staff - Toilet

No Asbestos

B00E - R1006 - Staff - Toilet

No Asbestos

B00E - R1007 - Staff - Toilet

No Asbestos

B00E - R1008 - Staff - Toilet

No Asbestos

B00E - R1009 - Cleaning Store - Distributed

No Asbestos

B00E - R1010 - Interview/Meeting

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00E - R1011 - Interview/Meeting

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00E - R1012 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B00E - R1013 - Preparation/Printing

No Asbestos

B00E - R1014 - Interview/Meeting

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00E - R1015 - Interview/Meeting

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00E - R1016 - Archive Store

No Asbestos

B00E - R1017 - Movement

No Asbestos

B00E - R1018 - Stairs

No Asbestos

B00E - R1019 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00E - R1020 - Movement

No Asbestos

B00E - R1021 - Staff Lounge

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00E - R1022 - Staff Kitchen

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00F - Performing Arts/Pupil Facilities - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - Practice/Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0002 - Performance Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0003 - Main Switchroom

No Asbestos

B00F - R0004 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0005 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0006 - Toilets-Girls

No Asbestos

B00F - R0007 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0008 - Movement

No Asbestos

B00F - R0009 - Stairs

No Asbestos

B00F - R0010 - Cleaning Store - Distributed

No Asbestos

B00F - R0011 - Toilets-Boys

No Asbestos

B00F - R0012 - Performance Workshop

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R9001 - Toilets-Girls

No Asbestos

B00F - R9002 - Toilets-Boys

No Asbestos

B00F - R9003 - Movement

No Asbestos

B00F - R9004 - Cleaning Store - Distributed

No Asbestos

B00F - R9005 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00F - R9006 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00G - General Learning/Pupil Facilities - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0002 - Plant

No Asbestos

B00G - R0003 - Movement

No Asbestos

B00G - R0004 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0005 - Toilets-Disabled

No Asbestos

B00G - R0006 - Student Laundry - Type 2

No Asbestos

B00G - R0007 - Access Shower/Toilet - Type 2

No Asbestos

B00G - R0008 - Cleaning Store - Distributed

No Asbestos

B00G - R0009 - G.L.S. Store

No Asbestos

B00G - R0010 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0011 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0012 - Toilets-Girls

No Asbestos

B00G - R0013 - Toilets-Boys

No Asbestos

B00G - R0014 - Movement

No Asbestos

B00G - R0015 - Stairs

No Asbestos

B00G - R0016 - Movement

No Asbestos

B00G - R0017 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0018 - Change

No Asbestos

B00G - R0019 - Change

No Asbestos

B00G - R0020 - Fitness Store

No Asbestos

B00G - R0021 - Practice/Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00G - R0022 - Fitness Laboratory

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00G - R0023 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B00G - R0024 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00G - R1001 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00G - R1002 - Movement

No Asbestos

B00G - R1003 - General Learning Space - Type 2

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00G - R1004 - Shared Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00G - R1005 - Movement

No Asbestos

B00G - R1006 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00G - R1007 - G.L.S. Store

No Asbestos

B00G - R1008 - Cleaning Store - Distributed

No Asbestos

B00G - R1009 - Stairs

No Asbestos

B00G - R1010 - Movement

No Asbestos

B00G - R1011 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00G - R1012 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00G - R1013 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00G - R1014 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B00G - R1015 - Seminar - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00G - R1016 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00H - Library - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - R0001 - Library Administration

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0002 - Senior Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0003 - Main Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0004 - Computer Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0005 - Computer Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0006 - Staff - Toilet

No Asbestos

B00H - R0007 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0008 - Toilets-Disabled

No Asbestos

B00H - R0009 - Movement

No Asbestos

B00H - R0010 - Main Entry

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0011 - Communication Space

No Asbestos

B00H - R0012 - System Administrators Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0013 - Careers Advisers Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0014 - Seminar - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0015 - Seminar - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0016 - Seminar - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0017 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0018 - Stairs

No Asbestos

B00H - R0019 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

B00H - R0020 - Lift

No Asbestos

B00H - R0021 - Stairs

No Asbestos

B00H - R9001 - Movement

No Asbestos

B00H - R9002 - Stairs

No Asbestos

B00H - R9003 - Plant

No Asbestos

B00H - R9004 - Lift

No Asbestos

B00H - R9005 - Movement

No Asbestos

B00H - R9006 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

B00I - Multi Purpose Facilities/Pupil Facilities - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00I - R0001 - Covered Outdoor Space

No Asbestos

B00I - R0002 - General Storeroom

No Asbestos

B00I - R0003 - Maintenance Bulk Store

No Asbestos

B00I - R0004 - Change

No Asbestos

B00I - R0005 - Toilets-Boys

No Asbestos

B00I - R0006 - Toilets-Girls

No Asbestos

B00I - R0007 - Change

No Asbestos

B00I - R0008 - Access Student Shower/Toilet - Type 2

No Asbestos

B00I - R0009 - Staff Shower

No Asbestos

B00I - R0010 - Sport Equipment Store

No Asbestos

B00I - R0011 - Movement Studio

No Asbestos

B00I - R0012 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00I - R0013 - Chair Store

No Asbestos

B00I - R0014 - Control Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00I - R0015 - Gymnasium

No Asbestos

B00I - R0016 - Large Equipment Store

No Asbestos

B00I - R0017 - Cleaning Supplies Store

No Asbestos

B00I - R0018 - Garden Store Room

No Asbestos

B00I - R0019 - Cleaning Store - Distributed

No Asbestos

B00I - R0020 - Movement

No Asbestos

B00I - R0021 - Plant

No Asbestos

B00I - R0022 - Outdoor Equipment Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

B00I - R0023 - Sport Equipment Store

No Asbestos

B00I - R0024 - First Aid

No Asbestos

B00I - R0025 - Plant

No Asbestos

B00I - R0026 - Student Canteen

No Asbestos

B00I - R0027 - Office/Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00J - Administration - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00J - R0001 - Movement

No Asbestos

B00J - R0002 - Interview/Meeting

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00J - R0003 - Interview/Meeting

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00J - R0004 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00J - R0005 - Staff - Toilet

No Asbestos

B00J - R0006 - Staff - Toilet

No Asbestos

B00J - R0007 - Security Store

No Asbestos

B00J - R0008 - Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00J - R0009 - Administration - Clerical

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00J - R0010 - Clinic - Boys

No Asbestos

B00J - R0011 - Communications Cupboard

No Asbestos

B00J - R0012 - Staff - Toilet

No Asbestos

B00J - R0013 - Staff - Toilet

No Asbestos

B00J - R0014 - Clinic - Girls

No Asbestos

B00J - R0015 - Interview/Office - Type 2

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00J - R0016 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00J - R0017 - Student Reception

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00J - R0018 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00J - R0019 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00J - R0020 - Interview/Office - Type 1

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R0021 - Visitors Office						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R0022 - Public Reception						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R0023 - Cleaning Store - Distributed						
No Asbestos						
B00J - R0024 - Tea Room						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017