Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Northern Beaches Secondary College Manly Campus (8567)**
Region :	**Northern Sydney**
State Electorate :	**Manly**
Local Government Area :	**Warringah**

Initial Survey :	**Noel Arnold & Associates : 13 - Mar - 2008**
Reviewed By :	**AECOM : 27 - Oct - 2014**

8567 - Northern Beaches Secondary College Manly Campus
Site Plan (All Sites)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00A - General Learning/Administration - 1954 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	80m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction (~7m)					
Underfloor Voids - Slab on Ground	Non Accessible Area - No underfloor voids identified. Building constructed slab on ground.					
Ceiling Voids	Insulation around re-heat elements (if present) in air conditioning duct work	NA	Throughout	Minimal Damage (2)	Medium (2)	Medium Priority (4-5)
	Assumed Asbestos - Void accessed through R1011. No safe access to material which is assumed to be present					

Interior

B00A - R0001 - Cleaning Store - Distributed

No Asbestos

B00A - R0002 - Sport Equipment Store

No Asbestos

B00A - R0003 - General Learning Space

No Asbestos

B00A - R0004 - General Learning Space

No Asbestos

B00A - R0005 - General Learning Space

No Asbestos

B00A - R0006 - General Learning Space

No Asbestos

B00A - R0007 - General Learning Space

No Asbestos

B00A - R0008 - Printing/Photocopying

No Asbestos

B00A - R0009 - Administration - Clerical

No Asbestos

B00A - R0010 - Interview/Meeting

No Asbestos

B00A - R0011 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00A/R0012/Floor Coverings Res/Textile/S1					**Chrysotile (white asbestos)**

B00A - R0012 - Resources Store

Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00A/R0012/Floor Coverings Res/Textile/S1					**Chrysotile (white asbestos)**

B00A - R0013 - Resources Store

No Asbestos

B00A - R0014 - Cleaning Store - Distributed

No Asbestos

B00A - R0015 - Movement

No Asbestos

B00A - R0016 - Resources Store

No Asbestos

B00A - R0017 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00A - R0018 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
	8567/B00A/R0018/Ceiling Structures/Linings/S34					**No Asbestos Detected**
Glazing putty	Mastic					
	8567/B00A/R0019/Glazing putty/S35					**No Asbestos Detected**
B00A - R0019 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
	8567/B00A/R0018/Ceiling Structures/Linings/S34					**No Asbestos Detected**
Glazing putty	Mastic					
	8567/B00A/R0019/Glazing putty/S35					**No Asbestos Detected**
B00A - R0020 - Stairs						
No Asbestos						
B00A - R0021 - Stairs						
No Asbestos						
B00A - R1001 - Resources Store						
No Asbestos						
B00A - R1002 - Cleaning Store - Distributed						
No Asbestos						
B00A - R1003 - Communication Space						
Floor Coverings Res/Textile	Vinyl Tiles					
	8567/B00A/R1003/Floor Coverings Res/Textile/S2					**No Asbestos Detected**
B00A - R1004 - General Learning Space						
No Asbestos						
B00A - R1005 - General Learning Space						
No Asbestos						
B00A - R1006 - General Learning Space						
No Asbestos						
B00A - R1007 - General Learning Space						
No Asbestos						
B00A - R1008 - General Learning Space						
No Asbestos						
B00A - R1009 - General Learning Space						
No Asbestos						
B00A - R1010 - Cleaning Store - Distributed						
Floor Coverings Res/Textile	Vinyl Tiles					
	8567/B00A/R1003/Floor Coverings Res/Textile/S2					**No Asbestos Detected**
B00A - R1011 - Interview/Office - Type 1						
No Asbestos						
B00A - R1012 - Movement						
No Asbestos						
B00A - R1013 - Stairs						
No Asbestos						
B00A - R1014 - Stairs						
Non Accessible						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00B - Administration/General Learning - 1954 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	90m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction (generally 6-8m)					
Ceiling Voids	Non Accessible Area - Access hatch near R1014 screwed shut.					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	8567/B00B/Underfloor Voids - Packing to Floor Joists/S31				**Chrysotile (white asbestos) , Amosite (brown asbestos)**	
Underfloor Voids	Fibre cement pipe risers for electrical services near R0001.	3Unit	East side of underfloor void near R0001.	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - No access due to electrical hazard.					

Interior

B00B - R0001 - Movement

No Asbestos

B00B - R0002 - Garden Store Room

No Asbestos

B00B - R0003 - Cleaning Supplies Store

No Asbestos

B00B - R0004 - Archive Store

No Asbestos

B00B - R0005 - Toilets-Boys

No Asbestos

B00B - R0006 - Cleaning Store - Distributed

No Asbestos

B00B - R0007 - Student Drinking Facilities

No Asbestos

B00B - R0008 - Toilets-Girls

Partition Walls (Cubicles)	Compressed AC Sheet	30m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00B/R0008/Partition Walls (Cubicles)/S3				**Chrysotile (white asbestos)**	

B00B - R0011 - Administration - Clerical

No Asbestos

B00B - R0012 - Administration - Executive

No Asbestos

B00B - R0013 - Music Store

No Asbestos

B00B - R0014 - Staff - Toilet

No Asbestos

B00B - R0015 - Deputy Principal Office

No Asbestos

B00B - R0016 - Principal Office

No Asbestos

B00B - R0017 - Staff - Toilet

No Asbestos

B00B - R0018 - Staff - Toilet

No Asbestos

B00B - R0019 - Deputy Principal Office

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00B - R0020 - Main Switchroom

No Asbestos

B00B - R0021 - Administration - Clerical

No Asbestos

B00B - R0024 - Public Reception

No Asbestos

B00B - R0025 - Movement

Floor Coverings Res/Textile	Vinyl Tiles					
	8567/B00B/R0025/Floor Coverings Res/Textile/S32					**No Asbestos Detected**

B00B - R0027 - Stairs

Non Accessible

B00B - R0028 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	8567/B00B/R0028/Ceiling Structures/Linings/S33					**No Asbestos Detected**

B00B - R0029 - Clinic

No Asbestos

B00B - R0030 - Toilets-Unisex

No Asbestos

B00B - R0031 - Administration - Clerical

No Asbestos

B00B - R0032 - Movement

No Asbestos

B00B - R0033 - Tea Room

No Asbestos

B00B - R0034 - External Movement

Recently Modified Space	Requires Inspection					

B00B - R1001 - System Administrators Office

No Asbestos

B00B - R1002 - General Storeroom

No Asbestos

B00B - R1003 - Sport Equipment Store

No Asbestos

B00B - R1004 - Computer Store

No Asbestos

B00B - R1005 - Resources Store

No Asbestos

B00B - R1006 - General Learning Space

No Asbestos

B00B - R1007 - General Learning Space

No Asbestos

B00B - R1008 - General Learning Space

No Asbestos

B00B - R1009 - Senior Study

No Asbestos

B00B - R1010 - Resources Store

Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00B/R1010/Floor Coverings Res/Textile/S5					**Chrysotile (white asbestos)**

B00B - R1011 - General Learning Space

No Asbestos

B00B - R1012 - General Learning Space

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

No Asbestos

B00B - R1013 - General Learning Space

No Asbestos

B00B - R1014 - Staff - Toilet

No Asbestos

B00B - R1015 - Resources Store

No Asbestos

B00B - R1016 - Staff - Toilet

No Asbestos

B00B - R1018 - Resources Store

Non Accessible

B00B - R1019 - Staff Study

No Asbestos

B00B - R1021 - Staff Study

No Asbestos

B00B - R1023 - Resources Store

Floor Coverings Res/Textile	Vinyl Tiles					
	8567/B00A/R1003/Floor Coverings Res/Textile/S2					**No Asbestos Detected**

B00B - R1024 - Stairs

Non Accessible

B00B - R1025 - External Movement

No Asbestos

B00B - R1026 - Stairs

No Asbestos

B00B - R1027 - Movement

Window sealant	Mastic					
	8567/B00A/R0019/Glazing putty/S35					**No Asbestos Detected**

B00B - R1028 - Staff Study

No Asbestos

B00B - R1029 - Tea Room

No Asbestos

B00B - R1030 - Movement

No Asbestos

B00B - R1031 - Handwashing Facilities

No Asbestos

B00B - R2001 - Staff Study

No Asbestos

B00B - R2002 - Staff Kitchen

No Asbestos

B00B - R2003 - Study Space

No Asbestos

B00B - R2004 - Resources Store

No Asbestos

B00B - R2005 - Resources Store

Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00B/R2005/Floor Coverings Res/Textile/S6					**Chrysotile (white asbestos)**

B00B - R2006 - General Learning Space

No Asbestos

B00B - R2007 - General Learning Space

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00B - R2008 - General Learning Space						
No Asbestos						
B00B - R2009 - Senior Study						
No Asbestos						
B00B - R2010 - Resources Store						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00B/R2005/Floor Coverings Res/Textile/S6					**Chrysotile (white asbestos)**
B00B - R2011 - General Learning Space						
No Asbestos						
B00B - R2012 - General Learning Space						
No Asbestos						
B00B - R2013 - General Learning Space						
No Asbestos						
B00B - R2014 - General Storeroom						
No Asbestos						
B00B - R2015 - Commonroom						
No Asbestos						
B00B - R2016 - Staff Kitchen						
No Asbestos						
B00B - R2018 - Stairs						
No Asbestos						
B00B - R2019 - Stairs						
No Asbestos						
B00B - R2020 - Movement						
Window putty	Mastic					
	8567/B00B/R2020/Window putty/S30					**No Asbestos Detected**
B00B - R2021 - Stairs						
No Asbestos						
B00B - R2022 - Movement						
No Asbestos						
B00B - R2023 - Handwashing Facilities						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00C - Library/Pupil Facilities/Science Learning - 1969 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	North facing, South facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction (generally 7-8m)					
Ceiling Voids	Flat AC Sheeting	100m2	Bulkhead lining to gabled roof	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Ceiling void access via R2028. No direct access to bulkhead lining for detailed inspection or sampling due to height and occupation of building.					
Underfloor Voids - Slab on Ground	Non Accessible Area - No underfloor voids identified. Building appears to be constructed slab on ground.					

Interior

B00C - R0001 - Sport Equipment Store

No Asbestos

B00C - R0002 - Cleaning Store - Distributed

Floor Coverings Res/Textile	Vinyl Tiles	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00B/R1010/Floor Coverings Res/Textile/S5				**Chrysotile (white asbestos)**	

B00C - R0003 - Other-Vacant

No Asbestos

B00C - R0004 - Student Canteen

No Asbestos

B00C - R0005 - Staff - Toilet

Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00B/R0008/Partition Walls (Cubicles)/S3				**Chrysotile (white asbestos)**	

B00C - R0006 - Pantry

Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R0006/Floor Coverings Res/Textile/S7				**Chrysotile (white asbestos)**	

B00C - R0008 - General Assistants

Floor Coverings Res/Textile	Vinyl Tiles	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R0008/Floor Coverings Res/Textile/S8				**Chrysotile (white asbestos)**	

B00C - R0009 - Sport Equipment Store

No Asbestos

B00C - R0010 - Music Learning Space

Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9				**No Asbestos Detected**	

B00C - R0011 - Music Store

Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R0006/Floor Coverings Res/Textile/S7				**Chrysotile (white asbestos)**	

B00C - R0013 - Kiln Space

No Asbestos

B00C - R0014 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0015 - Cleaning Store - Distributed

No Asbestos

B00C - R0016 - Staff - Toilet

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00B/R0008/Partition Walls (Cubicles)/S3					**Chrysotile (white asbestos)**
Floor Coverings Res/Textile	Vinyl Sheet					
	8567/B00C/R0016/Floor Coverings Res/Textile/S10					**No Asbestos Detected**
B00C - R0017 - Tea Room						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R0008/Floor Coverings Res/Textile/S8					**Chrysotile (white asbestos)**
Window sealant	Mastic					
	8567/B00A/R0019/Glazing putty/S35					**No Asbestos Detected**
B00C - R0018 - Movement						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
B00C - R0021 - Office/Store						
No Asbestos						
B00C - R0022 - Seminar						
No Asbestos						
B00C - R0023 - Seminar						
No Asbestos						
B00C - R0024 - Seminar						
No Asbestos						
B00C - R0025 - Study Space						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
Window Infil panel	Flat AC Sheeting	2m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R1025/Wall Linings Internal/S11					**Chrysotile (white asbestos)**
B00C - R0028 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
B00C - R0029 - Cleaning Store - Distributed						
No Asbestos						
B00C - R0031 - General Storeroom						
No Asbestos						
B00C - R0033 - External Movement						
Window sealant	Mastic					
	8567/B00A/R0019/Glazing putty/S35					**No Asbestos Detected**
B00C - R0034 - Movement						
Door and window sealant	Mastic					
	8567/B00A/R0019/Glazing putty/S35					**No Asbestos Detected**
B00C - R0035 - Stairs						
Non Accessible						
B00C - R0036 - No Access						
No Asbestos						
B00C - R0037 - Stairs						
Non Accessible						
B00C - R0038 - Stairs						
Non Accessible						
B00C - R0039 - External Movement						
No Asbestos						
B00C - R0040 - Movement						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00C - R0041 - Computer Resource						
No Asbestos						
B00C - R0042 - Main Entry						
No Asbestos						
B00C - R0043 - Main Area						
No Asbestos						
B00C - R0044 - Library Administration						
No Asbestos						
B00C - R0045 - Tea Room						
No Asbestos						
B00C - R0046 - Movement						
No Asbestos						
B00C - R0047 - Store - Coolroom						
No Asbestos						
B00C - R0048 - General Storeroom						
No Asbestos						
B00C - R1001 - Cleaning Store - Distributed						
No Asbestos						
B00C - R1002 - Chemical Store						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
B00C - R1003 - Laboratory L.S.						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
Window Infil panel	Flat AC Sheeting	3m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R1025/Wall Linings Internal/S11					**Chrysotile (white asbestos)**
Laboratory workbench top	Flat AC Sheeting	2m2	North facing	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00C/R1003/Laboratory workbench top/S12					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00C - R1005 - Preparation - Science						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
Flue	Fibre Cement Pipe	2m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R1005/Flue/S15					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Fume Cupboard	Flat AC Sheeting	3Unit	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R1005/Fume Cupboard/S14					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00C - R1007 - Laboratory L.S.						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
Window Infil panel	Flat AC Sheeting	3m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R1025/Wall Linings Internal/S11					**Chrysotile (white asbestos)**
Laboratory workbench top	Flat AC Sheeting	2m2	North facing	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00C/R1003/Laboratory workbench top/S12					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00C - R1008 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Window Infil panel	Flat AC Sheeting	1m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R1025/Wall Linings Internal/S11					**Chrysotile (white asbestos)**
B00C - R1009 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
B00C - R1010 - Cleaning Store - Distributed						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
B00C - R1011 - Staff - Toilet						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Sheet					
	8567/B00C/R0016/Floor Coverings Res/Textile/S10					**No Asbestos Detected**
Incinerette	Encapsulated Insulation material within unit	1Unit(s)	East facing	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Equipment dismantling required /					
B00C - R1014 - Art Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
Window Infil panel	Flat AC Sheeting	3m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R1025/Wall Linings Internal/S11					**Chrysotile (white asbestos)**
B00C - R1015 - Resources Store						
No Asbestos						
B00C - R1016 - Art Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
Window Infil panel	Flat AC Sheeting	3m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R1025/Wall Linings Internal/S11					**Chrysotile (white asbestos)**
B00C - R1017 - Resources Store						
No Asbestos						
B00C - R1018 - Art Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
Window Infil panel	Flat AC Sheeting	1m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R1025/Wall Linings Internal/S11					**Chrysotile (white asbestos)**
B00C - R1022 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
B00C - R1023 - Cleaning Store - Distributed						
No Asbestos						
B00C - R1024 - Staff Study						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
B00C - R1025 - Computer Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
Window Infil panel	Flat AC Sheeting	1m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R1025/Wall Linings Internal/S11					**Chrysotile (white asbestos)**
B00C - R1026 - Resources Store						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
B00C - R1027 - Resources Store						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
B00C - R1033 - Movement						
Window sealant	Mastic					
	8567/B00A/R0019/Glazing putty/S35					**No Asbestos Detected**
B00C - R1034 - Stairs						
Non Accessible						
B00C - R1035 - Stairs						
Non Accessible						
B00C - R1036 - Stairs						
Window putty	Putty					
	8567/B00A/R0019/Glazing putty/S35					**No Asbestos Detected**
B00C - R1037 - Staff Study						
No Asbestos						
B00C - R1038 - Tea Room						
No Asbestos						
B00C - R1039 - Tea Room						
No Asbestos						
B00C - R1040 - Staff Study						
No Asbestos						
B00C - R1041 - Resources Store						
No Asbestos						
B00C - R1042 - Movement						
No Asbestos						
B00C - R1043 - Movement						
No Asbestos						
B00C - R2001 - Cleaning Store - Distributed						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
B00C - R2002 - Resources Store						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
B00C - R2003 - Laboratory L.S.						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
Window Infil panel	Flat AC Sheeting	3m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R1025/Wall Linings Internal/S11					**Chrysotile (white asbestos)**
Laboratory workbench top	Flat AC Sheeting	2m2	North facing	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00C/R1003/Laboratory workbench top/S12					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00C - R2004 - Preparation - Science						
Flue	Fibre Cement Pipe	6m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R1005/Flue/S15					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Fume Cupboard	Flat AC Sheeting	2Unit	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R1005/Fume Cupboard/S14					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
B00C - R2005 - Resources Store						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
B00C - R2006 - Laboratory L.S.						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
Window Infil panel	Flat AC Sheeting	3m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R1025/Wall Linings Internal/S11					**Chrysotile (white asbestos)**
Laboratory workbench top	Flat AC Sheeting	2m2	North facing	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00C/R1003/Laboratory workbench top/S12					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00C - R2007 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
Window Infil panel	Flat AC Sheeting	1m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R1025/Wall Linings Internal/S11					**Chrysotile (white asbestos)**
B00C - R2009 - Pantry						
No Asbestos						
B00C - R2010 - Preparation						
Window Infil panel	Flat AC Sheeting	1m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R1025/Wall Linings Internal/S11					**Chrysotile (white asbestos)**
B00C - R2013 - Careers Advisers Office						
Window Infil panel	Flat AC Sheeting	1m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00C/R1025/Wall Linings Internal/S11					**Chrysotile (white asbestos)**
B00C - R2014 - Resources Store						
No Asbestos						
B00C - R2016 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
Ceiling Structures/Linings	Vermiculite					
	8567/B00C/R1028/Ceiling Structures/Linings/S9					**No Asbestos Detected**
B00C - R2017 - Cleaning Store - Distributed						
No Asbestos						
B00C - R2018 - Resources Store						
No Asbestos						
B00C - R2020 - Stairs						
Window sealant	Mastic					
	8567/B00A/R0019/Glazing putty/S35					**No Asbestos Detected**
B00C - R2021 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
Non Accessible						
B00C - R2022 - Stairs						
Non Accessible						
B00C - R2023 - Stairs						
Non Accessible						
B00C - R2024 - Cleaning Store - Distributed						
No Asbestos						
B00C - R2025 - Staff - Toilet						
No Asbestos						
B00C - R2026 - Computer Learning Space						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00C - R2027 - Computer Learning Space

No Asbestos

B00C - R2028 - Food Technology L.S.

No Asbestos

B00C - R2029 - Laundry

No Asbestos

B00C - R2030 - Darkroom Space

No Asbestos

B00C - R2031 - Dark Room

No Asbestos

B00C - R2032 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00D - Music/Science Learning - 1954 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction (6-8m)					
Underfloor Voids - Slab on Ground	Non Accessible Area - Building generally constructed slab on ground. No access to small subfloor hatch / service riser with contractor keys provided.					
Ceiling Voids	No Asbestos Found					

Interior

B00D - R0001 - Study Space

No Asbestos

B00D - R0003 - General Learning Space

No Asbestos

B00D - R0004 - Preparation - Science

No Asbestos

B00D - R0005 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0006 - Resources Store

No Asbestos

B00D - R0007 - Laboratory L.S.

No Asbestos

B00D - R0012 - Resources Store

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	
	8567/B00D/R0012/Floor Coverings Res/Textile/S24	**No Asbestos Detected**

B00D - R0013 - Tea Room

No Asbestos

B00D - R0014 - Staff Study

Floor Coverings Res/Textile	Vinyl Tiles	
	8567/B00D/R0012/Floor Coverings Res/Textile/S24	**No Asbestos Detected**

B00D - R0015 - Movement

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	
	8567/B00D/R0012/Floor Coverings Res/Textile/S24	**No Asbestos Detected**

B00D - R0016 - External Movement

No Asbestos

B00D - R0017 - External Movement

No Asbestos

B00D - R0018 - Other-Vacant

No Asbestos

B00D - R0019 - Other-Vacant

No Asbestos

B00D - R1001 - Practice/Seminar

No Asbestos

B00D - R1002 - Resources Store

Floor Coverings Res/Textile	Vinyl Tiles	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00B/R1010/Floor Coverings Res/Textile/S5				**Chrysotile (white asbestos)**	

B00D - R1004 - Resources Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00D - R1005 - Music Learning Space						
No Asbestos						
B00D - R1006 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
No Asbestos						
B00D - R1007 - Resources Store						
No Asbestos						
B00D - R1008 - Practice/Seminar						
No Asbestos						
B00D - R1010 - Music Learning Space						
Floor Coverings Res/Textile	Vinyl Tiles					
	8567/B00D/R1011/Floor Coverings Res/Textile/S25					**No Asbestos Detected**
B00D - R1011 - Music Store						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8567/B00D/R1011/Floor Coverings Res/Textile/S25					**No Asbestos Detected**
B00D - R1012 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8567/B00D/R1012/Floor Coverings Res/Textile/S26					**No Asbestos Detected**
B00D - R1013 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles					
	8567/B00D/R1011/Floor Coverings Res/Textile/S25					**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00E - Technological & Applied Studies - 1954 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	70m2	North facing, South facing, West facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction (3-4m)					
Ceiling Voids	Resinous Membrane	80m2	Floor throughout central walkway	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00E/Ceiling Voids/S27					**Chrysotile (white asbestos)**
Ceiling Voids	Flat AC Sheeting	100m2	Walls and infill panels throughout central walkway.	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00E/Ceiling Voids/S29					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Underfloor Voids	AC Fragments/Debris	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	8567/B00E/Underfloor Voids/S28					**Chrysotile (white asbestos)**

Interior

B00E - R0003 - Performance Store

No Asbestos

B00E - R0004 - Performance Store

Ceiling Structures/Linings	Flat AC Sheeting	17m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00E/R9001/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00E - R0005 - Wood Technology L.S.

Wall Linings Internal	Flat AC Sheeting	60m2	North facing, South facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00E/R0001/Wall Linings Internal/S21					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00E - R0006 - Project Store - Type 1

No Asbestos

B00E - R0007 - Materials Store

Ceiling Structures/Linings	Flat AC Sheeting	17m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00E/R9001/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00E - R0009 - Materials Store

Ceiling Structures/Linings	Flat AC Sheeting	25m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00E/R9001/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00E - R0010 - Materials Store

Wall Linings Internal	Flat AC Sheeting	2m2	North facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00E/R0001/Wall Linings Internal/S21					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00E - R0012 - Staff Study

Wall Linings Internal	Flat AC Sheeting	30m2	North facing, South facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00E/R0001/Wall Linings Internal/S21					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00E - R0014 - Staff - Toilet

No Asbestos

B00E - R0015 - Staff - Toilet

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Floor Coverings Res/Textile	Vinyl Tiles					
	8567/B00E/R0015/Floor Coverings Res/Textile/S22					**No Asbestos Detected**
B00E - R0016 - Design L.S.						
Wall Linings Internal	Flat AC Sheeting	40m2	North facing, South facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00E/R0001/Wall Linings Internal/S21					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Ceiling Structures/Linings	Flat AC Sheeting	83m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00E/R9001/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R0017 - Resources Store						
Floor Coverings Res/Textile	Vinyl Tiles	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00B/R1010/Floor Coverings Res/Textile/S5					**Chrysotile (white asbestos)**
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00E/R9001/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R0018 - Design L.S.						
Wall Linings Internal	Flat AC Sheeting	50m2	North facing, South facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00E/R0001/Wall Linings Internal/S21					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Ceiling Structures/Linings	Flat AC Sheeting	77m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00E/R9001/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Bituflu	Resinous pipe	3m	NE corner	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Not sampled due limited extent. Likely					
B00E - R0019 - Resources Store						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00E/R9001/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Floor Coverings Res/Textile	Vinyl Tiles					
	8567/B00E/R0015/Floor Coverings Res/Textile/S22					**No Asbestos Detected**
B00E - R0020 - Design/Technology L.S.						
Wall Linings Internal	Flat AC Sheeting	40m2	North facing, South facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00E/R0001/Wall Linings Internal/S21					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Ceiling Structures/Linings	Flat AC Sheeting	66m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00E/R9001/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R0021 - Resources Store						
Ceiling Structures/Linings	Flat AC Sheeting	17m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00E/R9001/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R0022 - Resources Store						
No Asbestos						
B00E - R0023 - Multi Media Workshop						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Wall Linings Internal	Flat AC Sheeting	25m2	North facing, South facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00E/R0001/Wall Linings Internal/S21					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R0025 - Resources Store						
Ceiling Structures/Linings	Flat AC Sheeting	17m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00E/R9001/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R0026 - Resources Store						
No Asbestos						
B00E - R0028 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00E/R9001/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R0029 - External Movement						
No Asbestos						
B00E - R0030 - Dust Extraction Space						
No Asbestos						
B00E - R0031 - Performance Workspace						
Wall Linings Internal	Compressed AC Sheet	6m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00E/Ceiling Voids/S27					**Chrysotile (white asbestos)**
B00E - R0032 - Handwashing Facilities						
No Asbestos						
B00E - R0033 - Metal Technology L.S.						
Wall Linings Internal	Flat AC Sheeting	75m2	North facing, South facing, East facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00E/R0001/Wall Linings Internal/S21					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R0034 - Welding Area						
Wall Linings Internal	Flat AC Sheeting	5m2	North facing, east facing, upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00E/R0001/Wall Linings Internal/S21					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R0035 - Wood Technology L.S.						
Wall Linings Internal	Compressed AC Sheet	6m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00E/Ceiling Voids/S27					**Chrysotile (white asbestos)**
B00E - R0036 - Handwashing Facilities						
No Asbestos						
B00E - R0037 - Handwashing Facilities						
No Asbestos						
B00E - R0038 - Staff Lounge						
No Asbestos						
B00E - R0039 - Tea Room						
No Asbestos						
B00E - R0040 - Movement						
No Asbestos						
B00E - R9001 - General Storeroom						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Redundant Flues	Fibre Cement Pipe	6m	North facing	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Not sampled due limited extent and					
Ceiling Structures/Linings	Flat AC Sheeting	140m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00E/R9001/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R9004 - Movement						
No Asbestos						
B00E - R9005 - Staff - Toilet						
No Asbestos						
B00E - R9006 - Uniform Shop						
No Asbestos						
B00E - R9007 - Performance Store						
Floor Coverings Res/Textile	Vinyl Tiles					
	8567/B00E/R9007/Floor Coverings Res/Textile/S38					**No Asbestos Detected**
Ceiling Structures/Linings	Compressed AC Sheet	48m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00E/R9001/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - Room+1 - Upper Walkway accessed from room BR0021						
Wall Linings Internal	Flat AC Sheeting	200m2	North facing, South facing, All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00E/Room+1/Wall Linings Internal/S23					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00F - Multi Purpose Facilities - 1954 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction (4m)					
Ceiling Voids	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	8567/B00E/Underfloor Voids/S28				**Chrysotile (white asbestos)**	
Underfloor Voids - Packing to Floor Joists	Packing					
	8567/B00F/Underfloor Voids - Packing to Floor Joists/S37				**No Asbestos Detected**	

Interior

B00F - R0003 - Control Room

No Asbestos

B00F - R0004 - Other-Vacant

No Asbestos

B00F - R0005 - Multi-Purpose Space

No Asbestos

B00F - R0007 - Ancillary Staff

Ceiling Structures/Linings	Flat AC Sheeting					
	8567/B00F/R0007/Ceiling Structures/Linings/S18				**No Asbestos Detected**	

B00F - R0011 - Toilets-Disabled

Ceiling Structures/Linings	Flat AC Sheeting					
	8567/B00F/R0007/Ceiling Structures/Linings/S18				**No Asbestos Detected**	

B00F - R0012 - Toilets-Boys

Ceiling Structures/Linings	Flat AC Sheeting					
	8567/B00F/R0007/Ceiling Structures/Linings/S18				**No Asbestos Detected**	
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	8567/B00B/R0008/Partition Walls (Cubicles)/S3				**Chrysotile (white asbestos)**	

B00F - R0017 - Stage

No Asbestos

B00F - R0018 - Stairs

No Asbestos

B00F - R0019 - Movement

No Asbestos

B00F - R0020 - Toilet - Lobby

No Asbestos

B00F - R0021 - Toilets-Girls

No Asbestos

B00F - R0022 - Change

No Asbestos

B00F - R0023 - Chair Store

No Asbestos

B00F - R0024 - Movement

No Asbestos

B00F - R0025 - Movement

No Asbestos

B00F - R0026 - Public Reception

No Asbestos

B00F - R0027 - Performance Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00F - R0028 - Performance Store						
No Asbestos						
B00F - R0029 - Change						
No Asbestos						
B00F - R0030 - Toilet - Lobby						
No Asbestos						
B00F - R0031 - Shower						
No Asbestos						
B00F - R0032 - Cleaning Store - Distributed						
No Asbestos						
B00F - R0033 - Plant						
No Asbestos						
B00F - R9001 - General Storeroom						
Ceiling Structures/Linings	Flat AC Sheeting	27m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00E/R9001/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00F - R9002 - Performance Store						
Ceiling Structures/Linings	Flat AC Sheeting	49m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8567/B00E/R9001/Ceiling Structures/Linings/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00F - R9003 - General Storeroom						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00G - Storage - 1960 - Fibre Clad Shed (Fibre Clad Shed)

Exterior

Ceiling Void	Requires Inspection
Underfloor Void	Requires Inspection

Interior

B00G - R0001 - General Storeroom

Recently Modified Space	Requires Inspection

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00H - Storage - 2000 - Steel (Steel)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00H - R0001 - General Assistants

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00Z - Storage - 1954 - Brick/Block (Brick/Block)

Exterior

No Asbestos

Interior

B00Z - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Build+1 - Covered Walkway Buildings B - C

Exterior

Eaves Linings	Flat AC Sheeting	10m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction - Height					

Interior

Build+1 - Room+1 - Second Floor Walkway

Ceiling Structures/Linings	Vermiculite	
	8567/B00C/R1028/Ceiling Structures/Linings/S9	**No Asbestos Detected**

Build+1 - Room+2 - First Floor Walkway

Ceiling Structures/Linings	Vermiculite	
	8567/B00C/R1028/Ceiling Structures/Linings/S9	**No Asbestos Detected**

Build+1 - Room+3 - Ground Floor Walkway

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Build+2 - Covered Walkway Buildings C - D

Exterior

Eaves Linings	Flat AC Sheeting	10m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction - Height					

Interior

Build+2 - Room+1 - First Floor Walkway

Ceiling Structures/Linings	Vermiculite	
	8567/B00C/R1028/Ceiling Structures/Linings/S9	**No Asbestos Detected**

Build+2 - Room+2 - Ground Floor Walkway

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

8567_ASB_150514_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017