Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Randwick Boys High School (8161)**
Region :	**Sydney**
State Electorate :	**Coogee**
Local Government Area :	**Randwick**

Initial Survey :	**Noel Arnold & Associates : 25 - Jan - 2008**
Register Issue Date :	**23 - Mar - 2017**

8161 - Randwick Boys High School
Site Plan (10522)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00A - Administration/Staff Facilities - 1992 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00A - R0001 - Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0002 - Security Store

No Asbestos

B00A - R0005 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0006 - Duplicating Workroom

No Asbestos

B00A - R0007 - Leading Teacher

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0008 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0009 - Senior Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0011 - Senior Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0012 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0014 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0015 - Staff - Toilet

No Asbestos

B00A - R0022 - Covered Area

No Asbestos

B00A - R0023 - External Movement

No Asbestos

B00A - R0024 - Stairs

No Asbestos

B00A - R0025 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00A - R0026 - External Movement

No Asbestos

B00A - R0027 - External Stairs

No Asbestos

B00A - R0028 - External Movement

No Asbestos

B00A - R0029 - Disabled Toilet

No Asbestos

B00A - R0030 - Staff Kitchen

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00A - R0031 - Pupil Entry

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0032 - Administration - Clerical

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0033 - Outdoor Learning Area

No Asbestos

B00A - R1003 - Staff - Toilet

No Asbestos

B00A - R1004 - Staff - Toilet

No Asbestos

B00A - R1005 - Staff - Toilet

No Asbestos

B00A - R1012 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B00A - R1014 - Cleaning Store - Distributed

No Asbestos

B00A - R1016 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R1020 - Commonroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R1021 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R1022 - Stairs

No Asbestos

B00A - R1023 - Movement

No Asbestos

B00A - R1024 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R1025 - Staff Study

No Asbestos

B00A - R1026 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R1027 - Stairs

No Asbestos

B00A - R1028 - Movement

No Asbestos

B00A - R1029 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R1030 - Movement

No Asbestos

B00A - R1031 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R1032 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00A - R1033 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00B - Library - 1976 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00B - M1001 - Plant

No Asbestos

B00B - M1002 - Plant

No Asbestos

B00B - R0001 - Librarian

Ceiling Structures/Linings	Vermiculite					
	8161/B00B/R0002/Ceiling Structures/Linings/S11					**No Asbestos Detected**

B00B - R0002 - Staff - Toilet

Ceiling Structures/Linings	Vermiculite					
	8161/B00B/R0002/Ceiling Structures/Linings/S11					**No Asbestos Detected**

B00B - R0003 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00B/R0003/Floor Coverings Res/Textile/S12					**Chrysotile (white asbestos)**

B00B - R0006 - Main Area

Ceiling Structures/Linings	Vermiculite					
	8161/B00B/R0002/Ceiling Structures/Linings/S11					**No Asbestos Detected**

B00B - R0007 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0008 - Cleaning Store - Distributed

No Asbestos

B00B - R0009 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00B/R0003/Floor Coverings Res/Textile/S12					**Chrysotile (white asbestos)**

B00B - R0010 - Staff - Toilet

Ceiling Structures/Linings	Vermiculite					
	8161/B00B/R0002/Ceiling Structures/Linings/S11					**No Asbestos Detected**

B00B - R0011 - Workroom

Ceiling Structures/Linings	Vermiculite					
	8161/B00B/R0002/Ceiling Structures/Linings/S11					**No Asbestos Detected**

B00B - R0012 - Movement

Ceiling Structures/Linings	Vermiculite					
	8161/B00B/R0002/Ceiling Structures/Linings/S11					**No Asbestos Detected**

B00B - R0014 - External Movement

No Asbestos

B00B - R0015 - Stairs

No Asbestos

B00B - R0016 - Stairs

No Asbestos

B00B - R0017 - Audio Visual Workroom

Ceiling Structures/Linings	Vermiculite					
	8161/B00B/R0002/Ceiling Structures/Linings/S11					**No Asbestos Detected**

B00B - R1001 - Main Area

Ceiling Structures/Linings	Vermiculite					
	8161/B00B/R0002/Ceiling Structures/Linings/S11					**No Asbestos Detected**

B00B - R1002 - Cleaning Store - Distributed

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00B - R1003 - Main Area						
Ceiling Structures/Linings	Vermiculite					
	8161/B00B/R0002/Ceiling Structures/Linings/S11					**No Asbestos Detected**
B00B - R1004 - Seminar						
Ceiling Structures/Linings	Vermiculite					
	8161/B00B/R0002/Ceiling Structures/Linings/S11					**No Asbestos Detected**
B00B - R1005 - Seminar						
Ceiling Structures/Linings	Vermiculite					
	8161/B00B/R0002/Ceiling Structures/Linings/S11					**No Asbestos Detected**
B00B - R1006 - Seminar						
Ceiling Structures/Linings	Vermiculite					
	8161/B00B/R0002/Ceiling Structures/Linings/S11					**No Asbestos Detected**
B00B - R1007 - Seminar						
Ceiling Structures/Linings	Vermiculite					
	8161/B00B/R0002/Ceiling Structures/Linings/S11					**No Asbestos Detected**
B00B - R1008 - Seminar						
Ceiling Structures/Linings	Vermiculite					
	8161/B00B/R0002/Ceiling Structures/Linings/S11					**No Asbestos Detected**
B00B - R1009 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
Floor Coverings Res/Textile	Vinyl Tiles	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00B/R0003/Floor Coverings Res/Textile/S12					**Chrysotile (white asbestos)**
B00B - R1010 - Stairs						
Ceiling Structures/Linings	Vermiculite					
	8161/B00B/R0002/Ceiling Structures/Linings/S11					**No Asbestos Detected**
B00B - R1011 - Stairs						
Ceiling Structures/Linings	Vermiculite					
	8161/B00B/R0002/Ceiling Structures/Linings/S11					**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00C - Physical Education/General Learning - 1992 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Gymnasium

No Asbestos

B00C - R0002 - Movement

No Asbestos

B00C - R0003 - Staff Change

No Asbestos

B00C - R0004 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R0005 - Toilets-Disabled

No Asbestos

B00C - R0006 - Toilets-Disabled

No Asbestos

B00C - R0007 - Sport Equipment Store

No Asbestos

B00C - R0008 - Student Canteen

No Asbestos

B00C - R0009 - Sport Equipment Store

No Asbestos

B00C - R0010 - Shower/Change

No Asbestos

B00C - R0011 - Shower/Change

No Asbestos

B00C - R0012 - Toilets-Boys

No Asbestos

B00C - R0013 - Toilets-Girls

No Asbestos

B00C - R0014 - Movement

No Asbestos

B00C - R0015 - Movement

No Asbestos

B00C - R0016 - Plant

No Asbestos

B00C - R0017 - Plant

No Asbestos

B00C - R0018 - Plant

No Asbestos

B00C - R1001 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R1002 - Study Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00C - R1003 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R1004 - General Learning Space

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R1005 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R1006 - General Storeroom						
No Asbestos						
B00C - R1007 - General Storeroom						
No Asbestos						
B00C - R1008 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R1009 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R1010 - Plant						
No Asbestos						
B00C - R1011 - Study Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R1012 - Movement						
No Asbestos						
B00C - R1013 - Plant						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00D - General Learning/Science Learning - 1976 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	50m2	North facing, South facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Window shades	Compressed AC Sheet	40m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00D/Window shades/S3				**Chrysotile (white asbestos) , Amosite (brown asbestos)**	
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00D - R0001 - Staff - Toilet

No Asbestos

B00D - R0002 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	3m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00D/R1001/Ceiling Structures/Linings/S2				**Chrysotile (white asbestos) , Amosite (brown asbestos)**	

B00D - R0003 - Movement

No Asbestos

B00D - R0004 - Serviced Learning Space

Ceiling Structures/Linings	Vermiculite	
	8161/B00D/R0004/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00D - R0005 - General Learning Space

Ceiling Structures/Linings	Vermiculite	
	8161/B00D/R0004/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00D - R0006 - General Learning Space

Ceiling Structures/Linings	Vermiculite	
	8161/B00D/R0004/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00D - R0007 - Cleaning Store - Distributed

Non Accessible

B00D - R0008 - Chemical Store

Ceiling Structures/Linings	Vermiculite	
	8161/B00D/R0004/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00D - R0009 - Apparatus Store

Ceiling Structures/Linings	Vermiculite	
	8161/B00D/R0004/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00D - R0010 - Main Switchroom

Ceiling Structures/Linings	Vermiculite	
	8161/B00D/R0004/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00D - R0011 - Laboratory L.S.

Ceiling Structures/Linings	Vermiculite	
	8161/B00D/R0004/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00D - R0012 - Preparation

Ceiling Structures/Linings	Vermiculite	
	8161/B00D/R0004/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00D - R0013 - Apparatus Store

Ceiling Structures/Linings	Vermiculite	
	8161/B00D/R0004/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00D - R0014 - Laboratory L.S.

Ceiling Structures/Linings	Vermiculite	
	8161/B00D/R0004/Ceiling Structures/Linings/S1	**No Asbestos Detected**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00D - R0015 - Movement						
Ceiling Structures/Linings	Vermiculite					
	8161/B00D/R0004/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00D - R0016 - Toilets-Boys						
No Asbestos						
B00D - R0017 - Cleaning Store - Distributed						
No Asbestos						
B00D - R0018 - Movement						
No Asbestos						
B00D - R0019 - Cleaning Store - Distributed						
No Asbestos						
B00D - R0020 - Movement						
No Asbestos						
B00D - R0021 - Stairs						
No Asbestos						
B00D - R0022 - Stairs						
No Asbestos						
B00D - R1001 - Staff - Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00D/R1001/Ceiling Structures/Linings/S2					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00D - R1002 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	119m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00D/R1001/Ceiling Structures/Linings/S2					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00D - R1003 - Staff - Toilet						
Ceiling Structures/Linings	Vermiculite					
	8161/B00D/R0004/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00D - R1004 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8161/B00D/R0004/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00D - R1005 - Staff Study						
Ceiling Structures/Linings	Vermiculite					
	8161/B00D/R0004/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00D - R1006 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8161/B00D/R0004/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00D - R1007 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8161/B00D/R0004/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00D - R1008 - General Storeroom						
Ceiling Structures/Linings	Vermiculite					
	8161/B00D/R0004/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00D - R1009 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
No Asbestos						
B00D - R1010 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8161/B00D/R0004/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00D - R1011 - General Storeroom						
Ceiling Structures/Linings	Vermiculite					
	8161/B00D/R0004/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00D - R1012 - General Storeroom						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Vermiculite					
	8161/B00D/R0004/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00D - R1013 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8161/B00D/R0004/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00D - R1014 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8161/B00D/R0004/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00D - R1015 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8161/B00D/R0004/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00D - R1016 - Cleaning Store - Distributed						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00D/R1001/Ceiling Structures/Linings/S2					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00D - R1017 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00D/R1001/Ceiling Structures/Linings/S2					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00D - R1018 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00D/R1001/Ceiling Structures/Linings/S2					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00D - R1019 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00D/R1001/Ceiling Structures/Linings/S2					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00D - R1020 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00D/R1001/Ceiling Structures/Linings/S2					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00E - Science Learning - 1992 - Brick/Block (Brick/Block)

Exterior

Window shades	Compressed AC Sheet	60m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00E/Window shades/S4					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Eaves Linings	Flat AC Sheeting	30m2	North facing, South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Requires Inspection					

Interior

B00E - R0001 - Cleaning Store - Distributed

No Asbestos

B00E - R0002 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0003 - Movement

No Asbestos

B00E - R0004 - Movement

No Asbestos

B00E - R0005 - Staff - Toilet

No Asbestos

B00E - R0006 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0007 - Cleaning Store - Distributed

No Asbestos

B00E - R0008 - Movement

No Asbestos

B00E - R0009 - Staff Study

Ceiling Structures/Linings	Vermiculite	
	8161/B00E/R0009/Ceiling Structures/Linings/S5	**No Asbestos Detected**

B00E - R0010 - Laboratory L.S.

Ceiling Structures/Linings	Vermiculite	
	8161/B00E/R0009/Ceiling Structures/Linings/S5	**No Asbestos Detected**

B00E - R0013 - Laboratory L.S.

Ceiling Structures/Linings	Vermiculite	
	8161/B00E/R0009/Ceiling Structures/Linings/S5	**No Asbestos Detected**

B00E - R0016 - Toilets-Boys

No Asbestos

B00E - R0017 - Stairs

No Asbestos

B00E - R0018 - Stairs

No Asbestos

B00E - R0019 - Gymnasium

No Asbestos

B00E - R0020 - Preparation - Science

No Asbestos

B00E - R0021 - Chemical Store

No Asbestos

B00E - R1001 - Cleaning Store - Distributed

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00E/R1001/Ceiling Structures/Linings/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R1002 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00E/R1001/Ceiling Structures/Linings/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R1003 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	118m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00E/R1001/Ceiling Structures/Linings/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R1004 - Staff - Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00E/R1001/Ceiling Structures/Linings/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R1005 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00E/R1001/Ceiling Structures/Linings/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R1006 - Cleaning Store - Distributed						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00E/R1001/Ceiling Structures/Linings/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R1007 - Staff Study						
Ceiling Structures/Linings	Vermiculite					
	8161/B00E/R0009/Ceiling Structures/Linings/S5					**No Asbestos Detected**
B00E - R1008 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8161/B00E/R0009/Ceiling Structures/Linings/S5					**No Asbestos Detected**
B00E - R1009 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8161/B00E/R0009/Ceiling Structures/Linings/S5					**No Asbestos Detected**
B00E - R1010 - Computer Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8161/B00E/R0009/Ceiling Structures/Linings/S5					**No Asbestos Detected**
B00E - R1011 - Computer Store						
Ceiling Structures/Linings	Vermiculite					
	8161/B00E/R0009/Ceiling Structures/Linings/S5					**No Asbestos Detected**
B00E - R1012 - Computer Resource						
Ceiling Structures/Linings	Vermiculite					
	8161/B00E/R0009/Ceiling Structures/Linings/S5					**No Asbestos Detected**
B00E - R1013 - Computer Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8161/B00E/R0009/Ceiling Structures/Linings/S5					**No Asbestos Detected**
B00E - R1014 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8161/B00E/R0009/Ceiling Structures/Linings/S5					**No Asbestos Detected**
B00E - R1015 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8161/B00E/R0009/Ceiling Structures/Linings/S5					**No Asbestos Detected**
B00E - R1016 - Stairs						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00E/R1001/Ceiling Structures/Linings/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R1017 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00E/R1001/Ceiling Structures/Linings/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R1018 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00E/R1001/Ceiling Structures/Linings/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00E - R1019 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00E/R1001/Ceiling Structures/Linings/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00F - General Learning/Pupil Facilities - 1976 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	North facing, South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Window shades	Compressed AC Sheet	32m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00F/Window shades/S7					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00F - R0001 - Staff - Toilet

No Asbestos

B00F - R0002 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0003 - Cleaning Store - Distributed

No Asbestos

B00F - R0004 - Movement

No Asbestos

B00F - R0006 - Laboratory L.S.

Ceiling Structures/Linings	Vermiculite	
	8161/B00F/R1005/Ceiling Structures/Linings/S8	**No Asbestos Detected**

B00F - R0007 - Preparation

Ceiling Structures/Linings	Vermiculite	
	8161/B00F/R1005/Ceiling Structures/Linings/S8	**No Asbestos Detected**

B00F - R0008 - Apparatus Store

Ceiling Structures/Linings	Vermiculite	
	8161/B00F/R1005/Ceiling Structures/Linings/S8	**No Asbestos Detected**

B00F - R0009 - Laboratory L.S.

Ceiling Structures/Linings	Vermiculite	
	8161/B00F/R1005/Ceiling Structures/Linings/S8	**No Asbestos Detected**

B00F - R0010 - Stairs

No Asbestos

B00F - R0011 - Movement

No Asbestos

B00F - R0012 - Toilets-Disabled

No Asbestos

B00F - R0013 - Toilets - Boys

No Asbestos

B00F - R1001 - Staff - Toilet

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00F/R1002/Ceiling Structures/Linings/S9					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00F - R1002 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00F/R1002/Ceiling Structures/Linings/S9					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00F - R1003 - Cleaning Store - Distributed

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00F/R1002/Ceiling Structures/Linings/S9					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00F - R1004 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	70m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8161/B00F/R1002/Ceiling Structures/Linings/S9					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00F - R1005 - Staff Study						
Ceiling Structures/Linings	Vermiculite					
	8161/B00F/R1005/Ceiling Structures/Linings/S8					**No Asbestos Detected**
B00F - R1006 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8161/B00F/R1005/Ceiling Structures/Linings/S8					**No Asbestos Detected**
B00F - R1007 - General Storeroom						
Ceiling Structures/Linings	Vermiculite					
	8161/B00F/R1005/Ceiling Structures/Linings/S8					**No Asbestos Detected**
B00F - R1008 - General Storeroom						
Ceiling Structures/Linings	Vermiculite					
	8161/B00F/R1005/Ceiling Structures/Linings/S8					**No Asbestos Detected**
B00F - R1009 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8161/B00F/R1005/Ceiling Structures/Linings/S8					**No Asbestos Detected**
B00F - R1010 - General Learning Space						
Ceiling Structures/Linings	Vermiculite					
	8161/B00F/R1005/Ceiling Structures/Linings/S8					**No Asbestos Detected**
B00F - R1011 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00F/R1002/Ceiling Structures/Linings/S9					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00F - R1012 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8161/B00F/R1002/Ceiling Structures/Linings/S9					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00G - Technological & Applied Studies/Art - 1976 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Materials Technology L.S.

No Asbestos

B00G - R0002 - Metal Technology Bay

No Asbestos

B00G - R0003 - Materials Technology L.S.

No Asbestos

B00G - R0004 - Materials Technology L.S.

No Asbestos

B00G - R0005 - Wood Technology Bay

No Asbestos

B00G - R0006 - Dust Extraction Space

No Asbestos

B00G - R0007 - Materials Technology L.S.

No Asbestos

B00G - R0008 - Plant

No Asbestos

B00G - R0009 - Lift

No Asbestos

B00G - R0010 - Movement

No Asbestos

B00G - R0011 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0012 - Materials Technology L.S.

No Asbestos

B00G - R0013 - Dust Extraction Space

No Asbestos

B00G - R0014 - Wood Technology Bay

No Asbestos

B00G - R0015 - Materials Technology L.S.

No Asbestos

B00G - R0016 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0017 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0018 - Materials Store

No Asbestos

B00G - R0019 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0020 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0021 - Cleaning Store - Distributed

No Asbestos

B00G - R0022 - Materials Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00G - R0023 - Workshop Area						
No Asbestos						
B00G - R0024 - Welding Area						
No Asbestos						
B00G - R0025 - Welding Store						
No Asbestos						
B00G - R0026 - L.P.G. Store						
No Asbestos						
B00G - R0027 - Movement						
No Asbestos						
B00G - R0028 - Plant						
No Asbestos						
B00G - R0029 - Stairs						
No Asbestos						
B00G - R0030 - Stairs						
No Asbestos						
B00G - R0031 - Plant						
No Asbestos						
B00G - R1001 - Design L.S.						
No Asbestos						
B00G - R1002 - Resource/Project Store						
No Asbestos						
B00G - R1003 - Resource/Project Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R1004 - Resources Store						
No Asbestos						
B00G - R1005 - Design L.S.						
No Asbestos						
B00G - R1006 - Art Learning Space						
No Asbestos						
B00G - R1007 - Art Learning Space						
No Asbestos						
B00G - R1008 - Lift						
No Asbestos						
B00G - R1009 - Movement						
No Asbestos						
B00G - R1010 - General Storeroom						
No Asbestos						
B00G - R1011 - Art Learning Space						
No Asbestos						
B00G - R1012 - Kiln Space						
No Asbestos						
B00G - R1013 - Art Learning Space						
No Asbestos						
B00G - R1014 - Darkroom Space						
No Asbestos						
B00G - R1015 - Design L.S.						
No Asbestos						
B00G - R1016 - Cleaning Store - Distributed						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00G - R1017 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R1018 - Computer Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R1019 - Computer Store						
No Asbestos						
B00G - R1020 - Computer Resource						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R1021 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R1022 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
No Asbestos						
B00G - R1023 - Stairs						
No Asbestos						
B00G - R1024 - Plant						
No Asbestos						
B00G - R1025 - Stairs						
No Asbestos						
B00G - R1026 - Plant						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00H - Multi Purpose Facilities - 1958 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00H - M0001 - Control Room

No Asbestos

B00H - M0002 - Performing Arts Store

No Asbestos

B00H - R0001 - Performing Arts Changeroom

Non Accessible

B00H - R0002 - Performing Arts Changeroom

No Asbestos

B00H - R0003 - Multi-Purpose Space

No Asbestos

B00H - R0004 - Chair Store

No Asbestos

B00H - R0005 - Toilets-Girls

No Asbestos

B00H - R0006 - Staff Kitchen

No Asbestos

B00H - R0007 - Toilets-Boys

No Asbestos

B00H - R0008 - Movement

No Asbestos

B00H - R0009 - Movement

No Asbestos

B00H - R0010 - Stage

No Asbestos

B00H - R0012 - Staff Study

No Asbestos

B00H - R0013 - Movement

No Asbestos

B00H - R0014 - Movement

No Asbestos

B00H - R0015 - Movement

No Asbestos

B00H - R0016 - Distribution Board Cupboard Note: No inspection of live electrical installation.

Non Accessible

B00H - R9001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00I - General Learning - 2003 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00I - R0001 - Senior Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00I - R0002 - General Storeroom

No Asbestos

B00I - R0003 - Main Switchroom

No Asbestos

B00I - R0004 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00I - R0005 - Practice/Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00I - R0006 - Movement

No Asbestos

B00I - R0007 - Performance Workspace

No Asbestos

B00I - R0008 - Performing Arts Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00I - R0009 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00I - R0010 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00I - R0011 - Senior Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00I - R0012 - Movement

No Asbestos

B00I - R0013 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00I - R0014 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00I - R0015 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00I - R0016 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00I - R0017 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00I - R0018 - Shower/Change

No Asbestos

B00I - R0019 - Toilets - Boys

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

No Asbestos

B00I - R0020 - Toilets-Disabled

No Asbestos

B00I - R0021 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B00I - R0022 - Cleaning Store - Distributed

No Asbestos

B00I - R0023 - Toilets - Girls

No Asbestos

B00I - R0024 - Shower/Change

No Asbestos

B00I - R0025 - Music Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0026 - Practice/Seminar

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0027 - Music Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0028 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0029 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0030 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00J - Pupil Facilities - 1976 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00J - R0001 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00J - R0002 - Office/Store

No Asbestos

B00J - R0003 - Student Canteen

No Asbestos

B00J - R0004 - Movement

No Asbestos

B00J - R0005 - Covered Area

No Asbestos

B00J - R1001 - Art Outdoor Area

No Asbestos

B00J - R1002 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	
	8161/B00J/R1002/Ceiling Structures/Linings/S10	**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00K - Music - 1976 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00K - R0001 - Cleaning Supplies Store

No Asbestos

B00K - R0002 - Sport Equipment Store

No Asbestos

B00K - R0003 - Music Store

No Asbestos

B00K - R0004 - Music Store

No Asbestos

B00K - R0005 - Cleaning Supplies Store

No Asbestos

B00K - R0006 - Staff Study

No Asbestos

B00K - R0007 - Staff Study

No Asbestos

B00K - R0008 - General Assistants

No Asbestos

B00K - R0009 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00K - R0010 - Cleaning Store - Distributed

No Asbestos

B00K - R0011 - Music Learning Space

No Asbestos

B00K - R0012 - Staff Study

No Asbestos

B00K - R0013 - Movement

No Asbestos

B00K - R0014 - Practice/Seminar

No Asbestos

B00K - R0015 - Music Learning Space

No Asbestos

B00K - R0016 - Movement

No Asbestos

B00K - R0017 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 710 - D15773 - Home Science/Pantry/Laundry : Placement Date - 10/11/2009

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	14.4 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2

R2 - Food Technology L.S.

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	73 m2

R3 - Laundry

Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017