Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Sandy Hollow Public School (1974)**
Region :	**Hunter/Central Coast**
State Electorate :	**Upper Hunter**
Local Government Area :	**Muswellbrook**

Initial Survey :	**Noel Arnold & Associates : 21 - May - 2008**
Register Issue Date :	**22 - Mar - 2017**

1974 - Sandy Hollow Public School
Site Plan (11279)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - Administration - 1970 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/Build+1/Eaves Linings/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00A - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00A/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

B00A - R0002 - Clerical Office/Workroom

No Asbestos

B00A - R0003 - Staff Kitchen

Floor Coverings Res/Textile	Vinyl Tiles					
	1974/B00A/R0003/Floor Coverings Res/Textile/S4					No Asbestos Detected

B00A - R0004 - Sick Bay

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00A/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting	1m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00A/R0004/In-fill-panel/S2					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00A/R0004/Wall Linings Internal/S3					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00A - R0008 - Staff Room

No Asbestos

B00A - R0009 - Principal

No Asbestos

B00A - R0010 - General Storeroom

No Asbestos

B00A - R0011 - Movement

No Asbestos

B00A - R0012 - Staff Toilet

No Asbestos

B00A - R0013 - Staff Shower/Change

No Asbestos

B00A - R0014 - Interview

No Asbestos

B00A - R0015 - Duplicating Workroom

No Asbestos

B00A - R0016 - Staff Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00B - Library - 1970 - Timber (Timber)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 1974/B00B/R0001/Ceiling Structures/Linings/S6	**No Asbestos Detected**

B00B - R0002 - Reading Area

No Asbestos

B00B - R0003 - Library Office/Workroom

No Asbestos

B00B - R0004 - Resources

No Asbestos

B00B - R0005 - K.L.A. Store

No Asbestos

B00B - R0006 - Reading Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00C - General Learning - 1970 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/Build+1/Eaves Linings/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)
In-fill-panel	Flat AC Sheeting	12m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00C/R0017/In-fill-panel/S10					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00C - R0001 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00C/R0017/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)

B00C - R0002 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00C/R0017/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet					
	1974/B00C/R0002/Partition Walls (Cubicles)/S11					No Asbestos Detected

B00C - R0003 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00C/R0017/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)

B00C - R0004 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00C/R0017/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet					
	1974/B00C/R0002/Partition Walls (Cubicles)/S11					No Asbestos Detected

B00C - R0005 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00C/R0017/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)

B00C - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00C/R0017/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)

B00C - R0007 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00C/R0017/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting	12m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00C/R0017/In-fill-panel/S10					Chrysotile (white asbestos)

B00C - R0008 - Withdrawal Space - 1hb

Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00C/R0012/Floor Coverings Res/Textile/S7					Chrysotile (white asbestos)

B00C - R0009 - Home Base Store

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00C/R0012/Floor Coverings Res/Textile/S7					**Chrysotile (white asbestos)**
B00C - R0010 - Home Base						
No Asbestos						
B00C - R0011 - Home Base						
No Asbestos						
B00C - R0012 - Entry Vestibule						
Floor Coverings Res/Textile	Vinyl Tiles	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00C/R0012/Floor Coverings Res/Textile/S7					**Chrysotile (white asbestos)**
B00C - R0013 - K.L.A. Store						
No Asbestos						
B00C - R0014 - Distribution Board					Note: No inspection of live electrical installation.	
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00C/R0012/Floor Coverings Res/Textile/S7					**Chrysotile (white asbestos)**
Wall Linings Internal	Flat AC Sheeting	1m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	1974/B00C/R0014/Wall Linings Internal/S8					**Chrysotile (white asbestos)**
B00C - R0015 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00C/R0012/Floor Coverings Res/Textile/S7					**Chrysotile (white asbestos)**
B00C - R0016 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00C/R0012/Floor Coverings Res/Textile/S7					**Chrysotile (white asbestos)**
B00C - R0017 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00C/R0017/Ceiling Structures/Linings/S9					**Chrysotile (white asbestos)**
In-fill-panel	Flat AC Sheeting	2m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00C/R0017/In-fill-panel/S10					**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00D - General Learning/Pupil Facilities - 1970 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00D/Eaves Linings/S14					Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting	12m2	South, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00C/R0017/In-fill-panel/S10					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00D - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00D/R0001/Ceiling Structures/Linings/S13					Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting	12m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00C/R0017/In-fill-panel/S10					Chrysotile (white asbestos)

B00D - R0002 - Staff Toilet

No Asbestos

B00D - R0003 - Staff Toilet

No Asbestos

B00D - R0004 - Movement

No Asbestos

B00D - R0005 - Canteen

No Asbestos

B00D - R0006 - Home Base

No Asbestos

B00D - R0007 - General Storeroom

No Asbestos

B00D - R0008 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1974/B00D/R0008/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)

B00D - R0009 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00E - Building Services - 1970 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Cleaning Supplies

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00F - Library - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - Reading Area

No Asbestos

B00F - R0002 - Library Office/Workroom

No Asbestos

B00F - R0003 - K.L.A. Store

No Asbestos

B00F - R0004 - Communications Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017