Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Spring Ridge Public School (3091)**
Region :	**New England**
State Electorate :	**Upper Hunter**
Local Government Area :	**Liverpool Plains**

Initial Survey :	**Noel Arnold & Associates : 19 - Mar - 2008**
Reviewed By :	**AECOM : 29 - Apr - 2016**

3091 - Spring Ridge Public School
Site Plan (12011)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00A - Library - 1980 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

Interior

B00A - R0001 - Movement

No Asbestos

B00A - R0002 - Reading Area

No Asbestos

B00A - R0003 - Library Office/Workroom

No Asbestos

B00A - R0004 - Communications Room

No Asbestos

B00A - R0005 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3091/B00A/R0005/Wall Linings Internal/S2					**Chrysotile (white asbestos)**
Electrical Mounting Board	Resinous Board	1Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00B - General Learning - 1965 - Timber (Timber)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible Height Restriction					
Eaves Linings	Flat AC Sheeting	20m2	North, east	Good Condition (1)	Low (1)	Low Priority (2-3)
	3091/B00B/Eaves Linings/S5					**Chrysotile (white asbestos)**

Interior

B00B - R0001 - Movement

No Asbestos

B00B - R0002 - Home Base

Wall Linings Internal	Flat AC Sheeting	30m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3091/B00B/R0002/Wall Linings Internal/S3					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00B - R0006 - Home Base

No Asbestos

B00B - R0007 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles					
	3091/B00B/R0007/Floor Coverings Res/Textile/S4					**No Asbestos Detected**

B00B - R0008 - General Storeroom

No Asbestos

B00B - R0009 - Withdrawal Space - 1hb

No Asbestos

B00B - R0010 - Interview

No Asbestos

B00B - R0011 - Withdrawal Space - 2hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00C - Communal Facilities - 1920 - Timber Shed (Timber Shed)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00C - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00D - Pupil Facilities/Building Services - 1966 - Timber (Timber)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3091/B00D/Eaves Linings/S1					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

Interior

B00D - R0001 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3091/B00D/Eaves Linings/S1					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00D - R0003 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3091/B00D/Eaves Linings/S1					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00D - R0004 - General Assistant/Bulk Store

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3091/B00D/Eaves Linings/S1					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00D - R0005 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3091/B00D/Eaves Linings/S1					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00E - Staff Facilities/Administration - 1912 - Timber (Timber)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible

Interior

B00E - R0002 - Clerical Office

No Asbestos

B00E - R0004 - Entry Vestibule

No Asbestos

B00E - R0005 - Principal

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00F - Building Services - 2001 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B00F - R0001 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00G - General Learning - 2006 - Steel (Steel)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00G - R0001 - Home Base

No Asbestos

B00G - R0002 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00H - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00H - R0001 - Home Base

No Asbestos

B00H - R0002 - Home Base Store

No Asbestos

B00H - R0003 - Practical Activities

No Asbestos

B00H - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00I - Residential Facilities - 1960 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Void	Requires Inspection
Underfloor Void	Requires Inspection

Interior

B00I - R0001 - Residence - Laundry

Recently Modified Space	Requires Inspection

B00I - R0002 - Residence - Pantry

Recently Modified Space	Requires Inspection

B00I - R0003 - Residence - Kitchen

Recently Modified Space	Requires Inspection

B00I - R0004 - Residence - Living

Recently Modified Space	Requires Inspection

B00I - R0005 - Residence - Movement

Recently Modified Space	Requires Inspection

B00I - R0006 - Residence - Bedroom

Recently Modified Space	Requires Inspection

B00I - R0007 - Residence - Bathroom

Recently Modified Space	Requires Inspection

B00I - R0008 - Residence - Bedroom

Recently Modified Space	Requires Inspection

B00I - R0009 - Residence - Bedroom

Recently Modified Space	Requires Inspection

B00I - R0010 - Residence - Bedroom

Recently Modified Space	Requires Inspection

B00I - R0011 - Residence - Movement

Recently Modified Space	Requires Inspection

B00I - R0012 - Residence - Movement

Recently Modified Space	Requires Inspection

B00I - R0013 - Residence - Toilet

Recently Modified Space	Requires Inspection

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B0I2 - Residential Facilities - 1970 - Fibre Clad Shed (Fibre Clad Shed)

Exterior

Ceiling Void	Requires Inspection
Underfloor Void	Requires Inspection

Interior

B0I2 - R0001 - Residence - Garage

Recently Modified Space	Requires Inspection

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017