Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Sackville Street Public School (4491)**
Region :	**South Western Sydney**
State Electorate :	**Macquarie Fields**
Local Government Area :	**Campbelltown**

Initial Survey :	**Noel Arnold & Associates : 14 - May - 2008**
Reviewed By :	**Parsons Brinckerhoff : 05 - Aug - 2015**

4491 - Sackville Street Public School
Site Plan (11356)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - General Learning - 1977 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Non Accessible Area - No manhole access point
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00A - R0001 - Home Base

No Asbestos

B00A - R0002 - Toilets - Boys/Girls

Wall Linings Internal	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00A/R0002/Wall Linings Internal/S6					**Chrysotile (White asbestos)**

B00A - R0003 - Withdrawal Space - 1hb

No Asbestos

B00A - R0004 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00A/R0004/Floor Coverings Res/Textile/S5					**Chrysotile (White asbestos)**

B00A - R0005 - General Storeroom

No Asbestos

B00A - R0006 - Home Base

No Asbestos

B00A - R0007 - General Storeroom

No Asbestos

B00A - R0008 - Home Base Store

No Asbestos

B00A - R0009 - Withdrawal Space - 1hb

No Asbestos

B00A - R0010 - Toilets - Boys/Girls

Wall Linings Internal	Flat AC Sheeting	10m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00A/R0002/Wall Linings Internal/S6					**Chrysotile (White asbestos)**

B00A - R0011 - General Storeroom

No Asbestos

B00A - R0012 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00A/R0004/Floor Coverings Res/Textile/S5					**Chrysotile (White asbestos)**

B00A - R0013 - Home Base

No Asbestos

B00A - R0014 - General Storeroom

No Asbestos

B00A - R0015 - Toilets - Boys/Girls

Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00A/R0002/Wall Linings Internal/S6					**Chrysotile (White asbestos)**

B00A - R0016 - Withdrawal Space - 1hb

No Asbestos

B00A - R0017 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00A/R0004/Floor Coverings Res/Textile/S5					**Chrysotile (White asbestos)**

B00A - R0018 - External Movement

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result
No Asbestos		

B00A - R0019 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00B - General Learning/Pupil Facilities - 1977 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Non Accessible Area - No manhole access point
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00B - R0001 - Home Base

No Asbestos

B00B - R0002 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00B/R0002/Floor Coverings Res/Textile/S7					**Chrysotile (White asbestos)**

B00B - R0003 - Home Base

No Asbestos

B00B - R0004 - Toilets - Girls

No Asbestos

B00B - R0005 - Toilets - Boys

No Asbestos

B00B - R0006 - External Movement

No Asbestos

B00B - R0007 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00C - General Learning/Pupil Facilities - 1977 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Non Accessible Area - No manhole access point					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00C - R0001 - Home Base

No Asbestos

B00C - R0002 - Practical Activities - 1hb

No Asbestos

B00C - R0003 - Cleaning Supplies

Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00C/R0005/Floor Coverings Res/Textile/S9					**Chrysotile (White asbestos)**
Ceiling Structures/Linings	Vermiculite					
	4491/B00C/R0003/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B00C - R0004 - Community Clinic

Ceiling Structures/Linings	Vermiculite					
	4491/B00C/R0003/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B00C - R0005 - Interview

Ceiling Structures/Linings	Vermiculite					
	4491/B00C/R0003/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B00C - R0006 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00C/R0005/Floor Coverings Res/Textile/S9					**Chrysotile (White asbestos)**
Ceiling Structures/Linings	Vermiculite					
	4491/B00C/R0003/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B00C - R0007 - Cleaning Distributed Store

Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00C/R0005/Floor Coverings Res/Textile/S9					**Chrysotile (White asbestos)**

B00C - R0008 - Movement

Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00C/R0005/Floor Coverings Res/Textile/S9					**Chrysotile (White asbestos)**
Ceiling Structures/Linings	Vermiculite					
	4491/B00C/R0003/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B00C - R0009 - Toilets - Girls

No Asbestos

B00C - R0010 - Toilets - Boys

No Asbestos

B00C - R0011 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00D - General Learning - 1977 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Non Accessible Area - No manhole access point
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00D - R0001 - Home Base

No Asbestos

B00D - R0002 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00D/R0002/Floor Coverings Res/Textile/S10					**Chrysotile (White asbestos)**

B00D - R0003 - Home Base

No Asbestos

B00D - R0004 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00D/R0002/Floor Coverings Res/Textile/S10					**Chrysotile (White asbestos)**

B00D - R0005 - Home Base

No Asbestos

B00D - R0006 - External Movement

No Asbestos

B00D - R0007 - Movement

No Asbestos

B00D - R0008 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00E - General Learning/Pupil Facilities - 1977 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Non Accessible Area - No manhole access point
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00E - R0001 - Sports Store

No Asbestos

B00E - R0002 - Home Base

No Asbestos

B00E - R0003 - Practical Activities - 1hb

No Asbestos

B00E - R0004 - Home Base

No Asbestos

B00E - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0006 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	North, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00E/R0008/Partition Walls (Cubicles)/S11					**Chrysotile (White asbestos)**

B00E - R0007 - Cleaning Distributed Store

No Asbestos

B00E - R0008 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	North, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00E/R0008/Partition Walls (Cubicles)/S11					**Chrysotile (White asbestos)**

B00E - R0009 - External Movement

No Asbestos

B00E - R0010 - External Movement

No Asbestos

B00E - R0011 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00F - General Learning - 1977 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Non Accessible Area - No manhole access point
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00F - R0001 - Home Base

No Asbestos

B00F - R0002 - Practical Activities - 1hb

No Asbestos

B00F - R0003 - Home Base

No Asbestos

B00F - R0004 - Movement

No Asbestos

B00F - R0005 - External Movement

No Asbestos

B00F - R0006 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00G - General Learning/Pupil Facilities - 1979 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	Non Accessible Area - No manhole access point					

Interior

B00G - R0001 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00G/R0001/Partition Walls (Cubicles)/S12					Chrysotile (White asbestos)
Ceiling Structures/Linings	Vermiculite 4491/B00C/R0003/Ceiling Structures/Linings/S15					No Asbestos Detected

B00G - R0002 - Disabled Toilet

Ceiling Structures/Linings	Vermiculite 4491/B00C/R0003/Ceiling Structures/Linings/S15					No Asbestos Detected

B00G - R0003 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00G/R0001/Partition Walls (Cubicles)/S12					Chrysotile (White asbestos)
Ceiling Structures/Linings	Vermiculite 4491/B00C/R0003/Ceiling Structures/Linings/S15					No Asbestos Detected

B00G - R0004 - General Storeroom

Ceiling Structures/Linings	Vermiculite 4491/B00C/R0003/Ceiling Structures/Linings/S15					No Asbestos Detected

B00G - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0006 - General Storeroom

Ceiling Structures/Linings	Vermiculite 4491/B00C/R0003/Ceiling Structures/Linings/S15					No Asbestos Detected

B00G - R0007 - Home Base

No Asbestos

B00G - R0008 - Practical Activities - 1hb

No Asbestos

B00G - R0009 - Home Base

No Asbestos

B00G - R0010 - Movement

No Asbestos

B00G - R0011 - Music Store

No Asbestos

B00G - R0012 - Special Programs Room

No Asbestos

B00G - R0013 - Craft Store

Ceiling Structures/Linings	Vermiculite 4491/B00C/R0003/Ceiling Structures/Linings/S15					No Asbestos Detected

B00G - R0014 - Personal Effects Storage

No Asbestos

B00G - R0015 - Home Base

No Asbestos

B00G - R0016 - Practical Activities - 1hb

No Asbestos

B00G - R0017 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00G - R0018 - External Movement

No Asbestos

B00G - R0019 - External Movement

No Asbestos

B00G - R0020 - External Movement

No Asbestos

B00G - R0021 - External Movement

No Asbestos

B00G - R0022 - External Movement

No Asbestos

B00G - R0023 - External Stairs

No Asbestos

B00G - R1001 - External Movement

No Asbestos

B00G - R1002 - Practical Activities - 1hb

No Asbestos

B00G - R1003 - Home Base

No Asbestos

B00G - R1004 - Withdrawal Space - 1hb

No Asbestos

B00G - R1005 - External Movement

No Asbestos

B00G - R1006 - Home Base

No Asbestos

B00G - R1007 - Personal Effects Storage

No Asbestos

B00G - R1008 - Movement

No Asbestos

B00G - R1009 - Special Programs Store

No Asbestos

B00G - R1010 - Movement

No Asbestos

B00G - R1011 - Home Base

No Asbestos

B00G - R1012 - Personal Effects Storage

No Asbestos

B00G - R1013 - Practical Activities - 1hb

No Asbestos

B00G - R1014 - Personal Effects Storage

No Asbestos

B00G - R1015 - Home Base

No Asbestos

B00G - R1016 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00G - R1017 - Staff Room Annexe

No Asbestos

B00G - R1018 - Withdrawal Space - 1hb

No Asbestos

B00G - R1019 - Toilets - Boys

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00G/R0001/Partition Walls (Cubicles)/S12					**Chrysotile (White asbestos)**
B00G - R1020 - Cleaning Distributed Store						
No Asbestos						
B00G - R1021 - Toilets - Girls						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00G/R0001/Partition Walls (Cubicles)/S12					**Chrysotile (White asbestos)**
B00G - R1022 - External Movement						
No Asbestos						
B00G - R1023 - External Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00H - Administration/Library - 1977 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found	
Ceiling Voids	Non Accessible Area - No manhole access point	

Interior

B00H - R0001 - Entry Vestibule

Ceiling Structures/Linings	Vermiculite 4491/B00C/R0003/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B00H - R0006 - Main Switch Board

No Asbestos

B00H - R0007 - Deputy Principal

Ceiling Structures/Linings	Vermiculite 4491/B00C/R0003/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B00H - R0008 - Interview

Ceiling Structures/Linings	Vermiculite 4491/B00C/R0003/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B00H - R0009 - Staff Toilet

Ceiling Structures/Linings	Vermiculite 4491/B00C/R0003/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B00H - R0010 - Cleaning Distributed Store

No Asbestos

B00H - R0011 - Staff Toilet

Ceiling Structures/Linings	Vermiculite 4491/B00C/R0003/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B00H - R0012 - Sick Bay

Ceiling Structures/Linings	Vermiculite 4491/B00C/R0003/Ceiling Structures/Linings/S15					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00H/R0013/Floor Coverings Res/Textile/S2					**Chrysotile (White asbestos)**

B00H - R0013 - Security Store

Ceiling Structures/Linings	Vermiculite 4491/B00C/R0003/Ceiling Structures/Linings/S15					**No Asbestos Detected**
Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00H/R0013/Floor Coverings Res/Textile/S2					**Chrysotile (White asbestos)**

B00H - R0015 - Deputy Principal

Ceiling Structures/Linings	Vermiculite 4491/B00C/R0003/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B00H - R0016 - External Movement

No Asbestos

B00H - R0017 - External Movement

No Asbestos

B00H - R0018 - Movement

Ceiling Structures/Linings	Vermiculite 4491/B00C/R0003/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B00H - R0019 - Clerical/Printing

Ceiling Structures/Linings	Vermiculite 4491/B00C/R0003/Ceiling Structures/Linings/S15					**No Asbestos Detected**

B00H - R0020 - Staff Room

Ceiling Structures/Linings	Vermiculite 4491/B00C/R0003/Ceiling Structures/Linings/S15					**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00H - R0021 - Staff Kitchen						
Ceiling Structures/Linings	Vermiculite					
	4491/B00C/R0003/Ceiling Structures/Linings/S15					**No Asbestos Detected**
B00H - R0022 - Staff Room Annexe						
No Asbestos						
B00H - R0023 - Interview/Office - Type 3						
No Asbestos						
B00H - R0024 - Principal						
No Asbestos						
B00H - R0025 - External Movement						
No Asbestos						
B00H - R1001 - External Movement						
No Asbestos						
B00H - R1002 - Entry Vestibule						
No Asbestos						
B00H - R1003 - Toilets - Girls						
Wall Linings Internal	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00H/R1003/Wall Linings Internal/S3					**Chrysotile (White asbestos)**
B00H - R1004 - Cleaning Distributed Store						
No Asbestos						
B00H - R1005 - Library Office/Workroom						
No Asbestos						
B00H - R1006 - Communications Room						
No Asbestos						
B00H - R1007 - K.L.A. Store						
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4491/B00H/R1007/Floor Coverings Res/Textile/S14					**Chrysotile (white asbestos)**
B00H - R1008 - Library Office/Workroom						
No Asbestos						
B00H - R1011 - Reading Area						
No Asbestos						
B00H - R1012 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00H - R1013 - Shower/Change						
Wall Linings Internal	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00H/R1003/Wall Linings Internal/S3					**Chrysotile (White asbestos)**
B00H - R1014 - Toilets - Boys						
Wall Linings Internal	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00H/R1003/Wall Linings Internal/S3					**Chrysotile (White asbestos)**
B00H - R1015 - Special Programs Room						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00I - Pupil Facilities/Communal Facilities - 1977 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	Non Accessible Area - No manhole access point					

Interior

B00I - R0001 - Cleaning Supplies

Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00I/R0002/Floor Coverings Res/Textile/S4					Chrysotile (White asbestos)

B00I - R0002 - Cleaning Distributed Store

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4491/B00I/R0002/Floor Coverings Res/Textile/S4					Chrysotile (White asbestos)

B00I - R0003 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00I - R0004 - Toilets - Boys

No Asbestos

B00I - R0005 - Movement

No Asbestos

B00I - R0006 - Sports Store

No Asbestos

B00I - R0007 - Toilets - Girls

No Asbestos

B00I - R0008 - Raised Platform

No Asbestos

B00I - R0009 - Hall Chair Store

No Asbestos

B00I - R0010 - Uniform Shop

No Asbestos

B00I - R0011 - Communal Space

No Asbestos

B00I - R0012 - Staff Toilet

No Asbestos

B00I - R0013 - Canteen Office/Store

No Asbestos

B00I - R0014 - Canteen Office/Store

No Asbestos

B00I - R0015 - Canteen

No Asbestos

B00I - R0016 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00J - Building Services - 1977 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00J - R0001 - External Movement

No Asbestos

B00J - R0002 - General Assistant/Bulk Store

No Asbestos

B00J - R0003 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00K - Other-After School Care - 1999 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00K - R0001 - External Movement

No Asbestos

B00K - R0002 - External Movement

No Asbestos

B00K - R0003 - No Access

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00L - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00L - R0001 - External Movement

No Asbestos

B00L - R0002 - Practical Activities - 1hb

No Asbestos

B00L - R0003 - Home Base Store

No Asbestos

B00L - R0004 - Home Base

No Asbestos

B00L - R0005 - Withdrawal Space - 2hb

No Asbestos

B00L - R0006 - Home Base

No Asbestos

B00L - R0007 - Home Base Store

No Asbestos

B00L - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00M - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00M - R0001 - External Movement

No Asbestos

B00M - R0002 - Practical Activities - 1hb

No Asbestos

B00M - R0003 - Home Base Store

No Asbestos

B00M - R0004 - Home Base

No Asbestos

B00M - R0005 - Withdrawal Space - 2hb

No Asbestos

B00M - R0006 - Home Base

No Asbestos

B00M - R0007 - Home Base Store

No Asbestos

B00M - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017