Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Tuggerawong Public School (4097)**
Region :	**Hunter/Central Coast**
State Electorate :	**Wyong**
Local Government Area :	**Wyong**

Initial Survey :	**Noel Arnold & Associates : 29 - Mar - 2008**
Reviewed By :	**AECOM : 22 - Jun - 2016**

4097 - Tuggerawong Public School
Site Plan (11351)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00A - Administration - 1983 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible	
Ceiling Voids - Flat Roof	No Asbestos Found	

Interior

B00A - R0001 - Movement

No Asbestos

B00A - R0002 - Movement

No Asbestos

B00A - R0003 - Staff Toilet

No Asbestos

B00A - R0004 - Staff Toilet

No Asbestos

B00A - R0005 - Interview

No Asbestos

B00A - R0006 - Deputy Principal

No Asbestos

B00A - R0007 - Principal

No Asbestos

B00A - R0008 - Entry Vestibule

No Asbestos

B00A - R0009 - Clerical Office

No Asbestos

B00A - R0010 - Sick Bay

No Asbestos

B00A - R0011 - General Storeroom

No Asbestos

B00A - R0014 - Duplicating Workroom

Floor Coverings Res/Textile	Vinyl Tiles	
	4097/B00A/R0018/Floor Coverings Res/Textile/S3	**No Asbestos Detected**

B00A - R0015 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0016 - Cleaning Distributed Store

No Asbestos

B00A - R0017 - Security Store

No Asbestos

B00A - R0018 - Staff Room

Floor Coverings Res/Textile	Vinyl Tiles	
	4097/B00A/R0018/Floor Coverings Res/Textile/S3	**No Asbestos Detected**

B00A - R0019 - Security Store

No Asbestos

B00A - R0020 - Main Switch Board

No Asbestos

B00A - R0021 - Cleaning Supplies

Floor Coverings Res/Textile	Vinyl Tiles	
	4097/B00A/R0021/Floor Coverings Res/Textile/S13	**No Asbestos Detected**

B00A - R0022 - Movement

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4097/B00A/R0023/Ceiling Structures/Linings/S2					**Chrysotile (white asbestos)**
B00A - R0023 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4097/B00A/R0023/Ceiling Structures/Linings/S2					**Chrysotile (white asbestos)**
B00A - R0024 - Movement						
No Asbestos						
B00A - R0025 - Interview						
No Asbestos						
B00A - R0026 - Disabled Shower/Toilet						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - General Learning - 1983 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible	
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible	

Interior

B00B - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4097/B00B/R0001/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)

B00B - R0002 - General Storeroom

Floor Coverings Res/Textile	Vinyl Sheet	
	4097/B00B/R0004/Floor Coverings Res/Textile/S12	No Asbestos Detected

B00B - R0003 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Sheet	
	4097/B00B/R0004/Floor Coverings Res/Textile/S12	No Asbestos Detected

B00B - R0004 - Sports Store

Floor Coverings Res/Textile	Vinyl Sheet	
	4097/B00B/R0004/Floor Coverings Res/Textile/S12	No Asbestos Detected

B00B - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4097/B00B/R0001/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)

B00B - R0006 - Personal Effects Storage

No Asbestos

B00B - R0007 - Personal Effects Storage

No Asbestos

B00B - R0008 - Home Base

No Asbestos

B00B - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4097/B00B/R0001/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)

B00B - R0010 - Security Store

No Asbestos

B00B - R0011 - Withdrawal Space - 1hb

No Asbestos

B00B - R0012 - Security Store

No Asbestos

B00B - R0013 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00B - R0014 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4097/B00B/R0001/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)

B00B - R0015 - Home Base

No Asbestos

B00B - R0016 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00C - Pupil Facilities - 1983 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4097/B00D/Eaves Linings/S16				**Chrysotile (white asbestos)**	

Interior

B00C - R0001 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4097/B00C/R0001/Partition Walls (Cubicles)/S5				**Chrysotile (white asbestos)**	
Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4097/B00B/R0001/Ceiling Structures/Linings/S4				**Chrysotile (white asbestos)**	

B00C - R0002 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4097/B00C/R0002/Ceiling Structures/Linings/S14				**Chrysotile (white asbestos)**	
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4097/B00C/R0001/Partition Walls (Cubicles)/S5				**Chrysotile (white asbestos)**	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00D - General Learning - 1983 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4097/B00D/Eaves Linings/S16					**Chrysotile (white asbestos)**
Underfloor Voids	AC Fragments/Debris	4Unit	Variable positions	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4097/B00D/Underfloor Voids/S15					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

Interior

B00D - R0001 - Withdrawal Space - 1hb

No Asbestos

B00D - R0002 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00E - General Learning - 1983 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4097/B00E/Eaves Linings/S7					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

Interior

B00E - R0001 - Withdrawal Space - 1hb

No Asbestos

B00E - R0002 - Practical Activities - 1hb

No Asbestos

B00E - R0003 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4097/B00E/R0003/Floor Coverings Res/Textile/S8					**Chrysotile (white asbestos)**

B00E - R0004 - Home Base

In-fill-panel	Flat AC Sheeting	2m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4097/B00E/R0005/Electrical Backing Board/S9					**Chrysotile (white asbestos)**

B00E - R0005 - Home Base

In-fill-panel	Flat AC Sheeting	2m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4097/B00E/R0005/Electrical Backing Board/S9					**Chrysotile (white asbestos)**

B00E - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4097/B00E/R0006/Ceiling Structures/Linings/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00E - R0007 - Covered Outdoor Learning Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00F - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00F - R0001 - Movement

No Asbestos

B00F - R0002 - Practical Activities - 1hb

No Asbestos

B00F - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00H - General Learning - 1983 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found	
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible	
Eaves Linings	Flat AC Sheeting 4097/B00H/R0010/Ceiling Structures/Linings/S1	**No Asbestos Detected**

Interior

B00H - R0001 - Home Base Store

No Asbestos

B00H - R0002 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4097/B00H/R0010/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00H - R0003 - Withdrawal Space - 1hb

No Asbestos

B00H - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4097/B00H/R0010/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00H - R0005 - Home Base Store

No Asbestos

B00H - R0006 - Home Base

No Asbestos

B00H - R0007 - Practical Activities - 1hb

No Asbestos

B00H - R0008 - Home Base

No Asbestos

B00H - R0009 - Practical Activities - 1hb

No Asbestos

B00H - R0010 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4097/B00H/R0010/Ceiling Structures/Linings/S1	**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00J - Library - 1996 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found	
Eaves Linings	Flat AC Sheeting 4097/B00J/Eaves Linings/S10	**No Asbestos Detected**
Ceiling Voids	No Asbestos Found	

Interior

B00J - R0001 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00J - R0002 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00J - R0003 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found	

B00J - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4097/B00J/R0004/Ceiling Structures/Linings/S11	**No Asbestos Detected**

B00J - R0005 - Movement

No Asbestos

B00J - R0006 - Covered Outdoor Learning Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00K - Other-Community Use - 2007 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00K - R0001 - Other

No Asbestos

B00K - R0002 - Toilets - Boys/Disabled Cubicle

No Asbestos

B00K - R0003 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00L - Pupil Facilities - 2007 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible	
Ceiling Voids	No Asbestos Found	

Interior

B00L - R0001 - External Movement

No Asbestos

B00L - R0002 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00M - Building Services - 2008 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B00M - R0001 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00N - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B00N - R0001 - Communal Space

No Asbestos

B00N - R0002 - Raised Platform

No Asbestos

B00N - R0003 - Cleaning Distributed Store

No Asbestos

B00N - R0004 - General Storeroom

No Asbestos

B00N - R0005 - Movement

No Asbestos

B00N - R0006 - Toilets - Boys

No Asbestos

B00N - R0007 - Sound Cupboard

No Asbestos

B00N - R0008 - Movement

No Asbestos

B00N - R0009 - Toilets - Girls

No Asbestos

B00N - R0010 - P.E. Store

No Asbestos

B00N - R0011 - Communal/Performance Store

No Asbestos

B00N - R0012 - Hall Chair Store

No Asbestos

B00N - R0013 - Main Switch Board

No Asbestos

B00N - R0014 - Disabled Shower/Toilet

No Asbestos

B00N - R0015 - Movement

No Asbestos

B00N - R0016 - Ramp

No Asbestos

B00N - R0017 - Movement

No Asbestos

B00N - R0018 - Covered Outdoor Learning Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 603 - D11274 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 23/04/2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D13559 - Learning Unit - Standard With P.A.A. : Placement Date - 3/12/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 801 - D15102 - FSU : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	8.64 m2

Interior

R1 - Canteen

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	45 m2

R2 - Covered Area

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017