Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Tanilba Bay Public School (4547)**
Region :	**Hunter/Central Coast**
State Electorate :	**Port Stephens**
Local Government Area :	**Port Stephens**

Initial Survey :	**Noel Arnold & Associates : 20 - May - 2008**
Reviewed By :	**AECOM : 29 - Apr - 2016**

4547 - Tanilba Bay Public School
Site Plan (11485)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00A - Administration - 1982 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found	
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible slab on ground no access points.	
Eaves Linings	Flat AC Sheeting 4547/B00A/R0020/Ceiling Structures/Linings/S1	**No Asbestos Detected**

Interior

B00A - R0001 - Clerical Office/Workroom

No Asbestos

B00A - R0002 - Principal

No Asbestos

B00A - R0003 - Staff Toilet

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4547/B00A/R0005/Partition Walls (Cubicles)/S3				**Chrysotile (white asbestos)**	

B00A - R0004 - Disabled Toilet

No Asbestos

B00A - R0005 - Staff Toilet

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4547/B00A/R0005/Partition Walls (Cubicles)/S3				**Chrysotile (white asbestos)**	

B00A - R0006 - Interview

Floor Coverings Res/Textile	Vinyl Tiles 4547/B00A/R0010/Floor Coverings Res/Textile/S2	**No Asbestos Detected**

B00A - R0007 - Movement

Floor Coverings Res/Textile	Vinyl Tiles 4547/B00A/R0010/Floor Coverings Res/Textile/S2	**No Asbestos Detected**

B00A - R0008 - Community Clinic

Floor Coverings Res/Textile	Vinyl Tiles 4547/B00A/R0010/Floor Coverings Res/Textile/S2	**No Asbestos Detected**

B00A - R0009 - Sick Bay - Shower/Toilet

No Asbestos

B00A - R0010 - Cleaning Distributed Store

Floor Coverings Res/Textile	Vinyl Tiles 4547/B00A/R0010/Floor Coverings Res/Textile/S2	**No Asbestos Detected**

B00A - R0011 - Security Store

Floor Coverings Res/Textile	Vinyl Tiles 4547/B00A/R0010/Floor Coverings Res/Textile/S2	**No Asbestos Detected**

B00A - R0012 - Staff Room

No Asbestos

B00A - R0013 - Deputy Principal

No Asbestos

B00A - R0014 - Deputy Principal

No Asbestos

B00A - R0015 - Duplicating Workroom

No Asbestos

B00A - R0016 - Clerical Office

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
No Asbestos						
B00A - R0017 - Sick Bay						
Floor Coverings Res/Textile	Vinyl Tiles					
	4547/B00A/R0010/Floor Coverings Res/Textile/S2					**No Asbestos Detected**
B00A - R0018 - Entry Vestibule						
No Asbestos						
B00A - R0019 - Movement						
No Asbestos						
B00A - R0020 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
	4547/B00A/R0020/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00A - R0021 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
	4547/B00A/R0020/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00A - R0022 - Distribution Board						Note: No inspection of live electrical installation.
Ceiling Structures/Linings	Flat AC Sheeting					
	4547/B00A/R0022/Ceiling Structures/Linings/S5					**No Asbestos Detected**
Door Backing	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4547/B00A/R0022/Door Backing/S4					**Chrysotile (white asbestos)**
B00A - R0023 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
	4547/B00A/R0020/Ceiling Structures/Linings/S1					**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00B - General Learning - 1982 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible slab on ground no access points.	
Ceiling Voids - Raked Ceiling	No Asbestos Found	
Eaves Linings	Flat AC Sheeting	
	4547/B00B/Eaves Linings/S6	**No Asbestos Detected**

Interior

B00B - R0001 - Movement

No Asbestos

B00B - R0002 - Home Base

No Asbestos

B00B - R0003 - Home Base Store

No Asbestos

B00B - R0004 - Withdrawal Space - 1hb

No Asbestos

B00B - R0005 - Home Base

No Asbestos

B00B - R0006 - Home Base Store

No Asbestos

B00B - R0007 - Practical Activities - 1hb

No Asbestos

B00B - R0008 - General Storeroom

No Asbestos

B00B - R0009 - General Storeroom

No Asbestos

B00B - R0010 - Toilets - Girls

No Asbestos

B00B - R0011 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4547/B00A/R0005/Partition Walls (Cubicles)/S3				**Chrysotile (white asbestos)**	

B00B - R0013 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	
	4547/B00A/R0020/Ceiling Structures/Linings/S1	**No Asbestos Detected**

B00B - R0014 - Personal Effects Storage

No Asbestos

B00B - R0015 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	
	4547/B00B/Eaves Linings/S6	**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00C - General Learning - 1982 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found	
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible slab on ground no access points.	
Eaves Linings	Flat AC Sheeting 4547/B00B/Eaves Linings/S6	**No Asbestos Detected**
Wall Cladding	Flat AC Sheeting 4547/B00D/Wall Cladding/S7	**No Asbestos Detected**

Interior

B00C - R0001 - Home Base

No Asbestos

B00C - R0002 - Withdrawal Space - 1hb

No Asbestos

B00C - R0003 - Home Base Store

No Asbestos

B00C - R0004 - Kiln Room

No Asbestos

B00C - R0005 - Practical Activities - 1hb

No Asbestos

B00C - R0006 - Staff Room Annexe

No Asbestos

B00C - R0007 - General Storeroom

No Asbestos

B00C - R0008 - Interview

No Asbestos

B00C - R0009 - Home Base

No Asbestos

B00C - R0010 - Home Base Store

No Asbestos

B00C - R0011 - Practical Activities - 1hb

No Asbestos

B00C - R0012 - Home Base Store

No Asbestos

B00C - R0013 - Home Base

No Asbestos

B00C - R0014 - Home Base

No Asbestos

B00C - R0015 - Withdrawal Space - 1hb

No Asbestos

B00C - R0016 - Home Base Store

No Asbestos

B00C - R0017 - Home Base Store

No Asbestos

B00C - R0018 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4547/B00A/R0005/Partition Walls (Cubicles)/S3					**Chrysotile (white asbestos)**

B00C - R0019 - Toilets - Girls

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4547/B00A/R0005/Partition Walls (Cubicles)/S3					**Chrysotile (white asbestos)**
B00C - R0020 - Cleaning Distributed Store						
No Asbestos						
B00C - R0021 - Movement						
No Asbestos						
B00C - R0022 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
	4547/B00A/R0020/Ceiling Structures/Linings/S1					**No Asbestos Detected**
B00C - R0023 - Movement						
No Asbestos						
B00C - R0024 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00D - Communal Facilities/Tiered Learning - 1982 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found	
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible slab on ground no access points.	
Wall Cladding	Flat AC Sheeting 4547/B00D/Wall Cladding/S7	**No Asbestos Detected**

Interior

B00D - R0001 - Garden Store

No Asbestos

B00D - R0002 - General Assistant/Bulk Store

No Asbestos

B00D - R0003 - Sports Store

No Asbestos

B00D - R0004 - General Storeroom

No Asbestos

B00D - R0005 - Hall Chair Store

Floor Coverings Res/Textile	Vinyl Tiles 4547/B00A/R0010/Floor Coverings Res/Textile/S2	**No Asbestos Detected**

B00D - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0007 - Cleaning Distributed Store

Floor Coverings Res/Textile	Vinyl Tiles 4547/B00A/R0010/Floor Coverings Res/Textile/S2	**No Asbestos Detected**

B00D - R0008 - Special Programs Room

No Asbestos

B00D - R0009 - Canteen Office/Store

No Asbestos

B00D - R0010 - Staff Toilet

No Asbestos

B00D - R0011 - Canteen Office/Store

No Asbestos

B00D - R0012 - Canteen

No Asbestos

B00D - R0014 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4547/B00A/R0005/Partition Walls (Cubicles)/S3				**Chrysotile (white asbestos)**	

B00D - R0015 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4547/B00A/R0005/Partition Walls (Cubicles)/S3				**Chrysotile (white asbestos)**	

B00D - R0019 - Raised Platform

No Asbestos

B00D - R0020 - Movement

Floor Coverings Res/Textile	Vinyl Tiles 4547/B00A/R0010/Floor Coverings Res/Textile/S2	**No Asbestos Detected**

B00D - R0024 - External Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Flat AC Sheeting					
	4547/B00B/Eaves Linings/S6					**No Asbestos Detected**
B00D - R0025 - Communal Space						
No Asbestos						
B00D - R0026 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
	4547/B00B/Eaves Linings/S6					**No Asbestos Detected**
B00D - R0027 - Covered Outdoor Learning Area						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00E - Library - 1982 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible slab on ground no access points.	
Ceiling Voids - Raked Ceiling	No Asbestos Found	
Eaves Linings	Flat AC Sheeting 4547/B00B/Eaves Linings/S6	**No Asbestos Detected**
Wall Cladding	Flat AC Sheeting 4547/B00D/Wall Cladding/S7	**No Asbestos Detected**

Interior

B00E - R0001 - Movement

No Asbestos

B00E - R0002 - Communications Room

No Asbestos

B00E - R0003 - Library Office/Workroom

No Asbestos

B00E - R0004 - Movement

No Asbestos

B00E - R0005 - Reading Area

No Asbestos

B00E - R0006 - Security Store

No Asbestos

B00E - R0007 - Library Office/Workroom

Floor Coverings Res/Textile	Vinyl Tiles 4547/B00A/R0010/Floor Coverings Res/Textile/S2	**No Asbestos Detected**

B00E - R0008 - Cleaning Distributed Store

Floor Coverings Res/Textile	Vinyl Tiles 4547/B00A/R0010/Floor Coverings Res/Textile/S2	**No Asbestos Detected**

B00E - R0009 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00F - General Learning - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible slab on ground no access points.
Ceiling Voids	No Asbestos Found

Interior

B00F - R0001 - Movement

No Asbestos

B00F - R0002 - Personal Effects Storage

No Asbestos

B00F - R0003 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0006 - Practical Activities - 1hb

No Asbestos

B00F - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0008 - Practical Activities - 1hb

No Asbestos

B00F - R0009 - Personal Effects Storage

No Asbestos

B00F - R0010 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0011 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00F - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0013 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00G - General Learning - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible slab on ground no access points.
Ceiling Voids	No Asbestos Found

Interior

B00G - R0001 - Personal Effects Storage

No Asbestos

B00G - R0002 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0003 - Practical Activities - 1hb

No Asbestos

B00G - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0006 - Practical Activities - 1hb

No Asbestos

B00G - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0008 - Personal Effects Storage

No Asbestos

B00G - R0009 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0010 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0011 - Personal Effects Storage

No Asbestos

B00G - R0012 - Practical Activities - 1hb

No Asbestos

B00G - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0014 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0015 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0016 - Practical Activities - 1hb

No Asbestos

B00G - R0017 - Personal Effects Storage

No Asbestos

B00G - R0018 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00G - R0019 - Distribution Board

Note: No inspection of live electrical installation.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

No Asbestos

B00G - R0020 - Movement

No Asbestos

B00G - R0021 - Movement

No Asbestos

B00G - R0022 - Movement

No Asbestos

B00G - R0023 - Movement

No Asbestos

B00G - R0024 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00H - General Learning - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible slab on ground no access points.
Ceiling Voids	No Asbestos Found

Interior

B00H - R0001 - Toilets - Boys

No Asbestos

B00H - R0002 - Disabled Toilet

No Asbestos

B00H - R0003 - Cleaning Supplies

No Asbestos

B00H - R0004 - Toilets - Girls

No Asbestos

B00H - R0005 - Personal Effects Storage

No Asbestos

B00H - R0006 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0007 - Practical Activities - 1hb

No Asbestos

B00H - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0009 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0010 - Practical Activities - 1hb

No Asbestos

B00H - R0011 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0012 - Personal Effects Storage

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0013 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00H - R0014 - Movement

No Asbestos

B00H - R0015 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0016 - Movement

No Asbestos

B00H - R0017 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00I - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00I - R0001 - Movement

No Asbestos

B00I - R0002 - Practical Activities - 1hb

No Asbestos

B00I - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00I - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00I - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00I - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00I - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found

B00I - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00J - General Learning/Other - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible slab on ground no access points.
Ceiling Voids	No Asbestos Found

Interior

B00J - R0001 - External Movement

No Asbestos

B00J - R0002 - Garden Store

No Asbestos

B00J - R0003 - General Assistant/Bulk Store

No Asbestos

B00J - R0004 - Sports Store

No Asbestos

B00J - R0005 - Practical Activities - 1hb

No Asbestos

B00J - R0006 - Home Base Store

No Asbestos

B00J - R0007 - Home Base

No Asbestos

B00J - R0008 - Withdrawal Space - 2hb

No Asbestos

B00J - R0009 - Practical Activities - 1hb

No Asbestos

B00J - R0010 - Home Base

No Asbestos

B00J - R0011 - Home Base Store

No Asbestos

B00J - R0012 - Main Switch Board

No Asbestos

B00J - R0013 - Practical Activities - 1hb

No Asbestos

B00J - R0014 - Withdrawal Space - 1hb

No Asbestos

B00J - R0015 - Home Base Store

No Asbestos

B00J - R0016 - Home Base

No Asbestos

B00J - R0017 - Special Programs Room

No Asbestos

B00J - R0018 - Special Programs Store

No Asbestos

B00J - R0019 - Cleaning Distributed Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D13065 - Learning Unit - Standard With P.A.A. : Placement Date - 17/12/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D13303 - Learning Unit - Standard With P.A.A. : Placement Date - 11/07/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D15866 - Learning Unit - Standard With P.A.A. : Placement Date - 20/12/2012

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 602 - D16166 - Learning Unit - Standard With P.A.A. : Placement Date - 10/12/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017