Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Warilla North Public School (4333)**
Region :	**Illawarra and South East**
State Electorate :	**Shellharbour**
Local Government Area :	**Shellharbour**

Initial Survey :	**Noel Arnold & Associates : 04 - May - 2008**
Reviewed By :	**AECOM : 18 - Jun - 2015**

4333 - Warilla North Public School
Site Plan (11379)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00A - Administration - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 4333/B00A/Eaves Linings/S10	**No Asbestos Detected**
Ceiling Voids - Flat Roof	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	

Interior

B00A - R0001 - Staff Room

No Asbestos

B00A - R0006 - Entry Vestibule

No Asbestos

B00A - R0007 - Principal

No Asbestos

B00A - R0008 - General Storeroom

No Asbestos

B00A - R0009 - Staff Toilet

No Asbestos

B00A - R0010 - General Storeroom

No Asbestos

B00A - R0011 - Staff Toilet

No Asbestos

B00A - R0012 - Staff Toilet

No Asbestos

B00A - R0013 - General Storeroom

No Asbestos

B00A - R0014 - Kiln Room

No Asbestos

B00A - R0015 - Interview

No Asbestos

B00A - R0016 - Movement

No Asbestos

B00A - R0017 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4333/B00A/Eaves Linings/S10	**No Asbestos Detected**

B00A - R0018 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4333/B00A/Eaves Linings/S10	**No Asbestos Detected**

B00A - R0019 - Cleaning Distributed Store

No Asbestos

B00A - R0020 - General Storeroom

No Asbestos

B00A - R0021 - General Storeroom

No Asbestos

B00A - R0022 - Sick Bay

No Asbestos

B00A - R0023 - Clerical Office

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00B - General Learning - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 4333/B00B/Eaves Linings/S11	**No Asbestos Detected**
Ceiling Voids - Flat Roof	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	

Interior

B00B - R0001 - Home Base

No Asbestos

B00B - R0002 - Home Base Store

No Asbestos

B00B - R0003 - Personal Effects Storage

No Asbestos

B00B - R0004 - Movement

No Asbestos

B00B - R0005 - Home Base

No Asbestos

B00B - R0006 - Home Base Store

No Asbestos

B00B - R0007 - Home Base

No Asbestos

B00B - R0008 - Home Base Store

No Asbestos

B00B - R0009 - Movement

No Asbestos

B00B - R0010 - Personal Effects Storage

No Asbestos

B00B - R0011 - Home Base

No Asbestos

B00B - R0012 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

B00C - Staff Facilities/General Learning - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 4333/B00C/Eaves Linings/S12	**No Asbestos Detected**
Ceiling Voids - Flat Roof	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	

Interior

B00C - R0001 - Movement

No Asbestos

B00C - R0002 - Main Switch Board

No Asbestos

B00C - R0004 - Withdrawal Space - 1hb

No Asbestos

B00C - R0005 - Home Base

No Asbestos

B00C - R0006 - Toilets - Boys/Girls

No Asbestos

B00C - R0007 - Home Base Store

No Asbestos

B00C - R0008 - Personal Effects Storage

No Asbestos

B00C - R0009 - Movement

No Asbestos

B00C - R0010 - Staff Toilet

No Asbestos

B00C - R0011 - Staff Kitchen

No Asbestos

B00C - R0012 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00H - Communal Facilities - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4333/B00H/Eaves Linings/S8					**Chrysotile (white asbestos)**
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00H - R0003 - Movement

No Asbestos

B00H - R0004 - Reading Area

No Asbestos

B00H - R0005 - Library Office/Workroom

No Asbestos

B00H - R0006 - Communications Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00I - Pupil Facilities - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Vermiculite	
	4333/B00I/Eaves Linings/S9	**No Asbestos Detected**
Ceiling Voids - Flat Roof	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	

Interior

B00I - R0001 - Canteen

No Asbestos

B00I - R0002 - Canteen Office/Store

No Asbestos

B00I - R0003 - Canteen Office/Store

No Asbestos

B00I - R0004 - Staff Toilet

No Asbestos

B00I - R0005 - Movement

No Asbestos

B00I - R0006 - General Storeroom

No Asbestos

B00I - R0007 - Toilets - Girls

No Asbestos

B00I - R0008 - Plant

No Asbestos

B00I - R0011 - Toilets - Boys

No Asbestos

B00I - R0012 - Cleaning Distributed Store

No Asbestos

B00I - R0013 - Toilets - Boys

No Asbestos

B00I - R0014 - Plant

No Asbestos

B00I - R0015 - Movement

No Asbestos

B00I - R0016 - General Storeroom

No Asbestos

B00I - R0017 - Disabled Shower/Toilet

No Asbestos

B00I - R0018 - Movement

No Asbestos

B00I - R0019 - Cleaning Distributed Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00J - Library - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 4333/B00J/Eaves Linings/S13	**No Asbestos Detected**
Ceiling Voids - Flat Roof	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	

Interior

B00J - R0001 - Home Base

No Asbestos

B00J - R0009 - Movement

No Asbestos

B00J - R0010 - Personal Effects Storage

No Asbestos

B00J - R0011 - Home Base

No Asbestos

B00J - R0012 - Home Base Store

No Asbestos

B00J - R0013 - Communal Space

No Asbestos

B00J - R0014 - Communal Space

No Asbestos

B00J - R0015 - Communications Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00K - Pupil Facilities - 1967 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids - Flat Roof	No Asbestos Found

Interior

B00K - R0001 - General Storeroom

No Asbestos

B00K - R0002 - Cleaning Supplies

No Asbestos

B00K - R0003 - Toilets - Girls

No Asbestos

B00K - R0004 - Cleaning Distributed Store

No Asbestos

B00K - R0005 - Toilets - Boys

No Asbestos

B00K - R0006 - Other-Vacant

No Asbestos

B00K - R0007 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017