Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Yetman Public School (3559)**
Region :	**New England**
State Electorate :	**Northern Tablelands**
Local Government Area :	**Inverell**

Initial Survey :	**Noel Arnold & Associates : 20 - May - 2008**
Reviewed By :	**Greencap-NAA : 04 - May - 2016**

3559 - Yetman Public School
Site Plan (11481)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00A - General Learning - 1966 - Timber (Timber)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found	
Ceiling Voids - Raked Ceiling	Non Accessible Area - height - 4 meters	

Interior

B00A - R0001 - External Movement

No Asbestos

B00A - R0002 - Special Programs Room

No Asbestos

B00A - R0003 - External Movement

No Asbestos

B00A - R0004 - General Storeroom

Partition Wall (Double Sided)	Flat AC Sheeting	
	3559/B00A/R0004/Wall Linings Internal/S8	**No Asbestos Detected**

B00A - R0005 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	
	3559/B00A/R0005/Ceiling Structures/Linings/S9	**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - General Learning/Library - 1962 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00B/Eaves Linings/S10					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Electrical Backing Board	Resinous Board	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00B/Electrical Backing Board/S2					**Chrysotile (white asbestos)**
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					

Interior

B00B - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00B/R0001/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00B - R0002 - Reading Area

No Asbestos

B00B - R0003 - Home Base

No Asbestos

B00B - R0004 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3559/B00B/R0005/Floor Coverings Res/Textile/S11					**No Asbestos Detected**

B00B - R0005 - Principal

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3559/B00B/R0005/Floor Coverings Res/Textile/S11					**No Asbestos Detected**

B00B - R0006 - Clerical Office

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00B/R0001/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Fume Cupboard	Vinyl Tiles (Under Floor Covering/Carpet)					
	3559/B00B/R0005/Floor Coverings Res/Textile/S11					**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00C - General Learning/Staff Facilities - 1967 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00C/Gable Verge Lining/S13					**Chrysotile (white asbestos)**
Panels Under Windows	Flat AC Sheeting	8m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00C/Panels Under Windows/S3					**Chrysotile (white asbestos)**
Eaves Linings	Flat AC Sheeting	10m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00C/Eaves Linings/S12					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Panels Above Doors and Windows	Flat AC Sheeting	3m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00C/Panels Above Doors and Windows/S14					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					

Interior

B00C - R0001 - External Movement

Panels Under Windows	Flat AC Sheeting	6m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00C/Panels Under Windows/S3					**Chrysotile (white asbestos)**
Panels Above Doors and Windows	Flat AC Sheeting	3m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00C/Panels Above Doors and Windows/S14					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Ceiling Structures/Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00B/R0001/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00C - R0002 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	56.81m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00C/R0002/Floor Coverings Res/Textile/S15					**Chrysotile (white asbestos)**
Floor Coverings Res/Textile	Adhesive					
	3559/B00C/R0002/Floor Coverings Res/Textile/S20					**No Asbestos Detected**

B00C - R0003 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00C/R0007/Floor Coverings Res/Textile/S4					**Chrysotile (white asbestos)**

B00C - R0004 - Personal Effects Storage

Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00C/R0007/Floor Coverings Res/Textile/S4					**Chrysotile (white asbestos)**

B00C - R0005 - Staff Room

No Asbestos

B00C - R0006 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00C/R0007/Floor Coverings Res/Textile/S4					**Chrysotile (white asbestos)**
Electrical Backing Board	Resinous Board	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00C/R0006/Electrical Backing Board/S16					**Chrysotile (white asbestos)**

B00C - R0007 - Movement

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00C/R0007/Floor Coverings Res/Textile/S4					**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

B00D - Pupil Facilities - 1960 - Timber (Timber)

Exterior

Wall Cladding	Flat AC Sheeting 3559/B00D/Wall Cladding/S5	**No Asbestos Detected**
Eaves Linings	Flat AC Sheeting 3559/B00D/Eaves Linings/S17	**No Asbestos Detected**
Ceiling Voids - Flat Roof	No Asbestos Found	
Underfloor Voids - Slab on Ground	No Asbestos Found	

Interior

B00D - R0001 - Canteen

No Asbestos

B00D - R0002 - External Movement

Wall Cladding	Flat AC Sheeting 3559/B00D/Wall Cladding/S5	**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00E - Pupil Facilities - 1966 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00E/Eaves Linings/S18					Chrysotile (white asbestos)
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00E - R0001 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00E/R0001/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)

B00E - R0002 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00E/R0001/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)

B00E - R0003 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00E/R0001/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)

B00E - R0004 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00E/R0001/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)

B00E - R0005 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00E/R0001/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)

B00E - R0006 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00E/R0001/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00F - Pupil Facilities - 1967 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	5m2	North, South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00F/Eaves Linings/S19					**Chrysotile (white asbestos)**
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00F - R0001 - Kiln Room

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3559/B00B/R0001/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Wall Linings Internal	Flat AC Sheeting					
	3559/B00F/R0001/Wall Linings Internal/S7					**No Asbestos Detected**

B00F - R0002 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Poor Condition - Extensive Damage (4)	Medium (2)	Medium Priority (4-5)
	3559/B00B/R0001/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

	Sample No	Test Result

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017