


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Adaminaby Public School (1007)
Region : Illawarra and South East
State Electorate : Monaro
Local Government Area : Snowy River

Initial Survey : Noel Arnold & Associates : 14 - May - 2008
Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library - 1909 - Timber (Timber)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - General Storeroom

No Asbestos

B00B - R0002 - Movement

No Asbestos

B00B - R0003 - Reading Area

No Asbestos

B00B - R0004 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Pupil Facilities - 1957 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	------	------------	--------------------	---------	--------------------

Assumed Asbestos

Ceiling Voids	Requires Inspection
---------------	---------------------

Underfloor Voids	Requires Inspection
------------------	---------------------

Interior**B00C - R0001 - Movement**

No Asbestos

B00C - R0002 - Toilets - Boys

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	1007/B00C/R0002/Wall Linings Internal/S1					

B00C - R0003 - Movement

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	1007/B00C/R0002/Wall Linings Internal/S1					

B00C - R0004 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	1007/B00C/R0002/Wall Linings Internal/S1					

B00C - R0005 - Drinking Facilities

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	1007/B00C/R0002/Wall Linings Internal/S1					

B00C - R0006 - Toilets - Girls

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	1007/B00C/R0002/Wall Linings Internal/S1					

B00C - R0007 - Movement

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	1007/B00C/R0002/Wall Linings Internal/S1					

B00C - R0008 - Personal Effects Storage

No Asbestos

B00C - R0009 - Movement

No Asbestos

B00C - R0010 - Home Base

No Asbestos

B00C - R0011 - Home Base

No Asbestos

B00C - R0012 - Withdrawal Space - 1hb

No Asbestos

B00C - R0013 - Home Base Store

No Asbestos

B00C - R0014 - Sick Bay

No Asbestos

B00C - R0015 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Shed - 1913 - Timber (Timber)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Sports Store

No Asbestos

B00D - R0002 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Library - 2007 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Reading Area

No Asbestos

B00E - R0002 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 505 - D13454 - Admin Staff/Principal/Secure Store : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		10 m2

R2 - Principal

Ceiling	Flat AC Sheet	Assumed Asbestos		16 m2
---------	---------------	------------------	--	-------

R3 - Staff Room

Ceiling	Flat AC Sheet	Assumed Asbestos		20 m2
---------	---------------	------------------	--	-------

R4 - Security Store

Ceiling	Flat AC Sheet	Assumed Asbestos		8 m2
---------	---------------	------------------	--	------

R5 - Clerical Office

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		18 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017