


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Arcadia Vale Public School (4132)
Region : Hunter/Central Coast
State Electorate : Lake Macquarie
Local Government Area : Lake Macquarie

Initial Survey : Noel Arnold & Associates : 22 - Apr - 2008
Reviewed By : AECOM : 17 - Jun - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Building Services - 1958 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids - Raked Ceiling No Asbestos Found

Interior

B00A - R0001 - Cleaning Supplies

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Pupil Facilities - 1970 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	30m2	South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4132/B00B/Wall Cladding/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Cladding	Flat AC Sheeting	16m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4132/B00B/Wall Cladding/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		
In-fill-panel	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4132/B00B/In-fill-panel/S2			Chrysotile (white asbestos)		

Interior

B00B - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4132/B00B/R0001/Ceiling Structures/Linings/S10			Chrysotile (white asbestos) , Crocidolite (blue asbestos)		
In-fill-panel	Flat AC Sheeting	1m	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4132/B00B/In-fill-panel/S2			Chrysotile (white asbestos)		

B00B - R0002 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4132/B00B/R0001/Ceiling Structures/Linings/S10			Chrysotile (white asbestos) , Crocidolite (blue asbestos)		
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4132/B00B/R0003/Partition Walls (Cubicles)/S9			Chrysotile (white asbestos)		

B00B - R0003 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4132/B00B/R0001/Ceiling Structures/Linings/S10			Chrysotile (white asbestos) , Crocidolite (blue asbestos)		
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4132/B00B/R0003/Partition Walls (Cubicles)/S9			Chrysotile (white asbestos)		

B00B - R0004 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles					
	4132/B00B/R0004/Floor Coverings Res/Textile/S8			No Asbestos Detected		

B00B - R0005 - Movement

Floor Coverings Res/Textile	Vinyl Tiles					
	4132/B00B/R0004/Floor Coverings Res/Textile/S8			No Asbestos Detected		

B00B - R0006 - Home Base

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Pupil Facilities - 1958 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	30m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4132/B00C/R0003/Ceiling Structures/Linings/S11					Chrysotile (white asbestos) , Crocidolite (blue asbestos)

Interior

B00C - R0001 - Canteen

No Asbestos

B00C - R0002 - No Access

No Asbestos

B00C - R0003 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4132/B00C/R0003/Ceiling Structures/Linings/S11					Chrysotile (white asbestos) , Crocidolite (blue asbestos)

B00C - R0004 - Home Base

No Asbestos

B00C - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	4132/B00C/R0005/Ceiling Structures/Linings/S3					
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	4132/B00C/R0005/Ceiling Structures/Linings/S3					

B00C - R0006 - Home Base

No Asbestos

B00C - R0007 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4132/B00C/R0007/Floor Coverings Res/Textile/S7					Chrysotile (white asbestos)

B00C - R0008 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4132/B00C/R0003/Ceiling Structures/Linings/S11					Chrysotile (white asbestos) , Crocidolite (blue asbestos)

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	4132/B00D/R0002/Floor Coverings Res/Textile/S4					

B00C - R0009 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4132/B00C/R0003/Ceiling Structures/Linings/S11					Chrysotile (white asbestos) , Crocidolite (blue asbestos)

B00C - R9001 - Sports Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Library - 1983 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
- Area inaccessible

Ceiling Voids - Raked Ceiling No Asbestos Found

Interior

B00D - R0001 - External Movement

No Asbestos

B00D - R0002 - Library Office/Workroom

Floor Coverings Res/Textile Vinyl Tiles
4132/B00D/R0002/Floor Coverings Res/Textile/S4 **No Asbestos Detected**

B00D - R0003 - No Access

Wall Linings Internal	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------	------------------	-----	------------	--------------------	---------	--------------------

4132/B00D/R0003/Wall Linings Internal/S5 **Chrysotile (white asbestos)**

B00D - R0004 - Reading Area

No Asbestos

B00D - R0005 - Toilets - Boys/Girls

Partition Walls (Cubicles)	Compressed AC Sheet	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	---------------------	-----	------------	--------------------	---------	--------------------

4132/B00D/R0005/Partition Walls (Cubicles)/S6 **Chrysotile (white asbestos)**

B00D - R0006 - Toilets - Boys/Girls

Partition Walls (Cubicles)	Compressed AC Sheet	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	---------------------	-----	------------	--------------------	---------	--------------------

4132/B00D/R0005/Partition Walls (Cubicles)/S6 **Chrysotile (white asbestos)**

B00D - R0007 - Security Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1958 - Timber Shed (Timber Shed)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Flat Roof No Asbestos Found

Interior

B00E - R0001 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00F - R0001 - External Movement

No Asbestos

B00F - R0002 - Practical Activities - 1hb

No Asbestos

B00F - R0003 - Home Base Store

No Asbestos

B00F - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0007 - Home Base Store

No Asbestos

B00F - R0008 - Practical Activities - 1hb

No Asbestos

B00F - R0009 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00G - R0001 - External Movement

No Asbestos

B00G - R0002 - Practical Activities - 1hb

No Asbestos

B00G - R0003 - Home Base Store

No Asbestos

B00G - R0004 - Home Base

No Asbestos

B00G - R0005 - Withdrawal Space - 2hb

No Asbestos

B00G - R0006 - Home Base

No Asbestos

B00G - R0007 - Home Base Store

No Asbestos

B00G - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 502 - D14787 - Admin Staff/Principal/Clerk/Dup/Clinic : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				23.04 m2

Interior

R1 - Clerical Office

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				16 m2

R10 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos				12 m2
---------	---------------	------------------	--	--	--	-------

R2 - Security Store

Ceiling	Flat AC Sheet	Assumed Asbestos				1 m2
---------	---------------	------------------	--	--	--	------

R3 - Duplicating Wookroom

Ceiling	Flat AC Sheet	Assumed Asbestos				12 m2
---------	---------------	------------------	--	--	--	-------

R4 - Clinic-Waiting

Ceiling	Flat AC Sheet	Assumed Asbestos				16 m2
---------	---------------	------------------	--	--	--	-------

R5 - Staff Room

Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2
---------	---------------	------------------	--	--	--	-------

R6 - Principal

Ceiling	Flat AC Sheet	Assumed Asbestos				16 m2
---------	---------------	------------------	--	--	--	-------

R7 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos				2 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				5 m2

R8 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos				2 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				5 m2

R9 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				27 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017